

## Work Order Detail

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 659,680.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
441	01/20/2012	04/25/2012	Closed	0.00	

Description: Prep for Service

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
156 - Complete Cooling Services, Inv. # 16147, Desc: Refurbished Radiator					\$1,588.67	\$1,588.67
163 - Dan Fredrickson Signs, Inv. # 710, Desc: Installation and					\$2,603.13	\$2,603.13
43 - Hogle Bus & Truck Co., Inv. # 4473, PO # 5526, Desc: Prep bus and paint white					\$4,250.00	\$4,250.00
159 - Sardo Bus & Coach Upholstery, Inv. # 42345, Desc: Install Complete new interior					\$10,067.24	\$10,067.24
13:Brakes		\$96.86	\$0		\$0.00	\$96.86
Pillsbury: Pad Fitting Kit; 1 per axle; EL3: 04-01-1008 (1.000)		\$96.86				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
13:Brakes		\$144.89	\$0		\$0.00	\$144.89
Pillsbury: Pads brake EL3: 04-01-1019 (1.000)		\$144.89				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
13:Brakes		\$1,994.36	\$2,400.00		\$0.00	\$4,394.36
Pillsbury: Sensor, ABS, 90, Brake (gillig also): R955342 (2.000)		\$80.24				
Pillsbury: Clevis Pin Kit Stainless Steel -Incl 1/2 & 1/4 pin: AS4012 (1.000)		\$2.31				
Pillsbury: Gasket Hub Cap Front Wheel MCI: 330-3060 (2.000)		\$3.74				
Pillsbury: Seal Frt. MCI EL3: 380048A (1.000)		\$34.97				
Pillsbury: Seal Rear Drive Axle MCI/Freightliner/Gillig/B.B. Q- Bus: 380003A (2.000)		\$63.74				
Pillsbury: Bearing Race Drive Axle Inner MCI D4500: 592A (2.000)		\$28.10				
Pillsbury: Bearing Drive Axle Inner MCI D4500: 594A		\$42.30				

Pillsbury: Bearing Drive Axle Outer MCI D4500: 580 (2.000)	\$36.54			
Pillsbury: Bearing Race Drive Axle Outer MCI D4500: 572 (2.000)	\$22.22			
Pillsbury: Seal Rear Drive Axle MCI/Freightliner/Gillig/B.B. Q- Bus: 380003A (1.000)	\$31.11			
Pillsbury: Gasket: M2534 (2.000)	\$1.36			
Pillsbury: Clevis Pin Kit Stainless Steel -Incl 1/2 & 1/4 pin: AS4012 (2.000)	\$4.62			
Pillsbury: Seal Frt. MCI EL3: 380048A (2.000)	\$69.94			
set 423 6420/6461a (1.000)	\$105.59			
Pillsbury: Bearing Front Wheel Outer MCI D4500: 555STRB (2.000)	\$70.08			
Pillsbury: Bearing Front Wheel Inner MCI D4500: 6461ATRB (1.000)	\$72.16			
Pillsbury: Bearing Race Front Wheel Outer MCI D4500: 552ATRB (2.000)	\$29.06			
Pillsbury: Gasket Hub Cap Front Wheel MCI: 330-3060 (2.000)	\$3.74			
Pillsbury: Sensor 5.8' Kit: R955338 (1.000)	\$53.99			
Pillsbury: Ring Exciter: 02-01-1081 (2.000)	\$612.00			
Pillsbury: Sensor 5.8' Kit: R955338 (1.000)	\$55.68			
Pillsbury: Clevis Pin Kit Stainless Steel -Incl 1/2 & 1/4 pin: AS4012 (2.000)	\$4.62			
Pillsbury: Gear Lube: Oil Gear 80W-90 BULK in Pints (20.000)	\$34.80			
5001247K Mounting Bracket Kit (1.000)	\$56.49			
Pillsbury: Pigtail Heater for Bendix AD-9 Air Dryer: 109869N (1.000)	\$10.58			
Pillsbury: Pad Fitting Kit; 1 per axle; EL3: 04-01-1008 (1.000)	\$96.86			
Pillsbury: Pads brake EL3: 04-01-1019 (1.000)	\$144.89			
Pillsbury: Radiator Bracket Upper MCI EL3: 06-01-1015 (1.000)	\$115.81			
Pillsbury: Hose, Radiator: 16-11-1123 (1.000)	\$34.04			
Pillsbury: Hose Hump Charge Air (Straight ) MCI D4500: 9L-3-163 (2.000)	\$62.86			
43380 MT Bracket (2.000)	\$9.92			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (48.00)		\$2,400.00		
Miscellaneous Labor		\$0		
Other			\$0	
20:Steering	\$347.18	\$0	\$0.00	\$347.18
Pillsbury: King Pin Kit EL3/ D4500 MCI: 01-01-1079	\$347.18			

(2.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$327.34	\$0	\$0.00	\$327.34
Pillsbury: Air Bag EL3:	\$327.34			
12-01-1048 (2.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$499.48	\$0	\$0.00	\$499.48
Pillsbury: Spring Air Bag, Drive	\$499.48			
Axle: 12-03-1041 (4.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$390.00	\$0	\$0.00	\$390.00
Pillsbury: Bushing- Radius	\$390.00			
Rod, EL3: 12-05-1002 (4.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$121.44	\$0	\$0.00	\$121.44
Pillsbury: Bushing-Sway Bar,	\$121.44			
EL3: 12-05-1012 (16.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$254.30	\$0	\$0.00	\$254.30
Pillsbury: End Bushing EL3	\$254.30			
MCI: 12-05-1013 (2.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$145.58	\$0	\$0.00	\$145.58
Pillsbury: Apex Bushing EL3	\$145.58			
MCI: 12-05-1019 (1.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$122.24	\$0	\$0.00	\$122.24
Young Building: Washer Sway	\$122.24			
Bar, EL3: 12-05-1034 (16.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$112.44	\$0	\$0.00	\$112.44
Pillsbury: Stud Sway Bar, EL3:	\$112.44			
12-05-1051 (4.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$676.56	\$0	\$0.00	\$676.56
Pillsbury: Shock, Absorber,	\$676.56			
Drive, EL3: 12-05-1188				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$45.77	\$988.00	\$0.00	\$1,033.77
Pillsbury: Bearing Race Front	\$45.77			
Wheel Inner MCI D4500:				
6420TRB (1.000)				
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (19.76)		\$988.00		
Miscellaneous Labor		\$0		

Other			\$0	
22:Tires	\$1,865.93	\$347.50	\$0.00	\$2,213.43
Pillsbury: Tire New Virgin	\$566.00			
FS400: 315/80R 22.5 New Virgin Tire (2.000)				
Pillsbury: Tire FS400 216126: 315/80R 22.5 L FI (4.000)	\$1,170.33			
Pillsbury: Cover Lug Nut MCI D4500 (Hug-A-Lug): 001812 (60.000)	\$129.60			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (1.57)		\$78.50		
0081 - WOLF, PATRICK (5.38)		\$269.00		
Miscellaneous Labor		\$0		
Other			\$0	
25:Transmission (Auto)	\$133.39	\$156.50	\$0.00	\$289.89
Pillsbury: Filter Kit	\$29.59			
Transmission Allison (Short Filter): 7741XE (1.000)				
Pillsbury: ATF (Synthetic) Bulk Quart: ATF Synthetic Bulk Pillsbury (30.000)	\$103.80			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (3.13)		\$156.50		
Miscellaneous Labor		\$0		
Other			\$0	
27:Wheels, Rims, Hubs & Mounts	\$634.00	\$0	\$0.00	\$634.00
Pillsbury: Wheel, Aluminum 22.5: 29730AIP (2.000)	\$634.00			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
31:Charging	\$329.90	\$78.50	\$0.00	\$408.40
Work Comments: 31 - Removed and rplaced both batteries.				
Pillsbury: Battery 1400CCA Top Post Heavy Duty Workaholic: 8D-MHD(7271)	\$329.90			
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (1.57)		\$78.50		
Miscellaneous Labor		\$0		
Other			\$0	
31:Charging	\$144.99	\$0	\$0.00	\$144.99
Young Building: Pro Sport 12 Onboard Charger: 43012 (1.000)	\$144.99			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
31:Charging	\$26.62	\$76.50	\$0.00	\$103.12
Work Comments: KP- install new seal on alt				
Pillsbury: Alternator Kit Front Seal Delco 50DN Belt Drive: 10514967 (1.000)	\$26.62			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (1.53)		\$76.50		
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$490.00	\$0	\$0.00	\$490.00
Pillsbury: LED Tail Light Conversion Kit for EL3: M1-00642 (1.000)	\$490.00			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$623.58	\$0	\$0.00	\$623.58

Pillsbury: Light Non LED Amber Side Marker/Turn MCI EL3: 07-07-1003 (1.000)	\$18.20			
Pillsbury: Light Red Marker, EL3: 07-07-1013 (3.000)	\$120.36			
Pillsbury: Light Lamp Rear Stop 12v LED: 07-07-1017 (2.000)	\$352.10			
Pillsbury: Cornering Light, LED, MCI: 07-07-1476 (2.000)	\$132.92			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$0	\$0	\$0.00	\$0.00
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$0	\$0	\$0.00	\$0.00
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$0	\$0	\$0.00	\$0.00
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$22.12	\$0	\$0.00	\$22.12
Pillsbury: Lens High Mount: 07-07-1050 (2.000)	\$22.12			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$4.08	\$0	\$0.00	\$4.08
Pillsbury: Gasket Cover: 07-07-1051 (2.000)	\$4.08			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$27.02	\$0	\$0.00	\$27.02
Pillsbury: Switch Rocker Door EL3: 07-19-1016 (1.000)	\$27.02			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$163.65	\$0	\$0.00	\$163.65
Pillsbury: Light LED W/S Wash Illumination Bulb MCI D4500: 19-11-1512 (15.000)	\$163.65			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$72.90	\$0	\$0.00	\$72.90
Young Building: L.E.D. Green, Single Chip: 19-11-2087 (15.000)	\$72.90			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$46.86	\$0	\$0.00	\$46.86
Young Building: L.E.D. Red, Single Chip: 19-11-2089 (11.000)	\$46.86			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$230.30	\$518.00	\$0.00	\$748.30

Work Comments: KP\_ replace all interior fluorescent tubes, 3 ballasts; popped 1/4" rivets into forward portion of parcel rack--loosened from ceiling.

Young Building: L.E.D. Red, Single Chip: 19-11-2089 (4.000)	\$17.04			
Pillsbury: Ballast Interior Light EL3: 07-07-1040 (2.000)	\$135.26			
Pillsbury: Light Bulb Fluorescent 32 Watt T8 48" Bi- Pin: F32/741/ECO (26.000)	\$69.42			
Pillsbury: Light Bulb Pass. Sevice Module 28V 10W: 03-08-1162 (7.000)	\$5.60			
Pillsbury: Light Marker Lamp Clear: 15200C (2.000)	\$2.98			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (4.46)		\$223.00		
74 - PHIPPS, KEVIN (5.90)		\$295.00		
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$183.91	\$711.50	\$0.00	\$895.41

Work Comments: Inspection, make a List-o-parts  
KP-- O/H oil cooler/filter head asm.

Pillsbury: Gasket Oil Pan Series 60 Detroit Diesel: A-23522279 (1.000)	\$35.65			
Pillsbury: Oil Cooler Gasket Kit: 23537789 (1.000)	\$24.98			
Pillsbury: Isolator, Oil Pan Bolt Detroit: 23517242 (10.000)	\$30.50			
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)	\$15.88			
Pillsbury: Filter Coolant: 4206 (1.000)	\$9.38			
Pillsbury: Filter Fuel: 3118 (1.000)	\$4.02			
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)	\$3.91			
DDE/08929102 Oil Pan gasket (1.000)	\$29.81			
Pillsbury: Filter Air EL3: 6774 (1.000)	\$29.78			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (10.28)		\$514.00		
74 - PHIPPS, KEVIN (3.95)		\$197.50		
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$474.39	\$1,264.00	\$0.00	\$1,738.39

Work Comments: Install aux heater; make all mounting hardware, made to fit.Clean and reattach fuel line to filter housing.

24 Volt Blower Motor (2.000)	\$179.96			
Pillsbury: A/C Ester Oil 100: CQE31 (1.000)	\$19.49			
Pillsbury: Filter Dryer EL3: 16-04-1004 (1.000)	\$58.94			
Pillsbury: Freon R134A per Lb.: R134A (24.000)	\$216.00			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (12.33)		\$616.50		
6030 - STRICKER, DJ (12.95)		\$647.50		
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$169.59	\$0	\$0.00	\$169.59
Young Building: Coolant Pipe,	\$169.59			

Wabasto, EL3: 16-11-1155 (1.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$58.48	\$0	\$0.00	\$58.48
Pillsbury: Coolant Tube, Wabasto, EL3: 16-11-1153 (1.000)	\$58.48			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$164.54	\$0	\$0.00	\$164.54
Pillsbury: Isolator Radiator Lower: 06-01-1050 (2.000)	\$164.54			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$67.51	\$0	\$0.00	\$67.51
Pillsbury: Hose, Aux Heater: 16-11-1019 (1.000)	\$37.15			
Pillsbury: Hose Elbow, 1.375 to 1.5: 16-11-1017 (1.000)	\$30.36			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$25.95	\$0	\$0.00	\$25.95
Pillsbury: Hose Elbow: 16-11-1046 (1.000)	\$25.95			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$169.59	\$0	\$0.00	\$169.59
Young Building: Coolant Pipe, Wabasto, EL3: 16-11-1155 (1.000)	\$169.59			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$2,236.45	\$0	\$0.00	\$2,236.45
Pillsbury: ? Auxiliary Heater Kit: 16-16-1102 (1.000)	\$2,236.45			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$56.67	\$831.00	\$0.00	\$887.67
Work Comments: KP- remove rad/CAC asm and seperate. Installed recored radiator, CAC and all other related parts, filled with coolant.				
Pillsbury: Radiator Cap, 10LB, MCI EL3: 703-1708 (1.000)	\$5.01			
08-27-1002 Belt Fan Drive (1.000)	\$51.66			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (1.13)		\$56.50		
74 - PHIPPS, KEVIN (15.49)		\$774.50		
Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$198.36	\$0	\$0.00	\$198.36
Pillsbury: AD-IP Air Dryer 12V Complete: 109477X (1.000)	\$198.36			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
70:Body Sheet Metal	\$2,107.85	\$7,532.50	\$0.00	\$9,640.35
Work Comments: took electric shut-off door and the right rear engine access door off another bus				

	waiting to be repaired.				
Pillsbury: Mirror, LH, EL3: 03-22-1359 (1.000)	\$551.15				
Pillsbury: Mirror, RH, EL3: 03-22-1356 (1.000)	\$551.15				
Pillsbury: Bolt Kit for Mirror, EL3: 19-01-1776PK (1.000)	\$17.75				
Pillsbury: Rotor EL3: 15-02-1010 (2.000)	\$438.00				
Pillsbury: Guide, Side Rail, Set of 2: 03-09-1018 (12.000)	\$78.00				
Pillsbury: Shade, Grey, 45", EL3: 03-30-1015 (2.000)	\$150.16				
Pillsbury: Door seal: 03-31-1188 (1.000)	\$54.00				
Pillsbury: Seal E-Door Frame 200" EL3 MCI: 03-32-1083 (1.000)	\$40.88				
Young Building: Flap-Mud Drive Axle LH: 03-33-1020 (2.000)	\$113.38				
Pillsbury: Flap-Mud, Drive Axle RH: 03-33-1044 (2.000)	\$113.38				
Miscellaneous Parts	\$0				
77 - SCHNEIDER, NICHOLAS (54.44)		\$2,722.00			
82 - BLANCO, VICTOR (91.61)		\$4,580.50			
7050 - STRAND, MATTHEW (4.60)		\$230.00			
Labor Comments: Finishing touches					
Miscellaneous Labor		\$0			
Other			\$0		
70:Body Sheet Metal	\$127.60	\$0	\$0.00		\$127.60
Pillsbury: Ball Assembly: 03-08-1152 (10.000)	\$127.60				
Miscellaneous Parts	\$0				
Miscellaneous Labor		\$0			
Other			\$0		
72:Body Misc	\$123.04	\$1,416.00	\$0.00		\$1,539.04
Work Comments: Removed and installed new flooring.					
03-15-1155 (8.000)	\$123.04				
Miscellaneous Parts	\$0				
9024 - LEWISON, CHAD (26.00)		\$1,300.00			
77 - SCHNEIDER, NICHOLAS (2.32)		\$116.00			
Miscellaneous Labor		\$0			
Other			\$0		
72:Body Misc	\$1,065.42	\$581.50	\$0.00		\$1,646.92
Work Comments: KP- ent door and radiator door seals installed					
03-31-1190 Seal front Rad Door 34.85" LG (1.000)	\$12.81				
16-09-1005 Brushes pack of 2 (4.000)	\$97.56				
Pillsbury: Ballast Interior Light EL3: 07-07-1040 (8.000)	\$541.04				
Pillsbury: Filter Air EL3: 6774 (1.000)	\$29.78				
03-02-1038 Grabrail ASM- Stepwell (1.000)	\$166.71				
03-15-3826 Extrusion-Vinyl, Seat rail (4.000)	\$97.84				
03-15-3830 Filler-trim Seat Rail, 96" Long (8.000)	\$119.68				
Miscellaneous Parts	\$0				



5/7/2019

## Work Order Detail

6030 - STRICKER, DJ (10.26)		\$513.00			
74 - PHIPPS, KEVIN (1.37)		\$68.50			
Miscellaneous Labor		\$0			
Other				\$0	
77:Mirrors	\$0	\$133.50		\$0.00	\$133.50
Miscellaneous Parts	\$0				
6030 - STRICKER, DJ (2.67)		\$133.50			
Miscellaneous Labor		\$0			
Other				\$0	
DO:DOT Inspection	\$0	\$45.00		\$0.00	\$45.00
Miscellaneous Parts	\$0				
6030 - STRICKER, DJ (0.90)		\$45.00			
Miscellaneous Labor		\$0			
Other				\$0	
	\$0.00	\$17,323.13	\$17,080.00	\$0	\$18,509.04
					<u>\$52,912.17</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

		Location: HBG		Department: HBG1-Accounting	
	Recall:	Campaign #		Date:	
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
1320	02/16/2012	02/16/2012	Closed	0.00	
Description: Replace Batteries					
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>
32:Cranking			\$329.90	\$100.00	
				\$0.00	\$429.90
Work Comments: Batteries were over charged by on board charger.					
Pillsbury: Battery 1400CCA			\$329.90		
Top Post Heavy Duty					
Workaholic: 8D-MHD(7271)					
Miscellaneous Parts			\$0		
0081 - WOLF, PATRICK (2.00)				\$100.00	
Labor Comments: When to Holyoke and replaced batteries, found charge to be bad will replace when new one arrives					
Miscellaneous Labor				\$0	
Other					\$0
	\$0.00	\$329.90	\$100.00	\$0	\$0
					<u>\$429.90</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

		Miles: 659,860.0			
		Location: HBG		Department: HBG1-Accounting	
	Recall:	Campaign #		Date:	
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
3610	04/27/2012	04/30/2012	Closed	0.00	
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>
73:Seats			\$725.00	\$301.50	
				\$0.00	\$1,026.50
Work Comments: installed new drivers seat and am/fm radio					
Young Building: Seat Bostrom			\$725.00		
Driver's: 2345039-900 (1.000)					
Miscellaneous Parts			\$0		
77 - SCHNEIDER, NICHOLAS (6.03)				\$301.50	
Labor Comments: new drivers seat and am/fm radio					
Miscellaneous Labor				\$0	
Other					\$0
	\$0	\$725.00	\$301.50	\$0	\$0
					<u>\$1,026.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate: PRZ9154

		Location: HBG		Department: HBG1-Accounting			
		Recall:	Campaign #	Date:			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
3872	05/07/2012	06/04/2012	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
anit-freeze coolant leak-see notes			\$0	\$12.50		\$0.00	\$12.50
Maintenance Requested: 1885 - 05/22/2012 - anit-freeze coolant leak-see notes							
Requestor Notes: -check engine light came one after trip started							
-small anti-freeze coolant leak at left rear of bus (radiator?) stopped after it warmed up - maybe a clamp?							
Technician Response:							
Maint Req Status: Completed							
Miscellaneous Parts			\$0				
6030 - STRICKER, DJ (0.25)				\$12.50			
Miscellaneous Labor				\$0			
Other						\$0	
SEE COMMENTS			\$0	\$12.50		\$0.00	\$12.50
Maintenance Requested: 1758 - 05/14/2012 - SEE COMMENTS							
Requestor Notes: ROCK CHIP DOOR SIDE WINDSHIELD; ABS LIGHT IS ON; ENGINE LIGHT AND ASSIST LIGHT ARE ON							
Technician Response:							
Maint Req Status: Completed							
Miscellaneous Parts			\$0				
6030 - STRICKER, DJ (0.25)				\$12.50			
Miscellaneous Labor				\$0			
Other						\$0	
35:Instrument & Gauges			\$9.55	\$332.50		\$0.00	\$342.05
S449-711-031-0 Sensor			\$9.55				
Cable (1.000)							
Miscellaneous Parts			\$0				
6030 - STRICKER, DJ (6.65)				\$332.50			
Labor Comments: ABS light on. Found no connection from left front wheel sensor to ABS module.							
Replaced harness for the fron harness.							
Miscellaneous Labor				\$0			
Other						\$0	
40:Engine			\$0	\$124.00		\$0.00	\$124.00
Miscellaneous Parts			\$0				
6030 - STRICKER, DJ (2.48)				\$124.00			
Labor Comments: check " Engine light" and "ABS light" on. The engine light is the med jake brake, and the ABS light is a broken connection on the RHS steer sensor wire doesnt have a connection.							
Found jake brake wire shorted on housing.							
Miscellaneous Labor				\$0			
Other						\$0	
43:Cooling			\$51.26	\$15.00		\$0.00	\$66.26
Pillsbury: Sensor Coolant			\$51.26				
Surge Tank: 07-08-1119 (1.000)							
Miscellaneous Parts			\$0				
6030 - STRICKER, DJ (0.30)				\$15.00			
Labor Comments: coolane leak and install sensor							
Miscellaneous Labor				\$0			
Other						\$0	
70:Body Sheet Metal			\$0	\$216.00		\$0.00	\$216.00
Miscellaneous Parts			\$0				
82 - BLANCO, VICTOR (4.32)				\$216.00			
Miscellaneous Labor				\$0			
Other						\$0	
73:Seats			\$0	\$12.50		\$0.00	\$12.50
Miscellaneous Parts			\$0				
6030 - STRICKER, DJ (0.25)				\$12.50			
Labor Comments: installed recline knobs							

5/7/2019

## Work Order Detail

Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$1,195.02	\$741.50	\$0.00	\$1,936.52
Maintenance Requested: 1694 - 05/08/2012 - water leak inside middle of bus, pa system,wipers				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
24-51-0016 Strip/Lock	\$189.35			
Windshield 100' Roll (1.000)				
Pillsbury: Fence Rubber w/	\$595.95			
Shield Retainer MCI EL3:				
03-27-1046 (1.000)				
Pillsbury: Glass Windshield	\$188.00			
Front RH w/Mask MCI EL3:				
03-27-1326 (1.000)				
Pillsbury: Glass Windshield	\$188.00			
Front LH w/Mask MCI EL3:				
03-27-1325 (1.000)				
Pillsbury: W/S Washer Pump	\$33.72			
MCI: 03-34-1039 (1.000)				
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (9.25)		\$462.50		
Labor Comments: Caulked drivers window and sealed up top valance Replaced front windsheild fence, both windsheilds and buffed upper valance.				
0081 - WOLF, PATRICK (5.58)		\$279.00		
Miscellaneous Labor		\$0		
Other			\$0	
77:Mirrors	\$178.82	\$121.00	\$0.00	\$299.82
Pillsbury: Switch ASM-Joystick,	\$178.82			
Mirror: 07-08-1891 (2.000)				
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (2.42)		\$121.00		
Labor Comments: replaced mirror switches.				
Miscellaneous Labor		\$0		
Other			\$0	
78:Doors Entrance / Exit	\$0	\$73.50	\$0.00	\$73.50
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (1.47)		\$73.50		
Labor Comments: Rewired and replaced outside door switch and removed outside kneel switch.				
Miscellaneous Labor		\$0		
Other			\$0	
79:Lavatory	\$0	\$205.00	\$0.00	\$205.00
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (4.10)		\$205.00		
Labor Comments: Removed tube that connects the upper and lower tank, replaced fittings on the upper and lower tank. Reinstalled tube and sealed up.				
Miscellaneous Labor		\$0		
Other			\$0	
PU:Pick-up & Delivery	\$0	\$29.00	\$0.00	\$29.00
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (0.58)		\$29.00		
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$1,434.65	\$1,895.00	\$0
			\$0	\$0
				<u>\$3,329.65</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate: PRZ9154

		Location: HBG		Department: HBG1-Accounting
	Recall:	Campaign #		Date:
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>
4017	05/10/2012	05/11/2012	Closed	0.00

Comments: buffed wheels

5/7/2019

## Work Order Detail

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$0	\$125.00		\$0.00	\$125.00
Miscellaneous Parts		\$0				
77 - SCHNEIDER, NICHOLAS			\$125.00			
(2.50)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$125.00	\$0	\$0	<u>\$125.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 662,183.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5074	06/18/2012	06/20/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
35:Instrument & Gauges		\$0	\$165.00		\$0.00	\$165.00
Maintenance Requested: 2243 - 06/18/2012 - Buzzer sounding its coming from below AC control						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (3.30)			\$165.00			
Labor Comments: Buzzer was over speed from the dash display. Found someone had switched the display to French and set speed too low.						
Miscellaneous Labor			\$0			
Other					\$0	
52:Electrical Accessories		\$0	\$107.50		\$0.00	\$107.50
Maintenance Requested: 2228 - 06/15/2012 - no 110; wiper will not stop; no heat or cruise con						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (2.15)			\$107.50			
Labor Comments: 110volt plug in's dont work. tested plugs and no power. Reset breaker on the inverter unit and tested all the plugs for any kind of fault.						
Miscellaneous Labor			\$0			
Other					\$0	
75:Windows/windshields		\$34.23	\$26.50		\$0.00	\$60.73
Young Building: Relay 24V:		\$33.28				
7C-5-24 (2.000)						
Young Building: Base Relay		\$0.95				
V4 MCI D4500: 6992602						
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (0.53)			\$26.50			
Labor Comments: Windsheild wipers dont park. installed update kit and tested. wipers would park most of the time. Had Jason order a wiper motor.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$34.23	\$299.00	\$0	\$0	<u>\$333.23</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate: PRZ9154

Miles: 663,594.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5281	06/25/2012	06/26/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$291.50	\$61.50		\$0.00	\$353.00
Pillsbury: Wheel, Aluminum		\$291.50				

22.5: 29730AOP (1.000)				
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (1.23)		\$61.50		
Labor Comments: balance front tires				
Miscellaneous Labor		\$0		
Other			\$0	
38:Audio / Video Surveillance System	\$0	\$135.00	\$0.00	\$135.00
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (2.70)		\$135.00		
Labor Comments: Tested audio system and tuned rear and front levels to get the best sound.				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$0	\$0	\$0.00	\$0.00
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (0.00)		\$0.00		
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$0	\$41.00	\$0.00	\$41.00
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (0.82)		\$41.00		
Labor Comments: Complaint was that the bus was not as cold as the " other bus". Ckecked out A/C and found it to be cooling at 49°F coming out of the vents and cools well. No problem found.				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$309.47	\$254.00	\$0.00	\$563.47
Maintenance Requested: 2310 - 06/22/2012 - Dog tracks, windows wont draw up tight				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
746-014 Door Lock Actuator (1.000)	\$28.10			
746-014 Door Lock Actuator (1.000)	\$28.10			
03-29-1101 Finger Locking (1.000)	\$36.01			
3R-29-61 Tumbler ASM-Lock (3.000)	\$217.26			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (5.08)		\$254.00		
Labor Comments: Luggage bays dont lock. Two luggage bay doors dont lock with the key and four dont lock with the central locking system. Adjusted bay doors and removed locking pins from all the doors cleaned, lubed and re-installed. Two lock tumblers, one was missing and one had a key broke off in it, had Jason order lock tumblers. Two central lock actuators on the left and two on the right side would lock but not unlock. Replaced all four actuators, two we had non-stock item and we ordered two from FMP. Also installed realese pulls.				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$0	\$435.00	\$0.00	\$435.00
Maintenance Requested: 2329 - 06/25/2012 - LOTS OF STUFF SEE COMMENTS				
Requestor Notes: WIPERS WILL NOT TURN OFF FRONT TIRES HOP-SHAKE-VIBRATE REALLY BAD WHEN EMPTY LUGGAGE BAY LOCKS DONT WORK A/C NOT WORKING WELL OTHER BUSES WERE MUCH COOLER IT WAS PRETTY WARM IN THE BUS LEFT SUNSCREEN SLECTUALLY IN-OP WHINE IN SOUND SYSTEM CRUISE CONTROL DOESN'T STAY ON RIGHT MIRROR MOVES IN THE WIND LEFT SIDE FRONT PASSENGER WINDOWS LEEK AND WIND COMES IN - YOU CAN SEE THE WINDOW MOVING IN THE MIRROR				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			

6030 - STRICKER, DJ (8.70)		\$435.00			
Labor Comments: Lock all window due to them not being closed properly					
Miscellaneous Labor		\$0			
Other				\$0	
77:Mirrors	\$0	\$27.50		\$0.00	\$27.50
Miscellaneous Parts	\$0				
6030 - STRICKER, DJ (0.55)		\$27.50			
Labor Comments: Tighened up the mirror base					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$600.97	\$954.00	\$0	\$0
					<u>\$1,554.97</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 663,780.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5803	07/16/2012	07/24/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (0.00)			\$0.00			
Labor Comments: Coach needs to go up for a full alignment						
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$0	\$26.50		\$0.00	\$26.50
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (0.53)			\$26.50			
Labor Comments: Replaced bulb in light and had to remount switch in door handle						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$68.00		\$0.00	\$68.00
Maintenance Requested: 2556 - 07/16/2012 - SEE COMMENTS - LIGHT, WIPERS, STEERING, A/C						
Requestor Notes: LITE IN BATHROOM OUT						
IF WIPERS USED THEY DON'T SHUT OFF UNLESS THE BUS IS RESTARTED A COUPLE TIMES						
STEEERING BUS ROAMS HARED TO STAY STRAIGHT.						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (1.36)			\$68.00			
Labor Comments: A/C system cooled but not great, Right hand side heat valve was allowing hot coolant to flow. Turned heat valves off until the new one gets ordered. Sealed up vent flow coming out of the evaporator fans, checked fan speeds. System temp after all that was 59°F out of the vents.						
Miscellaneous Labor			\$0			
Other					\$0	
75:Windows/windshields		\$0	\$71.00		\$0.00	\$71.00
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (1.42)			\$71.00			
Labor Comments: Removed window wiper motor, replaced with a known good used.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$73.50		\$0.00	\$73.50
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (1.47)			\$73.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$239.00	\$0	\$0	<u>\$239.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 664,405.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5980	07/20/2012	07/23/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$23.65	\$172.50		\$0.00	\$196.15

Work Comments: 79 - Removed and replaced both shitter valves.

Young Building: Toilet Dump

\$19.71

Valve: 17K-5-51 (1.000)

Young Building: Seal; Slide

\$3.94

Valve;MCI EL3: 17-02-1192

(2.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (2.95)

\$147.50

6030 - STRICKER, DJ (0.50)

\$25.00

Labor Comments: Repalced top valve

Miscellaneous Labor

\$0

Other

\$0

\$0	\$23.65	\$172.50	\$0	\$0	<u>\$196.15</u>
-----	---------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 664,871.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
6066	07/24/2012	07/30/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

Inspection Diesel

PM:Preventative Maintenance

\$107.89

\$231.00

\$0.00

\$338.89

Pillsbury: Filter Oil MCI D4500

\$15.96

w/Detroit Diesel 60 Series:

1971MP (2.000)

Pillsbury: Filter Media: 4WZ68

\$4.06

(7.000)

Pillsbury: Fluid Windshield

\$3.18

Washer Fluid BULK/Gal After

Dilution: W/W Fluid BULK

(2.500)

Pillsbury: Oil: Oil 15W-40

\$80.29

BULK (37.000)

Pillsbury: Fluid Coolant Bulk

\$4.40

50/50 After Dilution: A/F 50/50

Green BULK (1.000)

Miscellaneous Parts

\$0

6030 - STRICKER, DJ (4.62)

\$231.00

Miscellaneous Labor

\$0

Other

\$0

36:Lighting

\$0

\$119.50

\$0.00

\$119.50

Miscellaneous Parts

\$0

6030 - STRICKER, DJ (2.39)

\$119.50

Labor Comments: Checked lighting inside and replaced LHS and RHS turn tail lights.

Miscellaneous Labor

\$0

Other

\$0

40:Engine

\$0

\$0

\$0.00

\$0.00

Miscellaneous Parts

\$0

6030 - STRICKER, DJ (0.00)

\$0.00

Labor Comments: Parts on order for the oil pan gasket.

5/7/2019

## Work Order Detail

Miscellaneous Labor		\$0			
Other				\$0	
41:A/C & Heating		\$0	\$57.50	\$0.00	\$57.50
Maintenance Requested: 2643 - 07/23/2012 - A/C NOT WORKING					
Requestor Notes:					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts		\$0			
6030 - STRICKER, DJ (1.15)			\$57.50		
Labor Comments: Changed filter, evap coil was dirty and cleaned out evap coil with the pressure washer.					
Tested coach running out side in the sun and 59°F coming out of the vents.					
Miscellaneous Labor		\$0			
Other				\$0	
72:Body Misc		\$0	\$312.00	\$0.00	\$312.00
Miscellaneous Parts		\$0			
6030 - STRICKER, DJ (2.46)			\$123.00		
Labor Comments: Replaced RHS bay door locks, and installed a floor trim for bay floor					
0081 - WOLF, PATRICK (3.78)			\$189.00		
Labor Comments: 72 - Drilled out the rivets on both roof hatches. Cleaned up and sealed with silicon.					
Reriveted back down again.					
Miscellaneous Labor		\$0			
Other				\$0	
PU:Pick-up & Delivery		\$0	\$22.50	\$0.00	\$22.50
Miscellaneous Parts		\$0			
6030 - STRICKER, DJ (0.45)			\$22.50		
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$107.89	\$742.50	\$0	\$0
					<u>\$850.39</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate: PRZ9154

Miles: 665,587.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
6444	08/06/2012	08/09/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$36.44	\$107.00		\$0.00	\$143.44

Work Comments: Accessory drive leaking oil, on which alt idler pulley asm is attached, saturating the belt with oil.

Pillsbury: Belt Alternator MCI

\$36.44

Motor Coach: 8L-27-132

(1.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (2.14)

\$107.00

Labor Comments: Remove alt belt, tensioner, idler plate asm, acc drive cover. Found a new O-ring elsewhere (n/c) and reassembled all parts, new belt.

Miscellaneous Labor

\$0

Other

\$0

50:Accessories

\$0

\$238.50

\$0.00

\$238.50

Maintenance Requested: 2821 - 08/06/2012 - CRUISE CONTROL DOESN'T WORK

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (4.77)

\$238.50

Labor Comments: Road tested--CC inop; checked VSS--OK; checked brake switches--OK; found that the Interlock module controls most of these actions. Installed remanned unit and CC works correctly. Sent old module in for rebuild. OH but wait-the module IS defective---does not allow the door lock asm to retract for opening. Put old module back in.

Miscellaneous Labor

\$0



5/7/2019

## Work Order Detail

Other					\$0	
78:Doors Entrance / Exit	\$0	\$258.50		\$0.00		\$258.50
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (5.17)		\$258.50				
Labor Comments: Ent door does not unlock correctly. After checking all plausible circuits, I found that the "interlock module" is defective in that it fails to allow the door locks to retract. I did find that the release solenoid sticks under heavy air pressure taking time to release. Ordered new solenoid.						
Miscellaneous Labor		\$0				
Other				\$0		
PU:Pick-up & Delivery	\$0	\$32.50		\$0.00		\$32.50
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.65)		\$32.50				
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$36.44	\$636.50	\$0	\$0	<u>\$672.94</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 665,595.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
6556	08/09/2012	08/13/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$465.73	\$311.50		\$0.00	\$777.23

Maintenance Requested: 2873 - 08/09/2012 - DOOR NOT WORKING PROPERLY

Requestor Notes:

Technician Response:

Maint Req Status: Completed

04-23-1022 booster asm module (1.000)	\$90.73
Pillsbury: Interlock Relay Module; el3: 07-18-1013 (1.000)	\$375.00
Miscellaneous Parts	\$0
74 - PHIPPS, KEVIN (6.23)	\$311.50

Labor Comments: Pulled threads out of acrylic block. Got new unit from C&J's -did not work, niether did used unit from them. Got a helicoil kit and repaired original block, installed and worked great.

Miscellaneous Labor		\$0				
Other				\$0		
PU:Pick-up & Delivery	\$0	\$25.00		\$0.00		\$25.00
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.50)		\$25.00				
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$465.73	\$336.50	\$0	\$0	<u>\$802.23</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
7545	09/13/2012	09/24/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
34:Ignition System		\$0	\$62.50		\$0.00	\$62.50
Miscellaneous Parts		\$0				

74 - PHIPPS, KEVIN (1.25)			\$62.50		
Labor Comments: Verbal complaint stated that bus would not start while at Mpls, EF went there with another bus and found that 526 started with no problem. I checked connections at starter, battery compartment, dash switch, and relay module. Did not find anything loose or corroded or amiss. Bus started every time without problem. Return to Charter. After talking to driver, learned that when he attempted to start the bus, the starter would "click" and not engage. Possible starter issue.					
Miscellaneous Labor			\$0		
Other				\$0	
43:Cooling	\$0	\$75.00		\$0.00	\$75.00
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (1.50)			\$75.00		
Labor Comments: Brought bus from charter, tightened hose clamp in engine comp, pressurized system and found no other leak.					
Miscellaneous Labor			\$0		
Other				\$0	
95:Service Calls	\$0	\$156.50		\$0.00	\$156.50
Miscellaneous Parts	\$0				
0147 - FICK, ERIC (3.13)			\$156.50		
Miscellaneous Labor			\$0		
Other				\$0	
PU:Pick-up & Delivery	\$0	\$97.50		\$0.00	\$97.50
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (1.95)			\$97.50		
Miscellaneous Labor			\$0		
Other				\$0	
	\$0	\$0	\$391.50	\$0	\$0
					<u>\$391.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 670,302.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
7841	09/21/2012	11/11/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$485.61	\$364.50		\$0.00	\$850.11

Maintenance Requested: 3442 - 09/24/2012 - A/C not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Freon R134A per \$23.65

Lb.: R134A (6.700)

16-06-1025 water valve repair \$178.06

kit (1.000)

Pillsbury: Valve, Coolant, MCI: \$283.90

16-14-1106 (1.000)

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (5.02) \$251.00

Labor Comments: 41 - A/C not working ---- Check ed out the A/C system found the system low on freon and heat valves not working. Filled the freon full. Closed the drivers heat valve. Looked up and ordered new valves.  
Waiting for valves

6030 - STRICKER, DJ (2.27) \$113.50

Labor Comments: Replaced RHS water valve and rebuilt LHS water valve.

Miscellaneous Labor \$0

Other \$0

43:Cooling	\$0	\$91.50		\$0.00	\$91.50
------------	-----	---------	--	--------	---------

Work Comments: Ran over to Holyoke. checked out for a coolant leak found a small leak at the thermostat housing. Filled the system compeatly full then filled three one gallon jugs for the driver to take with. put in the rear bay. Showed the dispatch person on Sat. morning how to check so he could show the driver.

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (1.83)

\$91.50

Labor Comments: Ran over to Holyoke. checked on the coolant leak. Found a loose clamp and tightened that. Crawled under the bus and found another leak at the thermostat housing. Topped off the system. Filled three jugs and put in the rear bay. just in case they need it. Will check on the leak on Monday. Showed Chad how to check the coolant so he could show the driver.

Miscellaneous Labor

\$0

Other

\$0

PU: Pick-up &amp; Delivery

\$0

\$110.50

\$0.00

\$110.50

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (1.48)

\$74.00

6030 - STRICKER, DJ (0.73)

\$36.50

Miscellaneous Labor

\$0

Other

\$0

\$0.00

\$485.61

\$566.50

\$0

\$0

\$1,052.11

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 669,327.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

8132

10/03/2012

10/05/2012

Closed

0.00

DetailDiscountsPartsLaborTiresOtherTotal

ds front running light and blinker out

\$11.61

\$12.50

\$0.00

\$24.11

Maintenance Requested: 3530 - 10/01/2012 - ds front running light and blinker out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Young Building: Light Side

\$11.61

Marker MCI: 53063 (1.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (0.25)

\$12.50

Labor Comments: Install new side marker. Brought to shop to do.

Miscellaneous Labor

\$0

Other

\$0

41: A/C &amp; Heating

\$0

\$64.00

\$0.00

\$64.00

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (1.28)

\$64.00

Labor Comments: Bus did not heat up, found no fuses for heater. Put in 3 fuses and heater ran great.

1--5amp

2--20amp

Miscellaneous Labor

\$0

Other

\$0

\$0

\$11.61

\$76.50

\$0

\$0

\$88.11

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

8216

10/05/2012

10/05/2012

Closed

0.00

DetailDiscountsPartsLaborTiresOtherTotal

oil leak tag on doorside

\$0

\$1.50

\$0.00

\$1.50

Maintenance Requested: 3593 - 10/04/2012 - oil leak tag on doorside

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

5/7/2019

## Work Order Detail

74 - PHIPPS, KEVIN (0.03) Labor Comments: Checked oil level--GOOD. Oil vapor will sling outward through hub cap. \$1.50  
 Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$1.50 \$0 \$0 \$1.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 670,116.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
8358	10/10/2012	10/16/2012	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
temperature control doesn't adjust down to cold 1		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 3646 - 10/08/2012 - temperature control doesn't adjust down to cold te

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 6030 - STRICKER, DJ (0.00) \$0.00

Labor Comments: Completed, Used other work order #7841

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$0 \$0 \$0 \$0.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 670,298.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
8586	10/18/2012	10/19/2012	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
turn signal switch is loose		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 3759 - 10/17/2012 - turn signal switch is loose

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 0081 - WOLF, PATRICK (0.00) \$0.00

Miscellaneous Labor \$0  
 Other \$0

36:Lighting \$0 \$51.00 \$0.00 \$51.00

Miscellaneous Parts \$0  
 74 - PHIPPS, KEVIN (1.02) \$51.00

Labor Comments: Remove steering wheel and column components to tighten turn signal switch asm.

Put lockite on screws.

Miscellaneous Labor \$0  
 Other \$0

PU:Pick-up & Delivery \$0 \$82.50 \$0.00 \$82.50

Miscellaneous Parts \$0  
 74 - PHIPPS, KEVIN (1.65) \$82.50

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$133.50 \$0 \$0 \$133.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 671,399.0

Recall: Location: HBG Campaign # Department: HBG1-Accounting Date:

WO #	Open Date	Close Date	Status	Downtime	Accident	
8713	10/23/2012	10/25/2012	Closed	0.00		
Detail	Discounts	Parts	Labor	Tires	Other	Total
Inspection Diesel						
PM:Preventative Maintenance		\$124.96	\$385.00		\$0.00	\$509.96
Pillsbury: Oil Sample Bottle		\$10.10				
Kit: SOS Sample Bottle Kit						
Pillsbury: Filter Oil MCI D4500		\$15.96				
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Bulk in Quarts:		\$85.47				
Oil 15W-40 Bulk (37.000)						
Pillsbury: Filter Media: 4WZ68		\$3.94				
(7.000)						
Pillsbury: Fluid Windshield		\$1.49				
Washer Fluid BULK/Gal After						
Dilution: W/W Fluid BULK						
(1.000)						
Pillsbury: Fluid Coolant Bulk		\$8.00				
50/50 After Dilution: A/F 50/50						
Green BULK (2.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (5.47)			\$273.50			
Labor Comments: PM - Performed the service and safty check as per the attatched sheet.						
74 - PHIPPS, KEVIN (2.23)			\$111.50			
Miscellaneous Labor			\$0			
Other					\$0	
20:Steering		\$156.34	\$362.00		\$0.00	\$518.34
Pillsbury: Draglink End LH		\$156.34				
EL3 MCI: 11-04-1006 (2.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.65)			\$232.50			
Labor Comments: Removed the front drag link removeda nd replaced both ends. Mounted back into the bus.						
74 - PHIPPS, KEVIN (2.59)			\$129.50			
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$165.04	\$74.00		\$0.00	\$239.04
Pillsbury: Fog Lamp RH, Dual		\$92.56				
Halagon, EL3: 07-07-1026						
(see note) (1.000)						
Pillsbury: Light Bulb 12 Volt		\$2.07				
Mini Fog/Driving: BP1255/H3						
(1.000)						
Pillsbury: Light Bulb Pass.		\$0.80				
Sevice Module 28V 10W:						
03-08-1162 (1.000)						
Pillsbury: Flourescent Light		\$1.98				
32W-48"Coach: FO32735ECO						
(1.000)						
Pillsbury: Ballast Interior Light		\$67.63				
EL3: 07-07-1040 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.48)			\$24.00			
Labor Comments: Install 1 new fog lamp (RH), install a good used one on the L with new bulb.						
0081 - WOLF, PATRICK (1.00)			\$50.00			
Labor Comments: 36 - Removed and replaced the ballast and bulb on an isle light						
Miscellaneous Labor			\$0			
Other					\$0	
40:Engine		\$420.03	\$826.50		\$0.00	\$1,246.53
Young Building: Hose		\$143.44				
Hydraulic 1": 16M2T (22.000)						

Young Building: Crimp Fitting	\$35.64			
4G-8FJX Female JIC 37?				
Swivel Straight: G25170-1616				
(2.000)				
Pillsbury: Isolator, Oil Pan Bolt	\$30.50			
Detroit: 23517242 (10.000)				
Pillsbury: Spacer Detroit Oil	\$33.70			
Pan: 23517243 (10.000)				
Pillsbury: Belt Alternator MCI	\$16.71			
EL3: 08-27-1018 (1.000)				
Pillsbury: Belt Alternator MCI	\$32.80			
Motor Coach: 8L-27-132				
(1.000)				
Pillsbury: Belt EL3:	\$46.49			
08-27-1002 (1.000)				
Pillsbury: Thermostat 190?	\$56.78			
Series 60 Detroit Diesel:				
23532436 (2.000)				
Part Comments: This quantity should be 2; and 2 seals???				
Pillsbury: Fluid Anti Freeze (gal	\$23.97			
jug): A/F Full Strength 100% Gr				
(3.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK		\$598.50		
Labor Comments: 40 - Removed the alt. drain hose. made up a new hose with new fittings. Removed the fuel line to the speros heater and had to remove several inches that were rubbed thru. Mounted the end back on the hose. Bleed the line out tot cleana d prime the system. Mounted and tied everything back up again.				
74 - PHIPPS, KEVIN (4.56)		\$228.00		
Labor Comments: Take t-stat housing out and install new t-stats. Clean all parts, new piece of hose. Replace bad belts with new. Oily, worn, and cracked. Install 2 new t-stats and fill.				
Miscellaneous Labor		\$0		
Other			\$0	
50:Accessories	\$134.91	\$0	\$0.00	\$134.91
Pillsbury: Belt Alternator MCI	\$16.71			
EL3: 08-27-1018 (1.000)				
Pillsbury: Belt, A/C, MCI, E-	\$33.74			
Coach: 08-27-1029 (1.000)				
Pillsbury: Belt Alternator MCI	\$32.80			
Motor Coach: 8L-27-132				
(1.000)				
Pillsbury: Belt EL3:	\$51.66			
08-27-1002 (1.000)				
Part Comments: Extra set of belts.				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
FF:Fuel Filter	\$8.59	\$49.00	\$0.00	\$57.59
Pillsbury: Filter Fuel: 3118	\$4.23			
(1.000)				
Pillsbury: Filter, Fuel, MCI:	\$4.36			
3120 (1.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.98)		\$49.00		
Labor Comments: Removed and replace both fuel filters.				
Miscellaneous Labor		\$0		
Other			\$0	
PU:Pick-up & Delivery	\$0	\$41.00	\$0.00	\$41.00
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.82)		\$41.00		
Labor Comments: Took the bus back to the Holyoke garage.				
Miscellaneous Labor		\$0		
Other			\$0	

\$0	\$1,009.87	\$1,737.50	\$0	\$0	<u>\$2,747.37</u>
-----	------------	------------	-----	-----	-------------------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 674,078.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
9036	11/06/2012	04/01/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$72.73	\$0		\$0.00	\$72.73

Work Comments: Fluids for luggage bay

Pillsbury: ATF (Synthetic) Bulk		\$34.60				
Quart: ATF Synthetic Bulk						
Pillsbury (10.000)						
Pillsbury: Fluid Coolant Bulk		\$12.10				
50/50 After Dilution: A/F 50/50						
Green BULK (2.500)						
Pillsbury: Oil Bulk in Quarts:		\$26.03				
Oil 15W-40 Bulk (10.000)						
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
13:Brakes		\$0	\$88.50		\$0.00	\$88.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.77)			\$88.50			
Miscellaneous Labor			\$0			
Other					\$0	
27:Wheels, Rims, Hubs & Mounts		\$20.16	\$61.00		\$0.00	\$81.16
Pillsbury: Hub Cap, Stainless		\$20.16				
Steel: MW1273 (2.000)						
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (1.22)			\$61.00			
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$1.68	\$17.50		\$0.00	\$19.18
Work Comments: Bay lights out						
Young Building: Bulb 28 Volt		\$1.68				
Dual Contact Dual Element:						
1683 (2.000)						
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (0.35)			\$17.50			
Miscellaneous Labor			\$0			
Other					\$0	
38:Audio / Video Surveillance System		\$0	\$74.00		\$0.00	\$74.00

Maintenance Requested: 3990 - 11/03/2012 - see comments

Requestor Notes: There are a couple issues with the DVD player that could all be related. The DVD player is not secured tightly to the cabinet behind the driver's seat. In fact, the cabinet seems loose; it rattles on an almost constant basis. Because the DVD player is not secure, it moves a little while traveling ? this causes the movie to skip. The lead person (Robbie) from Colonial Church had to eventually stand by the cabinet and literally hold the DVD player so they could watch a movie. He thought the cables leading to the DVD player were also not secure to the player which could be part of the problem as well.

On another issue (more mechanical in nature) ? we stopped at McDonalds in Sauk Center and when we left ? the bus would not go into Drive. I also tried Reverse ? nothing. I shut the bus down, waited a couple seconds and started it back up. Everything was fine then. It was probably a computer glitch.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0	
6030 - STRICKER, DJ (1.48)		\$74.00
Miscellaneous Labor		\$0

Other			\$0	
41:A/C & Heating	\$304.92	\$1,417.50	\$0.00	\$1,722.42
16-06-1019 oring, discharge	\$11.18			
(2.000)				
16-11-1043 hose assy (1.000)	\$112.82			
pag 100 (2.000)	\$40.02			
pag 100 (1.000)	\$20.01			
Pillsbury: Filter Dryer EL3:	\$43.23			
16-04-1004 (1.000)				
Pillsbury: Freon R134A per	\$77.66			
Lb.: R134A (22.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK		\$1,417.50		
Labor Comments: 41 - Recovered all the freon that was left in the system. Removed and replace the leaking hose. Drained and refilled the compresor oil. Filled with nitrogen and checked for leaks. Vacumed down the system. Couldn't keep a good vacuum so I filled back up with nitrogen again. Found the valve steims on the compressor leaking. Tightened up the npacking nuts. didn't find any other leaks. Vacumed down again. Filled with freon.				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$24.31	\$41.50	\$0.00	\$65.81
Maintenance Requested: 3935 - 10/30/2012 - see comments				
Requestor Notes: PA very soft in back of bus.				
window seat 40 rattles and moves, passenger complaint.				
Lights out in 1st and 2nd bays.				
Bay 1 left lock does not work.				
Trim is loose on 2nd step back.				
Bad rattle and squeek from above driver.				
The door to master switch-lock-will freeze.				
Key is bent that opens the bay doors. Need new key.				
Technician Response:				
Maint Req Status: Completed				
03-27-1075 BAR-RELEASE	\$24.31			
(1.000)				
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (0.83)		\$41.50		
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$58.50	\$0.00	\$58.50
Maintenance Requested: 4387 - 12/07/2012 - see comments				
Requestor Notes: added 1 gallon of oil, need another gallin in supply				
door does not close properly				
clicking when you apply brake, coming from electrical cabinet under drivers left side				
Technician Response: Filled the jug back up with oil.				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (1.17)		\$58.50		
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$7.50	\$0.00	\$7.50
Maintenance Requested: 4398 - 12/10/2012 - battery low the door is still not shutting properl				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (1.60)		\$7.50		
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$1.50	\$0.00	\$1.50
Maintenance Requested: 4398 - 12/10/2012 - battery low the door is still not shutting properl				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				



Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (0.03)		\$1.50			
Miscellaneous Labor		\$0			
Other			\$0		
75:Windows/windshields	\$0	\$35.00	\$0.00		\$35.00
Maintenance Requested: 3932 - 10/30/2012 - windows rattle and have air gaps					
Requestor Notes: The driver indicated the windows rattle and that there is cold air coming in. He received passenger complaints regarding the issue.. He also indicated the front driver area "molding" rattles as well.					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts	\$0				
6030 - STRICKER, DJ (0.70)		\$35.00			
Miscellaneous Labor		\$0			
Other			\$0		
78:Doors Entrance / Exit	\$0	\$310.00	\$0.00		\$310.00
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (6.20)		\$310.00			
Miscellaneous Labor		\$0			
Other			\$0		
AD:Air Drier Service	\$126.34	\$82.50	\$0.00		\$208.84
Pillsbury: AD-IP Air Dryer	\$59.99				
Desiccant Cartridge Bendix: 109493BXR (1.000)					
Pillsbury: AD-IP DLU Air Dryer	\$66.35				
Valve Purge kit: K022105K (1.000)					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (1.65)		\$82.50			
Labor Comments: O/H air dryer					
Miscellaneous Labor		\$0			
Other			\$0		
PU:Pick-up & Delivery	\$0	\$2.50	\$0.00		\$2.50
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (0.05)		\$2.50			
Miscellaneous Labor		\$0			
Other			\$0		
	\$-72.50	\$550.14	\$2,197.50	\$0	\$0
					<u>\$2,747.64</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 673,214.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
9546	11/27/2012	11/29/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 4192 - 11/19/2012 - fan only works on high front wind sche cracked

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.00)		\$0.00				
Miscellaneous Labor		\$0				
Other				\$0		
41:A/C & Heating	\$0	\$87.50	\$0.00			\$87.50
Work Comments: Defroster fan only runs on high.						
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (1.75)		\$87.50				
Labor Comments: Cleaned and checked electrical connctions at relay box. Has 3 speeds now.						
Miscellaneous Labor		\$0				
Other				\$0		

5/7/2019

## Work Order Detail

70:Body Sheet Metal	\$0	\$96.00	\$0.00	\$96.00
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (1.92)		\$96.00		
Labor Comments: Refasten LH parcel rack to ceiling frame.				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$0	\$0	\$0.00	\$0.00
Maintenance Requested: 4238 - 11/26/2012 - crack in driver side windshield getting big				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.00)		\$0.00		
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$0	\$0	\$0.00	\$0.00
Maintenance Requested: 4251 - 11/27/2012 - very bad chip driver side annoying to passengers				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.00)		\$0.00		
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$188.00	\$136.00	\$0.00	\$324.00
Pillsbury: Glass Windshield	\$188.00			
Front LH w/Mask MCI EL3:				
03-27-1325 (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (2.72)		\$136.00		
Labor Comments: Replace damaged windscreen. Seal and clean.				
Miscellaneous Labor		\$0		
Other			\$0	
PU:Pick-up & Delivery	\$0	\$33.00	\$0.00	\$33.00
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.66)		\$33.00		
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$188.00	\$352.50	\$0
			\$0	\$0
				<u>\$540.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 674,854.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
10365	12/31/2012	02/27/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$349.90	\$32.50		\$0.00	\$382.40

Maintenance Requested: 4750 - 01/14/2013 - batterys low hard to start sick of jumping it

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Battery 1400CCA \$349.90

Top Post Heavy Duty

Workaholic: 8D-MHD(7271)

Miscellaneous Parts \$0

0148 - WOLF, JOHN (0.65) \$32.50

Labor Comments: Removed and replaced batteries.

Miscellaneous Labor \$0

Other \$0

70:Body Sheet Metal \$0 \$997.50 \$0.00 \$997.50

Miscellaneous Parts \$0

5/7/2019

## Work Order Detail

82 - BLANCO, VICTOR (19.95)			\$997.50			
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc	\$0	\$0		\$0.00		\$0.00
Maintenance Requested: 4580 - 12/27/2012 - key broke off in door for power/electric						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$349.90	\$1,030.00	\$0	\$0	<u>\$1,379.90</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 678,560.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
11755	02/20/2013	11/01/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$30.00		\$0.00	\$30.00
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$30.00			
Miscellaneous Labor			\$0			
Other					\$0	
30:Electrical		\$0	\$22.50		\$0.00	\$22.50
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$22.50			
Miscellaneous Labor			\$0			
Other					\$0	
38:Audio / Video Surveillance System		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 6614 - 06/20/2013 - see comments

Requestor Notes: no remote for DVD.

Retarder/engine brake applies at slight throttle position and when you slow down slightly, brake applies and transmission down shifts and goes to 2000 rpm's.

steering wheel off center when going straight down the road. Re-align steering wheel

Technician Response: retarder wii come on when throttle is released or brakes applied. if no retarder is wanted the switch must be turned off.

Maint Req Status: Completed

Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$206.50		\$0.00	\$206.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (4.13)			\$206.50			
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$0	\$0		\$0.00	\$0.00
Work Comments: Repair front bumper, front entrance door and spare tire area. Paint front end and the entrance door.						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$0	\$30.00		\$0.00	\$30.00

Maintenance Requested: 4738 - 01/14/2013 - Front storage DS will not stay up;see comments

Requestor Notes: Middle storage driver side cannot unlock; bottom dump handle frozen

Technician Response: "middle stowage driver side" unlocks with ignition key.

Maint Req Status: Completed

Miscellaneous Parts \$0

74 - PHIPPS, KEVIN (0.60) \$30.00

Labor Comments: 1st bay door-- release mech pulled beyond its limit, put back in place and bent back to correct position. Electric locks may/may not work due to dirt and wear. Did spray rods but may not always work. Ignition key works in all locks.

Miscellaneous Labor \$0

Other \$0

78:Doors Entrance / Exit \$0 \$125.00 \$0.00 \$125.00

Maintenance Requested: 7102 - 10/08/2013 - cargo door doesn't work

Requestor Notes: Cargo door front driverside doesn't stay up. Needs a new broom.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0

157 - BROIN, DOUGLAS \$125.00

Miscellaneous Labor \$0

Other \$0

PU:Pick-up &amp; Delivery \$0 \$1.50 \$0.00 \$1.50

Miscellaneous Parts \$0

74 - PHIPPS, KEVIN (0.03) \$1.50

Miscellaneous Labor \$0

Other \$0

Shop Costs \$10.00

\$0 \$0 \$415.50 \$0 \$0 \$425.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 682,862.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
12667	03/25/2013	04/01/2013	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
--------	-----------	-------	-------	-------	-------	-------

Inspection Diesel

LOF:Lube, Oil, Filter \$130.34 \$577.50 \$0.00 \$707.84

Pillsbury: Filter Oil MCI D4500 \$15.96

w/Detroit Diesel 60 Series:

1971MP (2.000)

Pillsbury: Oil Analysis Kit: \$8.75

Sample Kit (1.000)

Pillsbury: Filter, Fuel, MCI: \$4.36

3120 (1.000)

Pillsbury: Filter Fuel: 3118 \$4.23

(1.000)

Pillsbury: Filter Media: 4WZ68 \$3.85

(7.000)

Pillsbury: Fluid Windshield \$2.88

Washer Fluid BULK/Gal After

Dilution: W/W Fluid BULK

(2.000)

Pillsbury: Oil Bulk in Quarts: \$85.47

Oil 15W-40 Bulk (37.000)

Pillsbury: Fluid Coolant Bulk \$4.84

50/50 After Dilution: A/F 50/50

Green BULK (1.000)

Miscellaneous Parts \$0

155 - HOUSLEY, ANTHONY \$307.50

(6.15)

Labor Comments: oil change and a look over to find problems or leaking hoses

0081 - WOLF, PATRICK (5.40) \$270.00

Miscellaneous Labor \$0

Other \$0

20:Steering	\$27.84	\$127.50	\$0.00	\$155.34
Pillsbury: Element Power	\$9.64			
steering reservoir: 11-08-1074				
(1.000)				
Pillsbury: Fluid ATF Bulk: ATF	\$18.20			
Dexron VI bulk (10.000)				
Miscellaneous Parts	\$0			
155 - HOUSLEY, ANTHONY		\$127.50		
(2.55)				
Labor Comments: I did a power steering flush, and so i replaced the filter along with put new fluids in the resovor				
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$117.48	\$284.00	\$0.00	\$401.48
12-05-1147 shock absorber	\$117.48			
(2.000)				
Miscellaneous Parts	\$0			
155 - HOUSLEY, ANTHONY		\$284.00		
(5.68)				
Labor Comments: replaced both shocks on the rear drive axle				
Miscellaneous Labor		\$0		
Other			\$0	
25:Transmission (Auto)	\$119.57	\$231.00	\$0.00	\$350.57
AT29552705 seal assy	\$49.03			
ZZ99473 sleeve (1.000)	\$70.54			
Miscellaneous Parts	\$0			
155 - HOUSLEY, ANTHONY		\$105.00		
(2.10)				
Labor Comments: took out yoke and seal along with the speedy sleeve and found out that we needed to wait for parts to show up				
Put lock tight on the one bolt running into the middle of the yoke and then also put lock tight on the 4 bolts that connect the drive line to the yoke. I torqued the single bolt running threw the yoke to 60ftlbs and then torqued the 4 bolts that run to the yoke to 130				
0081 - WOLF, PATRICK (2.52)		\$126.00		
Labor Comments: 25 - Removed and replaced the output shaft seal and speedy sleeve				
Miscellaneous Labor		\$0		
Other			\$0	
39:Other Electrical	\$0	\$99.00	\$0.00	\$99.00
Miscellaneous Parts	\$0			
155 - HOUSLEY, ANTHONY		\$99.00		
(1.98)				
Labor Comments: moved plug in for heater block and fastened it down with a clamp				
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$54.08	\$277.00	\$0.00	\$331.08
Pillsbury: Brush Condensor/	\$54.08			
Evaporator Fan Motor MCI				
D4500: 16G-8-64XCG (4.000)				
Miscellaneous Parts	\$0			
155 - HOUSLEY, ANTHONY		\$277.00		
(5.54)				
Labor Comments: replaced brushes on fans and also look at brushes to make sure they all had the correct about left				
Miscellaneous Labor		\$0		
Other			\$0	
PS:Power Steering Flush	\$0	\$69.00	\$0.00	\$69.00
Miscellaneous Parts	\$0			
155 - HOUSLEY, ANTHONY		\$69.00		
(1.38)				
Labor Comments: had to get the power steering sight glass power steering level in the middle				
Miscellaneous Labor		\$0		
Other			\$0	

## Work Order Detail

\$0	\$449.31	\$1,665.00	\$0	\$0	<u>\$2,114.31</u>
-----	----------	------------	-----	-----	-------------------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 683,421.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
12935	04/04/2013	04/18/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$42.50		\$0.00	\$42.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.85)			\$42.50			
Labor Comments: Steam cleaned off the alt. Checked for leaks. couldn't find were it was coming from.						
Will check again after weekend.						
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$0	\$231.50		\$0.00	\$231.50
Miscellaneous Parts		\$0				
6103 - STRAND, JACOB			\$231.50			
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$84.00		\$0.00	\$84.00
Work Comments: Inspect A/C						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$84.00			
Labor Comments: Inspected A/C system						
Miscellaneous Labor			\$0			
Other					\$0	
70:Body Sheet Metal		\$0	\$777.50		\$0.00	\$777.50
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (15.55)			\$777.50			
Miscellaneous Labor			\$0			
Other					\$0	
DO:DOT Inspection		\$0	\$48.50		\$0.00	\$48.50
Miscellaneous Parts		\$0				
75 - RADIL, WILLIAM (0.97)			\$48.50			
Labor Comments: Performed DOT inspection per inspection sheet.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$1,184.00	\$0	\$0	<u>\$1,184.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 684,547.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
13342	04/22/2013	04/23/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$55.68	\$857.50		\$0.00	\$913.18
Pillsbury: Sensor 5.8' Kit:		\$55.68				
R955338 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (17.15)			\$857.50			
Labor Comments: ABS light on since 4-11; LR sensor shorted. Replaced sensor with new and cleared fault.						
Miscellaneous Labor			\$0			
Other					\$0	
75:Windows/windshields		\$0	\$47.50		\$0.00	\$47.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.95)			\$47.50			
Labor Comments: Took window asm from 530 and installed.						

5/7/2019

## Work Order Detail

Miscellaneous Labor		\$0			
Other				\$0	
PU:Pick-up & Delivery	\$0	\$55.00		\$0.00	\$55.00
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (1.10)		\$55.00			
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$55.68	\$960.00	\$0	\$0
					<u>\$1,015.68</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 687,281.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
13948	05/13/2013	05/20/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$6.30	\$491.50		\$0.00	\$497.80

Maintenance Requested: 6120 - 05/10/2013 - need to check a/c, cover for engine don't open

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Freon R134A per

\$6.30

Lb.: R134A (2.500)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (9.83)

\$491.50

Labor Comments: 41 - Recovered the freon. Filled the system with nitrogen. Sprayed down with soapy water. Didn't find any leaks. injected dye into the system. vacumed back down and refilled the system.

Miscellaneous Labor

\$0

Other

\$0

52:Electrical Accessories

\$0

\$17.50

\$0.00

\$17.50

Maintenance Requested: 4710 - 01/10/2013 - 2nd tv back on passenger side not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (0.35)

\$17.50

Labor Comments: 52 - Removed and replaced the TV with a used one.

Miscellaneous Labor

\$0

Other

\$0

72:Body Misc

\$0

\$360.50

\$0.00

\$360.50

Maintenance Requested: 5945 - 04/27/2013 - see comments

Requestor Notes: drivers bay door will not stay up.

compressor on drivers side not working, no air flow

Technician Response:

Maint Req Status: Completed

Young Building: Motor Heater/

\$0.00

Defroster 24 Volt 5/16" Shaft

Gillig: 82-06324-000 (1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (7.21)

\$360.50

Labor Comments: 72 - Removed the inner door panel. Found the latch all bent to \*\*\*\* and the eye bolt was unbolted and still in the latch. Bent the latch all back into place. Mounted the eye bolt back onto the frame. Reattached the release cable.

41 - Removed and replaced the parcel rack blower motor with one that was for a gillig.

Miscellaneous Labor

\$0

Other

\$0

75:Windows/windshields

\$0

\$189.00

\$0.00

\$189.00

Maintenance Requested: 6132 - 05/11/2013 - 2 chips in windshield, fixable w/o replacing?

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (3.78)		\$189.00		
Labor Comments: 75 - Filled both windshield chips.				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$0	\$93.50	\$0.00	\$93.50

Maintenance Requested: 5998 - 05/01/2013 - see comments

Requestor Notes: bad water leaks, 2nd row back drivers side and last row drivers side. Pouring in.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (1.87)		\$93.50		
Labor Comments: 75 - Removed and replaced the latch assy. on the front e-window. Removed and replaced the front stiker post on the front e window.				
Shut the rear e-window tight.				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$0	\$35.00	\$0.00	\$35.00

Maintenance Requested: 5700 - 04/08/2013 - back emergency window leaks really bad

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.70)		\$35.00		
Labor Comments: 75 - Opened the window and closed it tight.				
Miscellaneous Labor		\$0		
Other			\$0	
77:Mirrors	\$0	\$6.00	\$0.00	\$6.00

Maintenance Requested: 5882 - 04/22/2013 - PS mirror broken falls down when on freeway

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.12)		\$6.00		
Labor Comments: 77 - Couldn't find anything wrong with the pasenger side mirror.				
Miscellaneous Labor		\$0		
Other			\$0	
PU:Pick-up & Delivery	\$0	\$46.50	\$0.00	\$46.50
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.93)		\$46.50		
Labor Comments: PU - Pick bus up from Holyoke & bring to the shop for repairs, Return when finished.				
Miscellaneous Labor		\$0		
Other			\$0	

\$0	\$6.30	\$1,239.50	\$0	\$0	\$1,245.80
-----	--------	------------	-----	-----	------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 687,999.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
14500	05/31/2013	06/12/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$32.50		\$0.00	\$32.50

Maintenance Requested: 6310 - 05/28/2013 - check steering, seems loose

Requestor Notes:

Technician Response:

Maint Req Status: Completed



5/7/2019

## Work Order Detail

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.65)		\$32.50		
Labor Comments: 20 - Checked out the steering for play. Couldn't find any play at all.				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$0	\$342.50	\$0.00	\$342.50
Maintenance Requested: 6349 - 05/30/2013 - check engine light is on				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (6.85)		\$342.50		
Labor Comments: 40 - Hooked up the lap top. Active code for the fan control. Trouble shoot problem. Removed and replaced the fan control solenod with the one out of 528. Ordered a new one for 528.				
Miscellaneous Labor		\$0		
Other			\$0	
PU:Pick-up & Delivery	\$0	\$97.00	\$0.00	\$97.00
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.58)		\$29.00		
0081 - WOLF, PATRICK (1.36)		\$68.00		
Labor Comments: PU - Picked the bus up from the HOLYOKE gararge and broght it to the shop for repairs. Returned when finished.				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$0	\$472.00	\$0
			\$0	\$0
				<u>\$472.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 688,831.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15103	06/26/2013	07/01/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$0	\$141.00		\$0.00	\$141.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (2.82)			\$141.00			
Labor Comments: Brass fitting on inlet cracked. Remounted dryer and put inlet fitting back in without added fitting. Needed to remove L tag tire to do this. Repaired panel under LR corner under bus that was damaged while loading onto trailer.						
Miscellaneous Labor			\$0			
Other					\$0	
BD:Break Down		\$188.54	\$157.50		\$0.00	\$346.04
towing call (1.000)		\$188.54				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (3.15)			\$157.50			
Labor Comments: Go to I35W at BV PRKWY. Air dryer blowing. Waited for tow.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$31.00		\$0.00	\$31.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.62)			\$31.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$188.54	\$329.50	\$0	\$0	<u>\$518.04</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 688,831.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

5/7/2019

## Work Order Detail

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15142	06/27/2013	07/01/2013	Closed	0.00	

Description: A/C issue

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$47.50		\$0.00	\$47.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.95)			\$47.50			
Labor Comments: Went through and checked all thing A/C. Found P/R blower inop on R side. Switched with 528. Explained pluses and minuses of system.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$47.50	\$0	\$0	<u>\$47.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 689,039.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15182	07/01/2013	07/10/2013	Closed	0.00	

  

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$0	\$111.00		\$0.00	\$111.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (2.22)			\$111.00			
Miscellaneous Labor			\$0			
Other					\$0	
16:Drive Train		\$0	\$162.50		\$0.00	\$162.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (3.25)			\$162.50			
Labor Comments: Splines worn on prop shaft. Removed for replacement. Recieved and installed new drive shaft						
Miscellaneous Labor			\$0			
Other					\$0	
27:Wheels, Rims, Hubs & Mounts		\$0	\$74.00		\$0.00	\$74.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.48)			\$74.00			
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$63.50		\$0.00	\$63.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.27)			\$63.50			
Labor Comments: 49 -- Checked out the air system. Does build air a little slow but still ok.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$43.50		\$0.00	\$43.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.87)			\$43.50			
Miscellaneous Labor			\$0			
Other					\$0	
SL:Sublet Labor		\$884.14	\$0		\$0.00	\$884.14
weld driveshaft (1.000)		\$884.14				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$884.14	\$454.50	\$0	\$0	<u>\$1,338.64</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 691,036.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

5/7/2019

## Work Order Detail

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15511	07/25/2013	08/06/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$805.21	\$312.50		\$0.00	\$1,117.71
R29248 ECAS valve (1.000)		\$499.95				
Pillsbury: Valve Suspension		\$305.26				
AUX EL3: 04-22-1013 (2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (6.25)			\$312.50			
Labor Comments: found valves coming out of the air tanks were bad, replaced both and replaced the solenoid for kneeling						
Miscellaneous Labor			\$0			
Other					\$0	
30:Electrical		\$180.13	\$134.00		\$0.00	\$314.13
Pillsbury: Alternator Kit Front		\$64.60				
Seal Delco 50DN Belt Drive: 10514967 (1.000)						
Pillsbury: Light License Plate: 15208 (1.000)		\$1.61				
04-22-1014 valve assy - solenoid (1.000)		\$113.92				
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$134.00			
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$79.00		\$0.00	\$79.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.58)			\$79.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$985.34	\$525.50	\$0	\$0	\$1,510.84

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 692,390.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15697	08/08/2013	08/20/2013	Closed	0.00	

Description: L.O.F...&amp;..list

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$101.50		\$0.00	\$101.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.73)			\$36.50			
Labor Comments: made new ground for alternator cause old one rotted						
157 - BROIN, DOUGLAS			\$65.00			
Miscellaneous Labor			\$0			
Other					\$0	
40:Engine		\$439.45	\$218.50		\$0.00	\$657.95
08929102 m-gasket (1.000)		\$30.76				
23505248 M-F/P gasket (1.000)		\$1.14				
11504571 bolt (10.000)		\$21.40				
23517242 isolator (10.000)		\$32.60				
23517243 spacer (10.000)		\$53.60				
R029466 idler bracket (1.000)		\$299.95				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (4.37)			\$218.50			

Miscellaneous Labor		Labor Comments: fuel pump gasket was leaking and oil pan leaking and put two new pulley system on			
		\$0			
Other		\$0			
AF:Air Filter Replacement	\$31.34	\$46.00	\$0.00	\$77.34	
Pillsbury: Filter Air EL3: 6774	\$31.34				
(1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$46.00			
(0.92)					
		Labor Comments: replaced air filter			
Miscellaneous Labor		\$0			
Other		\$0			
CFR:Coolant Filter Replacement	\$17.65	\$39.00	\$0.00	\$56.65	
Pillsbury: Filter Coolant: 4206	\$9.87				
(1.000)					
Pillsbury: Filter Coolant: 4072	\$7.78				
(1.000)					
Miscellaneous Parts	\$0				
157 - BROIN, DOUGLAS		\$39.00			
Miscellaneous Labor		\$0			
Other		\$0			
FF:Fuel Filter	\$8.59	\$0	\$0.00	\$8.59	
Pillsbury: Filter, Fuel, MCI:	\$4.36				
3120 (1.000)					
Pillsbury: Filter Fuel: 3118	\$4.23				
(1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$0.00			
(0.00)					
Miscellaneous Labor		\$0			
Other		\$0			
HUB:Hub Service	\$6.54	\$111.00	\$0.00	\$117.54	
Pillsbury: Oil Gear Synthetic:	\$6.54				
Oil Gear 75W-90 BULK in					
quarts (2.000)					
Miscellaneous Parts	\$0				
157 - BROIN, DOUGLAS		\$68.50			
7050 - STRAND, MATTHEW		\$42.50			
(0.85)					
		Labor Comments: changed hub oil			
Miscellaneous Labor		\$0			
Other		\$0			
LOF:Lube, Oil, Filter	\$106.05	\$219.00	\$0.00	\$325.05	
Pillsbury: Filter Oil MCI D4500	\$15.96				
w/Detroit Diesel 60 Series:					
1971MP (2.000)					
Pillsbury: Oil Bulk in Quarts:	\$90.09				
Oil 15W-40 Bulk (39.000)					
Miscellaneous Parts	\$0				
157 - BROIN, DOUGLAS		\$77.50			
7050 - STRAND, MATTHEW		\$141.50			
(2.83)					
		Labor Comments: changed oil and took oil pan off and put new gasket and spacers in ti			
Miscellaneous Labor		\$0			
Other		\$0			
		\$0	\$609.62	\$735.00	\$0
				\$0	\$1,344.62

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 692,734.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
16031	08/30/2013	09/09/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$344.96	\$0		\$0.00	\$344.96
Pillsbury: Steering Wheel w/ controls EL3: 11-02-1010 (1.000)		\$344.96				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$0	\$35.00		\$0.00	\$35.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.70)			\$35.00			
Labor Comments: Siliconed all seams on top of bus; rear roof hatch was not shut tight.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$24.00		\$0.00	\$24.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.48)			\$24.00			
Miscellaneous Labor			\$0			
Other					\$0	
RT:Road Test		\$0	\$45.00		\$0.00	\$45.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.90)			\$45.00			
Labor Comments: Dog tracks approx 6 inches.... Checked toe --is 1/16 to 1/4 in.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$344.96	\$104.00	\$0	\$0	<u>\$448.96</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 693,531.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
16245	09/13/2013	09/13/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$41.00		\$0.00	\$41.00
Work Comments: Part is on WO# 16031						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.82)			\$41.00			
Labor Comments: Install new steering wheel---part is on WO#16031---torqued the column nut to 45 ftlbs.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$45.00		\$0.00	\$45.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.90)			\$45.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$86.00	\$0	\$0	<u>\$86.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 695,774.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
16689	10/17/2013	10/18/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield Repair, Inv. # 2782946					\$35.00	\$35.00

5/7/2019

## Work Order Detail

Belt: Belt Replacement	\$36.44	\$25.00		\$0.00	\$61.44
Pillsbury: Belt Alternator MCI	\$36.44				
Motor Coach: 8L-27-132					
(1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$25.00			
(0.50)					
Labor Comments: belt was broke					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$36.44	\$25.00	\$0	\$35.00
					<u>\$96.44</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 697,780.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
16877	11/05/2013	11/07/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories		\$0	\$50.00		\$0.00	\$50.00

Maintenance Requested: 7166 - 10/24/2013 - TV monitor not working

Requestor Notes: TV monitor on the right side isn't working.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$50.00			
(1.00)					

Labor Comments: swapped monitors and adjusted the locks on the tv monitor

Miscellaneous Labor		\$0			
Other				\$0	
72:Body Misc	\$0	\$37.50		\$0.00	\$37.50

Maintenance Requested: 6931 - 08/30/2013 - See Comments

Requestor Notes: 1.) The bus leaks very bad when it rains

2.) Complaints that the driver's have a hard time keeping the bus on the road - dog tracking?

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$37.50			
(0.75)					

Labor Comments: drove fine on the test drive and leak has been sealed

Miscellaneous Labor		\$0			
Other				\$0	

	\$0	\$0	\$87.50	\$0	\$0	<u>\$87.50</u>
--	-----	-----	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 697,780.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
16913	11/07/2013	11/25/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$177.78	\$204.00		\$0.00	\$381.78

Pillsbury: Sensor, ABS, 90,	\$60.78				
Brake (gillig also): R955342					
(1.000)					
1428001 brake chamber	\$58.50				
(1.000)					
1428001 brake chamber	\$58.50				

(1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$204.00		
(4.08)				
	Labor Comments: fixed air leak and replaced brake chamber			
Miscellaneous Labor		\$0		
Other			\$0	
22:Tires	\$1,470.88	\$191.50	\$0.00	\$1,662.38
Pillsbury: Tire New Virgin	\$1,470.88			
FS400: 315/80R 22.5 New				
Virgin Tire (4.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$191.50		
(3.83)				
	Labor Comments: replaced drive tires			
Miscellaneous Labor		\$0		
Other			\$0	
30:Electrical	\$0	\$171.00	\$0.00	\$171.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$171.00		
(3.42)				
	Labor Comments: made new ground cable. And looked at lights			
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$0	\$57.50	\$0.00	\$57.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$57.50		
(1.15)				
	Labor Comments: worked on the proheat serviced it			
Miscellaneous Labor		\$0		
Other			\$0	
50:Accessories	\$0	\$0	\$0.00	\$0.00
	Maintenance Requested: 7178 - 10/28/2013 - TV Monitor not working			
	Requestor Notes: One of the TV monitors not working and luggage door is not staying open.			
	Going out of town Weds			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$0.00		
(0.00)				
	Labor Comments: i thought i closed this work order. request has been fixed			
Miscellaneous Labor		\$0		
Other			\$0	
50:Accessories	\$0	\$30.00	\$0.00	\$30.00
	Maintenance Requested: 7218 - 11/11/2013 - Speakers and radio problems			
	Requestor Notes: Speaker above drivers seat rattles and viberates when music is played			
	Driver radio not heard with volume full up.			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$30.00		
(0.60)				
	Labor Comments: coudnt not get probem to duplicate			
Miscellaneous Labor		\$0		
Other			\$0	
AD:Air Drier Service	\$170.28	\$105.00	\$0.00	\$275.28
Pillsbury: Purge Valve Repair	\$117.33			
Kit, AD-IP: K022105 (1.000)				
Pillsbury: AD-IP Air Dryer	\$52.95			
Desiccant Cartridge Bendix:				
109493BXR (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$105.00		
(2.10)				

Miscellaneous Labor	Labor Comments: air drier service		\$0		
Other				\$0	
Belt:Belt Replacement		\$13.69	\$57.50	\$0.00	\$71.19
Pillsbury: Belt Serpentine (EL3): 25-060295 (1.000)		\$13.69			
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW (1.15)			\$57.50		
	Labor Comments: replaced belt				
Miscellaneous Labor			\$0		
Other				\$0	
CR:Creep		\$0	\$106.00	\$0.00	\$106.00
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW (2.12)			\$106.00		
	Labor Comments: did a creep but have no paperwork, did not know about having to fill the check list out				
Miscellaneous Labor			\$0		
Other				\$0	
FF:Fuel Filter		\$26.35	\$91.00	\$0.00	\$117.35
Pillsbury: Filter Fuel: 3118 (1.000)		\$4.23			
Pillsbury: 3/8" Ball Valve: 63135 (2.000)		\$22.12			
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW (1.82)			\$91.00		
	Labor Comments: ball vavle was leaking fuel, replaced it				
Miscellaneous Labor			\$0		
Other				\$0	
		\$0	\$1,858.98	\$1,013.50	\$0
				\$0	\$2,872.48

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 699,986.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
17109	11/27/2013	12/11/2013	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38:Audio / Video Surveillance System			\$0	\$245.00		\$0.00	\$245.00
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$245.00			
Labor Comments: installed camera							
Miscellaneous Labor				\$0			
Other						\$0	
40:Engine			\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts			\$0				
Miscellaneous Labor				\$0			
Other						\$0	
41:A/C & Heating			\$17.46	\$30.00		\$0.00	\$47.46
W-14846C electrode ignition			\$17.46				
(1.000)							
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$30.00			
Labor Comments: installed wabasto coil and electrode							
Miscellaneous Labor				\$0			
Other						\$0	
49:Air System			\$7.44	\$89.00		\$0.00	\$96.44
Pillsbury: Valve Drain Air Tank:			\$7.44				
4R-19-130 (1.000)							
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$89.00			
Labor Comments: installed nozzle and cleaned wabasto. installed drain valve							



Miscellaneous Labor		\$0				
Other					\$0	
72:Body Misc	\$0	\$122.50		\$0.00		\$122.50
Miscellaneous Parts	\$0					
157 - BROIN, DOUGLAS		\$122.50				
Labor Comments: adjusted bag bay doors						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$24.90	\$486.50	\$0	\$0	<u>\$511.40</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 699,921.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
17156	12/03/2013	12/09/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$2,198.83	\$145.00		\$0.00	\$2,343.83
11-06-1001 cylinder-centering (1.000)		\$2,198.83				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.90)			\$145.00			
Labor Comments: replaced the tag cylinder						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$2,198.83	\$145.00	\$0	\$0	<u>\$2,343.83</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 700,645.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
17289	12/14/2013	12/26/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
11:Axles (front)		\$0	\$34.00		\$0.00	\$34.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.68)			\$34.00			
Labor Comments: has a snap ring loose in the front v rod						
Miscellaneous Labor			\$0			
Other					\$0	
13:Brakes		\$400.82	\$86.50		\$0.00	\$487.32
Pillsbury: Guide Pin Kit, Caliper;EL3: 04-01-1046 (2.000)		\$400.82				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.73)			\$86.50			
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$301.00		\$0.00	\$301.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.67)			\$33.50			
Labor Comments: put alcohol in the system						
157 - BROIN, DOUGLAS			\$267.50			
Labor Comments: found lots of air fittings loose.						
Miscellaneous Labor			\$0			

Other

\$0

\$0.00	\$400.82	\$421.50	\$0	\$0	<u>\$822.32</u>
--------	----------	----------	-----	-----	-----------------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 706,473.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
17444	01/02/2014	02/20/2014	Closed	0.00	

Description: PM Mileage 705,260

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
19 - C&J Bus Repair, Inv. # cvcs29981, Desc: tag steering					\$871.51	\$871.51
267 - Superglass Windshield Repair, Inv. # 2783095					\$35.00	\$35.00
13:Brakes		\$0	\$586.50		\$0.00	\$586.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (8.48)			\$424.00			

Labor Comments: redid the guide pins on the front calipers, guide pin part number is on the work order before this on

157 - BROIN, DOUGLAS	\$162.50
----------------------	----------

Labor Comments: repaired front brake calipers

Miscellaneous Labor	\$0		
Other		\$0	
20:Steering	\$0	\$0	\$0.00

Maintenance Requested: 7425 - 01/06/2014 - Tag steering fault light comes on

Requestor Notes: Window on table side is leaking alot of air

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0		
7050 - STRAND, MATTHEW (0.00)		\$0.00	

Labor Comments: unpluggedd the sesnor

Miscellaneous Labor	\$0		
Other			\$0
21:Suspension	\$0	\$128.50	\$0.00

Miscellaneous Parts	\$0		
7050 - STRAND, MATTHEW (2.57)		\$128.50	

Labor Comments: front v link snap ring was half popped out, pulled it out and cleaned it and reset it

Miscellaneous Labor	\$0		
Other			\$0
72:Body Misc	\$171.48	\$0	\$0.00

03-27-1137 str4iker assy-side sash (12.000)	\$171.48		
Miscellaneous Parts	\$0		

Miscellaneous Labor	\$0		
Other			\$0
75:Windows/windshields	\$0	\$25.00	\$0.00

Maintenance Requested: 7410 - 12/31/2013 - Right hand side windshield washer not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0		
7050 - STRAND, MATTHEW (0.50)		\$25.00	

Labor Comments: put new hose on the wiper

5/7/2019

## Work Order Detail

Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$15.00	\$59.00	\$0.00	\$74.00
Maintenance Requested: 7401 - 12/26/2013 - Right side windshield washer not working				
Requestor Notes: Drivers side window all iced up				
Had to reset trans 4 times				
Technician Response:				
Maint Req Status: Completed				
Pillsbury: Windshield Wash	\$15.00			
Pump: 151-512 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$59.00		
(1.18)				
Labor Comments: hooked up computer and found the code 23-12 which is for the shift selector and rsi link, and think that is the reason why its lossing communication				
Miscellaneous Labor		\$0		
Other			\$0	
LOF:Lube, Oil, Filter	\$112.03	\$126.00	\$0.00	\$238.03
Pillsbury: Oil Bulk in Quarts:	\$87.32			
Oil 15W-40 Bulk (37.000)				
Pillsbury: Oil Analysis Kit:	\$8.75			
Sample Kit (1.000)				
Pillsbury: Filter Oil MCI D4500	\$15.96			
w/Detroit Diesel 60 Series:				
1971MP (2.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$126.00		
(2.52)				
Labor Comments: did a complete service, the work orders got all messed up, i got clicked in on a old workorder, for both of my recent lof and repairs				
Miscellaneous Labor		\$0		
Other			\$0	
MS:Misc	\$106.52	\$327.50	\$0.00	\$434.02
Maintenance Requested: 7420 - 01/06/2014 - See Comments				
Requestor Notes: 1.) Tag Steering Fault light came on and the alarm was going off.				
2.) Door side, window right behind table was leaking air and group was complaining about the cold air.				
3.) One of the TV monitors is not working.				
Technician Response:				
Maint Req Status: Completed				
Pillsbury: Fog Lamp LH, Dual	\$89.34			
Halagon, EL3: 07-07-1025				
(see note) (1.000)				
Pillsbury: Light Bulb 12 Volt	\$7.10			
Mini Fog/Driving: BP1255/H3				
(2.000)				
Pillsbury: Hub Cap, Stainless	\$10.08			
Steel: MW1273 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$162.50		
(3.25)				
Labor Comments: fixed fog lights and fixed hub cap, fixed tv monitors and fixed windows				
157 - BROIN, DOUGLAS		\$165.00		
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$405.03	\$1,252.50	\$0
			\$906.51	<u>\$2,564.04</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 705,248.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

## Work Order Detail

17792                      02/05/2014                      02/09/2014                      Closed                      0.00

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield Repair, Inv. # 2783141					\$35.00	\$35.00
52:Electrical Accessories		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 7450 - 01/15/2014 - Video Screens keep going out when driving						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Labor Comments: fixed it on workorder 17444, just closing the maintenance work order						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$0	\$0	\$35.00	<u>\$35.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 707,152.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18078	03/04/2014	03/04/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$32.50		\$0.00	\$32.50
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$32.50			
Labor Comments: installed used washer pump						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$32.50	\$0	\$0	<u>\$32.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 707,983.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18083	03/04/2014	04/24/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$337.47	\$0		\$0.00	\$337.47
11-09-1002 pump power steering (1.000)		\$337.47				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
51:Communications		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 7575 - 02/26/2014 - Microphone cable has a short						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$0.00			
Labor Comments: installed used mic cable						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$4.56	\$137.50		\$0.00	\$142.06
Maintenance Requested: 7598 - 03/03/2014 - Panel below heater controls beeping						
Requestor Notes:						

Technician Response:

Maint Req Status: Completed

Pillsbury: Handle Valve Slide:

\$4.56

17L-5-212 (1.000)

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$137.50

Labor Comments: unplugged road relay

Miscellaneous Labor

\$0

Other

\$0

72:Body Misc

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 7593 - 03/01/2014 - see comments

Requestor Notes: alarm goes on and off when bus is in motion. Windshield wash not working.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

Miscellaneous Labor

\$0

Other

\$0

\$0.00

\$342.03

\$137.50

\$0

\$0

\$479.53

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 707,524.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

18091

03/04/2014

03/18/2014

Closed

0.00

DetailDiscountsPartsLaborTiresOtherTotal

75:Windows/windshields

\$0

\$130.00

\$0.00

\$130.00

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$130.00

(2.60)

Labor Comments: fixed the windsheild washer, then got called out on a service call for 115 blown brake line

Miscellaneous Labor

\$0

Other

\$0

\$0

\$0

\$130.00

\$0

\$0

\$130.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 707,983.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

18137

03/07/2014

03/10/2014

Closed

0.00

DetailDiscountsPartsLaborTiresOtherTotal

40:Engine

\$0

\$142.50

\$0.00

\$142.50

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (2.85)

\$142.50

Labor Comments: 40 steamed off the engine. Ran engine and checked for a leak . All I found leaking was the fill tub. Installed a stronger spring and cleaned off the O-ring.

Miscellaneous Labor

\$0

Other

\$0

\$0

\$0

\$142.50

\$0

\$0

\$142.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 708,321.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

5/7/2019

## Work Order Detail

18207                      03/18/2014                      03/20/2014                      Closed                      0.00

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$5.00		\$0.00	\$5.00
Maintenance Requested: 7635 - 03/07/2014 - Window shield washers don't work						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$5.00			
(0.10)						
Labor Comments: washers work just fine						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$5.00	\$0	\$0	<u>\$5.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 708,321.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18314	03/27/2014	04/01/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$2.91	\$18.50		\$0.00	\$21.41
Maintenance Requested: 7701 - 03/27/2014 - Side Marker light out/License plate light out						
Requestor Notes: Two cup holders broken . Drivers side						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Light Marker Lamp		\$1.99				
Clear: 15200C (1.000)						
Young Building: Pigtail:		\$0.92				
94902TLT (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$18.50			
(0.37)						
Labor Comments: After a exhausting search for this bus, i fixed the sider marker light and wired a new pigtail and liscence plate light						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$2.91	\$18.50	\$0	\$0	<u>\$21.41</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 711,405.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18526	04/14/2014	04/28/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$256.02	\$131.50		\$0.00	\$387.52
Pillsbury: Pads brake EL3:		\$256.02				
04-01-1019 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$131.50			
(2.63)						
Labor Comments: did a brake pad swap						
Miscellaneous Labor			\$0			
Other					\$0	
40:Engine		\$915.12	\$106.00		\$0.00	\$1,021.12
23515251 sensor (1.000)		\$40.12				

R029000 motor (1.000)	\$875.00			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (2.12)		\$106.00		
Labor Comments: fixed oil fil leak, idler leak				
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$0	\$34.00	\$0.00	\$34.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.68)		\$34.00		
Labor Comments: swapped the coolant sensor out, sensor is above on the engine section				
Miscellaneous Labor		\$0		
Other			\$0	
A/C:Prep	\$0	\$165.00	\$0.00	\$165.00
Miscellaneous Parts	\$0			
157 - BROIN, DOUGLAS		\$165.00		
Labor Comments: Prep A/C for summer				
Miscellaneous Labor		\$0		
Other			\$0	
Belt:Belt Replacement	\$36.44	\$26.00	\$0.00	\$62.44
Pillsbury: Belt Alternator MCI	\$36.44			
Motor Coach: 8L-27-132 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.52)		\$26.00		
Labor Comments: replaced the belt				
Miscellaneous Labor		\$0		
Other			\$0	
MS:Misc	\$65.92	\$186.00	\$0.00	\$251.92
Pillsbury: Alternator Kit Front	\$65.92			
Seal Delco 50DN Belt Drive: 10514967 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (3.72)		\$186.00		
Labor Comments: fixed all sorts of odds and ends and maintence requests				
Miscellaneous Labor		\$0		
Other			\$0	
MS:Misc	\$0	\$0	\$0.00	\$0.00
Maintenance Requested: 7704 - 03/28/2014 - Tables need to be fix.				
Requestor Notes: Right side front turn signal lite is out				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.00)		\$0.00		
Labor Comments: bolted the table back together				
Miscellaneous Labor		\$0		
Other			\$0	
TF:Transmission Flush	\$201.28	\$157.50	\$0.00	\$358.78
Pillsbury: Filter Kit	\$31.14			
Transmission Allison (Short Filter): 7741XE (1.000)				
Pillsbury: ATF (Synthetic) Bulk	\$170.14			
Quart: ATF Synthetic Bulk Pillsbury (28.500)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (3.15)		\$157.50		
Labor Comments: flushed transmission fluid				
Miscellaneous Labor		\$0		
Other			\$0	

\$0.00      \$1,474.78      \$806.00      \$0      \$0      \$2,280.78

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 712,490.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18736	04/30/2014	05/02/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$64.58	\$29.00		\$0.00	\$93.58
Work Comments: wipers making streak on windshield						
Pillsbury: Wiper Blade MCI		\$64.58				
EL3: 03-34-1177 (2.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$29.00			
Labor Comments: replaced wiper blades						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$64.58	\$29.00	\$0	\$0	<u>\$93.58</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 712,490.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18816	05/07/2014	05/08/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Belt:Belt Replacement		\$54.03	\$0		\$0.00	\$54.03
Pillsbury: Belt Alternator MCI		\$36.44				
Motor Coach: 8L-27-132						
(1.000)						
Pillsbury: Belt Alternator MCI		\$17.59				
EL3: 08-27-1018 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: both serp and alt belts were bad						
Miscellaneous Labor			\$0			
Other					\$0	
DO:DOT Inspection		\$0	\$152.50		\$0.00	\$152.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$84.00			
(1.68)						
Labor Comments: helped with dot						
157 - BROIN, DOUGLAS			\$68.50			
Labor Comments: Did DOT inspection.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$54.03	\$152.50	\$0	\$0	<u>\$206.53</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 715,222.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18996	05/21/2014	06/16/2014	Closed	0.00	



5/7/2019

## Work Order Detail

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00
Repair, Inv. # 2783412						
13:Brakes		\$981.28	\$305.00		\$0.00	\$1,286.28
Pillsbury: MCI Caliper Kit RHS:		\$981.28				
04-01-1042 (2.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (6.10)			\$305.00			
Labor Comments: Repair Rt drive caliper, adjust drives and tags brakes.						
Miscellaneous Labor			\$0			
Other					\$0	
40:Engine		\$0	\$21.50		\$0.00	\$21.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.43)			\$21.50			
Labor Comments: Tighten A/C and fan belts--very loose						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$981.28	\$326.50	\$0	\$35.00	<u>\$1,342.78</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 716,691.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19111	06/05/2014	06/16/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
A/C:Prep		\$828.99	\$129.00		\$0.00	\$957.99
2 spd carrier ge rebuild		\$828.99				
(1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$129.00			
Labor Comments: checked a/c for summer and installed a reman motor for the low speed on the condensor						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$828.99	\$129.00	\$0	\$0	<u>\$957.99</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 719,638.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19153	06/11/2014	06/30/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$95.48	\$78.50		\$0.00	\$173.98
Pillsbury: Fog Lamp LH, Dual		\$92.02				
Halagon, EL3: 07-07-1025						
(see note) (1.000)						
Pillsbury: Pigtail Light: 67050		\$1.47				
(1.000)						
Pillsbury: Light Marker Lamp		\$1.99				
Clear: 15200C (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$78.50			
(1.57)						
Labor Comments: Fixed license plate lights						
Miscellaneous Labor			\$0			
Other					\$0	
38:Audio / Video Surveillance System		\$0	\$14.00		\$0.00	\$14.00

Maintenance Requested: 7870 - 05/09/2014 - DVD player and two monitors aren't working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
157 - BROIN, DOUGLAS		\$14.00		
Labor Comments: replaced dvd player				
Miscellaneous Labor		\$0		
Other			\$0	
38:Audio / Video Surveillance System	\$0	\$0	\$0.00	\$0.00

Maintenance Requested: 7857 - 05/08/2014 - DVD Player doesn't work

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
157 - BROIN, DOUGLAS		\$0.00		
Labor Comments: completed on another line.				
Miscellaneous Labor		\$0		
Other			\$0	
38:Audio / Video Surveillance System	\$0	\$0	\$0.00	\$0.00

Maintenance Requested: 7810 - 04/28/2014 - Speakers blown and DVD system working intermittent

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
157 - BROIN, DOUGLAS		\$0.00		
Labor Comments: completed on another line.				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$568.21	\$127.50	\$0.00	\$695.71

accessory drive gear (1.000)

Pillsbury: Gasket Oil Pan:

08929102 (1.000)

Pillsbury: Oil Pan Bolts,

Detroit: 11504571 (10.000)

Pillsbury: Isolator, Oil Pan Bolt

Detroit: 23517242 (10.000)

Pillsbury: Spacer Detroit Oil

Pan: 23517243 (10.000)

Miscellaneous Parts

7050 - STRAND, MATTHEW

(2.55)

Labor Comments: repaced the accessory drive gear. had to run to c and j to get it

Miscellaneous Labor

Other

75:Windows/windshields	\$62.56	\$99.00	\$0.00	\$161.56
Pillsbury: Decal Nameplate-	\$62.56			
emergency exit: 03-15-7274				
(8.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$99.00		
(1.98)				

Labor Comments: missing emergency window plates

Miscellaneous Labor

Other

77:Mirrors	\$0	\$82.50	\$0.00	\$82.50
------------	-----	---------	--------	---------

Maintenance Requested: 7974 - 06/11/2014 - Right mirror very loose

Requestor Notes: Water temp guage doesn't work

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

157 - BROIN, DOUGLAS

Labor Comments: repaired wiring on mirrors.

Miscellaneous Labor

Other

5/7/2019

## Work Order Detail

AF:Air Filter Replacement	\$31.34	\$0	\$0.00	\$31.34
Pillsbury: Filter Air EL3: 6774	\$31.34			
(1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$0.00		
(0.00)				
Labor Comments: Replace air filter				
Miscellaneous Labor		\$0		
Other			\$0	
FF:Fuel Filter	\$8.31	\$46.50	\$0.00	\$54.81
Pillsbury: Filter, Fuel, MCI:	\$4.08			
3120 (1.000)				
Pillsbury: Filter Fuel: 3118	\$4.23			
(1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$32.50		
(0.65)				
Labor Comments: Replaced fuel filters				
157 - BROIN, DOUGLAS		\$14.00		
Labor Comments: replaced fuel filters.				
Miscellaneous Labor		\$0		
Other			\$0	
HUB:Hub Service	\$0	\$0	\$0.00	\$0.00
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
LOF:Lube, Oil, Filter	\$372.83	\$100.00	\$0.00	\$472.83
Pillsbury: Filter Oil MCI D4500	\$15.96			
w/Detroit Diesel 60 Series:				
1971MP (2.000)				
Pillsbury: Oil Bulk in Quarts:	\$348.12			
Oil 15W-40 Bulk (36.000)				
Pillsbury: Oil Analysis Kit:	\$8.75			
Sample Kit (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$100.00		
(2.00)				
Labor Comments: did a ful service				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0.00	\$1,138.73	\$548.00	\$0
			\$0	\$1,686.73

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 717,007.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19204	06/18/2014	06/19/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$0	\$37.50		\$0.00	\$37.50

Maintenance Requested: 7991 - 06/16/2014 - Very loose mirror,  
Requestor Notes: Foot rest on the bottom of seat 33 missing a screw on one end.

Window leaks above drivers head( coming from top of eyebrow window)

Mirror right side still loose- everythings a blur

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
7050 - STRAND, MATTHEW \$37.50  
(0.75)

Labor Comments: only had time to fix mirror, had to take it off and retap the whole and but new bolt in

Miscellaneous Labor  
Other

\$0

\$0

\$0	\$0	\$37.50	\$0	\$0	<u>\$37.50</u>
-----	-----	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 719,053.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19414	07/10/2014	07/16/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$89.57	\$423.50		\$0.00	\$513.07
Pillsbury: Tie Down ring-recessed: B901 (1.000)		\$13.97				
Pillsbury: Freon R134A per Lb.: R134A (24.000)		\$75.60				
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$109.00			
Labor Comments: charged a/c system						
7050 - STRAND, MATTHEW (6.29)			\$314.50			
Labor Comments: fixed high side hose						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$89.57	\$423.50	\$0	\$0	<u>\$513.07</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 719,638.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19499	07/18/2014	07/30/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
12:Axles (rear)		\$0	\$0		\$0.00	\$0.00
Maintenance Requested:						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Labor Comments: looked at it, its actually the front right tire that is going whack						
Miscellaneous Labor			\$0			
Other					\$0	
38:Audio / Video Surveillance System		\$0	\$31.00		\$0.00	\$31.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.62)			\$31.00			
Labor Comments: fixed the dvd player						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$182.50		\$0.00	\$182.50
Maintenance Requested: 8105 - 07/16/2014 - Def fan works on high only						
Requestor Notes: Def fan works only on high , low&med doesn't work .						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.65)			\$182.50			

Labor Comments: found that the control panel had rotte pin after doing many series of electrical tests, waiting on parts

Miscellaneous Labor			\$0			
Other					\$0	
43:Cooling		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 8092 - 07/14/2014 - Was very low on Anti-Freez						
Requestor Notes: DVD and TV monitors aren't working.						
TV monitors mount on wrong						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: filled with antifreeze						
Miscellaneous Labor			\$0			
Other					\$0	
73:Seats		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 8043 - 06/27/2014 - Broken foot rest seat37						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: seat and broken foot rests						
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$0	\$213.50	\$0	\$0
						<u>\$213.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 721,670.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19506	07/18/2014	07/30/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38:Audio / Video Surveillance System		\$65.30	\$87.50		\$0.00	\$152.80
Work Comments: check dvd system						
Pillsbury: Microphone P.A. MCI		\$65.30				
D4500: 7J-13-96 (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$87.50			
Labor Comments: dvd player is working fine. one monitor is inop and the two rear monitors are facing the wrong way. Removed the two rear monitors and reinstalled them facing the rear. removed the inop monitor and repaired a bad video connection. microphone is working at this time but installed a spare microphone for the driver.						
Miscellaneous Labor			\$0			
Other					\$0	
40:Engine		\$392.05	\$40.00		\$0.00	\$432.05
Work Comments: oil leak						
Pillsbury: Belt Alternator MCI		\$17.59				
EL3: 08-27-1018 (1.000)						
Pillsbury: Belt Alternator MCI		\$38.36				
Motor Coach: 8L-27-132						
(1.000)						
Pillsbury: plate assy, oil:		\$336.10				
23529372 (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$40.00			
Labor Comments: engine is leaking oil from the oil fill tube and behind the tensioner. Installed new longer oil fill tube and resealed the engine cover behind the tensioner. The belts were						

Miscellaneous Labor	oil soaked so i installed a new drive and alternator belt.	\$0					
Other						\$0	
		\$0	\$457.35	\$127.50	\$0	\$0	<u>\$584.85</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 721,669.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19538	07/23/2014	07/30/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$735.44	\$269.00		\$0.00	\$1,004.44
Tire Temporary: Tire New		\$735.44				
Virgin FS400: 315/80R 22.5						
New Virgin Tire (2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$146.50			
(2.93)						
Labor Comments: replaced tread on front and switch them to tag except for one						
157 - BROIN, DOUGLAS			\$122.50			
Labor Comments: Installed 2 new tires if front and 1 used tire on tag.						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$203.55	\$104.00		\$0.00	\$307.55
Maintenance Requested: 8111 - 07/23/2014 - Right side AC fan on dash notworking						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Blower Parcel rack		\$203.55				
Heater MCI D4500: 16L-14-68						
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$64.00			
(1.28)						
Labor Comments: fixed the pin for the low med high setting for the fan and then replaced right side fans						

ASSIGN A MANAGED WORK CODE

HAPPY :0

157 - BROIN, DOUGLAS			\$40.00			
Labor Comments: installed new r/f blower motor and repaired wiring						
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$938.99	\$373.00	\$0	\$0
						<u>\$1,311.99</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 722,868.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19628	07/30/2014	08/08/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$177.16	\$79.50		\$0.00	\$256.66
Pillsbury: Draglink End LH		\$177.16				
EL3 MCI: 11-04-1006 (2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$79.50			
(1.59)						

Labor Comments: replaced both drag links on steering rod					
Miscellaneous Labor		\$0			
Other				\$0	
36:Lighting		\$65.04	\$172.50	\$0.00	\$237.54
Work Comments: R/F fog lamp inop					
07-07-1009 lamp-comb fr lh (1.000)		\$32.52			
07-07-1010 lamp-comb fr rh (1.000)		\$32.52			
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW (1.45)			\$72.50		
Labor Comments: replaced turn signal lamps					
157 - BROIN, DOUGLAS			\$100.00		
Labor Comments: No power at fog lamp. Traced wires to find a spot in the harness that is bad. Repaired wiring and tested.					
Miscellaneous Labor		\$0			
Other				\$0	
38:Audio / Video Surveillance System		\$429.00	\$170.50	\$0.00	\$599.50
Maintenance Requested: 8138 - 08/01/2014 - TV and DVD player intermitently.					
Requestor Notes:					
Technician Response:					
Maint Req Status: Completed					
Pillsbury: Dvd Player elite system: 710089 (1.000)		\$429.00			
Miscellaneous Parts		\$0			
157 - BROIN, DOUGLAS			\$166.50		
Labor Comments: Installed new dvd player. None of the wiring was the same to install the REI dvd players that we stock, so I re wired the entertainment system for REI. Also repaired the video connections.					
6103 - STRAND, JACOB			\$4.00		
Labor Comments: Doug looked it over at night.					
Miscellaneous Labor		\$0			
Other				\$0	
40:Engine		\$7.00	\$187.50	\$0.00	\$194.50
Work Comments: Engine will shut down					
Pillsbury: Oil Gear Synthetic: Oil Gear 75W-90 BULK in quarts (2.000)		\$5.98			
Pillsbury: Gasket Fuel Pump, Detroit Series 60: 23505248 (1.000)		\$1.02			
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW (0.97)			\$48.50		
Labor Comments: replaced fuel pump gasket and found that the fuel pump coupler was bad, took one off a used compressor, and ordered two for stock					
157 - BROIN, DOUGLAS			\$139.00		
Labor Comments: Found a code for engine overheating. Radiator is plugged with oil and dirt. found the fan gear box is empty on oil. There is no vent on gear box ,so the oil is blowing out into the radiator. Filled gear box and made a vent. Washed radiator and test drove.					
Miscellaneous Labor		\$0			
Other				\$0	
41:A/C & Heating		\$0	\$131.50	\$0.00	\$131.50
Miscellaneous Parts		\$0			
157 - BROIN, DOUGLAS			\$131.50		
Labor Comments: added comp oil					
Miscellaneous Labor		\$0			
Other				\$0	
CFR:Coolant Filter Replacement		\$9.87	\$21.50	\$0.00	\$31.37
Pillsbury: Filter Coolant: 4206 (1.000)		\$9.87			
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW (0.43)			\$21.50		

Labor Comments: repaced coolant filter

Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep	\$0	\$84.00		\$0.00		\$84.00
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (1.68)		\$84.00				
Labor Comments: creeped it and found bad tie rods, leaking fuel pump gasket, and a/c compressor oil was low						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$688.07	\$847.00	\$0	\$0	<u>\$1,535.07</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 724,461.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
19819	08/14/2014	08/18/2014	Closed	0.00		
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>
72:Body Misc			\$0	\$31.50		\$0.00
Miscellaneous Parts			\$0			
157 - BROIN, DOUGLAS				\$31.50		
Labor Comments: Installed used light cover track on inside of coach.						
Miscellaneous Labor				\$0		
Other					\$0	
	\$0	\$0	\$31.50	\$0	\$0	<u>\$31.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 726,516.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
198935	08/29/2014	08/30/2014	Closed	0.00		
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>
22:Tires			\$0	\$67.50		\$0.00
Work Comments: Right inner tire low.						
Miscellaneous Parts			\$0			
157 - BROIN, DOUGLAS				\$67.50		
Labor Comments: Removed Right inner drive tire and fixed leak.						
Miscellaneous Labor				\$0		
Other					\$0	
LOF:Lube, Oil, Filter			\$106.76	\$307.00		\$0.00
Pillsbury: Filter Oil MCI D4500			\$14.80			
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Bulk in Quarts:			\$91.96			
Oil 15W-40 Bulk (38.000)						
Miscellaneous Parts			\$0			
7050 - STRAND, MATTHEW (2.02)				\$101.00		
Labor Comments: started a service						
157 - BROIN, DOUGLAS				\$206.00		
Labor Comments: L-O-F						
Miscellaneous Labor				\$0		
Other					\$0	
	\$0	\$106.76	\$374.50	\$0	\$0	<u>\$481.26</u>



## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 726,925.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199002	09/04/2014	09/30/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$302.50	\$218.00		\$0.00	\$520.50
Pillsbury: Glass Windshield		\$302.50				
Front LH w/Mask MCI EL3:						
03-27-1325 (1.000)						
Miscellaneous Parts		\$0				
6004 - GLAZER, DANIEL			\$101.50			
(2.03)						
0081 - WOLF, PATRICK (2.33)			\$116.50			
Labor Comments: 75 - - - Removed and replaced the drivers windshield (cracked)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$302.50	\$218.00	\$0	\$0	<u>\$520.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 729,915.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199007	09/04/2014	09/29/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$36.69	\$49.00		\$0.00	\$85.69
Work Comments: ABS light is on						
Pillsbury: Sensor ABS		\$36.69				
Freightliner Front: R955341						
(1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$49.00			
Labor Comments: Removed and replaced R/F wheel speed sensor.						
Miscellaneous Labor			\$0			
Other					\$0	
52:Electrical Accessories		\$0	\$14.00		\$0.00	\$14.00
Miscellaneous Parts		\$0				
6103 - STRAND, JACOB			\$14.00			
Labor Comments: -3 monitors have lines in the screen and one is really glitchy(flashy etc.)						
Going to order the montiors and wait till they come in.						
Miscellaneous Labor			\$0			
Other					\$0	
FF:Fuel Filter		\$8.14	\$61.00		\$0.00	\$69.14
Pillsbury: Filter Fuel: 3118		\$4.06				
(1.000)						
Pillsbury: Filter, Fuel, MCI:		\$4.08				
3120 (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$61.00			
Labor Comments: Replaced two fuel filters.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$44.83	\$124.00	\$0	\$0	<u>\$168.83</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 727,551.0

## Work Order Detail

		Location: PBG		Department: PBG5-Charter			
Recall:		Campaign #		Date:			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
199045	09/08/2014	09/30/2014	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine			\$733.96	\$0		\$0.00	\$733.96
23529249 oil pan (1.000)			\$626.13				
23539104 gasket (1.000)			\$43.07				
08923313 m plug (3.000)			\$4.83				
23511574 c plug (1.000)			\$0.74				
23517728 plug pipe (1.000)			\$4.89				
23522281 bolt assy (10.000)			\$54.30				
Miscellaneous Parts			\$0				
Miscellaneous Labor				\$0			
Other						\$0	
41:A/C & Heating			\$289.50	\$142.00		\$0.00	\$431.50
Maintenance Requested: 8226 - 09/06/2014 - drivers side a/c fan not kicking on.							
Requestor Notes:							
Technician Response:							
Maint Req Status: Completed							
Pillsbury: Blower Parcel Rack:			\$289.50				
03-07-1124 (1.000)							
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$23.50			
(0.47)							
Labor Comments: pulled in and started to take apart							
157 - BROIN, DOUGLAS				\$118.50			
Labor Comments: Tested all wiring and relays to find motor is bad. Removed and replaced parcel rack							
blower motor on L/H side							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$1,023.46	\$142.00	\$0	\$0	\$1,165.46

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 728,116.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
199201	09/20/2014	09/29/2014	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
RT:Road Test			\$0	\$26.00		\$0.00	\$26.00
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$26.00			
(0.52)							
Labor Comments: problem with dash going out, i think it was just the computers getting overloaded for a							
brief second, i drove to elko and back and could not get problem to duplicate.							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$0	\$26.00	\$0	\$0	\$26.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 730,495.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #			Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
199452	10/13/2014	10/20/2014	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System			\$126.76	\$99.00		\$0.00	\$225.76

5/7/2019

Work Order Detail

Pillsbury: Bellow ASM-Air, TRL.	\$120.75					
Axle, EL3: 12-03-1029 (1.000)						
Pillsbury: Valve Drain Air Tank:	\$6.01					
4R-19-130 (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$99.00				
(1.98)						
Labor Comments: found leak and replaced air bag and air release valve						
Miscellaneous Labor		\$0				
Other				\$0		
72:Body Misc	\$17.59	\$161.00		\$0.00		\$178.59
Maintenance Requested: 8347 - 10/07/2014 - The small door, where the outside door						
Requestor Notes: controls doesn't stay shut.						
Water leaks into many areas of the bus.						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Belt Alternator MCI	\$17.59					
EL3: 08-27-1018 (1.000)						
Miscellaneous Parts	\$0					
157 - BROIN, DOUGLAS		\$101.00				
Labor Comments: sealed water leaks.						
7050 - STRAND, MATTHEW		\$60.00				
(1.20)						
Labor Comments: replaced alt belt and sealed roof hatch and checked all doors and lubed rear hatch						
Miscellaneous Labor		\$0				
Other				\$0		
CR:Creep	\$0	\$41.50		\$0.00		\$41.50
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$41.50				
(0.83)						
Labor Comments: creeped it since i had it in the air						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$144.35	\$301.50	\$0	\$0	<u>\$445.85</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 730,999.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
199552	10/21/2014	10/21/2014	Closed	0.00		
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
0142 - GALLINGER, CHAD			\$0.00			
(0.00)						
Labor Comments: checked oil						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$0	\$0	\$0	<u>\$0.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate: PRZ9154

Miles: 732,132.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
199660	10/29/2014	10/29/2014	Closed	0.00		
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>

5/7/2019

## Work Order Detail

43:Cooling	\$0	\$82.50		\$0.00	\$82.50
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (1.65)		\$82.50			
Labor Comments: 43 -- Found broken hose on the bus. Looked up and ordered a new hose.					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$0	\$82.50	\$0	\$0
					<u>\$82.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 732,826.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199664	10/29/2014	10/31/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$131.50		\$0.00	\$131.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$131.50			
(2.63)						
Labor Comments: redid oil pan and bolts, parts are on pervious work order						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 8421 - 10/29/2014 - Please fix temperture control for air/heat						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: stuck on full, know about the problem and will address						
Miscellaneous Labor			\$0			
Other					\$0	
43:Cooling		\$142.27	\$120.00		\$0.00	\$262.27
Pillsbury: Filter Coolant w/Full		\$31.38				
Charge MCI D4500 w/ Detroit						
60 Series Engine: 4088						
(1.000)						
Pillsbury: Fluid Coolant Bulk		\$46.80				
50/50 After Dilution: A/F 50/50						
Green BULK (10.000)						
06-08-1006 coolant hose		\$64.09				
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$58.50			
(1.17)						
Labor Comments: blew radiator hose						
157 - BROIN, DOUGLAS			\$61.50			
Labor Comments: installed coolant hose						
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$113.20	\$120.00		\$0.00	\$233.20
Pillsbury: Purge Valve Repair		\$66.72				
Kit, AD-IP: K022105 (1.000)						
Pillsbury: AD-IP Air Dryer		\$46.48				
Desiccant Cartridge Bendix:						
109493BXR (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$34.00			
Labor Comments: rebuilt air dryer						
7050 - STRAND, MATTHEW			\$86.00			
(1.72)						

Labor Comments: rebuilt air drier						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter	\$113.59	\$205.00		\$0.00		\$318.59
Pillsbury: Filter Oil MCI D4500	\$14.80					
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Bulk in Quarts:	\$89.54					
Oil 15W-40 Bulk (37.000)						
Pillsbury: Oil Analysis Kit:	\$9.25					
Sample Kit (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$96.50				
(1.93)						
Labor Comments: complete service						
157 - BROIN, DOUGLAS		\$108.50				
Labor Comments: finished engine service						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0.00	\$369.06	\$576.50	\$0	\$0	\$945.56

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 732,826.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199711	11/03/2014	11/06/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$781.50		\$0.00	\$781.50

Work Comments: Repairing the right front bumper corner. The previous repair did not hold when the bumper had hit a curb of some sort. using 3m green apoxy on the broken/cracked plastic then fiberbond on top of that. glaze then paint

Miscellaneous Parts		\$0				
0423 - KRANZ, DANIEL			\$781.50			
(15.63)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$781.50	\$0	\$0	\$781.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 733,663.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199839	11/12/2014	12/14/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
84:Decals / Placards		\$163.50	\$130.00		\$0.00	\$293.50
Pillsbury: Nameplate		\$16.18				
Emergency exit lh: 03-15-7257						
(2.000)						
Pillsbury: Nameplate		\$15.72				
Emergency exit rh:						
03-15-7258 (2.000)						
Pillsbury: Decal " Passenger		\$12.68				
window release": 03-15-1427						
(2.000)						
Pillsbury: Decal " Emergency		\$72.00				
Exit" english: 03-15-1430						

(16.000)  
Pillsbury: Decal Nameplate-  
emergency exit: 03-15-7274

\$46.92

(6.000)  
Miscellaneous Parts  
157 - BROIN, DOUGLAS

\$0

\$130.00

Labor Comments: Installed missing window decals.

Miscellaneous Labor  
Other

\$0

\$0

\$0      \$163.50      \$130.00      \$0      \$0      \$293.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 734,812.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199962	11/25/2014	12/14/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$42.07	\$217.00		\$0.00	\$259.07

Pillsbury: Fuel Nozzle

\$24.61

Webasto: W-470716 (1.000)

Pillsbury: Ignition Electrode

\$17.46

Webasto Thermo 230/300

Heater: 16-16-1109 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW  
(3.34)

\$167.00

Labor Comments: got the webasto working correctly and tuned it up

157 - BROIN, DOUGLAS

\$50.00

Labor Comments: wabasto wont trun on. Found the road relay on dash was unplugged. plugged in relay  
and found how to turn off the over speed alarm. somebody unplugged the relay  
because the alarm would sound when going over 5mph.

Miscellaneous Labor  
Other

\$0

\$0

50:Accessories		\$95.47	\$182.50		\$0.00	\$277.97
----------------	--	---------	----------	--	--------	----------

Pillsbury: Light Bulb 12 Volt

\$4.12

Mini Fog/Driving: BP1255/H3  
(1.000)

Pillsbury: Spring Gas R. Hand

\$51.11

Locking Radiator Door MCI

D4500: 03-31-2819 (1.000)

Pillsbury: Light Bulb Pass.

\$1.88

Sevice Module 28V 10W:

03-08-1162 (2.000)

Pillsbury: Belt Alternator MCI

\$38.36

Motor Coach: 8L-27-132

(1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW  
(3.65)

\$182.50

Labor Comments: fixed bunch of lights, got fluids ready and supply door in order, also checked out the  
inside and made sure everything worked correctly

Miscellaneous Labor  
Other

\$0

\$0

\$0      \$137.54      \$399.50      \$0      \$0      \$537.04

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 735,869.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

5/7/2019

## Work Order Detail

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
200193	12/17/2014	12/26/2014	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield						\$35.00	\$35.00
Repair, Inv. # 2783933							
22:Tires			\$0	\$156.50		\$0.00	\$156.50
Work Comments: L/H inner drive tire is low.							
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$37.50			
(0.75)							
Labor Comments: Leaking valve stem							
157 - BROIN, DOUGLAS				\$119.00			
Labor Comments: Removed tire and found valve stem is leaking from making contact with the caliper.							
Installed new valve stem and reinstalled tire.Checked all other rims and tires.							
Miscellaneous Labor				\$0			
Other						\$0	
35:Instrument & Gauges			\$0	\$306.50		\$0.00	\$306.50
Maintenance Requested: 8586 - 12/17/2014 - Air supply low alarm wouldn't not shut							
Requestor Notes: off. Gauges were fine, per Jason-I unplugged the fuse below the drivers window.							
Jason needs to have the buis to look at the problem.							
Tires are wearing thin, No tractic on snow and Ice							
Technician Response:							
Maint Req Status: Completed							
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$189.00			
(3.78)							
Labor Comments: water and oil in the air system, drained it and shot alcholol in system and took sensors out to get water and moisture out							
157 - BROIN, DOUGLAS				\$117.50			
Labor Comments: Removed the sensor for the low air alarm and foud alot of water. Blew out the water and all is working fine.							
Miscellaneous Labor				\$0			
Other						\$0	
75:Windows/windshields			\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 8576 - 12/16/2014 - Windshield chip drivers side							
Requestor Notes:							
Technician Response:							
Maint Req Status: Completed							
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$0.00			
(0.00)							
Labor Comments: safeglass fixed chip							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$0	\$463.00	\$0	\$35.00	\$498.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 736,755.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
200259	12/24/2014	01/24/2015	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
52:Electrical Accessories			\$482.80	\$312.50		\$0.00	\$795.30
Pillsbury: Dvd Player,advanced system 12/24V: 710088 (1.000)			\$429.00				
Pillsbury: Cable Dvd to sys 2000: 512216 (1.000)			\$33.50				

5/7/2019

## Work Order Detail

Pillsbury: cable(E) vcm to vcp  
3ft: 511074 (1.000)

\$20.30

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$312.50

(6.25)

Labor Comments: redid the dvd system

Miscellaneous Labor

\$0

Other

\$0

\$0	\$482.80	\$312.50	\$0	\$0	<u>\$795.30</u>
-----	----------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 736,755.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200322	01/02/2015	01/24/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CR:Creep		\$0	\$123.50		\$0.00	\$123.50

Work Comments: Needs inspection

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$123.50

Labor Comments: Inspected bus

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$123.50	\$0	\$0	<u>\$123.50</u>
-----	-----	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 737,070.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200423	01/12/2015	01/24/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
MS:Misc		\$0	\$84.00		\$0.00	\$84.00

Work Comments: Due to lack of weatherstrip between windscreen and dash, keys w/ fuel key fell down  
in there somewhere.

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (1.68)

\$84.00

Labor Comments: Removed lower valance, found keys, filled in gap with weatherstrip

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$84.00	\$0	\$0	<u>\$84.00</u>
-----	-----	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 737,186.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200498	01/16/2015	01/24/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$1,210.70	\$87.50		\$0.00	\$1,298.20

Work Comments: L3 fogged

Pillsbury: Glass Unit-double

\$1,210.70

glazed: 03-27-1079 (1.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (1.75)

\$87.50

Labor Comments: Change out #L3 side window.



Miscellaneous Labor  
Other

\$0

\$0

\$0 \$1,210.70 \$87.50 \$0 \$0 \$1,298.20

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 737,186.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200500	01/16/2015	01/24/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$24.00		\$0.00	\$24.00

Maintenance Requested: 8630 - 01/02/2015 - Alarm going off for exceeding 75mp

Requestor Notes: gauage for oil temp not working,

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$24.00

(0.48)

Labor Comments: took it for a road test to see if the drivers display alarm was still going off, and found  
out the webasto was not working

Miscellaneous Labor

\$0

Other

\$0

38:Audio / Video Surveillance System

\$0

\$54.00

\$0.00

\$54.00

Work Comments: DVD not working on R/H center monitor.

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$54.00

Labor Comments: Repaired wiring to video monitor

Miscellaneous Labor

\$0

Other

\$0

41:A/C &amp; Heating

\$0

\$206.00

\$0.00

\$206.00

Work Comments: Webasto not working

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$31.50

(0.63)

Labor Comments: got 526 in to look at the heat

157 - BROIN, DOUGLAS

\$174.50

Labor Comments: Webasto ignition unit was bad and the collar for the fan motor to fuel pump was broken  
so the fuel pump wouldnt run. Replaced parts from used wabasto and orderd new  
ones to replace them.

Miscellaneous Labor

\$0

Other

\$0

49:Air System

\$0

\$62.50

\$0.00

\$62.50

Work Comments: Air leak over drive axle.

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$62.50

Labor Comments: Replaced brass fitting for air system

Miscellaneous Labor

\$0

Other

\$0

50:Accessories

\$28.01

\$95.00

\$0.00

\$123.01

Maintenance Requested: 8618 - 12/30/2014 - Ice is forming on drivers side window

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Fan Auxillary Dash

\$28.01

2-Speed 12V Defrost School

Bus/Minicoach: USB093

(1.000)

Pillsbury: Switch 3-Way

\$0.00

Auction: LR39145 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$95.00

(1.90)

Labor Comments: installed fan on drivers window

Miscellaneous Labor

\$0

Other

\$0

\$0	\$28.01	\$441.50	\$0	\$0	<u>\$469.51</u>
-----	---------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 738,255.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200563	01/22/2015	01/24/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$0	\$41.00		\$0.00	\$41.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.82)			\$41.00			

Labor Comments: 01 -- Added alcohol to the wet tank looked at the front door opening very slow. Needs new pins and bushings.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$41.00	\$0	\$0	<u>\$41.00</u>
-----	-----	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 739,565.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200684	02/02/2015	02/21/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$0	\$66.00		\$0.00	\$66.00

Work Comments: L/R tag tire low

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$66.00

Labor Comments: patched the tire

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$66.00	\$0	\$0	<u>\$66.00</u>
-----	-----	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 739,565.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200690	02/03/2015	02/21/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$1,268.15	\$179.00		\$0.00	\$1,447.15

Work Comments: #R5 fogged

Pillsbury: Glass Unit-double glazed: 03-27-1079 (1.000)

\$1,268.15

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (3.58)

\$179.00

Labor Comments: Replace R5, 1st sash was defective, used 2nd glass.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$1,268.15	\$179.00	\$0	\$0	<u>\$1,447.15</u>
-----	------------	----------	-----	-----	-------------------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 739,763.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200718	02/05/2015	02/21/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$367.72	\$117.50		\$0.00	\$485.22
Work Comments: L/R tag tire leaking						
Pillsbury: Tire New Virgin		\$367.72				
FS400: 315/80R 22.5 New						
Virgin Tire (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$117.50			
Labor Comments: Found a nail in tire. Tire already had a patch and the bead was falling apart. replaced with new tire.						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$29.08	\$292.50		\$0.00	\$321.58
Work Comments: wabasto is not running right and blowing alot of smoke.						
Pillsbury: Fuel Nozzle		\$29.08				
Webasto: W-470716 (1.000)						
11112778c webasto fuel		\$0.00				
pump (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$99.00			
(1.98)						
Labor Comments: i got webasto working for the day so it could go on trip						
157 - BROIN, DOUGLAS			\$193.50			
Labor Comments: Removed webasto and found bad fuel pump. Removed and replaced fuel pump and nozzle. test and all is working fine at this time.						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$0	\$101.00		\$0.00	\$101.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$101.00			
(2.02)						
Labor Comments: fixed foot rests, dvd monitor, took used latch and fixed e window latch, fixed piece of trim in rear and ordered up asile lights						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$115.81	\$154.00		\$0.00	\$269.81
Pillsbury: Oil Bulk in Quarts:		\$91.76				
Oil 15W-40 Bulk (37.000)						
Pillsbury: Oil Analysis Kit:		\$9.25				
Sample Kit (1.000)						
Pillsbury: Filter Oil MCI D4500		\$14.80				
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$154.00			
(3.08)						
Labor Comments: did complete service						
Miscellaneous Labor			\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$512.61	\$665.00	\$0	\$0	<u>\$1,177.61</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 740,600.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200973	02/24/2015	02/28/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$0		\$0.00	\$0.00
Work Comments: I will fix front corner bumper passenger side						
Miscellaneous Parts		\$0				
9037 - WEED, TERRY (29.35)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$0	\$0	\$0	<u>\$0.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 740,600.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200998	02/25/2015	03/04/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$260.00	\$314.50		\$0.00	\$574.50
Work Comments: Left side of bus loses air and leans						
Pillsbury: Air Spring Trailing		\$260.00				
Axle EL3 MCI: 12-03-1074						
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$124.00			
(2.48)						
Labor Comments: fixed two air leaks						
157 - BROIN, DOUGLAS			\$190.50			
Labor Comments: Found L/R tag air bag was losing air causing the bus to lean. Replaced air bag.						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$128.19	\$288.50		\$0.00	\$416.69
Work Comments: Int. lights out						
Pillsbury: Switch Pass.		\$55.86				
Overhead Light: 03-08-1160						
(2.000)						
Pillsbury: Light Bulb Pass.		\$4.70				
Sevice Module 28V 10W:						
03-08-1162 (5.000)						
Pillsbury: Ballast Interior Light		\$67.63				
EL3: 07-07-1040 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$158.50			
(3.17)						
Labor Comments: ballast was out, rewired that, fixed reading lights that were burnt out, fixed foot rests that were loose, ran thru all the lights inside						
157 - BROIN, DOUGLAS			\$130.00			
Labor Comments: Replaced int. lights and ballast						
Miscellaneous Labor			\$0			
Other					\$0	
79:Lavatory		\$0	\$127.50		\$0.00	\$127.50
Work Comments: Lavatory light and buzzer will come on and off while driving.						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$127.50			
Labor Comments: Inspected wiring in dash and lavatory to find two wires behind the lav wall were touching and causing the alarm to go off when hitting bumps. Repaired wires and						

tested.

Miscellaneous Labor		\$0			
Other				\$0	
HUB:Hub Service	\$47.92	\$66.50	\$0.00	\$114.42	
Pillsbury: Oil Gear Synthetic:	\$47.92				
Oil Gear 75W-90 BULK in quarts (8.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW (1.33)		\$66.50			
Labor Comments: did hub service, bunch of silver in tag hubs					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0.00	\$436.11	\$797.00	\$0	\$0
					<u>\$1,233.11</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 741,255.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
201086	03/03/2015	03/20/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$502.04	\$471.50		\$0.00	\$973.54
Work Comments: Front brake rotors are wearing abnormal						
Pillsbury: Rotor EL3:		\$502.04				
15-02-1010 (2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (6.96)			\$348.00			
Labor Comments: front brakes, full meal deal						
157 - BROIN, DOUGLAS			\$123.50			
Labor Comments: Orderd front brake parts						
Miscellaneous Labor			\$0			
Other					\$0	
20:Steering		\$420.45	\$802.50		\$0.00	\$1,222.95
Work Comments: tag axle tie rod loose and metal in R/R tag hub oil						
Pillsbury: Bearing: 555-S (1.000)		\$82.37				
Pillsbury: bearing: 6420 (1.000)		\$91.83				
Pillsbury: bearing: 6461-A (1.000)		\$164.75				
Pillsbury: Bearing Race Front		\$46.53				
Wheel Outer MCI D4500: 552ATRB (1.000)						
Pillsbury: Seal Frt. MCI EL3: 380048A (1.000)		\$34.97				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (6.16)			\$308.00			
Labor Comments: brake job on steers, another work order open to						
157 - BROIN, DOUGLAS			\$494.50			
Labor Comments: orderd tag axle part and replaced bearings and seal on R/R tag axle.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$922.49	\$1,274.00	\$0	\$0	<u>\$2,196.49</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 742,004.0

Location: PBG

Department: PBG5-Charter

		Recall:	Campaign #		Date:			
<u>WO #</u>	<u>Open Date</u>		<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
201196	03/11/2015		03/21/2015	Closed	0.00			
<u>Detail</u>			<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes				\$1,262.50	\$385.00		\$0.00	\$1,647.50
Pillsbury: Wheel Guard 10				\$11.38				
Hole .047" Teflon MCI D4500:								
15K-1-11 (2.000)								
Pillsbury: Sensor ABS				\$73.44				
Freightliner Front: R955341								
(2.000)								
Pillsbury: Hub Bolt; MCI EL3				\$157.20				
(10 per wheel): 15-02-1009								
(20.000)								
Pillsbury: bearing: 6420				\$183.66				
(2.000)								
Pillsbury: Bearing: 555-S				\$164.74				
(2.000)								
Pillsbury: Seal Frt. MCI EL3:				\$69.94				
380048A (2.000)								
Pillsbury: Bearing Race Front				\$46.53				
Wheel Outer MCI D4500:								
552ATRB (1.000)								
Pillsbury: bearing: 6461-A				\$329.50				
(2.000)								
Pillsbury: Pads brake EL3:				\$226.11				
04-01-1019 (1.000)								
Miscellaneous Parts				\$0				
157 - BROIN, DOUGLAS					\$385.00			
Labor Comments: replaced steer axle brakes,bearings,abs sensors and rotors								
Miscellaneous Labor					\$0			
Other							\$0	
			\$0	\$1,262.50	\$385.00	\$0	\$0	\$1,647.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 742,709.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
201482	04/06/2015	04/08/2015	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids			\$9.36	\$338.50		\$0.00	\$347.86
Pillsbury: Fluid Coolant Bulk			\$9.36				
50/50 After Dilution: A/F 50/50							
Green BULK (2.000)							
Miscellaneous Parts			\$0				
0081 - WOLF, PATRICK (6.77)				\$338.50			
Labor Comments: 01 -- Fluids Check fluids, A/C and evrything else for trip to Ohio.							
Miscellaneous Labor				\$0			
Other						\$0	
31:Charging			\$466.20	\$165.00		\$0.00	\$631.20
Work Comments: 31 -- Bad battery cable and weak batteries.							
Pillsbury: Battery 8D Top stud			\$458.20				
1/2 pos 3/8 neg							
1400CCA(mci): 8DAS (2.000)							
BP109 batt. term. 4/0 Pos.			\$8.00				
(1.000)							
Miscellaneous Parts			\$0				
0081 - WOLF, PATRICK (3.30)				\$165.00			
Labor Comments: 31 -- Bad battery cable and weak batteries. --- Removed and replaced the batteries and one cable end.							

5/7/2019

## Work Order Detail

Miscellaneous Labor		\$0			
Other				\$0	
FF:Fuel Filter		\$8.14	\$36.50	\$0.00	\$44.64
Work Comments: Fuel filters ---					
Pillsbury: Filter, Fuel, MCI:		\$4.08			
3120 (1.000)					
Pillsbury: Filter Fuel: 3118		\$4.06			
(1.000)					
Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (0.73)			\$36.50		
Labor Comments: Fuel filters --- Removed and replaced the fuel filters.					
Miscellaneous Labor			\$0		
Other				\$0	
	\$0	\$483.70	\$540.00	\$0	\$0
					<u>\$1,023.70</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 743,111.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
201732	04/27/2015	04/28/2015	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal			\$0	\$200.00		\$0.00	\$200.00
Miscellaneous Parts			\$0				
82 - BLANCO, VICTOR (4.00)				\$200.00			
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$0	\$200.00	\$0	\$0	\$200.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 743,111.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
201762	04/28/2015	05/11/2015	Closed	0.00		
Description: kneel inop. mirror loose. audio inop						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$34.55	\$178.50		\$0.00	\$213.05
Work Comments: kneel is inop						
Pillsbury: Switch ASM-Kneeling, EL3: 07-19-1015 (1.000)		\$34.55				
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$178.50			
Labor Comments: Tested all wiring to find the switch is bad. ordered new switch and installed.						
Miscellaneous Labor			\$0			
Other					\$0	
38:Audio / Video Surveillance System		\$498.85	\$512.50		\$0.00	\$1,011.35
Work Comments: Audio is inop						
Pillsbury: Dvd Player, advanced control head: 710232 (1.000)		\$498.85				
speaker (1.000)		\$0.00				
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$290.00			
Labor Comments: no audio from the first three seats back. I found one bad speaker on L/F that took the first 4 speakers out. Then found one speaker on the R/H side that too out the R/R side. Installed a new control head to fix the rest of the system						
7050 - STRAND, MATTHEW			\$222.50			

(4.45)

Labor Comments: trouble shoot the reason the right rear speakers were not working because one speaker was bad, and had to replace, trouble shoot left rear speakers not working, because of a bad control head

Miscellaneous Labor		\$0			
Other				\$0	
40:Engine	\$40.12	\$116.50	\$0.00		\$156.62
23515251 sensor (1.000)	\$40.12				
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$116.50			
(2.33)					

Labor Comments: needs new coolant temp sensor, ordered, replaced engine coolant sensor because, it was not working properly, test drove and verified fix

Miscellaneous Labor		\$0			
Other				\$0	
72:Body Misc	\$0	\$24.00	\$0.00		\$24.00
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$24.00			
(0.48)					

Labor Comments: rear latches on right rear door needed to be lubed, also re riveted the strikers for those latches

Miscellaneous Labor		\$0			
Other				\$0	
75:Windows/windshields	\$33.72	\$29.00	\$0.00		\$62.72
Pillsbury: W/S Washer Pump	\$33.72				
MCI: 03-34-1039 (1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$29.00			
(0.58)					

Labor Comments: noticed the washer pump was leaking washer fluid, replaced

Miscellaneous Labor		\$0			
Other				\$0	
77:Mirrors	\$0	\$50.00	\$0.00		\$50.00
Miscellaneous Parts	\$0				
157 - BROIN, DOUGLAS		\$50.00			
Miscellaneous Labor		\$0			
Other				\$0	

Work Comments: R/F mirror arm is loose.

Labor Comments: Tightened the mirror arm assy.

\$0 \$607.24 \$910.50 \$0 \$0 \$1,517.74

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 743,873.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
201824	05/04/2015	05/05/2015	Closed	0.00	

Description: tables

Detail	Discounts	Parts	Labor	Tires	Other	Total
70:Body Sheet Metal		\$0	\$177.50		\$0.00	\$177.50
Miscellaneous Parts		\$0				
9037 - WEED, TERRY (2.17)			\$108.50			
82 - BLANCO, VICTOR (1.38)			\$69.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$177.50	\$0	\$0	<u>\$177.50</u>

Work Comments: waps out seats and remove tables

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 743,891.0



Recall: Location: PBG Department: PBG5-Charter  
 Campaign # Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
201871	05/06/2015	05/14/2015	Closed	0.00	

Description: Tag tie rod

Detail	Discounts	Parts	Labor	Tires	Other	Total
11:Axles (front)		\$39.90	\$212.50		\$0.00	\$252.40

Work Comments: 11: Axles (front) -- Left front Leaking wheel seal

Pillsbury: Gasket Hub Cap

\$1.94

Front Wheel MCI: 330-3060

(1.000)

Pillsbury: Oil Gear Synthetic:

\$2.99

Oil Gear 75W-90 BULK in

quarts (1.000)

Pillsbury: Seal Frt. MCI EL3:

\$34.97

380048A (1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (4.25)

\$212.50

Labor Comments: 11: Axles (front) -- Left front Leaking wheel seal --- Removed the brake chamber, caliper, hub, bearings and the wheel seal. Cleaned everything up. Replaced the wheel seal. reassembled everything. Bent over the lock tabs. adjusted the brakes back up again. torqued the lug nuts.

Miscellaneous Labor

\$0

Other

\$0

29:Non-Driven Axles (Tags)

\$1,370.22

\$1,470.50

\$0.00

\$2,840.72

Work Comments: 29 -- Tag axle tie rod ends bad

T02-1019 X tube &amp; arms

\$1,254.57

(1.000)

ECBP109 super crimp

\$8.85

terminal (1.000)

ECBPP74 bulk top post

\$27.00

washer (100.000)

Pillsbury: Gasket Hub Cap

\$3.88

Front Wheel MCI: 330-3060

(2.000)

Pillsbury: Seal Frt. MCI EL3:

\$69.94

380048A (2.000)

Pillsbury: Oil Gear Synthetic:

\$5.98

Oil Gear 75W-90 BULK in

quarts (2.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK

\$1,470.50

Labor Comments: 29 -- Tag axle tie rod ends bad. --- Tie rod not available. Had to install a kit with new steering arms. Removed both tires, chambers, calipers, axle nuts, hubs, King pins and spindles. Cleaned everything up. Got hte spindles up on a anvil and hammered the armes loose. Replaced the wheel seal. Reassembled everything. Bent over the lock tabs. adjusted the brakes back up again. torqued the lug nuts. Installed the new tie rod and armes. Adjusted the toe on the axle to 1/16 of an inch on the forward side.

Miscellaneous Labor

\$0

Other

\$0

41:A/C &amp; Heating

\$200.00

\$118.50

\$0.00

\$318.50

used hvac fan control box from

\$200.00

abc (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$118.50

(2.37)

Labor Comments: rewired drivers hvac fan control box

Miscellaneous Labor

\$0

Other

\$0

DO:DOT Inspection

\$2.00

\$161.50

\$0.00

\$163.50

Work Comments: DO:DOT Inspection

DOT sticker (1.000)

\$2.00

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (3.23)

\$161.50

Labor Comments: DO:DOT Inspection -- Performed the DOT inspection as per the attached sheet.  
\$0

Miscellaneous Labor  
Other

\$0

\$0 \$1,612.12 \$1,963.00 \$0 \$0 \$3,575.12

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 744,590.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202111	05/26/2015	06/05/2015	Closed	0.00	

Description: PMI E-Window latch..50DN

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$743.00	\$275.00		\$0.00	\$1,018.00

Work Comments: 50DN is leaking bad from the case.

Pillsbury: Alternator 50DN \$743.00  
24Volt 270a Delco Belt Drive:  
10459123 (1.000)

Part Warranty: Schelen: One year from installation

Expired: No

Miscellaneous Parts \$0  
7050 - STRAND, MATTHEW \$114.00  
(2.28)

Labor Comments: replaced the 50 dn alternator

157 - BROIN, DOUGLAS \$161.00

Labor Comments: Removed and replaced 50DN

Miscellaneous Labor \$0  
Other \$0

40:Engine \$0 \$18.50 \$0.00 \$18.50

Miscellaneous Parts \$0  
157 - BROIN, DOUGLAS \$18.50

Labor Comments: Washed engine.

Miscellaneous Labor \$0  
Other \$0

49:Air System \$92.17 \$162.50 \$0.00 \$254.67

Work Comments: Door is leaking air

03-10-1026 valve-quick release (1.000) \$40.53

04-28-1003 valve-park brake (1.000) \$51.64

Miscellaneous Parts \$0  
157 - BROIN, DOUGLAS \$162.50

Labor Comments: Ordered parts for park brake and door.

Miscellaneous Labor \$0  
Other \$0

75:Windows/windshields \$34.29 \$73.50 \$0.00 \$107.79

Pillsbury: Latch Rotary: \$34.29  
03-27-1074 (1.000)

Miscellaneous Parts \$0  
157 - BROIN, DOUGLAS \$73.50

Labor Comments: Tested all E-windows and found one latch not working and one sticking. Lubbed one latch and replaced the other.

Miscellaneous Labor \$0  
Other \$0

AF:Air Filter Replacement \$32.51 \$29.00 \$0.00 \$61.51

Pillsbury: Filter Air EL3: 6774 \$32.51  
(1.000)

Miscellaneous Parts \$0  
7050 - STRAND, MATTHEW \$29.00  
(0.58)

Labor Comments: replaced the air filter

Miscellaneous Labor \$0

5/7/2019

## Work Order Detail

Other					\$0	
PMI: Preventative Maintenance Inspection	\$1.61	\$133.00		\$0.00		\$134.61
Pillsbury: Light License Plate:	\$1.61					
15208 (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$96.50				
(1.93)						
Labor Comments: did a pmi on it						
157 - BROIN, DOUGLAS		\$36.50				
Labor Comments: Did PMI						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$903.58	\$691.50	\$0	\$0	<u>\$1,595.08</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 744,966.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202235	06/05/2015	06/08/2015	Closed	0.00	

Description: air leak at door latch

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78: Doors Entrance / Exit		\$0	\$150.00		\$0.00	\$150.00
Work Comments: Air leak from door side latch.						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$150.00			
Labor Comments: Installed door latch quick release from part ordered on anothe wo.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$150.00	\$0	\$0	<u>\$150.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 744,966.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202257	06/08/2015	06/22/2015	Closed	0.00	

Description: park brake valve leaking

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49: Air System		\$70.00	\$91.50		\$0.00	\$161.50
Work Comments: air leak from park brake knob						
PP-1 Park brake Valve (1.000)		\$70.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$70.00			
(1.40)						
Labor Comments: replaced park brake valve, parts are on previous work order						
157 - BROIN, DOUGLAS			\$21.50			
Labor Comments: removed and replaced park brake valve assy.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$70.00	\$91.50	\$0	\$0	<u>\$161.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 745,483.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
-------------	------------------	-------------------	---------------	-----------------	-----------------

5/7/2019

## Work Order Detail

202299      06/12/2015      06/22/2015      Closed      0.00

Description: engine belts

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$38.36	\$48.50		\$0.00	\$86.86
Maintenance Requested: 8935 - 06/12/2015 - Serpentine belt needs to be replace.						
Requestor Notes:						
Technician Response: 40 -- Write-up Serpentine belt needs replacement.						
Maint Req Status: Completed						
Pillsbury: Belt Alternator MCI		\$38.36				
Motor Coach: 8L-27-132						
(1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.97)			\$48.50			
Labor Comments: 40 -- Write-up Serpentine belt needs replacement. -- Removed and replaced the serpentine belt.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$38.36	\$48.50	\$0	\$0	\$86.86

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 745,483.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202322	06/15/2015	07/01/2015	Closed	0.00	

Description: tires

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$1,638.00	\$280.00		\$0.00	\$1,918.00
Pillsbury: Tire, Steer,Toyo		\$1,638.00				
M144: 315/80R22.5 (4.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$134.00			
(2.68)						
Labor Comments: replaced drive tires						
157 - BROIN, DOUGLAS			\$146.00			
Labor Comments: Installed 4 new drive tires. test drove						
Miscellaneous Labor			\$0			
Other					\$0	
Belt:Belt Replacement		\$0	\$20.00		\$0.00	\$20.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$15.00			
(0.30)						
Labor Comments: belt had already been repalced, thanks pat						
157 - BROIN, DOUGLAS			\$5.00			
Labor Comments: brought bus in to replace belt and its already been replaced.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$1,638.00	\$300.00	\$0	\$0	\$1,938.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 747,044.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202600	07/09/2015	07/15/2015	Closed	0.00	

Description: creep for trip

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38:Audio / Video Surveillance System		\$0	\$23.50		\$0.00	\$23.50
Work Comments: one video monitor not working						

Miscellaneous Parts	\$0				
157 - BROIN, DOUGLAS		\$23.50			
Labor Comments: repaired bad video connection					
Miscellaneous Labor		\$0			
Other			\$0		
CR:Creep	\$9.60	\$186.00	\$0.00		\$195.60
Pillsbury: Oil Bulk in Quarts:	\$9.60				
Oil 15W-40 Bulk (4.000)					
Miscellaneous Parts	\$0				
157 - BROIN, DOUGLAS		\$69.50			
Labor Comments: creep for trip					
7050 - STRAND, MATTHEW (2.33)		\$116.50			
Labor Comments: looked bus over before its outta town trip					
Miscellaneous Labor		\$0			
Other			\$0		
	\$0	\$9.60	\$209.50	\$0	\$0
					<u>\$219.10</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 747,898.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202691	07/17/2015	07/21/2015	Closed	0.00	

Description: Chrome covers

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$30.24	\$0		\$0.00	\$30.24
Pillsbury: Hub Cap, Stainless		\$30.24				
Steel: MW1273 (3.000)						
Part Comments: caser installed						
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$30.24	\$0	\$0	\$0	<u>\$30.24</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 749,581.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202730	07/21/2015	07/29/2015	Closed	0.00	

Description: bag bay latch, monitor, cup holders

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$155.00		\$0.00	\$155.00
Maintenance Requested: 8959 - 07/20/2015 - Major problems with bay doors						
Requestor Notes: Both bay door one on each side of the bus is having issues						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.42)			\$71.00			
Labor Comments: repaired both front bag bay latches, replaced 5 cup holders and reattached r/h center video monitor.						
157 - BROIN, DOUGLAS			\$84.00			
Labor Comments: repaired both front bag bay latches, replaced 5 cup holders and reattached r/h center video monitor.						
Miscellaneous Labor			\$0			
Other					\$0	

\$0      \$0      \$155.00      \$0      \$0      \$155.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 750,480.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202816	07/28/2015	08/03/2015	Closed	0.00	

Description: L-O-F tierod end

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$90.79	\$191.00		\$0.00	\$281.79
Work Comments: front steering tierod end is loose.						
Pillsbury: Draglink End LH		\$90.79				
EL3 MCI: 11-04-1006 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.05)			\$102.50			
Labor Comments: fixed tie rod on the steering shaft drag link						
157 - BROIN, DOUGLAS			\$88.50			
Labor Comments: Removed and replaced front tie rod end						
Miscellaneous Labor			\$0			
Other					\$0	
38:Audio / Video Surveillance System		\$0	\$38.50		\$0.00	\$38.50
Miscellaneous Parts		\$0				
0142 - GALLINGER, CHAD (0.77)			\$38.50			
Labor Comments: replaced inline fuse in DVD player						
Miscellaneous Labor			\$0			
Other					\$0	
CFR:Coolant Filter Replacement		\$31.38	\$0		\$0.00	\$31.38
Pillsbury: Filter Coolant w/Full Charge MCI D4500 w/ Detroit 60 Series Engine: 4088 (1.000)		\$31.38				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Labor Comments: replaced coolant filter while doing the service						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$123.01	\$215.50		\$0.00	\$338.51
Pillsbury: Oil Bulk in Quarts: Oil 15W-40 Bulk (40.000)		\$96.00				
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)		\$9.25				
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)		\$14.80				
Pillsbury: Fluid Windshield Washer Fluid BULK/Gal After Dilution: W/W Fluid BULK (2.000)		\$2.96				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.19)			\$159.50			
Labor Comments: did a complete service						
157 - BROIN, DOUGLAS			\$56.00			
Labor Comments: helped on engine service.						
Miscellaneous Labor			\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			

(0.00)

Labor Comments: did a lof

Miscellaneous Labor

\$0

Other

\$0

\$0.00	\$245.18	\$445.00	\$0	\$0	<u>\$690.18</u>
--------	----------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 750,480.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202888	08/04/2015	08/13/2015	Closed	0.00	

Description: Coolant temp all over the place

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00

Repair, Inv. # 2784501

36:Lighting		\$6.17	\$71.00		\$0.00	\$77.17
-------------	--	--------	---------	--	--------	---------

Pillsbury: Kit Bracket

\$3.98

Hardware Mount: 15414

Pillsbury: Light Bulb 12 Volt

\$2.19

Mini Fog/Driving: BP1255/H3

(1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$71.00

(1.42)

Labor Comments: replace both of the license plate brackets, and one fog light was out

Miscellaneous Labor

\$0

Other

\$0

38:Audio / Video Surveillance System		\$0	\$3.50		\$0.00	\$3.50
--------------------------------------	--	-----	--------	--	--------	--------

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$3.50

(0.07)

Labor Comments: bad connection on one of the monitors

Miscellaneous Labor

\$0

Other

\$0

40:Engine		\$370.49	\$810.00		\$0.00	\$1,180.49
-----------	--	----------	----------	--	--------	------------

Work Comments: 40 -- Coolant temp all over the place

23522323 harness (1.000)

\$312.23

23532436 thermostat (2.000)

\$58.26

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$183.00

(3.66)

Labor Comments: test drove and found the coolant would jump all over the place, one second its 190 nexts its 150 and then its 200 then back down to 180, all over the place, replace the sensor and test drove, still bounces all over the place. the sensor was also just replace in april, i still replaced it anyway maybe a short in the wiring or bad 5 volt supply, might need a new harness.

74 - PHIPPS, KEVIN (6.16)

\$308.00

Labor Comments: I think sender is good; I agree engine harness needs replacing; I cleaned oil from ECM/eng connector; temp does move alot but within a range and not randomly. I suggested to Tom that a harness is a good bet and that we should change out t-stats and see how engine acts after that. Small possible that something is going on inside engine--exhaust getting into coolant under load? Injecto harness ordered--will install when recieved.

0081 - WOLF, PATRICK (2.08)

\$104.00

Labor Comments: 40 -- Coolant temp all over the place ---- Assist Kevin in troouble shooting coolant temp. issue.

157 - BROIN, DOUGLAS

\$215.00

Labor Comments: Removed and replaced engine harness per Tom D.

Miscellaneous Labor

\$0

Other

\$0

41:A/C & Heating		\$1,047.13	\$111.00		\$0.00	\$1,158.13
------------------	--	------------	----------	--	--------	------------

Work Comments: A/C clutch plate cracked.

Pillsbury: Clutch Assy 24vdc: \$989.25  
 16-02-1040 (1.000)  
 Pillsbury: Bearing: \$57.88  
 3206A2RS1VP (1.000)  
 Miscellaneous Parts \$0  
 74 - PHIPPS, KEVIN (2.22) \$111.00

Labor Comments: Installed new asm--box was open and the flex plate doesn't impress me because of the amount of adjustment needed to make good gap--45 ths (30-60). Installed new bearing in idler pulley. New connector and tied up.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$1,423.79 \$995.50 \$0 \$35.00 \$2,454.29

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 751,512.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
202981	08/13/2015	08/17/2015	Closed	0.00	

Description: Windshield

Detail	Discounts	Parts	Labor	Tires	Other	Total
75:Windows/windshields		\$302.50	\$306.00		\$0.00	\$608.50

Maintenance Requested: 8984 - 08/07/2015 - Drivers windshield cracked in stock..

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Glass Windshield \$302.50  
 Front LH w/Mask MCI EL3:  
 03-27-1325 (1.000)  
 Miscellaneous Parts \$0  
 0081 - WOLF, PATRICK (6.12) \$306.00

Labor Comments: 75 Drivers side windshield cracked. ---- Removed and replaced the windshield.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$302.50 \$306.00 \$0 \$0 \$608.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 751,512.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
203016	08/17/2015	08/28/2015	Closed	0.00	

Description: needs injector wiring harness

Detail	Discounts	Parts	Labor	Tires	Other	Total
40:Engine		\$0	\$383.50		\$0.00	\$383.50

Work Comments: When you wiggle the wiring harness for the injectors it will cut some injectors out.

Injector Harness (1.000) \$0.00

Part Comments: billed on work order 202888

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$216.00  
 (4.32)

Labor Comments: installed injector harness, took on test drive

157 - BROIN, DOUGLAS \$167.50

Labor Comments: Installed new injector wiring harness.

Miscellaneous Labor \$0  
 Other \$0



\$0 \$0 \$383.50 \$0 \$0 \$383.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 751,512.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203065	08/21/2015	08/28/2015	Closed	0.00	

Description: Repair from Incident 8-17-15

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$609.00	\$437.50		\$0.00	\$1,046.50
03-21-1054 bumper assy- front rh (1.000)		\$609.00				
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (8.75)			\$437.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$609.00	\$437.50	\$0	\$0	<u>\$1,046.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 725,917.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203424	09/18/2015	09/25/2015	Closed	0.00	

Description: tag brakes; list

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$703.58	\$519.00		\$0.00	\$1,222.58
Work Comments: "cracks" in inner rotor						
Pillsbury: Wheel Guard 10		\$12.94				
Hole .047" Teflon MCI D4500:						
15K-1-11 (2.000)						
Pillsbury: Pads brake EL3:		\$113.06				
04-01-1019 (1.000)						
Part Comments: Set off shelf						
Pillsbury: Seal Frt. MCI EL3:		\$64.52				
380048A (2.000)						
Pillsbury: Rotor EL3:		\$509.58				
15-02-1010 (2.000)						
Pillsbury: Gasket Hub Cap		\$3.48				
Front Wheel MCI: 330-3060						
(2.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (10.38)			\$519.00			
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$20.86	\$21.50		\$0.00	\$42.36
Pillsbury: Light Non LED		\$20.86				
Amber Side Marker/Turn MCI						
EL3: 07-07-1003 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.43)			\$21.50			
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$189.19	\$0		\$0.00	\$189.19
03-32-1030 grab rail assy- foamed (1.000)		\$189.19				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	

\$0.00	\$913.63	\$540.50	\$0	\$0	<u>\$1,454.13</u>
--------	----------	----------	-----	-----	-------------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 754,151.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203456	09/22/2015	09/25/2015	Closed	0.00	

Description: coolant leak

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
43:Cooling		\$0	\$77.50		\$0.00	\$77.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.55)			\$77.50			
Labor Comments: Tighten clamps in and around water pump. Pressure wash engine compartment.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$77.50	\$0	\$0	<u>\$77.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 754,151.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203469	09/22/2015	09/25/2015	Closed	0.00	

Description: Replaced Radio

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories		\$394.00	\$95.00		\$0.00	\$489.00
Pillsbury: Radio CD-2000,AM/ FM/CD,MOD ADV: 710338 (1.000)		\$394.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.90)			\$95.00			
Labor Comments: Radio was junk, replaced it, but had to figure out the rats nest of wiring to get it to work right						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$394.00	\$95.00	\$0	\$0	<u>\$489.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 755,468.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203607	10/01/2015	10/15/2015	Closed	0.00	

Description: Monitors Dont Stay Up, Trans

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$70.49	\$212.00		\$0.00	\$282.49
Work Comments: 25 --- Tran. shifting hard into 1st gear. ----						
Pillsbury: Sensor		\$70.49				
Transmission Output Speed						
Allison B500: 29544139 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.09)			\$54.50			
Labor Comments: installed new speed sensor on the out put, did not get to dig in it, pat fixed it						

0081 - WOLF, PATRICK (3.15)

\$157.50

Labor Comments: 25 --- Tran. shifting hard into 1st gear. ---- Checked the ATF, Looked ok , was full.

Put up on lifts. Checked the engine/trans. mounts, u-joints and slip joint. Talked to Ed

@ Inerstate. He told me to Reset the unadaptive shifts. If the hard shifting into 1st comes back right away the problem is c5 has excessive clearance or solenoid sticky.

Hooked the computer up with Allison Doc. Reset the unadaptive shifts. The trans now shifts into 1st much smoother.

Miscellaneous Labor

\$0

Other

\$0

25:Transmission (Auto)

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 9164 - 10/07/2015 - Transmission not shifting out of gear

Requestor Notes: was downshifting very hard

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (0.00)

\$0.00

Miscellaneous Labor

\$0

Other

\$0

72:Body Misc

\$0

\$13.50

\$0.00

\$13.50

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$13.50

(0.27)

Labor Comments: trying to find away to keep the dvd moniotrs up with out having to replace them

Miscellaneous Labor

\$0

Other

\$0

\$0

\$70.49

\$225.50

\$0

\$0

\$295.99

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 756,772.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

203824

10/19/2015

10/22/2015

Closed

0.00

Description: Lav. door locked

DetailDiscountsPartsLaborTiresOtherTotal

79:Lavatory

\$0

\$6.50

\$0.00

\$6.50

Work Comments: 79 -- Lav. door locked.

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (0.13)

\$6.50

Labor Comments: 79 -- Lav. door locked. ---- Broke into the lav. checked the lock mech. all seemed fine. Don't no how it could have gotten locked.

Miscellaneous Labor

\$0

Other

\$0

\$0

\$0

\$6.50

\$0

\$0

\$6.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 757,861.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

203970

11/02/2015

11/11/2015

Closed

0.00

Description: FF,Diff,PMI, AD

DetailDiscountsPartsLaborTiresOtherTotal

20:Steering

\$285.57

\$202.50

\$0.00

\$488.07

Work Comments: drag link end at wheel end loose.

01-02-1006 drag link (1.000)

\$285.57

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (4.05)

\$202.50

Miscellaneous Labor

\$0

Other			\$0	
22:Tires	\$0	\$60.00	\$0.00	\$60.00
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (1.20)		\$60.00		
Labor Comments: Mount and balance used tire for L tag; 100 psi, torqued to 475 ft lbs.				
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$6.29	\$260.00	\$0.00	\$266.29
Pillsbury: Disc Protection	\$6.29			
TH230/300 wabasto:				
WE88441A (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (5.20)		\$260.00		
Labor Comments: Take aux heater out, take apart and clean, check adjustments.				
Miscellaneous Labor		\$0		
Other			\$0	
AD:Air Drier Service	\$113.20	\$47.50	\$0.00	\$160.70
Pillsbury: Purge Valve Repair	\$66.72			
Kit, AD-IP: K022105 (1.000)				
Pillsbury: AD-IP Air Dryer	\$46.48			
Desiccant Cartridge Bendix:				
109493BXR (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.95)		\$47.50		
Labor Comments: O/H air dryer				
Miscellaneous Labor		\$0		
Other			\$0	
DF:Differential Service	\$124.80	\$27.50	\$0.00	\$152.30
Pillsbury: Oil Gear Synthetic:	\$124.80			
Oil Gear 75W-90 BULK in				
quarts (40.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.55)		\$27.50		
Labor Comments: Flushed PS system; took canister plug from 522 and made it work for this bus				
Miscellaneous Labor		\$0		
Other			\$0	
FF:Fuel Filter	\$8.14	\$31.00	\$0.00	\$39.14
Pillsbury: Filter Fuel: 3118	\$4.06			
(1.000)				
Pillsbury: Filter, Fuel, MCI:	\$4.08			
3120 (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.62)		\$31.00		
Labor Comments: Change out fuel filters				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$4.72	\$271.50	\$0.00	\$276.22
Pillsbury: Filter Media: 4WZ68	\$4.72			
(8.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (5.43)		\$271.50		
Miscellaneous Labor		\$0		
Other			\$0	
PS:Power Steering Flush	\$58.52	\$103.50	\$0.00	\$162.02
Pillsbury: Filter Hydraulic:	\$10.28			
7557 (1.000)				
Pillsbury: Fluid ATF (Synthetic)	\$48.24			
Bulk Quart: ATF Synthetic Bulk				
(8.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (2.07)		\$103.50		
Miscellaneous Labor		\$0		
Other			\$0	
RT:Road Test	\$0	\$20.00	\$0.00	\$20.00
Miscellaneous Parts	\$0			

5/7/2019

## Work Order Detail

74 - PHIPPS, KEVIN (0.40)  
Miscellaneous Labor  
Other

\$20.00  
\$0

\$0

\$0.00 \$601.24 \$1,023.50 \$0 \$0 \$1,624.74

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 758,873.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204137	11/16/2015	11/19/2015	Closed	0.00	

Description: entrance door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$361.50		\$0.00	\$361.50

Work Comments: 78 -- Lock not working on the front door. The lower window was removed to get inside the bus.

Miscellaneous Parts \$0  
0081 - WOLF, PATRICK (7.23) \$361.50

Labor Comments: 78 -- Lock not working on the front door. The lower window was removed to get inside the bus. ---- Removed the inner door panel. Pulled the lock apart. Repaired the lock assy. and reassembled everthing. Cleaned up the door fram and the glass. Sealed the glass back into the door

Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$174.48	\$465.00		\$0.00	\$639.48

Maintenance Requested: 9257 - 11/05/2015 - Ent door hinge bearings/pins bad

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Bearing Mount \$122.46  
hinge: 03-32-1008 (2.000)  
Pillsbury: pin-pivot, hinge: \$52.02  
03-32-1054 (2.000)  
Miscellaneous Parts \$0  
0081 - WOLF, PATRICK (9.30) \$465.00

Labor Comments: 78 -- Entrance door bearings and pins bad. ---- Removed the door, bumperet and the inner panel covering the beaings. Removed and replaced the bearings and pins for the door. Adjusted thedoor and put everything back together.

Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$174.48 \$826.50 \$0 \$0 \$1,000.98

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 758,873.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204241	11/20/2015	11/23/2015	Closed	0.00	

Description: Radio/DVD/PA problems

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
See Comments		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 9301 - 11/23/2015 - See Comments

Requestor Notes: 1.) Chip in Windshield - lower right-hand side

2.) Entry door - lower bumper needs to be replaced

3.) Bathroom door locks on it's own - people get trapped inside

4.) Temperature gauge goes from 150-200 and anything in-between

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0

5/7/2019

## Work Order Detail

7050 - STRAND, MATTHEW  
(0.00)

\$0.00

Labor Comments: ordered new bathroom locks

Miscellaneous Labor

\$0

Other

\$0

52:Electrical Accessories

\$0

\$97.50

\$0.00

\$97.50

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW  
(1.95)

\$97.50

Labor Comments: could not get the bus to make the same problem. Found the sub was bouncing  
around, so I tightened it down

Miscellaneous Labor

\$0

Other

\$0

\$0

\$0

\$97.50

\$0

\$0

\$97.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 759,693.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

204285

11/24/2015

11/27/2015

Closed

0.00

Description: Entrance Door Trim &amp; LR Bumper Corner

DetailDiscountsPartsLaborTiresOtherTotal

70:Body Sheet Metal

\$0.99

\$238.50

\$0.00

\$239.49

Pillsbury: Reflector Red

\$0.99

adhesive 3": 98175R (1.000)

Miscellaneous Parts

\$0

0423 - KRANZ, DANIEL (0.32)

\$16.00

9037 - WEED, TERRY (4.45)

\$222.50

Miscellaneous Labor

\$0

Other

\$0

\$0

\$0.99

\$238.50

\$0

\$0

\$239.49

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 760,375.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

204368

12/01/2015

12/14/2015

Closed

0.00

Description: Lavatory Handle and Radio

DetailDiscountsPartsLaborTiresOtherTotal

50:Accessories

\$0

\$103.50

\$0.00

\$103.50

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW  
(2.07)

\$103.50

Labor Comments: had to trouble shoot why the radio was not working. Found a lot of corrosion on the  
supply line to the radio connector, just hardwired them together

Miscellaneous Labor

\$0

Other

\$0

78:Doors Entrance / Exit

\$0

\$25.00

\$0.00

\$25.00

Maintenance Requested: 9319 - 12/02/2015 - Driver side 1st bay door

Requestor Notes: Driver Side 1st bay door had to take off skrey eye because it would not unlock - no wire  
to pull

Bolt on driver seat

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$25.00

(0.50)	Labor Comments: went thru all the doors , all work good. Someone must have already fixed it					
Miscellaneous Labor			\$0			
Other					\$0	
79:Lavatory	\$0	\$26.50		\$0.00		\$26.50
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$26.50				
(0.53)	Labor Comments: got the wrong parts and can not make them work, have to find out what went wrong, trying to get the right parts					
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$155.00	\$0	\$0	<u>\$155.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 760,731.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204433	12/07/2015	12/14/2015	Closed	0.00	

Description: LOF, Wheel Seal

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$0	\$37.50		\$0.00	\$37.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$37.50			
(0.75)	Labor Comments: Left rear drive Chamber sticking, took out and cleaned the pin up					
Miscellaneous Labor			\$0			
Other					\$0	
27:Wheels, Rims, Hubs & Mounts		\$34.00	\$174.00		\$0.00	\$208.00
Pillsbury: Gasket Hub Cap		\$1.74				
Front Wheel MCI: 330-3060						
(1.000)						
Pillsbury: Seal Frt. MCI EL3:		\$32.26				
380048A (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$174.00			
(3.48)	Labor Comments: Front right Wheel seal leak, replaced					
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$8.99	\$33.50		\$0.00	\$42.49
Pillsbury: Light Bulb Pass.		\$7.00				
Sevice Module 28V 10W:						
03-08-1162 (7.000)						
Pillsbury: Light License Plate:		\$1.99				
15208 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$33.50			
(0.67)	Labor Comments: Fixed seven burnt out reading lights Fixed License plate light that was burnt out Replaced 2 cup holders					
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$110.45	\$170.00		\$0.00	\$280.45
Pillsbury: Oil Bulk in Quarts:		\$86.40				
Oil 15W-40 Bulk (40.000)						
Pillsbury: Oil Analysis Kit:		\$9.25				
Sample Kit (1.000)						
Pillsbury: Filter Oil MCI D4500		\$14.80				
w/Detroit Diesel 60 Series:						

5/7/2019

## Work Order Detail

1971MP (2.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$170.00				
(3.40)						
Labor Comments: did a service						
Miscellaneous Labor		\$0				
Other				\$0		
SC:Steam Clean	\$0	\$29.00		\$0.00		\$29.00
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$29.00				
(0.58)						
Labor Comments: cleaned engine						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$153.44	\$444.00	\$0	\$0	<u>\$597.44</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 761,100.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204458	12/09/2015	12/22/2015	Closed	0.00	

Description: lav/body

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
39:Other Electrical		\$0	\$216.50		\$0.00	\$216.50
Work Comments: 39 -- Relay box in the bag bay keeps clicking with the key on						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.33)			\$216.50			
Labor Comments: 39 -- Relay box in the bag bay keeps clicking with the key on ---- Checked the parts room for a new relay box. None in there. Went down to the body shop area and pulled a relay box out of 5522. Installed the relay box in 526.						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$0	\$80.00		\$0.00	\$80.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.60)			\$30.00			
Labor Comments: was going to do locks, but nooo						
7050 - STRAND, MATTHEW			\$50.00			
(1.00)						
Labor Comments: Replaced DVD monitor						
Miscellaneous Labor			\$0			
Other					\$0	
79:Lavatory		\$767.24	\$490.00		\$0.00	\$1,257.24
Work Comments: 79 -- Lav. door keeps locking by its self.						
8639 Micro switch (1.000)		\$20.00				
Pillsbury: Standard Mini lamp:		\$1.04				
356 (4.000)						
17-03-1658 kit-lavatory handle		\$746.20				
(1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (6.88)			\$344.00			
Labor Comments: 79 -- Lav. door keeps locking by its self. ----- Pulled the lock off Tried to get it to work correctly but to many parts were missing. Installed a hole new Up date (Lock-system). Got all the lights working correctly. Installed a new micro switch for the dead bolt. Filled all the holes in the fiberglass panels with plugs.						
0146 - SHIPPY, CURTIS (2.92)			\$146.00			
Labor Comments: Had to make a part for the lock on the bathroom door.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$767.24	\$786.50	\$0	\$0	<u>\$1,553.74</u>



## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 761,100.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204609	12/21/2015	12/24/2015	Closed	0.00	

Description: Radio Did not shut off

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 9369 - 12/19/2015 - Will not start in garage

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						

Labor Comments: the radio was not shutting off. I reset it. I was not the one who plugged it in. It started right up for me

Miscellaneous Labor			\$0			
Other					\$0	

\$0	\$0	\$0	\$0	\$0	\$0	\$0.00
-----	-----	-----	-----	-----	-----	--------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 761,100.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204620	12/22/2015	01/15/2016	Closed	0.00	

Description: bay door locks

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$277.50		\$0.00	\$277.50
locks for luggage bays (6.000)		\$0.00				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (5.55)			\$277.50			

Labor Comments: Install new locks in bay doors; L1 door needs new handle--ordered

Miscellaneous Labor			\$0			
Other					\$0	

\$0	\$0	\$277.50	\$0	\$0	\$277.50
-----	-----	----------	-----	-----	----------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 762,493.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204714	01/04/2016	01/05/2016	Closed	0.00	

Description: Marker Light

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Right side middle marker light not working		\$20.86	\$16.00		\$0.00	\$36.86

Maintenance Requested: 9403 - 01/04/2016 - Right side middle marker light not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Non LED	\$20.86					
Amber Side Marker/Turn MCI						
EL3: 07-07-1003 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$16.00			

(0.32)

Labor Comments: replaced marker light

Miscellaneous Labor

\$0

Other

\$0

\$0	\$20.86	\$16.00	\$0	\$0	<u>\$36.86</u>
-----	---------	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 762,495.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204745	01/06/2016	01/07/2016	Closed	0.00	

Description: PMI,TF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
PMI:Preventative Maintenance Inspection		\$10.84	\$151.50		\$0.00	\$162.34

Work Comments: PMI -- Preventative maint.

Pillsbury: Fluid Windshield \$1.48

Washer Fluid BULK/Gal After

Dilution: W/W Fluid BULK

(1.000)

Pillsbury: Fluid Coolant Bulk \$9.36

50/50 After Dilution: A/F 50/50

Green BULK (2.000)

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (3.03) \$151.50

Labor Comments: PMI -- Preventative maint. ---- Greased and performed the safty check as per the attached sheet. Added 2 pints of alchohal to the wet tank.

Miscellaneous Labor \$0

Other \$0

TF:Transmission Flush	\$206.48	\$143.50	\$0.00	\$349.98
-----------------------	----------	----------	--------	----------

Work Comments: TF -- Transmision flush

Pillsbury: Filter Kit \$31.61

Transmission Allison (Short

Filter): 7741XE (1.000)

Pillsbury: Fluid ATF (Synthetic) \$174.87

Bulk Quart: ATF Synthetic Bulk

(29.000)

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (2.87) \$143.50

Labor Comments: TF -- Transmission flush ----- Drained the trans. removed and replaced both filters and all O-rings cleaned everything up installed new gaskets. filled with new ATF and topped off the system.

Miscellaneous Labor \$0

Other \$0

\$0.00	\$217.32	\$295.00	\$0	\$0	<u>\$512.32</u>
--------	----------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 763,189.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204841	01/13/2016	01/19/2016	Closed	0.00	

Description: list

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$0	\$10.00		\$0.00	\$10.00

Miscellaneous Parts \$0

74 - PHIPPS, KEVIN (0.20) \$10.00

Labor Comments: Check fluids and lights, fans.--OK

Miscellaneous Labor \$0

5/7/2019

Work Order Detail

Other				\$0	
72:Body Misc	\$0	\$10.00	\$0.00		\$10.00
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (0.20)		\$10.00			
Labor Comments: Show Curt what to make for a close out at floor hatch					
Miscellaneous Labor		\$0			
Other			\$0		
72:Body Misc	\$0	\$0	\$0.00		\$0.00
Maintenance Requested: 9353 - 12/14/2015 - Water leaks in very badly					
Requestor Notes:					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$0.00			
(0.00)					
Labor Comments: body shop took care of it					
Miscellaneous Labor		\$0			
Other			\$0		
75:Windows/windshields	\$0	\$48.50	\$0.00		\$48.50
03-27-1079 dbl glazed	\$0.00				
window (1.000)					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (0.97)		\$48.50			
Labor Comments: Change out L2 window					
Miscellaneous Labor		\$0			
Other			\$0		
79:Lavatory	\$0	\$191.00	\$0.00		\$191.00
Maintenance Requested: 9427 - 01/11/2016 - Bathroom door lock is buster					
Requestor Notes: Passenger was lock in restroom.					
Metal plate on first step is very loose					
Bus wasn't slowing when foot is taken off gas pedal, sometimes spped increased. It was hard to sloiw bus down at times. Engine brake wouldn't kick in either.					
TV screens all hang down					
Exhaust smell is really bad.					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (0.62)		\$31.00			
Labor Comments: 79 -- Passenger was lock in restroom. ---- Looked at the restroom door. Installed a new door handle on the outside of the door. They had braken the dead bolt right off the handle.					
7050 - STRAND, MATTHEW		\$160.00			
(3.20)					
Labor Comments: fixed lavatory door fixed the first step came up with solution to the rear hatch					
Miscellaneous Labor		\$0			
Other			\$0		
	\$0	\$0	\$259.50	\$0	\$0
					<u>\$259.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 765,114.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205044	01/28/2016	01/29/2016	Closed	0.00	

Description: Fix Rub Rail on right side asap

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$55.00		\$0.00	\$55.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (1.10)			\$55.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$55.00	\$0	\$0	<u>\$55.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 764,114.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205083	02/01/2016	02/03/2016	Closed	0.00	

Description: DVD Monitor, Hub Service

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
HUB:Hub Service		\$24.96	\$59.00		\$0.00	\$83.96
Pillsbury: Oil Gear Synthetic:		\$24.96				
Oil Gear 75W-90 BULK in quarts (8.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.18)			\$59.00			
Labor Comments: did a hub service						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$0	\$39.00		\$0.00	\$39.00
Maintenance Requested: 9526 - 02/01/2016 - Monitor next to entry door doesn't work						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.78)			\$39.00			
Labor Comments: rewired dvd monitor and moved base over						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$24.96	\$98.00	\$0	\$0	<u>\$122.96</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 766,360.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205146	02/05/2016	02/08/2016	Closed	0.00	

Description: Engine hatch, Oil sample

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$7.00	\$37.50		\$0.00	\$44.50
Work Comments: 40 Get a oilsample.						
Pillsbury: Oil Analysis Kit:		\$7.00				
Sample Kit (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.75)			\$37.50			
Labor Comments: 40 Get a oilsample. ---- Resampled the oil. Registered and sent sample in.						
Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$0	\$179.00		\$0.00	\$179.00
Work Comments: 78 -- Floor hatch to engine leaking fumes into bus. ----						

5/7/2019

## Work Order Detail

Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (3.58)		\$179.00				
Labor Comments: 78 -- Floor hatch to engine leaking fumes into bus. ---- Removed the floor hatch and riveted a piece of square tubing onto it. sealed with weatherstrip and floor trim.						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$7.00	\$216.50	\$0	\$0	<u>\$223.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 768,247.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205219	02/10/2016	02/19/2016	Closed	0.00	

Description: LOF, Governor, Fan Clutch, Relay Valves

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$44.00		\$0.00	\$44.00

Maintenance Requested: 9586 - 02/12/2016 - No lights in dash buttons

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.88)			\$44.00			

Labor Comments: lights on the dash light up, maybe didnt have the headlights on

Miscellaneous Labor			\$0			
Other					\$0	
43:Cooling		\$974.83	\$131.00		\$0.00	\$1,105.83

Pillsbury: Tensioner Arm Fan

\$81.83

Drive MCI: 06-06-1081 (1.000)

98004 fan clutch (1.000)

\$893.00

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$131.00

(2.62)

Labor Comments: replaced the fan clutch

Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$18.50		\$0.00	\$18.50

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$18.50

(0.37)

Labor Comments: Checked for air leaks

Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 9598 - 02/15/2016 - Doesn't hold air will stopped

Requestor Notes: Bus doesn't hold air while stopped.

Have to rev. engine to release brake.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			

Labor Comments: did a air brake test, seems to be just fine

Miscellaneous Labor			\$0			
Other					\$0	
75:Windows/windshields		\$29.74	\$36.00		\$0.00	\$65.74

Maintenance Requested: 9576 - 02/10/2016 - crack windshield

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Striker Assy-side	\$29.74
------------------------------	---------

5/7/2019

## Work Order Detail

sash: 03-27-1137 (2.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$36.00		
(0.72)				
Labor Comments: fixed window latch				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$0	\$0	\$0.00	\$0.00
Maintenance Requested: 9581 - 02/11/2016 - Windshield crack				
Requestor Notes: Driver reported that their is a rock chip in the windsield. Also, the bottom part of the main entry door is cracked.				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$0.00		
(0.00)				
Labor Comments: crack has been filled and is not a safety issue				
Miscellaneous Labor		\$0		
Other			\$0	
LOF:Lube, Oil, Filter	\$110.75	\$32.50	\$0.00	\$143.25
Pillsbury: Filter Oil MCI D4500	\$15.10			
w/Detroit Diesel 60 Series:				
1971MP (2.000)				
Pillsbury: Oil Analysis Kit:	\$9.25			
Sample Kit (1.000)				
Pillsbury: Oil Bulk in Quarts:	\$86.40			
Oil 15W-40 Bulk (40.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$32.50		
(0.65)				
Labor Comments: did a serice				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$6.00	\$146.00	\$0.00	\$152.00
Pillsbury: Light Bulb Pass.	\$6.00			
Sevice Module 28V 10W:				
03-08-1162 (6.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$146.00		
(2.92)				
Labor Comments: did a service				
Miscellaneous Labor		\$0		
Other			\$0	
Radio/DVD/PA:Radio repair	\$636.00	\$194.00	\$0.00	\$830.00
DVD Monitors (6.000)	\$636.00			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$194.00		
(3.88)				
Labor Comments: installed 6 new dvd monitors				
Miscellaneous Labor		\$0		
Other			\$0	
SC:Steam Clean	\$0	\$4.00	\$0.00	\$4.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$4.00		
(0.08)				
Labor Comments: steam cleaned				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0.00	\$1,757.32	\$606.00	\$0
			\$0	\$0
				<u>\$2,363.32</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 769,514.0

Location: PBG

Department: PBG5-Charter

## Work Order Detail

Date:

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
33:Horn & Alarm		\$0	\$73.50		\$0.00	\$73.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.47)			\$73.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$73.50	\$0	\$0	\$73.50

License Plate:

Department: PBG5-Charter

Date:

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 9691 - 02/29/2016 - Oil temp guage doesn't work						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Labor Comments: Oil Temp Gauge does not work on dash, not a big deal, drivers dont need to know that info						
Miscellaneous Labor			\$0			
Other					\$0	
FF:Fuel Filter		\$8.40	\$36.00		\$0.00	\$44.40
Pillsbury: Filter Fuel: 3118 (1.000)		\$4.19				
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)		\$4.21				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.72)			\$36.00			
Labor Comments: did FF						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$8.40	\$36.00	\$0	\$0	\$44.40

License Plate:

Department: PBG5-Charter

Date:

Description: Maintenance Request						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$0	\$36.00		\$0.00	\$36.00
Maintenance Requested: 9751 - 03/14/2016 - Oil coming out of hub door side tandam wheels						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						

5/7/2019

## Work Order Detail

32605 Aux Cord (1.000) \$0.00  
 Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$36.00  
 (0.72)

Labor Comments: cleaned tag hubs out, they were spot on where they should be with oil level  
 Checked Fluids  
 Install Aux Cord

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$36.00 \$0 \$0 \$36.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 772,531.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205878	03/28/2016	03/29/2016	Closed	0.00	

Description: Creep For Trip To Chicago

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CR:Creep		\$5.24	\$42.50		\$0.00	\$47.74

Pillsbury: Light Bulb Pass.

\$2.00

Sevice Module 28V 10W:

03-08-1162 (2.000)

Pillsbury: Oil Bulk in Quarts:

\$3.24

Oil 15W-40 Bulk (1.500)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$42.50

(0.85)

Labor Comments: Creep for trip to chicago

Miscellaneous Labor \$0  
 Other \$0

\$0 \$5.24 \$42.50 \$0 \$0 \$47.74

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 773,512.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206019	04/07/2016	04/11/2016	Closed	0.00	

Description: PMI

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$53.00	\$96.00		\$0.00	\$149.00

Pillsbury: Fitting 37? JIC

\$53.00

1/2".I.D.x 7/8"-14 F

SwivelReusable:

24710N610OB (4.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$96.00

(1.92)

Labor Comments: Replacing both Front Brake Lines

Miscellaneous Labor \$0  
 Other \$0

31:Charging		\$27.96	\$15.00		\$0.00	\$42.96
-------------	--	---------	---------	--	--------	---------

Pillsbury: Alternator Kit Front

\$27.96

Seal Delco 50DN Belt Drive:

10514967 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$15.00

(0.30)



Labor Comments: 50 DN Front seal was leaking, replaced it					
Miscellaneous Labor		\$0			
Other				\$0	
79:Lavatory	\$41.47	\$61.50	\$0.00		\$102.97
Pillsbury: Valve Slide, lavatory:	\$41.47				
17-05-1095 (1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$61.50			
(1.23)					
Labor Comments: Bottle Stuck in the shitter vavle, had to take apart and replace valve					
Miscellaneous Labor		\$0			
Other				\$0	
Belt:Belt Replacement	\$36.05	\$25.00	\$0.00		\$61.05
Pillsbury: Belt, A/C, MCI, E-	\$36.05				
Coach: 08-27-1029 (1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$25.00			
(0.50)					
Labor Comments: Replaced A/C Belt and Fan Clutch Belt.					
Did not have a Fan Clutch Belt in stock, took one out of the bus storage, because it					
was brand new and swapped it					
Miscellaneous Labor		\$0			
Other				\$0	
PMI:Preventative Maintenance Inspection	\$0	\$124.00	\$0.00		\$124.00
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$124.00			
(2.48)					
Labor Comments: PMI					
Miscellaneous Labor		\$0			
Other				\$0	
RT:Road Test	\$0	\$43.50	\$0.00		\$43.50
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$43.50			
(0.87)					
Labor Comments: Road Test					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$158.48	\$365.00	\$0	\$0
					<u>\$523.48</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 773,722.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206084	04/14/2016	05/10/2016	Closed	0.00	

Description: A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00
Repair, Inv. # 2785088, Desc:						
Chip Repair						
21:Suspension		\$924.00	\$204.00		\$0.00	\$1,128.00
Work Comments: Broken swaybar link						
Pillsbury: Washer Sway Bar,		\$924.00				
EL3: 12-05-1034 (4.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (2.50)			\$125.00			
Labor Comments: Look for material						
7050 - STRAND, MATTHEW			\$79.00			
(1.58)						
Labor Comments: RF Sway bar link broken, made new rod and stud and reassembled it						
Miscellaneous Labor			\$0			
Other					\$0	

5/7/2019

Work Order Detail

22:Tires	\$790.00	\$237.50	\$0.00	\$1,027.50
Pillsbury: Tire, Steer,Toyo	\$790.00			
M144: 315/80R22.5 (2.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (4.75)		\$237.50		
Labor Comments: Move RF to Ltag, mount and balance 2 new steers; 110psi; 475 ft lbs.				
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$3.22	\$29.00	\$0.00	\$32.22
Pillsbury: Pigtail Light: 67050	\$1.23			
(1.000)				
Pillsbury: Light License Plate:	\$1.99			
15208 (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.58)		\$29.00		
Labor Comments: Replace broken light				
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$381.70	\$293.00	\$0.00	\$674.70
Pillsbury: Freon R134A per	\$42.45			
Lb.: R134A (15.000)				
Pillsbury: Valve Runner Drain	\$10.26			
3/4" Dia: 17M-2-71 (2.000)				
16-147-1106 Valve S/A Glycol	\$328.99			
(1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (5.86)		\$293.00		
Labor Comments: Evap and cond brushes OK at this time; flushed out cond core; topped off freon. Added 2 new drains to RS evap. Needs drivers coolant valve.--coil bad-replaced with 522 coil; circuit bad in main controller--replaced with 522 controller-sent bad in for repair; valve inop- ordered and recieved				
Miscellaneous Labor		\$0		
Other			\$0	
DO:DOT Inspection	\$0	\$103.00	\$0.00	\$103.00
Work Comments: tag light L tag tire S/B body isol-front				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (2.06)		\$103.00		
Miscellaneous Labor		\$0		
Other			\$0	
	\$0.00	\$2,098.92	\$866.50	\$0
			\$35.00	<u>\$3,000.42</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 775,316.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206251	04/27/2016	04/29/2016	Closed	0.00	

Description: Rear Hatch linkage, Cig Lighter, Roof Leak

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$4.26	\$98.50		\$0.00	\$102.76
Pillsbury: Cigarette Lighter:		\$4.26				
10230 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$98.50			
(1.97)						

Labor Comments: fixed the rear hatch linkage  
fixed the rear door right side linkage  
sealed the roof hatches  
replaced cig lighter jack

Miscellaneous Labor  
Other

\$0

\$0

\$0	\$4.26	\$98.50	\$0	\$0	<u>\$102.76</u>
-----	--------	---------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 776,209.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206426	05/10/2016	05/11/2016	Closed	0.00	

Description: Lavatoy Lock

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$10.00		\$0.00	\$10.00

Maintenance Requested: 9940 - 05/03/2016 - inside door lock for restroom is missing.

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW	\$10.00
(0.20)	

Labor Comments: replaced the lock handle, with a part from a used kit

Miscellaneous Labor	\$0
Other	\$0

\$0	\$0	\$10.00	\$0	\$0	<u>\$10.00</u>
-----	-----	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 776,609.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206516	05/17/2016	05/19/2016	Closed	0.00	

Description: LH pent window

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$3,921.41	\$123.00		\$0.00	\$4,044.41

03-27-1018 Sash Window

\$3,921.41

(1.000)

Miscellaneous Parts	\$0
74 - PHIPPS, KEVIN (2.46)	\$123.00

Labor Comments: Replace LH sash with a little help from my friends...

Miscellaneous Labor	\$0
Other	\$0

\$0	\$3,921.41	\$123.00	\$0	\$0	<u>\$4,044.41</u>
-----	------------	----------	-----	-----	-------------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 777,005.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206550	05/19/2016	05/19/2016	Closed	0.00	

Description: coolant valve

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$105.00		\$0.00	\$105.00

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (2.10)

\$105.00

Labor Comments: Install coolant valve for drivers heat control; part previously charged to bus.

Miscellaneous Labor	\$0
---------------------	-----

5/7/2019

## Work Order Detail

Other					\$0	
AF:Air Filter Replacement	\$33.16	\$15.00		\$0.00	\$48.16	
Pillsbury: Filter Air EL3: 6774 (1.000)	\$33.16					
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.30)		\$15.00				
Labor Comments: Replace air filter						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$33.16	\$120.00	\$0	\$0	<u>\$153.16</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 778,741.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206728	06/04/2016	06/08/2016	Closed	0.00	

Description: 78 -- Large black box falling down

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$352.50		\$0.00	\$352.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (7.05)			\$352.50			
Labor Comments: 78 -- Wedged the box back up again rescrewed it into place. drilled several new holes and added more screws.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$352.50	\$0	\$0	<u>\$352.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 780,360.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206849	06/16/2016	06/29/2016	Closed	0.00	

Description: write-u p,LOF, PMI

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 10047 - 05/26/2016 - Right Hand Tag Oil Leak Outside						
Requestor Notes: 2. Right hand Front, 1st and 2nd Monitors stop working.						
3. Look in Left Hand Baggage door - Brown handle holding up Air Vent						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Labor Comments: 27 -- Right tag hub leaking. ---- Checked the right tag hub. Found the oil coming out the wheep hole. Removed a little excess oil from the hub and cleaned it all up.						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$111.12	\$268.50		\$0.00	\$379.62
Work Comments: LOF -- Lube, oil & filter						
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)		\$9.75				
Pillsbury: Oil Bulk in Quarts: Oil 15W-40 Bulk (37.000)		\$79.18				
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)		\$15.10				
Pillsbury: Fluid Windshield Washer Fluid BULK/Gal After		\$2.96				

Dilution: W/W Fluid BULK (2.000)						
Pillsbury: Filter Media: 4WZ68 (7.000)			\$4.13			
Miscellaneous Parts			\$0			
0081 - WOLF, PATRICK (5.37)				\$268.50		
Labor Comments: LOF -- Lube, oil & filter ---- Performed the service and safty check as per the attatched sheet.						
Miscellaneous Labor				\$0		
Other					\$0	
PMI:Preventative Maintenance Inspection			\$0	\$0	\$0.00	\$0.00
Work Comments: PMI -- Prev. maint. & Insp. ---- Performed the service and safty check as per the attatched sheet.						
Miscellaneous Parts			\$0			
0081 - WOLF, PATRICK (0.00)				\$0.00		
Labor Comments: PMI -- Prev. maint. & Insp. ---- Performed the service and safty check as per the attatched sheet.						
Miscellaneous Labor				\$0		
Other					\$0	
			\$0	\$111.12	\$268.50	\$0
					\$0	\$379.62

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 782,557.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207021	07/01/2016	07/07/2016	Closed	0.00	

Description: WIFI

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
52:Electrical Accessories		\$9.27	\$127.50		\$0.00	\$136.77
Pillsbury: plug kit-conn: 155-2271 (1.000)		\$4.59				
Pillsbury: Receptacle: 102-8804 (1.000)		\$4.68				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (2.55)			\$127.50			
Labor Comments: Wire in WIFI						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$9.27	\$127.50	\$0	\$0	\$136.77

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 783,350.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207121	07/13/2016	07/14/2016	Closed	0.00	

Description: FF, Coolant Filter, and Etc.

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$13.69	\$18.50		\$0.00	\$32.19
Pillsbury: Belt Serpentine (EL3): 25-060295 (1.000)		\$13.69				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.37)			\$18.50			
Labor Comments: replaced small altenator belt						
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$2.75	\$18.50		\$0.00	\$21.25
Pillsbury: Pigtail Light: 67050		\$1.23				

(1.000)					
Pillsbury: Light Marker Lamp	\$1.52				
Clear: 15200C (1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$18.50			
(0.37)					
Labor Comments: replaced license plate lamp					
Miscellaneous Labor		\$0			
Other			\$0		
72:Body Misc	\$0	\$16.50	\$0.00		\$16.50
Maintenance Requested: 10228 - 07/11/2016 - Bottom trim on bay #2 drivers side is loose					
Requestor Notes:					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$16.50			
(0.33)					
Labor Comments: set the trim piece in, letting chad know so the bodyshop can fix it					
Miscellaneous Labor		\$0			
Other			\$0		
CFR:Coolant Filter Replacement	\$31.38	\$12.50	\$0.00		\$43.88
Pillsbury: Filter Coolant w/Full	\$31.38				
Charge MCI D4500 w/ Detroit					
60 Series Engine: 4088					
(1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$12.50			
(0.25)					
Labor Comments: replaced coolant filter and steam cleaned engine compartment					
Miscellaneous Labor		\$0			
Other			\$0		
FF:Fuel Filter	\$8.40	\$23.50	\$0.00		\$31.90
Pillsbury: Filter Fuel: 3118	\$4.19				
(1.000)					
Pillsbury: Filter, Fuel, MCI:	\$4.21				
3120 (1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$23.50			
(0.47)					
Labor Comments: replaced ff					
Miscellaneous Labor		\$0			
Other			\$0		
Radio/DVD/PA:Radio repair	\$0	\$28.50	\$0.00		\$28.50
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$28.50			
(0.57)					
Labor Comments: RF DVD Monitor not coming on, found bad connection					
Miscellaneous Labor		\$0			
Other			\$0		
	\$0	\$56.22	\$118.00	\$0	\$0
					<u>\$174.22</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 784,859.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207258	07/25/2016	08/01/2016	Closed	0.00	

Description: Tires, Check Engine

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$0	\$76.00		\$0.00	\$76.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$76.00			

(1.52)

Labor Comments: found a good used tire, put on the right tag, took off tire off that rim and put them away.

Then took the tire that was bad and replaced it mounted it and balanced, put back in tire room for a spare to use.

Miscellaneous Labor

\$0

Other

\$0

40:Engine

\$392.56

\$696.00

\$0.00

\$1,088.56

Maintenance Requested: 10271 - 07/25/2016 - Engine light is on

Requestor Notes: Yellow engine light with wrench light on.

Change rear right tire(Tag Axle)

Windshield chip two Right side

Right rear two DVD monitors don't work

Wiggle wire up by DVD then it will work

Technician Response:

Maint Req Status: Completed

Pillsbury: Hose Hump Charge

\$32.80

Air (Straight ) MCI D4500:

9L-3-163 (1.000)

1024612 Solenoid (1.000)

\$119.92

1024612 Solenoid (2.000)

\$239.84

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$696.00

(13.92)

Labor Comments: Jake brakes were setting a code, after extensive troubleshooting found that the

solenoids were bad, took on test drive

Miscellaneous Labor

\$0

Other

\$0

\$0

\$392.56

\$772.00

\$0

\$0

\$1,164.56

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 788,082.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

207519

08/15/2016

08/16/2016

Closed

0.00

Description: PMI, parcel rack

DetailDiscountsPartsLaborTiresOtherTotal

72:Body Misc

\$2.51

\$59.00

\$0.00

\$61.51

Maintenance Requested: 10243 - 07/14/2016 - Left Parcel Rack Loose

Requestor Notes:

Technician Response: 72

Maint Req Status: Completed

Pillsbury: Parcel Rack Door

\$2.51

Spring LH EL3 MCI:

03-08-1095 (1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (1.18)

\$59.00

Labor Comments: 72 -- Left parcel rack loose ---- Pulled things all apart. to find what was wrong.

Jacked the parcel rack back into place. drilled new holes and riveted it back into place.

Miscellaneous Labor

\$0

Other

\$0

79:Lavatory

\$33.79

\$103.50

\$0.00

\$137.29

Pillsbury: Coupling End, Lav

\$33.79

MCI: 17B-5-50 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$103.50

(2.07)

Labor Comments: replaced the lavatory coupler, also helped pat refasten the parcel rack

Miscellaneous Labor

\$0

Other

\$0

PMI:Preventative Maintenance Inspection

\$28.08

\$335.50

\$0.00

\$363.58

Work Comments: PMI -- Preventative maint and Inspec.

Pillsbury: Fluid Coolant Bulk \$28.08  
 50/50 After Dilution: A/F 50/50  
 Green BULK (8.000)  
 Miscellaneous Parts \$0  
 0081 - WOLF, PATRICK (6.71) \$335.50

Labor Comments: PMI -- Preventative maint and Inspec. ---- Performed the preventative maint. and inspected as per the attached sheet.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$64.38 \$498.00 \$0 \$0 \$562.38

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 789,119.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207710	08/29/2016	08/29/2016	Closed	0.00	

Description: Rear Hatch

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$40.00		\$0.00	\$40.00

Maintenance Requested: 10382 - 08/29/2016 - Engine door latch is broken

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$40.00  
 (0.80)

Labor Comments: lubed up the latches and linkage for the rear engine door. Got new latches ordered.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$40.00 \$0 \$0 \$40.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 789,119.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207796	09/02/2016	09/06/2016	Closed	0.00	

Description: Rear Door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$164.87	\$49.50		\$0.00	\$214.37

Pillsbury: Latch assembly, ext.  
 door EL3: 03-30-1071 (2.000)

\$113.23

Pillsbury: Latch, RH, Exterior,  
 MCI: 03-30-1070 (1.000)

\$51.64

Miscellaneous Parts  
 7050 - STRAND, MATTHEW  
 (0.99)

\$0

\$49.50

Labor Comments: messed with rear door latch, been rigged to manytimes going to get the right linkage coming.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$164.87 \$49.50 \$0 \$0 \$214.37

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 789,119.0

Location: PBG

Department: PBG5-Charter



	Recall:	Campaign #		Date:
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>
207845	09/07/2016	09/07/2016	Closed	0.00

Description: Glass Repair

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00
Repair, Inv. # 2785326						
75:Windows/windshields		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 10342 - 08/17/2016 - chip in windshield/ directly below camera						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
6103 - STRAND, JACOB			\$0.00			
Labor Comments: SuperGlass repaired						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$0	\$0	\$35.00	<u>\$35.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 791,682.0

Location: PBG

Department: PBG5-Charter

	Recall:	Campaign #		Date:
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>
208080	09/22/2016	09/22/2016	Closed	0.00

Description: Video System Install

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38:Audio / Video Surveillance System		\$5,463.30	\$654.00		\$0.00	\$6,117.30
710467 Control Module		\$417.20				
(1.000)						
710473 Radio, ECD-5500		\$347.00				
(1.000)						
512604 Harness, Radio		\$73.75				
(1.000)						
710089 DVD Player (1.000)		\$429.00				
561030 Assy, Rack (1.000)		\$206.20				
700887 Amplifier, Video		\$90.35				
(1.000)						
512742 Cable, Mic Adapter		\$38.50				
(1.000)						
512743 Adapter, Data (1.000)		\$18.00				
512744 Adapter, Amp (1.000)		\$27.15				
512745 Adapter, Video/DVD		\$36.20				
(1.000)						
512747 Adapter, Video Trigger		\$16.00				
(1.000)						
512757 Cable, Rack Power		\$23.15				
(1.000)						
512758 Cable, ADV Retro		\$51.20				
DVD Audio (1.000)						
511867 Cable, Dist Amp		\$7.50				
(1.000)						
511253 Coax Cable (1.000)		\$10.50				
540762 Panel, Component		\$22.50				
Blak (1.000)						
512741 Adapter, Wireless		\$18.70				
Receiver (1.000)						
511822 Cable, Wireless		\$10.50				
Charger (1.000)						
511820 Cable, Wireless		\$14.40				
Receiver, Rack Power (1.000)						

5/7/2019

## Work Order Detail

769965 Kit, LCD Monitor w/ Mounting (6.000)	\$4,080.00					
MCDISCOUNT (6.000)	\$-780.00					
511899 Cable, Monitor Power 18Ft (2.000)	\$49.10					
511900 Cable, Monitor Power 29FT (2.000)	\$62.30					
511901 Harness, Power, X- Over (1.000)	\$93.10					
Freight (1.000)	\$101.00					
Miscellaneous Parts	\$0					
6076 - SCHILLER-FEIDT, MICHAEL (13.08)		\$654.00				
Miscellaneous Labor		\$0				
Other					\$0	
	\$0.00	\$5,463.30	\$654.00	\$0	\$0	<u>\$6,117.30</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 792,097.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208241	09/28/2016	09/28/2016	Closed	0.00	

Description: DVD Player

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$25.00		\$0.00	\$25.00

Maintenance Requested: 10467 - 09/26/2016 - DVD player not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.50)			\$25.00			
Labor Comments: found bad harness got new one coming						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$25.00	\$0	\$0	<u>\$25.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 792,097.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208272	09/30/2016	10/03/2016	Closed	0.00	

Description: LOF; PMI; HUB SRVC

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
46:Exhaust System		\$0	\$21.50		\$0.00	\$21.50
Miscellaneous Parts		\$0				
0146 - SHIPPY, CURTIS (0.43)			\$21.50			
Labor Comments: Welded a patch on a hole in muffler.						
Miscellaneous Labor			\$0			
Other					\$0	
HUB:Hub Service		\$57.16	\$74.00		\$0.00	\$131.16
Pillsbury: Hub Cap w/ Lube		\$39.16				
Window Steer Axle MCI D4500: 343-4176 (1.000)						
Pillsbury: Oil Gear 80W-140		\$18.00				
Synthetic Mobil Delvac: Gear oil 80W-140 in pints (6.000)						

5/7/2019

## Work Order Detail

Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (1.48)		\$74.00			
Labor Comments: Service hubs--put in 80/140 lube.					
Miscellaneous Labor		\$0			
Other			\$0		
LOF:Lube, Oil, Filter	\$142.83	\$93.50	\$0.00		\$236.33
Pillsbury: Oil Analysis Kit:	\$10.00				
Sample Kit (1.000)					
Pillsbury: Filter Oil MCI D4500	\$15.10				
w/Detroit Diesel 60 Series:					
1971MP (2.000)					
Pillsbury: Oil Bulk in Quarts:	\$75.60				
Oil 15W-40 Bulk (36.000)					
Pillsbury: Fluid Coolant Bulk	\$42.13				
50/50 After Dilution: A/F 50/50					
Green BULK (12.000)					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (1.87)		\$93.50			
Labor Comments: Perform LOF service					
Miscellaneous Labor		\$0			
Other			\$0		
PMI:Preventative Maintenance Inspection	\$15.52	\$216.00	\$0.00		\$231.52
Pillsbury: Light Bulb Pass.	\$2.00				
Service Module 28V 10W:					
03-08-1162 (2.000)					
Pillsbury: Filter Media: 4WZ68	\$13.52				
(8.000)					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (4.32)		\$216.00			
Labor Comments: Tighten 2 P/R door hinges; 2 passenger lights; 4 footrests tightened-missing screws; replace 6 cupholders; replace 1 P/R threshold strip (from 522); Needs door light--ordered; Tightened 1 seat pedestal bolt					
Miscellaneous Labor		\$0			
Other			\$0		
	\$0	\$215.51	\$405.00	\$0	\$0
					<u>\$620.51</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 792,097.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208330	10/04/2016	10/06/2016	Closed	0.00	

Description: DVD Player, Lighting

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$26.50		\$0.00	\$26.50
New MCI LED lights (2.000)		\$0.00				
Part Comments: Dan Knows what they are						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$26.50			
(0.53)						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$580.24	\$93.50		\$0.00	\$673.74
Pillsbury: Dvd Player elite		\$580.24				
system: 710089 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$93.50			
(1.87)						
Labor Comments: found bad wire and the DVD player was bad from REI, we had one on the shelf and it worked, Kranz is getting the other one warrentied						
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$580.24 \$120.00 \$0 \$0 \$700.24

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 792,671.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208370	10/06/2016	10/06/2016	Closed	0.00	

Description: DVD Player

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 10518 - 10/05/2016 - DVD player doesn't work

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$0.00  
 (0.00)

Labor Comments: Already been fixed

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$0 \$0 \$0 \$0.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 793,118.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208501	10/14/2016	10/14/2016	Closed	0.00	

Description: Webasto Tune Up

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$210.94	\$246.50		\$0.00	\$457.44
Pillsbury: Over Heat sensor:		\$180.22				
W-64182B (1.000)						
Pillsbury: Nozzle (0.65 GPH		\$17.97				
80H)wabasto: WE470716						
(1.000)						
Pillsbury: Electrode Ignition		\$12.75				
dw-thermo wabasto:						
WE14846D (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$246.50			
(4.93)						

Labor Comments: webasto tune up, found the over heat sensor was bad, it was rusted into it spot. Had to take the left side of the bumper out to extract it.  
 checked block heater  
 cleaned up the supplies in the supply door

Miscellaneous Labor \$0  
 Other \$0

\$0 \$210.94 \$246.50 \$0 \$0 \$457.44

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 793,183.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208557	10/18/2016	10/18/2016	Closed	0.00	

Description: susp rear lower RR

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$231.00	\$225.00		\$0.00	\$456.00
Pillsbury: Rod Assy-radius		\$231.00				
drive axle: 12-05-1010 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (4.50)			\$225.00			
Labor Comments: Out of shop from 6:30 to 8:55 due to clinic run.						
Replaced L lower tracking arm, rubber peeling out.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$231.00	\$225.00	\$0	\$0	<u>\$456.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 753,573.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208679	10/26/2016	10/28/2016	Closed	0.00	

Description: Air Drier

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$14.09	\$91.00		\$0.00	\$105.09
Pillsbury: Belt Serpentine		\$14.09				
(EL3): 25-060295 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$91.00			
(1.82)						
Labor Comments: searched for new dipstick and dipstick tube since in broke, also took out the small						
altenator belt with it. Replaced the belt						
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$122.92	\$126.00		\$0.00	\$248.92
Pillsbury: AD-IP Air Dryer		\$56.20				
Desiccant Cartridge Bendix:						
109493BXR (1.000)						
Pillsbury: Purge Valve Repair		\$66.72				
Kit, AD-IP: K022105 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$126.00			
(2.52)						
Labor Comments: air drier service, and also had to help a driver with a check engine light on 5619. This						
bus needs a new air compressor.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$137.01	\$217.00	\$0	\$0	<u>\$354.01</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 793,788.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208742	10/31/2016	11/08/2016	Closed	0.00	

Description: Write-ups,air compressor,dip stick tube

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$146.67	\$339.50		\$0.00	\$486.17
Work Comments: 40 -- Needs new dip stick tube (broken)						
Needs small alt. belt and main serp belt						
Pillsbury: Belt Serpentine		\$14.09				

(EL3): 25-060295 (1.000)					
Pillsbury: Belt Alternator MCI	\$38.74				
Motor Coach: 8L-27-132					
(1.000)					
23513842 seal (1.000)	\$2.01				
23533982 tube (1.000)	\$45.54				
Pillsbury: Oil Bulk in Quarts:	\$5.55				
Oil 15W-40 Bulk (2.500)					
Pillsbury: Filter Oil MCI D4500	\$7.55				
w/Detroit Diesel 60 Series:					
1971MP (1.000)					
23521379 Dip Stick Gauge	\$33.19				
(1.000)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (6.79)		\$339.50			
Labor Comments: 40 -- Needs new dip stick tube (broken) ---- Had to take all kinds of things apart to get the new Dip stick tube into place. made a new bracket to hold it in place.					
Needs small alt. belt and main serp belt ---- Removed and replaced both belts.					
Miscellaneous Labor		\$0			
Other			\$0		
49:Air System	\$207.47	\$1,064.00	\$0.00		\$1,271.47
Work Comments: 49 -- Needs new air compressor (lots of oil in the air system)					
Pillsbury: Gasket Governor:	\$1.23				
236577BXW (1.000)					
BW/204820 TU Flo Gasket	\$1.72				
(2.000)					
Pillsbury: Switch (Complete)	\$204.52				
Low Air Press MCI D4500:					
7L-8-885 (2.000)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK		\$1,064.00			
Labor Comments: 49 -- Needs new air compressor (lots of oil in the air system) ---- Cut the panel between the A/C compressor and the storage compartment. Removed and replaced the air compressor with a good used one off another engine. Had to replace the gasket at the air discharge port, leaking. Reattached the panel.					
Miscellaneous Labor		\$0			
Other			\$0		
72:Body Misc	\$0	\$59.00	\$0.00		\$59.00
Maintenance Requested: 10631 - 10/29/2016 - first overhead compartment(door) doesnt stay shut					
Requestor Notes:					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (1.18)		\$59.00			
Labor Comments: 72 --- first overhead compartment will not latch shut. ---- Made an adjustment on the DVD mounting bracket so it would sit back farther.					
Miscellaneous Labor		\$0			
Other			\$0		
73:Seats	\$0	\$11.50	\$0.00		\$11.50
Maintenance Requested: 10630 - 10/29/2016 - First set of seats arm rest dont go down					
Requestor Notes:					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (0.23)		\$11.50			
Labor Comments: 73 -- Write-up, First set of seats arm rest dont go down. ---- Checked out the arm rests and they work fine if you just no how to operate them. LACK OF TRAINING AGAIN					
!!!!!!!					
Miscellaneous Labor		\$0			
Other			\$0		
	\$0.00	\$354.14	\$1,474.00	\$0	\$0
					<u>\$1,828.14</u>

## 5526: 1998 MCI EL3

Miles: 793,989.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208863	11/08/2016	11/09/2016	Closed	0.00	

Description: DVD Player

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$22.50		\$0.00	\$22.50

Maintenance Requested: 10652 - 11/05/2016 - DVD player wont accept disc

Requestor Notes:

Technician Response:

Maint Req Status: Completed

DVD Player (1.000) \$0.00

Part Comments: Warrentied from REI

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$22.50			
(0.45)						

Labor Comments: dvd player would not accept dvds anymore, just installed about a month ago, replaced with dvd player that we got back from REI that was warrentied.

Miscellaneous Labor			\$0			
Other					\$0	

\$0	\$0	\$22.50	\$0	\$0	\$22.50
-----	-----	---------	-----	-----	---------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 794,358.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208988	11/17/2016	11/17/2016	Closed	0.00	

Description: Air System

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$0	\$71.50		\$0.00	\$71.50

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$71.50			
(1.43)						

Labor Comments: leans bad in the barn. tried to find the air leak, found a couple small leaks but dont think they pretain to the leaning. might have to take the air bags down and see if they are leaking inside, in the future

Miscellaneous Labor			\$0			
Other					\$0	

\$0	\$0	\$71.50	\$0	\$0	\$71.50
-----	-----	---------	-----	-----	---------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,367.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209244	12/07/2016	12/12/2016	Closed	0.00	

Description: FF,Writr-ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$112.50		\$0.00	\$112.50

Maintenance Requested: 10744 - 12/02/2016 - See Notes

Requestor Notes: 1) Drievre states that the Oil Temp Gauge never Moved  
 2) Cargo door for Spare Tire wont open ( Passenger Side)  
 3) Table Leg on Driver side broken

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
0081 - WOLF, PATRICK (2.25)

\$0  
\$112.50

Labor Comments: 1) Drievre states that the Oil Temp Gauge never Moved ---- The gauge is broken.  
Our swing dash needs to be repaired before we can swap it out again. Please have the drivers disregard this gauge till we get it back and swap it out.  
2) Cargo door for Spare Tire won't open ( Passenger Side) ---- Checked all the luggage bay doors and every one of them work fine. Even the one where the spare tire is.  
3) Table Leg on Driver side broken. ---- Installed a different table in the bus. pulled the other table out and brought to the shop for repairs.

Miscellaneous Labor

\$0

Other

\$0

CR:Creep

\$0 \$100.00

\$0.00

\$100.00

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (2.00)

\$100.00

Miscellaneous Labor

\$0

Other

\$0

FF:Fuel Filter

\$8.40 \$98.50

\$0.00

\$106.90

Work Comments: FF -- Fuel filter

Pillsbury: Filter Fuel: 3118  
(1.000)

\$4.19

Pillsbury: Filter, Fuel, MCI:  
3120 (1.000)

\$4.21

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (1.97)

\$98.50

Labor Comments: FF -- Fuel filter ---- Removed both fuel filters. Prefilled new filters and installed them.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$8.40 \$311.00 \$0 \$0 \$319.40

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 795,658.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209265	12/08/2016	12/19/2016	Closed	0.00	

Description: passenger door body repair and decals remove

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$253.50		\$0.00	\$253.50
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (5.07)			\$253.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$253.50	\$0	\$0	<u>\$253.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,367.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209376	12/14/2016	12/15/2016	Closed	0.00	

Description: Dump Valve

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$19.77	\$0		\$0.00	\$19.77

Maintenance Requested: 10785 - 12/10/2016 - lower valve frozen couldn't dump toilet

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Hub-Slide Valve Lav:

\$19.77



17-02-1194 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: washstall is now adding more anti freeze to the systems

Miscellaneous Labor

\$0

Other

\$0

\$0

\$19.77

\$0

\$0

\$0

\$19.77

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,451.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

209386

12/15/2016

12/21/2016

Closed

0.00

Description: brakes leaking air.

DetailDiscountsPartsLaborTiresOtherTotal

13:Brakes

\$354.14

\$171.50

\$0.00

\$525.64

Work Comments: 13 -- Left tag brake chamber leaking air. Waiting on Parts.

Pillsbury: Chamber Brake:

\$354.14

MJS1724ET051 (1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (3.43)

\$171.50

Labor Comments: 13 -- Left tag brake chamber leaking air. Waiting on Parts. ---- Removed and replaced the left tag brake chamber.

Miscellaneous Labor

\$0

Other

\$0

41:A/C &amp; Heating

\$0

\$400.00

\$0.00

\$400.00

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (2.68)

\$134.00

Labor Comments: 41 -- Got the toilet dumped. checked out the heat. Checked and found the wabasto not working. Got the bus into the shop for repairs.

7050 - STRAND, MATTHEW

\$266.00

(5.32)

Labor Comments: fixed the webasto

Miscellaneous Labor

\$0

Other

\$0

\$0

\$354.14

\$571.50

\$0

\$0

\$925.64

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,451.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

209544

12/29/2016

01/09/2017

Closed

0.00

Description: Fuel Door/Key Broke

DetailDiscountsPartsLaborTiresOtherTotal

78:Doors Entrance / Exit

\$0

\$3.50

\$0.00

\$3.50

Maintenance Requested: 10876 - 12/29/2016 - Key broke off in fuel door

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$3.50

(0.07)

Labor Comments: key was already extracted

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$3.50 \$0 \$0 \$3.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,451.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209570	01/03/2017	02/07/2017	Closed	0.00	

Description: Rear supply door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$503.50		\$0.00	\$503.50
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS (10.07)			\$503.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$503.50	\$0	\$0	<u>\$503.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,451.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209591	01/04/2017	02/07/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$86.00		\$0.00	\$86.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (1.72)			\$86.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$86.00	\$0	\$0	<u>\$86.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,451.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209592	01/04/2017	02/07/2017	Closed	0.00	

Description: decals remov and buf , buf rims

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$2,407.50		\$0.00	\$2,407.50
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS (27.38)			\$1,369.00			
82 - BLANCO, VICTOR (20.77)			\$1,038.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$2,407.50	\$0	\$0	<u>\$2,407.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 796,451.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209686	01/11/2017	01/17/2017	Closed	0.00	

Description: No start, Key busted off in door lock

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$87.50		\$0.00	\$87.50
Work Comments: 31 -- No start, key broken in battery door lock.						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.75)			\$87.50			
Labor Comments: 31 -- No start, key broken in battery door lock. ----- Broke my way into the battery door. Removed the door lock. Got the broken key out of the lock. Reinstalled the lock. Chared the batteries and started the bus.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$87.50	\$0	\$0	<u>\$87.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 798,911.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209918	01/26/2017	02/15/2017	Closed	0.00	

Description: PMI,AF,Write-ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$266.00		\$0.00	\$266.00
Maintenance Requested: 10940 - 01/18/2017 - Severe tracking to the right						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (3.75)			\$187.50			
Labor Comments: 20 -- Write-up for tracking Issue. ----- Put in the air and checked all the torque arms and v - links. Checked the ras steering with the measuring tools, all looks good. Drove behind it, its not really dogtracking at all. Adjusted the right mirror because the tipped mirror can make it look like its Dog-tracking.						
9127 - JACOBS, ANDREW (0.42)			\$21.00			
Labor Comments: follow pat while doing road test to see if dog tracking						
7050 - STRAND, MATTHEW (1.15)			\$57.50			
Labor Comments: put in the air and checked all the torque arms and vlinks. Checked the ras steering with the measuring tools, all looks good. Drove behind it, its not really dogtracking at all.						
Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$0	\$136.50		\$0.00	\$136.50
Work Comments: 78 -- Write-up for front right bag door not releasing.						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (2.73)			\$136.50			
Labor Comments: 78 -- Write-up for front right bag door not releasing. ----- Pulled the inner door panel off and bent the latch mech. back to gether again The drivers bend the shit out of theses all the time by pulling down on the door to hard before getting the released.						
Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$31.25	\$14.00		\$0.00	\$45.25
Maintenance Requested: 11037 - 02/10/2017 - See Notes RE Entry Door						
Requestor Notes: Driver states that the door switch on the dash will not shut the door but it will open the door						
Drivers states that they have to pull the door closed by hand set the deadbolt & re energize the air to the door to secure it.						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Switch Rocker Door			\$31.25			

5/7/2019

## Work Order Detail

EL3: 07-19-1016 (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$14.00				
(0.28)						
Labor Comments: door switch was broken, replaced it						
Miscellaneous Labor		\$0				
Other				\$0		
AF:Air Filter Replacement	\$33.16	\$49.00		\$0.00		\$82.16
Work Comments: AF -- Air filter replacement						
Pillsbury: Filter Air EL3: 6774	\$33.16					
(1.000)						
Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (0.98)		\$49.00				
Labor Comments: AF -- Air filter replacement ----- Removed and replaced the air filter.						
Miscellaneous Labor		\$0				
Other				\$0		
PMI:Preventative Maintenance Inspection	\$0	\$388.50		\$0.00		\$388.50
Work Comments: PMI -- Preventative Maintenance Inspection						
Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (7.77)		\$388.50				
Labor Comments: PMI -- Preventative Maintenance Inspection ----- Performed the preventative Maintenance and Inspection as per the attached sheet.						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$64.41	\$854.00	\$0	\$0	<u>\$918.41</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 800,846.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
210433	03/06/2017	03/06/2017	Closed	0.00	

Description: Left headlamp

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$2.69	\$8.50		\$0.00	\$11.19

Maintenance Requested: 11152 - 03/05/2017 - Left front headlight out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Headlight Halogen	\$2.69					
Low Beam: 9006 (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$8.50				
(0.17)						

Labor Comments: replaced the left front low beam headlamp

Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$2.69	\$8.50	\$0	\$0	<u>\$11.19</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 802,747.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
210585	03/17/2017	03/20/2017	Closed	0.00	

Description: Defroster Fan

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$9.00		\$0.00	\$9.00

Maintenance Requested: 11214 - 03/17/2017 - d/Side defroster fan inop

Requestor Notes:  
 Technician Response:  
 Maint Req Status: Completed

Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (0.18)			\$9.00			
Labor Comments: broke the ground, rewired it						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$9.00	\$0	\$0	<u>\$9.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 803,422.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
210683	03/24/2017	03/31/2017	Closed	0.00	

Description: LOF, LIST

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$243.75	\$94.50		\$0.00	\$338.25
Pillsbury: Pads brake EL3: 04-01-1019 (1.000)		\$243.75				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.89)			\$94.50			
Labor Comments: brake pads on the drives, bad replaced them						
Miscellaneous Labor			\$0			
Other					\$0	
21:Suspension		\$970.27	\$292.00		\$0.00	\$1,262.27
Pillsbury: Shock Absorber Front EL3 MCI: 12-05-1170 (2.000)		\$374.86				
Pillsbury: Spacer Link, EL3: 12-05-1035 (1.000)		\$6.30				
Pillsbury: Stud Sway Bar, EL3: 12-05-1051 (1.000)		\$32.33				
Pillsbury: Bushing, Torsoin Bar MCI: 12-05-6046 (4.000)		\$70.92				
Pillsbury: Sensor Assembly: 07-08-1068 (1.000)		\$141.33				
Pillsbury: Bushing-Sway Bar, EL3: 12-05-1012 (4.000)		\$35.00				
Pillsbury: Washer Sway Bar, EL3: 12-05-1034 (4.000)		\$34.28				
12-05-1026 Washer (4.000)		\$63.12				
Pillsbury: Bushing-Sway Bar, EL3: 12-05-1012 (4.000)		\$35.64				
Pillsbury: Spacer Link, EL3: 12-05-1035 (1.000)		\$6.42				
Pillsbury: Stud Sway Bar, EL3: 12-05-1051 (1.000)		\$32.93				
Pillsbury: Valve Asm- Leveling: 12-06-1055 (1.000)		\$137.14				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (5.84)			\$292.00			
Labor Comments: front shocks bad replaced both front sway bar bushing and rod bad relplaced all bushing rods and spacers and washers						
Miscellaneous Labor			\$0			

Other			\$0	
25:Transmission (Auto)	\$128.97	\$176.50	\$0.00	\$305.47
Pillsbury: Speedi-Sleeve	\$70.33			
Allison B500 Output: 99473 (1.000)				
Pillsbury: Seal Rear	\$58.64			
Transmission Output Allison B500: 29552705 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (3.53)		\$176.50		
Labor Comments: Transmission rear seal leaking pulled apart and the speedy sleeve was pretty bad tried to find a new yoke, unsuccessful went to the warehouse and took yoke off old transmission, wasnt as bad replaced the speedy sleeve and seal cleaned up the yoke and drive shaft and put back together				
Miscellaneous Labor		\$0		
Other			\$0	
31:Charging	\$30.04	\$96.00	\$0.00	\$126.04
Pillsbury: Alternator Kit Front	\$30.04			
Seal Delco 50DN Belt Drive: 10514967 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (1.92)		\$96.00		
Labor Comments: 50 dn front seal leaking, replaced it batteries were not equailizing, ran for half hour they equilizedout did not punch off for steamclean				
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$16.59	\$3.50	\$0.00	\$20.09
Maintenance Requested: 11243 - 03/23/2017 - Front parking lamp out/ Turn signal ok. Requestor Notes: Technician Response: Maint Req Status: Completed				
Pillsbury: Light led license: 15205 (1.000)	\$16.59			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.07)		\$3.50		
Labor Comments: replaced burnt out lamp				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$475.00	\$33.00	\$0.00	\$508.00
RO31997 ACC Drive Pulley (1.000)	\$475.00			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.66)		\$33.00		
Labor Comments: accessory drive gear on the engine leaking ordered new one				
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$461.36	\$64.00	\$0.00	\$525.36
Pillsbury: Gauge Sight MCI	\$21.98			
Surge Tank: 6R-14-60 (1.000)				
6L-8-287 Pump (1.000)	\$439.38			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (1.28)		\$64.00		
Labor Comments: sight glass is dirty cant see coolant level very well, replaced it coolant pump leaking, replaced it drain plug leaking, replaced it				
Miscellaneous Labor		\$0		

5/7/2019

Work Order Detail

Other					\$0	
72:Body Misc	\$44.58	\$15.00	\$0.00		\$59.58	
Pillsbury: Spring-Gas Helper	\$44.58					
L. Hand Radiator Door MCI						
D4500: 3L-31-948 (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$15.00				
(0.30)						
Labor Comments: bottom of the frame bracket loose, pounded it back and re riveted it						
Miscellaneous Labor		\$0				
Other			\$0			
79:Lavatory	\$383.04	\$67.50	\$0.00		\$450.54	
Pillsbury: Kit, Lav Retro Fit:	\$383.04					
T17-1107A (1.000)						
Part Comments: LAV KIT						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$67.50				
(1.35)						
Labor Comments: redid the lav kit						
Miscellaneous Labor		\$0				
Other			\$0			
LOF:Lube, Oil, Filter	\$265.82	\$156.50	\$0.00		\$422.32	
Pillsbury: Filter Oil MCI D4500	\$15.56					
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Analysis Kit:	\$10.00					
Sample Kit (1.000)						
Pillsbury: Oil Bulk in Quarts:	\$79.92					
Oil 15W-40 Bulk (36.000)						
Pillsbury: Fluid Antifreeze RV:	\$160.34					
A/F RV BULK (31.500)						
Part Comments: Added over winter for bathroom charged applied by wash stall.						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$156.50				
(3.13)						
Labor Comments: service						
Miscellaneous Labor		\$0				
Other			\$0			
PMI:Preventative Maintenance Inspection	\$0	\$0	\$0.00		\$0.00	
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$0.00				
(0.00)						
Labor Comments: serviced the bus						
Miscellaneous Labor		\$0				
Other			\$0			
	\$0.00	\$3,019.42	\$998.50	\$0	\$0	<u>\$4,017.92</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 803,978.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211029	04/18/2017	04/24/2017	Closed	0.00	

Description: A/C Prep

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
43:Cooling		\$10.53	\$81.00		\$0.00	\$91.53

Work Comments: 43 -- Steamed out the radiator and CAC. topped off the coolant.

Pillsbury: Fluid Coolant Bulk	\$10.53					
50/50 After Dilution: A/F 50/50						
Green BULK (3.000)						
Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (1.62)		\$81.00				

Labor Comments: 43 -- Steamed out the radiator and CAC. topped off the coolant.						
Miscellaneous Labor		\$0				
Other				\$0		
72:Body Misc		\$154.28	\$42.50	\$0.00		\$196.78
Work Comments: 72 -- Body misc. ---- Anti slip tape falling off the bottom step. Cleaned all the dirt and adhesive off the step and applied new tape.						
Pillsbury: Headlight, LED, MCI: 9705K (1.000)		\$77.14				
Pillsbury: Headlight, LED, MCI: 9706K (1.000)		\$77.14				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.85)			\$42.50			
Labor Comments: 72 -- Body misc. ---- Anti slip tape falling off the bottom step. Cleaned all the dirt and adhesive off the step and applied new tape.						
Miscellaneous Labor		\$0				
Other				\$0		
A/C:Prep		\$422.54	\$196.50	\$0.00		\$619.04
Work Comments: A/C : Prepare for Summer.						
Pillsbury: Water Valve repair kit, EL3: 16-06-1025 (2.000)		\$422.54				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (3.93)			\$196.50			
Labor Comments: A/C : Prepare for Summer. ---- Removed all the panels. checked every brush on condensor and evap motors. All are at least 60 %. Rinsed out the condensor core, radiator and CAC. (very dirty) Removed and rebuilt a water valve.						
Miscellaneous Labor		\$0				
Other				\$0		
		\$0	\$587.35	\$320.00	\$0	\$0
						<u>\$907.35</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 804,764.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211276	05/04/2017	05/11/2017	Closed	0.00	

Description: Broken Headlamp

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$81.50		\$0.00	\$81.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.63)			\$81.50			
Labor Comments: ran the a/c and cleaned out the condensor						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$95.00	\$133.50		\$0.00	\$228.50
Pillsbury: Holder cup w/ mounting screws black: TH2BLK (50.000)		\$95.00				
Part Comments: installed by wash stall						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.67)			\$133.50			
Labor Comments: took the headlamp that was smashed in out						
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$95.00	\$215.00	\$0	\$0
						<u>\$310.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 804,764.0

Location: PBG

Department: PBG5-Charter



	Recall:	Campaign #		Date:
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Accident</u>
211291	05/04/2017	05/17/2017	Closed	

Description: put a head light passenger side fix front bumper

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$668.50		\$0.00	\$668.50
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS (13.37)			\$668.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$668.50	\$0	\$0	<u>\$668.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 805,631.0

Location: PBG

Department: PBG5-Charter

	Recall:	Campaign #		Date:
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Accident</u>
211589	05/26/2017	06/02/2017	Closed	

Description: DOT,door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$213.50		\$0.00	\$213.50
Work Comments: 78 -- Entrance door switch not working.						
7L-8-553 outter door switch (from Eagan) (1.000)		\$0.00				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.27)			\$213.50			
Labor Comments: 78 -- Entrance door switch not working. ---- Trouble shoot door problem. Found a blown fuse and a bad exterior door switch. Removed and replaced both.						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$0	\$177.50		\$0.00	\$177.50
Work Comments: CR -- Creep						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (3.55)			\$177.50			
Labor Comments: CR -- Creep ---- Creep bus and checked out everything to make sure it could pass a DOT.						
Miscellaneous Labor			\$0			
Other					\$0	
DO:DOT Inspection		\$2.00	\$50.00		\$0.00	\$52.00
DOT Sticker 2\$ (1.000)		\$2.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.00)			\$50.00			
Labor Comments: DOT						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$2.00	\$441.00	\$0	\$0	<u>\$443.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 803,989.0

Location: PBG

Department: PBG5-Charter

	Recall:	Campaign #		Date:
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Accident</u>
211735	06/07/2017	06/09/2017	Closed	

Description: A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$78.93	\$205.00		\$0.00	\$283.93

Maintenance Requested: 11466 - 06/07/2017 - Air conditioning not cooling  
Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Freon R134A per \$27.96  
Lb.: R134A (12.000)  
Pillsbury: Viscosity 32 oz: PAG \$50.97  
Oil CQP100-32 (3.000)  
Miscellaneous Parts \$0  
7050 - STRAND, MATTHEW \$205.00  
(4.10)

Labor Comments: low on freon, charged to operating range, maybe a little over  
checked for leaks on the a/c compressor  
steam cleaned the a/c compressor and engine compartment  
fixed the door lock  
fixed a really bad rattle

Miscellaneous Labor \$0  
Other \$0

\$0 \$78.93 \$205.00 \$0 \$0 \$283.93

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate: PRZ9154

Miles: 807,825.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211919	06/22/2017	06/22/2017	Closed	0.00	

Description: Repair from 6-20-17 Incident

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$36.00	\$318.75		\$0.00	\$354.75
Miscellaneous Parts		\$36.00				
9024 - LEWISON, CHAD			\$318.75			

Labor Comments: sand and buff out doors  
Door will need to be fully painted in the future

Miscellaneous Labor \$0  
Other \$0

\$106.25 \$36.00 \$318.75 \$0 \$0 \$354.75

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 808,161.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211972	06/27/2017	06/30/2017	Closed	0.00	

Description: PMI, FF, Coolant Filter

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$43.74	\$101.50		\$0.00	\$145.24
Pillsbury: Stop-Bump, Drive		\$33.66				
Axle: 12-03-1025 (1.000)						
Pillsbury: Hub Cap, Stainless		\$10.08				
Steel: MW1273 (1.000)						
Used Tire (1.000)		\$0.00				
Used Lug Nut Covers		\$0.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$101.50			
(2.03)						

Labor Comments: Right Tag tire was beat up really bad, missing all lug nut covers and hub cap. They  
must have hit something hard.  
Replaced the tire with a used one in the tire cage.  
Left tag bumper was falling apart, broke loose and replaced.

Miscellaneous Labor		\$0		
Other			\$0	
25:Transmission (Auto)	\$58.64	\$91.50	\$0.00	\$150.14
Pillsbury: Seal Rear	\$58.64			
Transmission Output Allison				
B500: 29552705 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$91.50		
(1.83)				
Labor Comments: Trans seal leaking, installed a used yoke. Old one has already went thru 2 speed sleeves.				
Replaced Seal				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$200.47	\$24.00	\$0.00	\$224.47
Pillsbury: Tensioner, Detroit:	\$200.47			
23533015 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$24.00		
(0.48)				
Labor Comments: Serpentine belt was bouncing all over the place. Replaced the Tensioner.				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$31.80	\$70.00	\$0.00	\$101.80
Pillsbury: Striker Assy-side	\$29.74			
sash: 03-27-1137 (2.000)				
Pillsbury: Light Bulb Pass.	\$2.06			
Sevice Module 28V 10W:				
03-08-1162 (2.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$70.00		
(1.40)				
Labor Comments: Replaced a set of window strikers and reading light bulbs				
Miscellaneous Labor		\$0		
Other			\$0	
CFR:Coolant Filter Replacement	\$63.39	\$0	\$0.00	\$63.39
Pillsbury: Filter Coolant w/Full	\$63.39			
Charge MCI D4500 w/ Detroit				
60 Series Engine: 4088				
(2.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$0.00		
(0.00)				
Labor Comments: repalced Coolant Filter				
Miscellaneous Labor		\$0		
Other			\$0	
FF:Fuel Filter	\$8.53	\$36.50	\$0.00	\$45.03
Pillsbury: Filter, Fuel, MCI:	\$4.34			
3120 (1.000)				
Pillsbury: Filter Fuel: 3118	\$4.19			
(1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$36.50		
(0.73)				
Labor Comments: Replaced Fuel Filters and Coolant filter				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$0	\$128.50	\$0.00	\$128.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$128.50		
(2.57)				
Labor Comments: PMI				
Miscellaneous Labor		\$0		
Other			\$0	

\$0.00      \$406.57      \$452.00      \$0      \$0      \$858.57

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 808,579.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212030	07/05/2017	07/07/2017	Closed	0.00	

Description: No A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$201.00		\$0.00	\$201.00

Maintenance Requested: 11546 - 07/03/2017 - No A/C

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts      \$0

0081 - WOLF, PATRICK (4.02)      \$201.00

Labor Comments: 41 --- No A/C ---- Checked out the A/C It took the Inside temp down to 64 with no problem. The freon level is right in range also. Nothing found wrong with the A/C system.

Miscellaneous Labor      \$0

Other      \$0

\$0      \$0      \$201.00      \$0      \$0      \$201.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 808,579.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212046	07/06/2017	07/07/2017	Closed	0.00	

Description: Muffler

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
46:Exhaust System		\$754.93	\$136.50		\$0.00	\$891.43

Pillsbury: Exhaust Clamp 5"

\$5.36

Preformed Band Aluminized:

ABP N35-50PLA (1.000)

Pillsbury: Isolator Double U-

\$104.46

Shear: 08-20-1014 (3.000)

08-20-1024 muffler-

\$548.48

aluminized steel (1.000)

08-20-1025 pipe-tail exh strt

\$96.63

(1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$136.50

(2.73)

Labor Comments: Muffler had a hole in it. Replaced it and other hardware

Miscellaneous Labor      \$0

Other      \$0

\$0.00      \$754.93      \$136.50      \$0      \$0      \$891.43

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,055.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212381	07/31/2017	08/14/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$750.00	\$148.50		\$0.00	\$898.50

Work Comments: 41 -- #1 condensor fan on OverLoad

Rebuilt Condensor fan motor	\$0.00
(labeled DNI) (1.000)	
27 VDC GE Carrier Rebuild	\$750.00
Fan Motor (1.000)	
Miscellaneous Parts	\$0
0081 - WOLF, PATRICK (2.97)	\$148.50

Labor Comments: 41 -- #1 condensor fan on OverLoad ---- TRouble shoot condensor fan issue.  
Removed and replaced the fan motor.

Miscellaneous Labor	\$0					
Other					\$0	
	\$0	\$750.00	\$148.50	\$0	\$0	<u>\$898.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,055.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212403	08/01/2017	08/01/2017	Closed	0.00	

Description: Toilet

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 11653 - 08/01/2017 - needs toilet treatments

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW	\$0.00
(0.00)	

Labor Comments: Dont know what this means, guessing its a Wash Stall responsibility

Miscellaneous Labor	\$0					
Other					\$0	
	\$0	\$0	\$0	\$0	\$0	<u>\$0.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,959.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212418	08/01/2017	08/01/2017	Closed	0.00	

Description: Solenoid

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$58.82	\$0		\$0.00	\$58.82
Pillsbury: Contactor 24VDC:		\$58.82				
16-04-1204 (1.000)						
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$58.82	\$0	\$0	\$0	<u>\$58.82</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,964.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212877	08/28/2017	09/08/2017	Closed	0.00	

Description: Tag Tires/ Trans Flush

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$349.52	\$165.00		\$0.00	\$514.52
Maintenance Requested: 11931 - 08/28/2017 - bus vibration noticed by driver and passengers						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Tire TB Recap Tag:		\$349.52				
315/80R 22.5 TB Recap Tag						
(2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$165.00			
(3.30)						
Labor Comments: Looked over the suspension.						
Found tag tire cupping and wearing on the inside.						
Repalced both tag tires with tag recaps and save the good tire on the right side.						
Took on test drive and did not feel much of a vibration.						
Miscellaneous Labor			\$0			
Other					\$0	
31:Charging		\$14.08	\$40.00		\$0.00	\$54.08
Pillsbury: Belt Serpentine		\$14.08				
(EL3): 25-060295 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$40.00			
(0.80)						
Labor Comments: Alternator belt ripping apart, repalced it						
Miscellaneous Labor			\$0			
Other					\$0	
48:Fuel System		\$7.97	\$128.50		\$0.00	\$136.47
Pillsbury: Drive Coupler:		\$6.70				
23505249 (1.000)						
Pillsbury: Gasket Fuel Pump,		\$1.27				
Detroit Series 60: 23505248						
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$128.50			
(2.57)						
Labor Comments: I got taken off this bus a couple times.						
Fuel pump leaking oil, replaced the gasket and coupler and sealed it with anerobic gasket maker.						
Miscellaneous Labor			\$0			
Other					\$0	
TF:Transmission Flush		\$204.84	\$105.50		\$0.00	\$310.34
Pillsbury: Filter Kit		\$33.20				
Transmission Allison (Short						
Filter): 7741XE (1.000)						
Pillsbury: Fluid ATF (Synthetic)		\$171.64				
Bulk Quart: ATF Synthetic Bulk						
(28.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$105.50			
(2.11)						
Labor Comments: Trans flush and filter replacement.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$576.41	\$439.00	\$0	\$0	<u>\$1,015.41</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 812,021.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213102	09/11/2017	09/13/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$127.50		\$0.00	\$127.50
Miscellaneous Parts		\$0				
9127 - JACOBS, ANDREW (2.55)			\$127.50			
Labor Comments: recharge the a/c sysytem and steam off clutch						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$127.50	\$0	\$0	<u>\$127.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,053.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213541	10/05/2017	10/06/2017	Closed	0.00	

Description: polish

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$315.00		\$0.00	\$315.00
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (6.30)			\$315.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$315.00	\$0	\$0	<u>\$315.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,053.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213563	10/06/2017	10/09/2017	Closed	0.00	

Description: paint door will bring

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$306.00		\$0.00	\$306.00
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (6.12)			\$306.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$306.00	\$0	\$0	<u>\$306.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,053.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213672	10/12/2017	10/13/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$12.75	\$72.50		\$0.00	\$85.25
Pillsbury: Electrode Ignition		\$12.75				
dw-thermo wabasto: WE14846D (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$72.50			

(1.45)

Labor Comments: Webasto Service

Miscellaneous Labor

\$0

Other

\$0

AD:Air Drier Service

\$121.73

\$82.50

\$0.00

\$204.23

Pillsbury: Purge Valve Repair

\$64.48

Kit, AD-IP: K022105 (1.000)

Pillsbury: AD-IP Air Dryer

\$57.25

Desiccant Cartridge Bendix:

109493BXR (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$82.50

(1.65)

Labor Comments: Air Drier Service

Miscellaneous Labor

\$0

Other

\$0

\$0

\$134.48

\$155.00

\$0

\$0

\$289.48

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,209.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

213744

10/18/2017

10/23/2017

Closed

0.00

Description: LOF

DetailDiscountsPartsLaborTiresOtherTotal

13:Brakes

\$0

\$98.00

\$0.00

\$98.00

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$98.00

(1.96)

Labor Comments: LH Caliper not adjusting, took apart and fixed it

Miscellaneous Labor

\$0

Other

\$0

22:Tires

\$0

\$56.00

\$0.00

\$56.00

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$56.00

(1.12)

Labor Comments: Valve Stem Leaking on the inner dual LH side, replaced valve stem

Miscellaneous Labor

\$0

Other

\$0

36:Lighting

\$0

\$87.50

\$0.00

\$87.50

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$87.50

(1.75)

Labor Comments: No license plate lamps. Found a bad ground, cut out the bad part and rewired it.

Miscellaneous Labor

\$0

Other

\$0

LOF:Lube, Oil, Filter

\$109.54

\$186.00

\$0.00

\$295.54

Pillsbury: Filter Oil MCI D4500

\$17.10

w/Detroit Diesel 60 Series:

1971MP (2.000)

Pillsbury: Oil Bulk in Quarts:

\$82.44

Oil 15W-40 Bulk (36.000)

Pillsbury: Oil Analysis Kit:

\$10.00

Sample Kit (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$186.00

(3.72)

Labor Comments: LOF

Steam Clean

Road Test

Miscellaneous Labor

\$0



5/7/2019

## Work Order Detail

Other					\$0	
PMI:Preventative Maintenance Inspection	\$0	\$0		\$0.00	\$0.00	
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: serviced the bus						
Miscellaneous Labor			\$0			
Other				\$0		
	\$0	\$109.54	\$427.50	\$0	\$0	<u>\$537.04</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,569.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213873	10/27/2017	10/30/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$26.50		\$0.00	\$26.50

Maintenance Requested: 60633 - 10/23/2017 - see comments

Requestor Notes: 1. Power plug closest to the dash not working

2. Driver's side last window is not closing tight

3. Curbside, 4th window fogged up

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW			\$26.50			
(0.53)						

Labor Comments: Shut the windows

Checked the outlet, there is power on both outlets.

Will see about changing the fogged up window.

Miscellaneous Labor			\$0			
Other				\$0		

\$0	\$0	\$26.50	\$0	\$0	<u>\$26.50</u>
-----	-----	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,569.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213929	10/31/2017	11/01/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$40.00	\$40.00

Repair, Inv. # 2786162

22:Tires		\$1,500.00	\$149.00		\$0.00	\$1,649.00
----------	--	------------	----------	--	--------	------------

Pillsbury: Tire, Steer,Toyo

M144: 315/80R22.5 (4.000)

Miscellaneous Parts \$0

7050 - STRAND, MATTHEW \$149.00

(2.98)

Labor Comments: New Drive Tires

Miscellaneous Labor			\$0			
Other				\$0		

\$0	\$1,500.00	\$149.00	\$0	\$40.00	<u>\$1,689.00</u>
-----	------------	----------	-----	---------	-------------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

		Recall:	Campaign #			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
214167	11/16/2017	11/17/2017	Closed	0.00		
Description: Charging, Lighting, Body Misc						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$347.71	\$194.00		\$0.00	\$541.71
Pillsbury: Oil Bulk in Quarts:		\$6.87				
Oil 15W-40 Bulk (3.000)						
Pillsbury: Battery 1400CCA		\$340.84				
Top Post Heavy Duty						
Workaholic: 8D-MHD(7271)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$194.00			
(3.88)						
Labor Comments: batteries tested out to recharge them, charged each one for an hour. both tested out bad and replace. Replaced both baterries.						
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$78.02	\$49.00		\$0.00	\$127.02
Pillsbury: Ballast Interior Light		\$78.02				
EL3: 07-07-1040 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$49.00			
(0.98)						
Labor Comments: Interior light was out, tried bulb first. Ballast was bad, replaced it.						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$0	\$76.00		\$0.00	\$76.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.52)			\$76.00			
Labor Comments: Fixed floor hatch trim.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$425.73	\$319.00	\$0	\$0	\$744.73

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
214362	11/29/2017	12/04/2017	Closed	0.00		
Description: air not building						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$12.99	\$306.00		\$0.00	\$318.99
Work Comments: 49 -- Air pressure woldn't build above 50 psi for the front and 90 for the rear.						
Pillsbury: Governor, D2:		\$12.99				
H284358 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (6.12)			\$306.00			
Labor Comments: 49 -- Air pressure woldn't build above 50 psi for the front and 90 for the rear. ----						
Removed and replaced the governor. Had to turn up the set point.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$12.99	\$306.00	\$0	\$0	\$318.99

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

5/7/2019

## Work Order Detail

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214569	12/12/2017	12/13/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$160.50		\$0.00	\$160.50
Miscellaneous Parts		\$0				
9106 - MARIN RODRIGUEZ, CLAUDIO (3.21)			\$160.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$160.50	\$0	\$0	<u>\$160.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214587	12/13/2017	12/14/2017	Closed	0.00	

Description: rubber axle bumpers

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$33.66	\$116.00		\$0.00	\$149.66
Work Comments: 21 -- Rubber bumpers for drive and tag axles are shot.						
Pillsbury: Stop-Bump, Drive		\$33.66				
Axle: 12-03-1025 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (2.32)			\$116.00			
Labor Comments: 21 -- Rubber bumpers for drive and tag axles are shot. ----- Removed and replaced all the bad rubber bumpers.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$33.66	\$116.00	\$0	\$0	<u>\$149.66</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214837	12/28/2017	12/29/2017	Closed	0.00	

Description: Air System

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Labor Comments: Drained air from the system. Added alcohol to the system Creeped and checked fluids.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$0	\$0	\$0	<u>\$0.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215060	01/11/2018	01/17/2018	Closed	0.00	

<u>Detail</u>	Description: on Board charger not working.	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging			\$0	\$311.00		\$0.00	\$311.00
Work Comments: 31 -- On board charger not working.							
Miscellaneous Parts			\$0				
0081 - WOLF, PATRICK (6.22)				\$311.00			
Labor Comments: 31 -- On board charger not working. ----- Removed and replaced the charger with a ( Good Used ) one we had out of 522.							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$0	\$311.00	\$0	\$0	<u>\$311.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215311	01/25/2018	01/30/2018	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CR:Creep		\$0	\$149.00		\$0.00	\$149.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.98)			\$149.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$149.00	\$0	\$0	<u>\$149.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,270.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216196	03/23/2018	03/27/2018	Closed	0.00	

<u>Detail</u>	Description: Brake Lights	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting			\$10.45	\$410.00		\$0.00	\$420.45
Maintenance Requested: 61945 - 03/22/2018 - Brake Lights are out							
Requestor Notes:							
Technician Response:							
Maint Req Status: Completed							
Pillsbury: Pigtail, 3 Wire: 67090 (2.000)			\$3.12				
Pillsbury: Light Clearance Red: 1281369 (1.000)			\$7.33				
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW (8.20)				\$410.00			
Labor Comments: Both brake lights inop.							
Tested brake switches, modules, swapped modules around. Narrowed it down to a short in the back of the harness. Cut the wire and got one brake light to work. So I knew it was from the left brake light to after the splice. Instead of cutting the harness apart I used a spare factory wire and wired the brake light in and they both work. Put everything back together.							
Also dumped the wash stall water tanks on Saturday							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$10.45	\$410.00	\$0	\$0	<u>\$420.45</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,365.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
216459	04/10/2018	04/23/2018	Closed	0.00	

Description: A/C and Webasto, Radio Install

Detail	Discounts	Parts	Labor	Tires	Other	Total
41:A/C & Heating		\$288.29	\$224.50		\$0.00	\$512.79
Pillsbury: Hub: 16J-2-12 (1.000)		\$116.21				
Pillsbury: Carrier Front Seal Kit O5G A/C Compressor MCID4500: 16L-2-112 (1.000)		\$95.33				
Pillsbury: Nozzle (0.65 GPH 80H)wabasto: WE470716 (3.000)		\$55.02				
Pillsbury: Electrode Ignition dw-thermo wabasto: WE14846D (1.000)		\$21.73				
Miscellaneous Parts 7050 - STRAND, MATTHEW (4.49)		\$0	\$224.50			
Labor Comments: New A/C front seal. Cleaned the webasto and replaced the nozzle and sparker.						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair 619\$ radio install (1.000)		\$619.00	\$36.00		\$0.00	\$655.00
		\$619.00				
Part Comments: Kit includes:						
*HY-MD782U-1 UHF DMR Mobile Radio						
*K-794 Line kit, very thick mount						
*K332 Ground plane disc 6" dia, 3/8" mounting						
*C-BNC58-CR connector, BNC-Male, R858, crimp						
*B4502NS Antenna, UHF, no ground plane with spring						
*HY-IGNITION SENSE accessory plug, ignition sense, hytera MD752/MD662 (professional wireless)						
Miscellaneous Parts 9130 - PADELFORD, ERIC (0.72)		\$0	\$36.00			
Labor Comments: Matt and i installed new two way radio						
7050 - STRAND, MATTHEW (2.18)			\$0.00			
Labor Comments: Radio Install.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$907.29	\$260.50	\$0	\$0	\$1,167.79

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,857.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
216683	04/24/2018	05/02/2018	Closed	0.00	

Description: A/C Prep, Axle Gasket

Detail	Discounts	Parts	Labor	Tires	Other	Total
12:Axles (rear)		\$9.17	\$0		\$0.00	\$9.17
Maintenance Requested: 62135 - 04/22/2018 - righth rear oil hub seal leaking						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Gasket Rear Axle		\$3.77				

Flange: GKT1008 (1.000)					
Pillsbury: Oil Gear Synthetic:	\$5.40				
Oil Gear 75W-90 BULK in					
quarts (1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$0.00			
(1.22)					
Labor Comments: Replaced the Right side drive axle gasket					
Miscellaneous Labor		\$0			
Other				\$0	
12:Axles (rear)	\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 62130 - 04/22/2018 - see comments					
Requestor Notes: Oil leaking from drive axle and tag axle driver side					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$0.00			
(0.00)					
Miscellaneous Labor		\$0			
Other				\$0	
41:A/C & Heating	\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$0.00			
(1.58)					
Labor Comments: Cleaned the condensor and evaporator and checked brushes					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$9.17	\$0	\$0	\$9.17

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,857.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216769	04/30/2018	05/08/2018	Closed	0.00	

Description: A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$36.96	\$0		\$0.00	\$36.96
Pillsbury: Belt, A/C, MCI, E-		\$36.96				
Coach: 08-27-1029 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(2.40)						
Labor Comments: belt was slipping and adjstued the air gap on the clutch and checked for leaks on the a/c compressor.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$36.96	\$0	\$0	\$0	\$36.96

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 816,262.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216901	05/08/2018	05/11/2018	Closed	0.00	

Description: A/C not working

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$40.00	\$40.00
Repair, Inv. # 2786542						

5/7/2019

## Work Order Detail

41:A/C & Heating	\$136.89	\$364.00	\$0.00	\$500.89
Maintenance Requested: 62203 - 05/03/2018 - see comments				
Requestor Notes: A/C is not functioning				
back door (engine compartment) flies open				
Technician Response:				
Maint Req Status: Completed				
Pillsbury: Carrier Front Seal	\$95.33			
Kit O5G A/C Compressor				
MCID4500: 16L-2-112 (1.000)				
Pillsbury: Freon R134A per	\$41.56			
Lb.: R134A (17.835)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (7.28)		\$364.00		
Labor Comments: 41 -- A/C is not functioning ---- Closed off the A/C compressor. Reclaimed the freon. Removed the clutch assy. and the front seal. Cleaned up everything. Installed a new seal assy. Vacuummeddown the compressor. Opened the valves back up and filled the system back up with freon.				
72 -- back door (engine compartment) flies open ---- the release lever needs to be pulled back out in order to hold the door shut.				
Miscellaneous Labor		\$0		
Other			\$0	
HUB:Hub Service	\$0.57	\$141.50	\$0.00	\$142.07
Work Comments: HUB -- Hub Service				
Pillsbury: Oil Gear 80W-140	\$0.57			
Synthetic Mobil Delvac: Gear				
oil 80W-140 in pints (1.500)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (2.83)		\$141.50		
Labor Comments: HUB -- Hub Service ---- Drained then refilled with new gear lube, the tag and steering hubs				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$137.46	\$505.50	\$0
			\$40.00	<u>\$682.96</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 816,416.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217391	06/07/2018	06/13/2018	Closed	0.00	

Description: DOT,Hub leak,tire,CFR,suspension

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
12:Axles (rear)		\$9.17	\$126.50		\$0.00	\$135.67
Work Comments: 12 -- Right drive axle leaking Gear oil						
Pillsbury: Gasket Rear Axle		\$3.77				
Flange: GKT1008 (1.000)						
Pillsbury: Oil Gear Synthetic:		\$5.40				
Oil Gear 75W-90 BULK in						
quarts (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (2.53)			\$126.50			
Labor Comments: 12 -- Right drive axle leaking Gear oil ---- Pulled the axle out. Installed a new axle gasket and 2 new cones. Torqued to specs.						
9461 - BRIERCLIFFE,			\$0.00			
WILLIAM (0.00)						
Miscellaneous Labor			\$0			
Other					\$0	
21:Suspension		\$0	\$494.00		\$0.00	\$494.00
Work Comments: 21 -- Suspension = Drive axle v-Link shot						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (7.18)			\$359.00			
Labor Comments: 21 -- Suspension = Drive axle v-Link shot ---- Put up on lifts. and Jack stands.						

Pulled the old v-link out and installed a new one. Had to re tape one of the 3/4 " bolt holes.

9461 - BRIERCLIFFE, WILLIAM (2.70)		\$135.00			
Miscellaneous Labor		\$0			
Other				\$0	
22:Tires		\$0	\$137.00	\$0.00	\$137.00
Work Comments: 22 -- Tire leaking at the valve stem.					
Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (1.39)		\$69.50			
Labor Comments: 22 -- Tire leaking at the valve stem. ---- Pulled the tire off the us. Dismounted the tire and installed a new valve stem. Mounted back on the bus and torqued the lug nuts to 450 LBS.					
9461 - BRIERCLIFFE, WILLIAM (1.35)		\$67.50			
Miscellaneous Labor		\$0			
Other				\$0	
CFR:Coolant Filter Replacement	\$32.01	\$31.50		\$0.00	\$63.51
Work Comments: CFR -- Coolant filter replacement.					
Pillsbury: Filter Coolant w/Full	\$32.01				
Charge MCI D4500 w/ Detroit					
60 Series Engine: 4088					
(1.000)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (0.63)		\$31.50			
Labor Comments: CFR -- Coolant filter replacement. ---- Removed and replaced the coolant filter.					
Miscellaneous Labor		\$0			
Other				\$0	
DO:DOT Inspection	\$2.00	\$76.50		\$0.00	\$78.50
Work Comments: DOT -- DOT Inspection					
DOT sticker \$2.00 (1.000)	\$2.00				
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (1.53)		\$76.50			
Labor Comments: DOT -- DOT Inspection ---- Performed the DOT inspection as per the attached sheet.					
9461 - BRIERCLIFFE, WILLIAM (20.47)		\$0.00			
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$43.18	\$865.50	\$0	\$0
					<u>\$908.68</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 816,768.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217585	06/25/2018	06/26/2018	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
11:Axles (front)		\$0	\$10.00		\$0.00	\$10.00

Maintenance Requested: 62508 - 06/20/2018 - Rt front hub oil leaking-drivers side moulding lse

Requestor Notes: passenger side front hub oil seal is leaking  
moulding behind the front drivers side wheel at bottom of bus is barely hanging on

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$10.00			
(0.20)					

Labor Comments: Checked the front hubs, Both full of fluid. Cleaned them off.

Snapped back on the moulding the best I could, needs to go to the body shop.

Miscellaneous Labor	\$0				
Other				\$0	



\$0      \$0      \$10.00      \$0      \$0      \$10.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 817,804.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217847	07/16/2018	07/17/2018	Closed	0.00	

Description: Front Leveling Valve

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$6.28	\$62.50		\$0.00	\$68.78

Maintenance Requested: 62628 - 07/14/2018 - the bus is stuck in kneel mode

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Valve ASM, Leveling,

\$6.28

RH: 12-06-1028 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$62.50

(1.25)

Labor Comments: Front leveling valve rubber holder broke off. Put new one on.

Miscellaneous Labor

\$0

Other

\$0

\$0      \$6.28      \$62.50      \$0      \$0      \$68.78

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 818,302.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217996	07/25/2018	07/25/2018	Closed	0.00	

Description: Lighting

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 62698 - 07/24/2018 - lav light is out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: needs new microswitch, rigged it so it would work

Miscellaneous Labor

\$0

Other

\$0

36:Lighting      \$42.56      \$267.50      \$0.00      \$310.06

Maintenance Requested: 62662 - 07/19/2018 - left side turn signal-mid out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Non LED

\$42.56

Amber Side Marker/Turn MCI

EL3: 07-07-1003 (2.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$267.50

(5.35)

Labor Comments: replaced 2 side marker lamps

Miscellaneous Labor

\$0

Other

\$0

\$0 \$42.56 \$267.50 \$0 \$0 \$310.06

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 818,884.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218089	07/30/2018	08/01/2018	Closed	0.00	

Description: Leaking Hub, Air Filter

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
12:Axles (rear)		\$56.65	\$46.50		\$0.00	\$103.15

Maintenance Requested: 62724 - 07/27/2018 - leaking rear hub

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Oil Bulk in Quarts:

\$16.56

Oil 15W-40 Bulk (8.000)

Pillsbury: Oil Gear 80W-140

\$0.38

Synthetic Mobil Delvac: Gear

oil 80W-140 in pints (1.000)

Pillsbury: Hub Cap w/ Lube

\$39.71

Window Steer Axle MCI

D4500: 343-4176 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$46.50

(0.93)

Labor Comments: Replaced the hub cap that was leaking. Refilled with 80-140.

Checked engine oil found it 8 qts low.

Miscellaneous Labor

\$0

Other

\$0

79:Lavatory

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 62723 - 07/27/2018 - bathroom stinks

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: Next time let the Wash Stall know.

Miscellaneous Labor

\$0

Other

\$0

AF:Air Filter Replacement

\$33.98

\$0

\$0.00

\$33.98

Pillsbury: Filter Air EL3: 6774

\$33.98

(1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: Replaced air filter.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$90.63 \$46.50 \$0 \$0 \$137.13

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 819,088.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218142	08/01/2018	08/03/2018	Closed	0.00	

Description: PMI

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

5/7/2019

## Work Order Detail

20:Steering	\$94.65	\$79.00	\$0.00	\$173.65
Pillsbury: Draglink End LH	\$94.65			
EL3 MCI: 11-04-1006 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$79.00		
(1.58)				
Labor Comments: Replaced drag link on the steering shaft.				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$36.03	\$75.00	\$0.00	\$111.03
Pillsbury: Clip Rod:	\$1.74			
03-31-1100 (1.000)				
Pillsbury: Latch Rotary:	\$34.29			
03-27-1074 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$75.00		
(1.50)				
Labor Comments: Replaced e window latch.				
Replaced broken clip rod.				
Replaced 3 reading lights.				
Steam clean.				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$106.21	\$101.00	\$0.00	\$207.21
Headlights: high/low beam:Pass		Horn:Pass		Leaks:Pass
Turn signals:Pass				
Pillsbury: Spring Gas R. Hand	\$61.30			
Locking Radiator Door MCI				
D4500: 03-31-2819 (1.000)				
Pillsbury: Spring-Gas Helper	\$44.58			
L. Hand Radiator Door MCI				
D4500: 3L-31-948 (1.000)				
Pillsbury: Light Bulb Pass.	\$0.33			
Sevice Module 28V 10W:				
03-08-1162 (3.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$101.00		
(2.02)				
Labor Comments: PMI				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$236.89	\$255.00	\$0
			\$0	\$0
				<u>\$491.89</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 819,329.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218385	08/14/2018	08/16/2018	Closed	0.00	

Description: A./C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$69.00		\$0.00	\$69.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$69.00			
(1.38)						
Labor Comments: Cleaned engine off, searched for the engine leak, could not find it. Possibly the oil pan gasket.						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$254.04	\$153.00		\$0.00	\$407.04
Maintenance Requested: 62818 - 08/11/2018 - front ac is weak						
Requestor Notes:						

## Technician Response:

Maint Req Status: Completed

Pillsbury: Valve, Electric \$164.99  
 Unloader: 10610656 (1.000)  
 Pillsbury: Coil 24 Volt A/C \$55.75  
 Comp. Unloader Valve MCI  
 D4500: 16L-10-107 (1.000)  
 Pillsbury: Freon R134A per  
 Lb.: R134A (10.000) \$33.30  
 Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$153.00  
 (3.06)

Labor Comments: A/C not worknig sufficently. Found leak at the one unloader base. Replaced the base  
 and the electric unloader. Added 10 pounds of freon.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$254.04 \$222.00 \$0 \$0 \$476.04

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 819,925.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218570	08/22/2018	08/28/2018	Closed	0.00	

Description: Body Misc

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$1.00		\$0.00	\$1.00

Maintenance Requested: 62876 - 08/20/2018 - See Notes

Requestor Notes: Driver Side 1st &amp; Middle bay doors trim pieces are loose

Doorside 1st seat floor side tile peeled off.

## Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$1.00  
 (0.02)

Labor Comments: I glued the side piece inside up the other day. I let the body shop know about the  
 baggage door trim pieces

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$1.00 \$0 \$0 \$1.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 820,284.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218626	08/24/2018	08/28/2018	Closed	0.00	

Description: FF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$0	\$51.00		\$0.00	\$51.00

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$51.00  
 (1.02)

Labor Comments: Checked fluids. took for test drive. Camshaft seal is leaking pretty bad.

Miscellaneous Labor \$0  
 Other \$0

FF:Fuel Filter		\$8.53	\$35.00		\$0.00	\$43.53
Pillsbury: Filter Fuel: 3118		\$4.19				
(1.000)						

5/7/2019

## Work Order Detail

Pillsbury: Filter, Fuel, MCI:  
3120 (1.000)

\$4.34

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW  
(0.70)

\$35.00

Labor Comments: FF

Miscellaneous Labor

\$0

Other

\$0

\$0	\$8.53	\$86.00	\$0	\$0	<u>\$94.53</u>
-----	--------	---------	-----	-----	----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 820,462.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218815	09/05/2018	09/10/2018	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$164.00		\$0.00	\$164.00
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (3.28)			\$164.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$164.00	\$0	\$0	<u>\$164.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 820,940.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219122	09/20/2018	09/25/2018	Closed	0.00	

Description: Bag Bay Handle

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$103.32	\$80.00		\$0.00	\$183.32
Maintenance Requested: 63085 - 09/19/2018 - see comment						
Requestor Notes: door side luggage door will not lock when driving down road it stays open						
Technician Response:						
Maint Req Status: Completed						
03-29-1232 bushing long (1.000)		\$10.54				
03-29-1168D handle (1.000)		\$92.78				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.60)			\$80.00			
Labor Comments: Bag bay handle was busted. Tried to use on from the junk bus. No go. Ordered one from C&J.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$103.32	\$80.00	\$0	\$0	<u>\$183.32</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 821,420.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219187	09/24/2018	09/24/2018	Closed	0.00	

Description: Heating, Air Drier

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$11.50		\$0.00	\$11.50
Maintenance Requested: 63121 - 09/22/2018 - see comments						
Requestor Notes: thermostat doesn't work properly in front. It keeps full heat on no matter the temp setting						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.23)			\$11.50			
Labor Comments: Heat valve for the driver was on. The control valve looks to have been rebuilt not to long ago.						
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$165.48	\$123.50		\$0.00	\$288.98
Pillsbury: AD-IP Air Dryer		\$54.40				
Desiccant Cartridge Bendix: 109493BXR (1.000)						
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$77.16				
Pillsbury: Mounting Bracket Bendix AD-9 Air Dryer: 107695K (1.000)		\$33.92				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.47)			\$123.50			
Labor Comments: Rebuilt air drier. Went to take off the bracket the nut stripped on, ended up cutting bracket off and replacing it.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$165.48	\$135.00	\$0	\$0	\$300.48

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 821,420.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219254	09/26/2018	09/28/2018	Closed	0.00	

Description: fix back dork damage

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$589.50		\$0.00	\$589.50
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (11.79)			\$589.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$589.50	\$0	\$0	\$589.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 825,400.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219870	10/25/2018	11/26/2018	Closed	0.00	

Description: service call,PMI, LOF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$585.00		\$0.00	\$585.00

Maintenance Requested: 63408 - 10/24/2018 - bad engine oil leak

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0		
0081 - WOLF, PATRICK		\$585.00		
Labor Comments: 40 -- Bad engine oil leak ---- Steamed off the engine. ran the engine to find where the oil was coming from. Removed the air cleaner housing and all the intake pipes above the front of the engine. Opened the floor hatch. pulled both halves of the rocker off. cleaned up all around the seal area. Steamed off the rocker covers. Cleaned up the gaskets. Put new RTV in the corners. Torqued the cover bolts to specs. Put everything else back together.				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine		\$0	\$29.00	\$0.00 \$29.00
Maintenance Requested: 63406 - 10/24/2018 - noticed an old & new puddle of oil once bus moved				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts		\$0		
0081 - WOLF, PATRICK (0.58)		\$29.00		
Labor Comments: 40 -- Noticed an old & a new puddle of oil once the bus was moved. ---- Most of the work done on detail 40 above.				
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling		\$339.29	\$456.50	\$0.00 \$795.79
Work Comments: 43 -- Water pump leaking				
R23539929 water pump (1.000)		\$339.29		
Miscellaneous Parts		\$0		
0081 - WOLF, PATRICK (9.13)		\$456.50		
Labor Comments: 43 -- Water pump leaking ---- Removed and replaced the water pump.				
Miscellaneous Labor		\$0		
Other			\$0	
95:Service Calls		\$0	\$50.00	\$0.00 \$50.00
Miscellaneous Parts		\$0		
9461 - BRIERCLIFFE, WILLIAM (1.00)		\$50.00		
Labor Comments: Driver had called saying the bus felt as though it was bucking, swapped it out with 5525, driving 526 back i noticed on decel that once it down shifted from 3rd to 2nd that the bus would buck forward and the driver also mentioned that the red trans light was on at one point.				
Miscellaneous Labor		\$0		
Other			\$0	
LOF:Lube, Oil, Filter		\$0	\$300.00	\$0.00 \$300.00
Work Comments: LOF -- Lube, Oil, Filter				
Miscellaneous Parts		\$0		
0081 - WOLF, PATRICK (6.00)		\$300.00		
Labor Comments: LOF -- Lube, Oil, Filter ---- Performed the lof as per the attached sheet.				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection		\$0	\$138.50	\$0.00 \$138.50
Work Comments: PMI -- Preventative Maintenance Inspection.				
Headlights: high/low beam:Pass	Horn:Pass		Leaks:Pass	
Turn signals:Pass				
Miscellaneous Parts		\$0		
0081 - WOLF, PATRICK (2.77)		\$138.50		
Labor Comments: PMI -- Preventative Maintenance Inspection. ----- Performed the PMI as per the attached sheet.				
Miscellaneous Labor		\$0		
Other			\$0	
PU:Pick-up & Delivery		\$0	\$66.50	\$0.00 \$66.50
Miscellaneous Parts		\$0		
0150 - BERNARDY, ADAM (1.33)		\$66.50		

Labor Comments: Drove 5522 up to air port and switched it out for this one. brought 5526 back to the shop do to check engine light and def light.

Miscellaneous Labor

\$0

Other

\$0

\$0      \$339.29      \$1,625.50      \$0      \$0      \$1,964.79

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 825,261.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219999	11/01/2018	11/06/2018	Closed	0.00	

Description: Webasto Tune Up

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$135.50		\$0.00	\$135.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.71)			\$135.50			

Labor Comments: Webasto Tune Up

Miscellaneous Labor

\$0

Other

\$0

\$0      \$0      \$135.50      \$0      \$0      \$135.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 825,400.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220034	11/05/2018	11/06/2018	Closed	0.00	

Description: Transmission

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$0	\$59.00		\$0.00	\$59.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.18)			\$59.00			

Labor Comments: Checked codes found codes for output sensor.

Replaced the output sensor with used one from a previous tranny.

Took for test drive, still shifted a little hard.

Reset the Fast Adaptive and Unadaptive shifts.

Started to shift better as I went thru the gears.

Checked Transmission Fluid.

Miscellaneous Labor

\$0

Other

\$0

\$0      \$0      \$59.00      \$0      \$0      \$59.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 826,202.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220298	11/15/2018	11/19/2018	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$21.00		\$0.00	\$21.00

Maintenance Requested: 63520 - 11/10/2018 - lever for holding tank was frozen-not dumped

Requestor Notes:

Technician Response:

Maint Req Status: Completed



Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (0.42)		\$21.00				
Labor Comments: 79 -- lever for holding tank was frozen-not dumped ---- Dumped the toilet before I started to do the engine work.						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$0	\$21.00	\$0	\$0	<u>\$21.00</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 826,339.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220943	12/13/2018	12/19/2018	Closed	0.00	

Description: repair and paint two doors back with molding winged

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$1,027.50		\$0.00	\$1,027.50
Miscellaneous Parts		\$0				
9106 - MARIN RODRIGUEZ, CLAUDIO (20.55)			\$1,027.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$1,027.50	\$0	\$0	<u>\$1,027.50</u>

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 826,339.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221037	12/18/2018	01/03/2019	Closed	0.00	

Description: Creep

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$80.26	\$106.00		\$0.00	\$186.26
04-02-1002 brake chamber (1.000)		\$80.26				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.12)			\$106.00			
Labor Comments: Replaced the left front chamber, it was rotting out.						
Miscellaneous Labor			\$0			
Other					\$0	
20:Steering		\$0	\$182.50		\$0.00	\$182.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.65)			\$182.50			
Labor Comments: Steer tires wearing on the inside edge. Found the toe was 1/4 inch out when it should be 1/16-1/8 in. Lubed and broke the tie rod tube loose. Adjusted to 1/16 inch in.						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$60.00	\$82.50		\$0.00	\$142.50
Pillsbury: Wiper Blade MCI EL3: 03-34-1177 (2.000)		\$60.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.65)			\$82.50			
Labor Comments: Checked Fluids Changed wiper blades out Creeped bus and made list.						
Miscellaneous Labor			\$0			

Other

\$0

\$0	\$140.26	\$371.00	\$0	\$0	<u>\$511.26</u>
-----	----------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 827,588.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221638	01/17/2019	01/23/2019	Closed	0.00	

Description: hard shift

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$107.34	\$250.00		\$0.00	\$357.34
29544139 Sensor Assembly, Speed, Rear Output (1.000)		\$107.34				
Miscellaneous Parts		\$0				
0142 - GALLINGER, CHAD (5.00)			\$250.00			

Labor Comments: Had code 22-16 and 23-12 replaced out put speed sensor cleaned connections at shift selector , TCM and VIM road tested o/k

Miscellaneous Labor		\$0				
Other					\$0	

\$0.00	\$107.34	\$250.00	\$0	\$0	<u>\$357.34</u>
--------	----------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 828,028.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221977	02/01/2019	02/01/2019	Closed	0.00	

Description: Brake line broken

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$38.75	\$111.50		\$0.00	\$150.25

Maintenance Requested: 64229 - 01/29/2019 - pass side front air line leaking

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Hose ASM, Front	\$38.75
Brakes E-Coach: 04-20-1040 (1.000)	

Part Comments: 13 --

Miscellaneous Parts	\$0
0081 - WOLF, PATRICK (2.23)	\$111.50

Labor Comments: 13 -- Right front brake hose broken ---- Removed and replaced the brake hose. tid all bake up again.

Miscellaneous Labor	\$0
Other	\$0

\$0	\$38.75	\$111.50	\$0	\$0	<u>\$150.25</u>
-----	---------	----------	-----	-----	-----------------

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 828,518.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222203	02/11/2019	02/15/2019	Closed	0.00	

Description: steering noise

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

5/7/2019

## Work Order Detail

20:Steering	\$0	\$69.00	\$0.00	\$69.00
Maintenance Requested: 64383 - 02/09/2019 - See comments.				
Requestor Notes: 1. Power steering makes a lot of grinding noises.				
2. Driver-side window frosts over.				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0142 - GALLINGER, CHAD (1.38)		\$69.00		
Labor Comments: checked steering topped off fluid test drove bus. no steering issues at this time				
adjusted fan to blow on window				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$0	\$69.00	\$0
			\$0	\$69.00

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 830,803.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222619	02/27/2019	03/01/2019	Closed	0.00	

Description: Fuel door locked.

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$3.80	\$21.50		\$0.00	\$25.30

Maintenance Requested: 64476 - 02/16/2019 - Fuel door would not unlock - tried all 3 keys.

Requestor Notes:

Technician Response: 72 -- Fuel door would not unlock - tried all 3 keys.

Maint Req Status: Completed

Pillsbury: Holder cup w/  
mounting screws black:  
TH2BLK (2.000)

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (0.43) \$21.50

Labor Comments: 72 -- Fuel door would not unlock - tried all 3 keys. ---- The fuel door unlock for me  
with the same key that opens the battery switch. Must have been frozen.

Miscellaneous Labor \$0

Other \$0

\$0 \$3.80 \$21.50 \$0 \$0 \$25.30

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 831,756.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222722	03/05/2019	03/08/2019	Closed	0.00	

Description: service call

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
95:Service Calls		\$0	\$85.00		\$0.00	\$85.00

Miscellaneous Parts \$0

9461 - BRIERCLIFFE,  
WILLIAM (1.70) \$85.00

Labor Comments: called out for service call for the tranny being stuck in second gear, went out in service  
truck and cleared the codes and got it up and moving.

Miscellaneous Labor \$0

Other \$0

\$0 \$0 \$85.00 \$0 \$0 \$85.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 834,497.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223705	04/12/2019	04/22/2019	Closed	0.00	

Description: Interior lights, fog lights

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$0	\$10.00		\$0.00	\$10.00

Maintenance Requested: 64954 - 03/26/2019 - Transmission cut off twice

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0	\$10.00			
2138 - KREJCE, LUCAS			\$10.00		

Labor Comments: Pat drove had no issues, checked fluid and it was good

Miscellaneous Labor		\$0			
Other					\$0

36:Lighting		\$21.15	\$58.50		\$0.00	\$79.65
-------------	--	---------	---------	--	--------	---------

Maintenance Requested: 65082 - 04/09/2019 - see comments

Requestor Notes: bathroom light switch does not work

isle lights out (one on each side)

fog lights dont work

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Bulb 12 Volt	\$21.15				
Mini Fog/Driving: BP1255/H3					
(3.000)					

Miscellaneous Parts	\$0	\$58.50			
2138 - KREJCE, LUCAS			\$58.50		

Labor Comments: Added two new florescent bulbs inside for isle walkway. Put two new low beam fog lights in and one new bright fog light in.

Miscellaneous Labor		\$0			
Other					\$0

40:Engine		\$11.30	\$12.50		\$0.00	\$23.80
-----------	--	---------	---------	--	--------	---------

Maintenance Requested: 65104 - 04/12/2019 - Needs oil badly!

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Oil Bulk in Quarts:	\$11.30				
Oil 15W-40 Bulk (5.000)					
Miscellaneous Parts	\$0	\$12.50			
2138 - KREJCE, LUCAS			\$12.50		

Labor Comments: Added just under 5 quarts of oil to bus

Miscellaneous Labor		\$0			
Other					\$0

\$0	\$32.45	\$81.00	\$0	\$0	\$113.45
-----	---------	---------	-----	-----	----------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 835,542.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223907	04/20/2019	04/22/2019	Closed	0.00	

Description: coolant low

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
43:Cooling		\$17.58	\$67.50		\$0.00	\$85.08

Maintenance Requested: 65203 - 04/20/2019 - Shut down a couple times; check anti-freeze?

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Fluid Coolant Bulk \$17.58  
 50/50 After Dilution: A/F 50/50  
 Green BULK (3.000)  
 Miscellaneous Parts \$0  
 (1.35) \$67.50

Labor Comments: bring bus over and check coolant level is not in sight glass fill and found was 3.5 low  
 test cap and is fine look for leaks and found none trailer hook up

Miscellaneous Labor \$0  
 Other \$0

\$0 \$17.58 \$67.50 \$0 \$0 \$85.08

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 835,968.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223967	04/22/2019		Completed	0.00	

Description: no heat

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
95:Service Calls		\$0	\$51.50		\$0.00	\$51.50
Miscellaneous Parts (1.03)		\$0				
			\$51.50			

Labor Comments:

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$51.50 \$0 \$0 \$51.50

## 5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 836,653.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
224167	04/30/2019		In Progress	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 65225 - 04/24/2019 - foot throttle sticks. holds at 1500 rpm sometimes

Requestor Notes:

Technician Response:

Maint Req Status: Requested

Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
20:Steering		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
FF:Fuel Filter		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$0	\$57.50		\$0.00	\$57.50
Miscellaneous Parts		\$0				

5/7/2019

Work Order Detail

0081 - WOLF, PATRICK (1.15)			\$57.50			
Miscellaneous Labor			\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Headlights: high/low beam:Pass	Horn:Pass			Leaks:Pass		
Turn signals:Pass						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
PS:Power Steering Flush		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$57.50	\$0	\$0	<u>\$57.50</u>