

Email:

Work Order Detail**5527: 1998 MCI EL3**

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 373,730.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
781	01/31/2012	05/21/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
43 - Hoglund Bus & Truck Co., Inv. # 4760, PO # 5527, Desc: Prep and paint Complete Black					\$5,630.00	\$5,630.00
211 - Radio Eningeering Industries, Inv. # 327656, PO # 050112, Desc: Advanced Control Head, Hybrid					\$519.03	\$519.03
159 - Sardo Bus & Coach Upholstery, Desc: Complete new interior					\$10,067.24	\$10,067.24
11:Axles (front)		\$173.59	\$0		\$0.00	\$173.59
Pillsbury: King Pin Kit EL3/ D4500 MCI: 01-01-1079 (1.000)		\$173.59				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
11:Axles (front)		\$478.88	\$277.50		\$0.00	\$756.38
Work Comments: strip down front axle, removing brakes, hubs and spindles to replace king pins.						
Pillsbury: King Pin Kit EL3/ D4500 MCI: 01-01-1079 (1.000)		\$373.54				
Pillsbury: Bearing Front Wheel Outer MCI D4500: 555STRB (1.000)		\$25.30				
Pillsbury: Bearing Race Front Wheel Inner MCI D4500: 6420TRB (1.000)		\$27.75				
Pillsbury: Bearing Front Wheel Inner MCI D4500: 6461ATRB (1.000)		\$52.29				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (5.55)			\$277.50			
Miscellaneous Labor			\$0			
Other					\$0	
12:Axles (rear)		\$641.64	\$0		\$0.00	\$641.64
Pillsbury: Ring Exciter: 02-01-1081 (2.000)		\$605.10				
Pillsbury: Gear Lube: Oil Gear 80W-90 BULK in Pints (21.000)		\$36.54				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	

13:Brakes	\$1,389.96	\$0	\$0.00	\$1,389.96
Pillsbury: Pad Fitting Kit; 1 per axle; EL3: 04-01-1008 (2.000)	\$123.78			
Pillsbury: Pads brake EL3: 04-01-1019 (2.000)	\$378.00			
Pillsbury: Rotor EL3: 15-02-1010 (4.000)	\$888.18			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
13:Brakes	\$230.98	\$0	\$0.00	\$230.98
Pillsbury: Type 24 3" I/s Brake chamber: 1428001 (2.000)	\$115.26			
Pillsbury: Bushing Slack Adjuster: E2307 (6.000)	\$5.16			
Pillsbury: Sensor, ABS, 90, Brake (gillig also): R955342 (2.000)	\$105.36			
Pillsbury: Hub Bolt; MCI EL3 (10 per wheel): 15-02-1009 (10.000)	\$5.20			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
13:Brakes	\$70.13	\$485.50	\$0.00	\$555.63
Work Comments: measured and trimmed pushrod on new front chambers.; tag chambers--rebuild service brake portion, measure and cut pushrods, install. Adjust brakes.				
Pillsbury: Yoke 5/8x1/2(2.20)	\$19.90			
MCI EL3: 8292017P (2.000)				
Pillsbury: Yoke 5/8x1/2(2.20)	\$19.90			
MCI EL3: 8292017P (2.000)				
Pillsbury: Bearing Race Drive Axle Inner MCI D4500: 592A (1.000)	\$30.33			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (9.71)		\$485.50		
Miscellaneous Labor		\$0		
Other			\$0	
16:Drive Train	\$876.87	\$119.50	\$0.00	\$996.37
Work Comments: splines worn on drive shaft, removed and sent to Catco for new shaft to be made; Gathered all serial numbers from bus, engine and trans for records. installed new prop shaft, greased and torqued 135ftlbs.				
Rebuild Driveshaft (1.000)	\$806.93			
Part Comments: Re-built by Catco.				
Pillsbury: Seal Frt. MCI EL3: 380048A (2.000)	\$69.94			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (2.39)		\$119.50		
Miscellaneous Labor		\$0		
Other			\$0	
20:Steering	\$156.34	\$0	\$0.00	\$156.34
Pillsbury: Draglink End RH EL3 MCI: 11-04-1005 (1.000)	\$78.17			
Pillsbury: Draglink End LH EL3 MCI: 11-04-1006 (1.000)	\$78.17			
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
20:Steering	\$2,198.83	\$1,483.50	\$0.00	\$3,682.33
Work Comments: reassemble king pins and install on axle; torched all 10 bolts from RF hub asm. tag pins time consuming--drill, heat and beat the spindles , torch cut king pin out of rt tag.				
Pillsbury: Steering Centering Cylinder: 11-06-1001 (1.000)	\$2,198.83			
Miscellaneous Parts	\$0			

74 - PHIPPS, KEVIN (28.52)		\$1,426.00		
0146 - SHIPPY, CURTIS (1.15)		\$57.50		
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$1,244.04	\$0	\$0.00	\$1,244.04
Pillsbury: Bushing- Radius	\$390.00			
Rod, EL3: 12-05-1002 (4.000)				
Pillsbury: Bushing-Sway Bar,	\$121.44			
EL3: 12-05-1012 (16.000)				
Pillsbury: End Bushing EL3	\$254.30			
MCI: 12-05-1013 (2.000)				
Pillsbury: Apex Bushing EL3	\$145.58			
MCI: 12-05-1019 (1.000)				
Pillsbury: Shock Absorber	\$332.72			
Front EL3 MCI: 12-05-1170				
(2.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$0	\$683.00	\$0.00	\$683.00
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (13.66)		\$683.00		
Miscellaneous Labor		\$0		
Other			\$0	
22:Tires	\$0	\$51.00	\$0.00	\$51.00
Work Comments: install same drive tires; put new valve stem in LRI.				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (1.02)		\$51.00		
Miscellaneous Labor		\$0		
Other			\$0	
27:Wheels, Rims, Hubs & Mounts	\$216.14	\$1,246.00	\$0.00	\$1,462.14
Work Comments: clean bearings and reassemble hub to spindle, balance tire and put on bus.				
2/13--spent morning getting siezed keepers out of king pin on left tag--drill, hammer, heat.....				
Pillsbury: Gasket Rear Axle	\$7.30			
Flange: GKT1008 (2.000)				
Pillsbury: Gear Lube: Oil Gear	\$5.22			
80W-90 BULK in Pints				
Pillsbury: Seal Rear Drive Axle	\$63.74			
MCI/Freightliner/Gillig/B.B. Q-				
Bus: 380003A (2.000)				
Pillsbury: Seal Frt. MCI EL3:	\$139.88			
380048A (4.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (24.92)		\$1,246.00		
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$1,886.23	\$1,109.00	\$0.00	\$2,995.23
Work Comments: check and change interior lighting, 3 ballasts to check..put in 6 ballasts and all new lights; 2 reading lights; change out Rt headlight asm and cornering light.				
Pillsbury: Lens, Overhead	\$9.49			
light, MCI: 03-08-1169 (1.000)				
Pillsbury: Headlight RH MCI	\$347.05			
EL3: 07-07-1008 (1.000)				
Pillsbury: Lamp-Combined,	\$28.57			
Front, RH: 07-07-1010 (1.000)				
Pillsbury: Light Lamp Rear	\$352.10			
Stop 12v LED: 07-07-1017				
(2.000)				
Pillsbury: Lens High Mount:	\$22.12			
07-07-1050 (2.000)				
Pillsbury: Gasket Cover:	\$4.08			
07-07-1051 (2.000)				
Young Building: L.E.D. Green,	\$14.58			
Single Chip: 19-11-2087				

(3.000)				
Young Building: Light LED W/	\$59.10			
S Wash Illumination Bulb MCI				
D4500: 19-11-2088 (15.000)				
Pillsbury: Light Red Marker,	\$40.12			
EL3: 07-07-1013 (1.000)				
Pillsbury: LED Tail Light	\$490.00			
Conversion Kit for EL3:				
M1-00642 (1.000)				
Pillsbury: Switch Hazard, EL3:	\$30.47			
07-19-1023 (1.000)				
Pillsbury: Ballast Interior Light	\$405.78			
EL3: 07-07-1040 (6.000)				
Pillsbury: Light Bulb	\$82.77			
Fluorescent 32 Watt T8 48" Bi-				
Pin: F32/741/ECO (31.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (18.60)		\$930.00		
6030 - STRICKER, DJ (3.58)		\$179.00		
Labor Comments: Installed new tail light LEd kit				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$122.95	\$125.00	\$0.00	\$247.95
Pillsbury: Gasket Oil Pan:	\$29.67			
08929102 (1.000)				
Pillsbury: Isolator, Oil Pan Bolt	\$31.30			
Detroit: 23517242 (10.000)				
Pillsbury: Belt EL3:	\$61.98			
08-27-1002 (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (2.50)		\$125.00		
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$55.41	\$0	\$0.00	\$55.41
Pillsbury: Oil Cooler Gasket	\$25.63			
Kit: 23537789 (1.000)				
Pillsbury: Filter Air EL3: 6774	\$29.78			
(1.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$80.29	\$310.00	\$0.00	\$390.29
Work Comments: overhaul oil cooler/filter head asm.				
Pillsbury: Oil: Oil 15W-40	\$80.29			
BULK (37.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (6.20)		\$310.00		
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$3,667.09	\$1,021.00	\$0.00	\$4,688.09
Work Comments: 2/1--Remove r/s evap motor asm; remove lids and covers;				
discard worn brushes, clean squirrel cages and blow dust out of motors; clean out				
dirt from evap compartment.				
2/2--continue with motor removal and cleaning and brushes;				
new brushes in c/s evap motor; remove one cond motor for repair.				
2/3--check and clean defroster system, clean filters--OK				
2/8==went through parts with bobl, needed tubes and exhaust pipe for aux heater				
either not available or long lead time--up to someone else to decide.....				
2/23 installed repaired cond motor, attach wires and shroud asm				
2/27 installed aux heater, make brackets and supports.				
Pillsbury: Hose Elbow, 1.375	\$60.72			
to 1.5: 16-11-1017 (2.000)				
Pillsbury: Hose, Aux Heater:	\$37.15			
16-11-1019 (1.000)				
Pillsbury: ? Auxiliary Heater Kit:	\$2,548.20			

16-16-1102 (1.000)				
Pillsbury: Filter Frame, Main	\$134.13			
Evap, EL3: 16-06-1093				
Pillsbury: Filter, Main Evap,	\$6.95			
EL3: 16-06-1094 (1.000)				
Rebiuld Carrier Motor	\$751.96			
Tag#415 (1.000)				
Pillsbury: Brush Condensor/	\$69.04			
Evaporator Fan Motor MCI				
D4500: 16G-8-64XCG (8.000)				
Pillsbury: Filter Dryer EL3:	\$58.94			
16-04-1004 (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (20.42)		\$1,021.00		
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$216.00	\$386.00	\$0.00	\$602.00
Work Comments: Warmed bus, A/C started but turned off , hooked up guages and found system almost empty of freon. Pressurized with nitrogen and looked for leaks, found lower sight glass on reciever tank leaking. Bled pressure off and removed sight glass, cleaned, installed with thread sealer and rechecked--did not leak. Vacuumed down system. Filled system with R134a--24 lbs. Ran and found system to work very well.				
Pillsbury: Freon R134A per	\$216.00			
Lb.: R134A (24.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (7.72)		\$386.00		
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$393.88	\$377.00	\$0.00	\$770.88
Work Comments: drain cooling system, open radiator compartment to gain access to aux heater and oil cooler/filter head.				
Used Wabasto Exhaust Pipe	\$125.00			
16-16-1013U (1.000)				
Pillsbury: Tube Supply,	\$58.48			
Coolant: 16-11-1330 (1.000)				
Young Building: Coolant Pipe,	\$169.59			
Wabasto, EL3: 16-11-1155				
(1.000)				
Pillsbury: Fluid Anti Freeze (gal	\$39.95			
jug): A/F Full Strength 100% Gr				
(5.000)				
Pillsbury: Exhaust Clamp 3":	\$0.86			
51730050 (1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (7.54)		\$377.00		
Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$138.21	\$0	\$0.00	\$138.21
5001247K Drier Mtg. Bracket	\$56.49			
(1.000)				
Pillsbury: Heater Kit 24V ADIP	\$71.14			
Air Dryer: 109496BXW (1.000)				
Pillsbury: Pigtail Heater for	\$10.58			
Bendix AD-9 Air Dryer:				
109869N (1.000)				
Miscellaneous Parts	\$0			
Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$38.13	\$246.50	\$0.00	\$284.63
Pillsbury: Valve Pressure	\$38.13			
Protection 70 PSI: 288323				
(1.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (4.93)		\$246.50		
Miscellaneous Labor		\$0		

Other			\$0	
50:Accessories	\$126.09	\$547.00	\$0.00	\$673.09
Work Comments: check all pass call lights and reading lights				
Pillsbury: Valve Air, Passenger:	\$46.53			
03-08-1155 (9.000)				
Pillsbury: Cap End:	\$79.56			
03-08-1156 (6.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (10.94)		\$547.00		
Miscellaneous Labor		\$0		
Other			\$0	
70:Body Sheet Metal	\$778.55	\$12,722.00	\$0.00	\$13,500.55
Young Building: Seat Bostrom	\$675.00			
Driver's: 2345039-900 (1.000)				
03-15-3921 Extrusion-Vinyl	\$96.55			
Heat duct (5.000)				
19-05-0262 Plastic Bearing	\$7.00			
MCI (50.000)				
Miscellaneous Parts	\$0			
71 - KLINGBERG, KENNY (84.72)		\$4,236.00		
Labor Comments: Sanded body, took out seats, tore out floor, helped install floor, fixed dents, removed glue, took out vents, sand blasted vents, painted vents, fixed rear bumper, put stainless steel trim in, put transistion covers, fixed side panel that got hit				
82 - BLANCO, VICTOR (104.30)		\$5,215.00		
77 - SCHNEIDER, NICHOLAS (65.42)		\$3,271.00		
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$639.48	\$642.50	\$0.00	\$1,281.98
Work Comments: LH parcel rack is loose roughly 3rd the way back from drivers area, 1/4" rivets broken...pushed back up with jack, redrilled holes and riveted--along upper and sidewall. Make bracket for mudflap behind lt duals and attach mudflap; cut to fit flap for behind rt tag. remove rad door seal panel, clean old adhesive off, fasten back to door and put seal on.				
Pillsbury: Extrusion Lip Trim	\$76.74			
MCI EL3: 03-16-1405 (2.000)				
Pillsbury: Door seal:	\$54.00			
03-31-1188 (1.000)				
Young Building: Flap-Mud	\$113.38			
Drive Axle LH: 03-33-1020 (2.000)				
Part Comments: One flap cut and used for flap behind Rt tag				
Used LH Vent (1.000)	\$150.00			
Pillsbury: Latch assembly, ext. door EL3: 03-30-1071 (2.000)	\$103.28			
7r-13-146 (1.000)	\$142.08			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (12.85)		\$642.50		
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$153.68	\$113.50	\$0.00	\$267.18
03-15-3921 Vinyl, Heat Duct (8.000)	\$153.68			
Miscellaneous Parts	\$0			
6030 - STRICKER, DJ (2.27)		\$113.50		
Labor Comments: Installed shades with the shades i removed from 525, installed new shade guides and stops. Checked other buses for shades that are missing, wrapped up the used shades i didnt use for another time.				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$188.00	\$260.00	\$0.00	\$448.00

Pillsbury: Glass Windshield	\$188.00				
Front LH w/Mask MCI EL3:					
03-27-1325 (1.000)					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (5.20)		\$260.00			
Miscellaneous Labor		\$0			
Other			\$0		
77:Mirrors	\$178.82	\$0	\$0.00		\$178.82
Pillsbury: Switch ASM-Joystick,	\$178.82				
Mirror: 07-08-1891 (2.000)					
Miscellaneous Parts	\$0				
Miscellaneous Labor		\$0			
Other			\$0		
77:Mirrors	\$651.27	\$386.50	\$0.00		\$1,037.77
Work Comments: Install 2 new mirror heads; utilized used arm and harness removed from 525; checked and both work great.					
3/9/12--12N-2:45p					
Pillsbury: Mirror Convex (Dolly	\$11.89				
Jr.) 8" Offset Stud Black:					
801LDPOF (1.000)					
Pillsbury: Mirror Head, RH,	\$639.38				
MCI EL3: 03-22-1007 (2.000)					
Part Comments: 2--03-22-1007 MIRROR HEADS					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (7.73)		\$386.50			
Miscellaneous Labor		\$0			
Other			\$0		
78:Doors Entrance / Exit	\$0	\$0	\$0.00		\$0.00
Miscellaneous Parts	\$0				
Miscellaneous Labor		\$0			
Other			\$0		
AD:Air Drier Service	\$217.86	\$0	\$0.00		\$217.86
Pillsbury: AD-IP Air Dryer 12V	\$198.36				
Complete: 109477X (1.000)					
Pillsbury: Valve Drain Air Tank:	\$19.50				
4R-19-130 (2.000)					
Miscellaneous Parts	\$0				
Miscellaneous Labor		\$0			
Other			\$0		
CR:Creep	\$0	\$296.50	\$0.00		\$296.50
Work Comments: Start bus with charger; bring in and inspect; make parts list and numbers and give to BOBL					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (5.93)		\$296.50			
Miscellaneous Labor		\$0			
Other			\$0		
TF:Transmission Flush	\$352.91	\$270.00	\$0.00		\$622.91
Work Comments: Replaced broken accumulator bracket; drill and retap support point; hose to short, made new #20 hose.					
Pillsbury: Bracket,	\$216.06				
Accumulator: 13-021012					
(1.000)					
Pillsbury: Filter Kit	\$29.59				
Transmission Allison (Short					
Filter): 7741XE (1.000)					
Pillsbury: ATF (Synthetic) Bulk	\$107.26				
Quart: ATF Synthetic Bulk					
Pillsbury (31.000)					
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (5.40)		\$270.00			
Miscellaneous Labor		\$0			
Other			\$0		
	\$0.00	\$17,562.25	\$23,158.50	\$0	\$16,216.27
					<u>\$56,937.02</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 373,730.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
4508	05/29/2012	05/30/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
PU:Pick-up & Delivery		\$0	\$105.00		\$0.00	\$105.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (2.10)			\$105.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$105.00	\$0	\$0	<u>\$105.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 373,730.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
4629	05/31/2012	06/04/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$0	\$111.00		\$0.00	\$111.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (2.22)			\$111.00			
Labor Comments: LDI flat due to stem hitting caliper, changed to a differant style wheel to allow more space.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$111.00	\$0	\$0	<u>\$111.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 373,730.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
4635	05/31/2012	06/06/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
19 - C&J Bus Repair, Inv. #					\$222.77	\$222.77
CVC28740, PO # 5527, Desc:						
Charge Tag Steering						
13:Brakes		\$42.64	\$87.00		\$0.00	\$129.64
H56910F 100R5, SAE JI402		\$42.64				
(4.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.74)			\$87.00			
Labor Comments: Replace left front brake hose						
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$128.56	\$208.50		\$0.00	\$337.06
60421 Aux. Lighting (2.000)		\$36.52				
43380 MT Bracket (2.000)		\$9.92				
66851 Lamp Pigtail (2.000)		\$12.34				
Pillsbury: Flourescent Light		\$1.98				
32W-48"Coach: FO32735ECO						
(1.000)						
Pillsbury: Ballast Interior Light		\$67.63				
EL3: 07-07-1040 (1.000)						

5/7/2019

Work Order Detail

Pillsbury: Bulb 12 Volt Push-In Clearance & Marker: 194 (1.000)	\$0.17			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (4.17)		\$208.50		
Labor Comments: Install vertical brake lights, LED with lens. Replace one int light; Replace one ballast-- ballast out is new, Gave to Jason for warranty; new 194 bulb in L corner light.				
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$0	\$197.50	\$0.00	\$197.50
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (3.95)		\$197.50		
Labor Comments: Run and check A/C; pressure washed condensor core which does not have correct lid, told Ken, he be looking for one.				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$256.40	\$364.00	\$0.00	\$620.40
Pillsbury: Lock/Keys Kit EL3	\$144.84			
MCI: 3R-29-61 (2.000)				
Pillsbury: Knob Recliner, EL3: 223766-01 (18.000)	\$23.04			
03-29-1173 Spring, Locking Finger (1.000)	\$2.13			
03-30-1015 Handle-Latch (1.000)	\$75.08			
03-31-1338 Finger Lock (1.000)	\$11.31			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (7.28)		\$364.00		
Labor Comments: Rt rear engine door-- install new nylon hinge pin bushings, rivet and adjust latch posts; adjust upper hinge bracket. Install new latch asm in WCL compartment door; install new lock asm in battery switch access door; install recline knobs on seats;				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$449.95	\$206.00	\$0.00	\$655.95
Pillsbury: Wiper Motor EL3: 03-34-1002 (1.000)	\$449.95			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (4.12)		\$206.00		
Labor Comments: Wiper motor would not "park", install new motor, linkage position is 180 off, Will need to redo.				
Miscellaneous Labor		\$0		
Other			\$0	
DO:DOT Inspection	\$0	\$32.50	\$0.00	\$32.50
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.65)		\$32.50		
Miscellaneous Labor		\$0		
Other			\$0	
FF:Fuel Filter	\$8.38	\$34.00	\$0.00	\$42.38
Pillsbury: Filter Fuel: 3118 (1.000)	\$4.02			
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)	\$4.36			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.68)		\$34.00		
Labor Comments: install new fuel filters				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$885.93	\$1,129.50	\$0
			\$222.77	<u>\$2,238.20</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 373,921.0

Location: HBG

Department: HBG1-Accounting

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
4861	06/08/2012	06/11/2012	Closed	0.00		
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
PU:Pick-up & Delivery		\$0	\$75.00		\$0.00	\$75.00
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (1.50)			\$75.00			
Labor Comments: Test drove coach "per Kim's request" before it went out for the day.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$75.00	\$0	\$0	\$75.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 373,730.0

Location: HBG

Department: HBG1-Accounting

Recall:		Campaign #		Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
4908	06/11/2012	06/13/2012	Closed	0.00		
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
idles rough; door not tight; assits lite; radio		\$0	\$2.50		\$0.00	\$2.50
Maintenance Requested: 2181 - 06/12/2012 - idles rough; door not tight; assits lite; radio						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.05)			\$2.50			
Miscellaneous Labor			\$0			
Other					\$0	
22:Tires		\$1,294.30	\$436.00		\$0.00	\$1,730.30
Pillsbury: Wheel, Aluminum		\$633.60				
22.5: 29730AIP (2.000)						
Pillsbury: Wheel, Aluminum		\$582.00				
22.5: 29730AOP (2.000)						
Pillsbury: Hub Cover, Chrome		\$23.70				
8.5" Drive: MW1191 (2.000)						
Pillsbury: Hub Cap, Stainless		\$42.04				
Steel: MW1273 (4.000)						
Pillsbury: Cover Lug Nut MCI		\$12.96				
D4500 (Hug-A-Lug): 001812 (6.000)						
Part Comments: 22 - Removed all six outer tires. Dismounted four of them and remounted the tires on new rims. Polished the other two. Balanced them. Mounted all back on the bus and torqued the lugs to 450 LBS.						
Installed hub covers and lug nut covers.						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (7.50)			\$375.00			
74 - PHIPPS, KEVIN (1.22)			\$61.00			
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$181.90	\$14.00		\$0.00	\$195.90
Pillsbury: Fog Lamp LH, Dual		\$89.34				
Halagon, EL3: 07-07-1025 (see note) (1.000)						
Pillsbury: Fog Lamp RH, Dual		\$92.56				
Halagon, EL3: 07-07-1026 (see note) (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.28)			\$14.00			
Labor Comments: Install new fog lights.						
Miscellaneous Labor			\$0			
Other					\$0	

5/7/2019

Work Order Detail

49:Air System	\$9.75	\$11.00	\$0.00	\$20.75
Work Comments: 49 - Located the air leak and removed and replaced the leaking drain valve.				
Pillsbury: Valve Drain Air Tank:	\$9.75			
4R-19-130 (1.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.22)		\$11.00		
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$587.82	\$276.50	\$0.00	\$864.32
Pillsbury: Kit-DOGA Wiper Arm & Blade Kit: 07-14-3519A (2.000)	\$587.82			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (5.53)		\$276.50		
Labor Comments: Remove lower plexi, install new arms, install plexi, found arms would rub on window rubber, took it all back apart and replaced arm brackets putting arms farther out, put all back together. Adjusted wipers and test run proved good.				
Miscellaneous Labor		\$0		
Other			\$0	
PU:Pick-up & Delivery	\$0	\$73.00	\$0.00	\$73.00
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (1.46)		\$73.00		
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$2,073.77	\$813.00	\$0
			\$0	\$2,886.77

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 373,730.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5087	06/18/2012	06/19/2012	Closed	0.00	

Description: repair av system

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
226 - Mobile Essences, Inv. #					\$1,058.33	\$1,058.33
1265, PO # 2780550, Desc: av						
Repair						
20:Steering		\$0	\$85.00		\$0.00	\$85.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.70)			\$85.00			
Labor Comments: Remove and center steering wheel; checked drag link end, needs replacement even though new. Part ordered						
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$0.41	\$26.50		\$0.00	\$26.91
Pillsbury: Bulb 12 Volt Push-in (Brake/Tail Light): 3157		\$0.41				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.53)			\$26.50			
Labor Comments: Install new bulb in Rt side center.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$22.50		\$0.00	\$22.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.45)			\$22.50			
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$26.50		\$0.00	\$26.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.53)			\$26.50			
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$0.41 \$160.50 \$0 \$1,058.33 \$1,219.24

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 374,268.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5251	06/22/2012	06/22/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$56.00		\$0.00	\$56.00
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (1.12)			\$56.00			

Labor Comments: Reset parameters in the Engine ECM to remove "Idle Shutdown" and enable cruise control. Test drove and all systems functioned. Drove back to Lakeville.

Miscellaneous Labor		\$0				
Other					\$0	

\$0 \$0 \$56.00 \$0 \$0 \$56.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 374,350.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5632	07/09/2012	07/09/2012	Closed	0.00	

Description: Fix AV ,speakers Mobil Essences LLC invoice 1280

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
226 - Mobile Essences, Inv. #					\$1,081.58	\$1,081.58
1280, Desc: n						

\$0 \$0 \$0 \$0 \$1,081.58 \$1,081.58

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 375,242.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
5975	07/20/2012	07/23/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$58.50		\$0.00	\$58.50

Maintenance Requested: 2624 - 07/20/2012 - right turn signal out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.17)			\$58.50			
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$0 \$58.50 \$0 \$0 \$58.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 375,242.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
6156	07/26/2012	07/27/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
BD:Break Down		\$0	\$50.00		\$0.00	\$50.00
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (0.52)			\$26.00			
Labor Comments: Called and siad bus would not start. Went to Lakeville shop and bus started.						
0081 - WOLF, PATRICK (0.48)			\$24.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$50.00	\$0	\$0	<u>\$50.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 375,242.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
6183	07/27/2012	07/31/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$14.82	\$26.50		\$0.00	\$41.32
Young Building: Pigtail: 66900		\$3.21				
(1.000)						
Young Building: Light Side		\$11.61				
Marker MCI: 53063 (1.000)						
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (0.53)			\$26.50			
Labor Comments: Replaced rear RHS Side marker light.						
Miscellaneous Labor			\$0			
Other					\$0	
40:Engine		\$87.20	\$1,336.50		\$0.00	\$1,423.70
08929387 Sensor ASM Mag		\$64.76				
Idler S (1.000)						
Pillsbury: Drive Coupler:		\$5.95				
23505249 (1.000)						
Pillsbury: Gasket Fuel Pump,		\$1.23				
Detroit Series 60: 23505248						
(1.000)						
Pillsbury: Gasket Air		\$2.06				
Compressor: 8929299						
Pillsbury: Fluid Coolant Bulk		\$13.20				
50/50 After Dilution: A/F 50/50						
Green BULK (3.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK			\$1,336.50			
Labor Comments: 40 - Pulled the engine codes. (S-21)=Too many SRS ,missing TRS. ---- Tried to Remove the srs sensor but it wouldn,t come out. Ended up breaking it off. Pulled the generator and mounting bracket off. removed the air compressor and fuel pump. Drilled holes in the edge of the srs sensor and pulled it out. Installed new gaskets on the compressor and fuel pump. New coupler on the fuel pump. Put everything back together and refilled the cooling sys. Cleared the codes. Started it up and all codes stayed away.						
Miscellaneous Labor			\$0			
Other					\$0	
BD:Break Down		\$0	\$29.00		\$0.00	\$29.00
Miscellaneous Parts		\$0				
6030 - STRICKER, DJ (0.58)			\$29.00			
Labor Comments: Bus would not start in the wash bay.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$37.50		\$0.00	\$37.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.75)			\$37.50			
Miscellaneous Labor			\$0			

Other

\$0

\$0	\$102.02	\$1,429.50	\$0	\$0	<u>\$1,531.52</u>
-----	----------	------------	-----	-----	-------------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 377,430.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
7003	08/27/2012	09/03/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
16:Drive Train		\$3,062.80	\$905.50		\$0.00	\$3,968.30

Work Comments: Complaint of grinding noise/vibration.

Pillsbury: Gasket Rear Axle

\$7.30

Flange: GKT1008 (2.000)

Pillsbury: Oil Gear Synthetic:

\$97.02

Oil Gear 75W-90 BULK in

quarts (42.000)

6.5-4-3731-1x end yoke assy

\$163.48

(1.000)

RC23160-430 DIFFERENTIAL

\$2,795.00

(1.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (18.11)

\$905.50

Labor Comments: Did feel vibration on way to shop. From acceleration and cruise from 5 to 60 mph.

Further test drive, could hear noise above diff and trans area. Put bus up and inspected drive line. A new prop shaft was installed a short time ago. Removed shaft and removed trans yoke and seal to check output shaft bearing assembly. All looked good there. Diff had alot of backlash and excessive movement making similar noise that was heard while driving. Removed axles and pulled diff out. Original diff with lots of wear. Found one ring bolt sheared off-held by magnets- and excessive bearing/race material. Spent time cleaning rear axle housing. Received reman diff and installed. Filled with oil, slid axles in and filled hubs with oil. Test drove--quiet and smooth.

Miscellaneous Labor

\$0

Other

\$0

21:Suspension		\$2,958.48	\$183.50		\$0.00	\$3,141.98
---------------	--	------------	----------	--	--------	------------

6.5-4-3731-1x end yoke assy

\$163.48

(1.000)

RC23160-430 DIFFERENTIAL

\$2,795.00

(1.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (3.67)

\$183.50

Miscellaneous Labor

\$0

Other

\$0

\$0.00	\$6,021.28	\$1,089.00	\$0	\$0	<u>\$7,110.28</u>
--------	------------	------------	-----	-----	-------------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 377,430.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
7422	09/10/2012	09/11/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$62.50		\$0.00	\$62.50

Maintenance Requested: 3248 - 09/10/2012 - BUS GOT STUCK IN KNEEL POSITION FOR A WHILE SEE CO

Requestor Notes: REAR INSIDE STORAGE DOOR LATCH IS BROKE DUCT TAPED SHUT PART ARE TAPED TO DOOR.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (1.25)

\$62.50

Labor Comments: Pick up bus at Charter and bring to shop. Knelt bus and recovered correctly. Also tried with wheels turned each way and bus recovered correctly. Checked for stored codes-- found none. Did notice that recover switch may take a couple seconds to react. Could not locate other issue of "rear storage comp..."-- all compartments are OK.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$62.50 \$0 \$0 \$62.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 377,430.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
7458	09/11/2012	09/12/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
PU:Pick-up & Delivery			\$27.50		\$0.00	\$27.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.55)			\$27.50			
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$0 \$27.50 \$0 \$0 \$27.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 378,672.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
7772	09/20/2012	09/24/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
SEE COMMENTS		\$0	\$131.00		\$0.00	\$131.00

Maintenance Requested: 3397 - 09/20/2012 - SEE COMMENTS

Requestor Notes: BUS WON'T KNEEL BUT LITE STAYS ON

HIGH BEAM LITE ON DASH IS OURT

ENGINE BRAKE LITE ON DASH STAYS ON

HEAD LIGHTS NEED ADJUSTING TOO LOW NEED TO BE RAISED UP

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (2.62)

\$131.00

Labor Comments: "Bus won't kneel... and Headlights need adj" --found ECAS module inop; brought 524 here and swapped module. 527 suspension worked fine. Ride height attained, kneel light went out and headlights were better--I still adjusted them some more. Found dirt and other crap inside module, cleaned it out and ti worked OK. Returned 524 module to 524 and brought both buses back to Charter.
-- Hi-beam indicator out due to another module being inop. Ordering new module.
--Engine brake light was not on while I had bus.

Miscellaneous Labor

\$0

Other

\$0

PU:Pick-up & Delivery		\$0	\$56.50		\$0.00	\$56.50
-----------------------	--	-----	---------	--	--------	---------

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (1.13)

\$56.50

Labor Comments: Return both buses to charter.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$187.50 \$0 \$0 \$187.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 379,530.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
8058	10/01/2012	10/04/2012	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
Inspection Diesel						
PM:Preventative Maintenance		\$123.64	\$692.00		\$0.00	\$815.64
Pillsbury: Filter Oil MCI D4500		\$15.96				
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Filter Media: 4WZ68 (8.000)		\$4.64				
Young Building: Parcel Rack		\$12.55				
Door Spring RH EL3 MCI: 03-08-1094 (5.000)						
Pillsbury: Parcel Rack Door		\$5.02				
Spring LH EL3 MCI: 03-08-1095 (2.000)						
Pillsbury: Oil Bulk in Quarts: Oil 15W-40 Bulk (37.000)		\$85.47				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.34)			\$217.00			
74 - PHIPPS, KEVIN (9.50)			\$475.00			
Labor Comments: LOF&I; repaired parcel rack doors;						
Miscellaneous Labor			\$0			
Other					\$0	
SEE COMMENTS		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 3521 - 09/29/2012 - SEE COMMENTS

Requestor Notes: Assist light on.

bus loses air from 120 to 110 and a little below - buzzer comes on.

Some bay doors do not lock with key.

Engine brake light comes on sometimes with retarder off.

Drivers side seat/row 4 window rattles.

No a/c in passenger area of bus, drivers air not very cool either.

High beam indicator is out.

kneeler does not work, kneeler light stays on

Technician Response: #1==driver needs to see to it that passenger call switches are OFF, and that chime switch is off.

Maint Req Status: Completed

Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.00)			\$0.00			
Labor Comments: See responses to list						
Miscellaneous Labor			\$0			
Other					\$0	
no ac bus won't start; rattels a lot		\$0	\$105.00		\$0.00	\$105.00

Maintenance Requested: 3526 - 10/01/2012 - no ac bus won't start; rattels a lot

Requestor Notes:

Technician Response: Found battery equalizer to be shorted causing poor charging to batteries. May also cause A/C problem. New equalizer o

Maint Req Status: Completed

Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.00)			\$0.00			
Labor Comments: A/C inop caused by insufficient voltage due to shorted equalizer, batts not charging causing bus not to start.						
0081 - WOLF, PATRICK (2.10)			\$105.00			
Miscellaneous Labor			\$0			
Other					\$0	
oil gauge and temp gauge do not work		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 3459 - 09/25/2012 - oil gauge and temp gauge do not work

Requestor Notes:

Technician Response: Ongoing issues with old worn dash circuit board. Installed swing board and sending old board out for repair/replacement

Maint Req Status: Completed

Miscellaneous Parts		\$0				
---------------------	--	-----	--	--	--	--

74 - PHIPPS, KEVIN (0.00)		\$0.00		
	Labor Comments: installed swing dash until other dash is repaired/replaced			
Miscellaneous Labor		\$0		
Other			\$0	
13:Brakes		\$937.50	\$47.50	\$0.00
	Work Comments: RF brake line leaking			\$985.00
Pillsbury: Rotor EL3:		\$937.50		
15-02-1010 (2.000)				
Miscellaneous Parts		\$0		
74 - PHIPPS, KEVIN (0.95)			\$47.50	
	Labor Comments: Made new brake hose for RF brake			
Miscellaneous Labor			\$0	
Other			\$0	
31:Charging		\$863.63	\$215.00	\$0.00
	Work Comments: Vanner--100amp equalizer--07-09-1024			\$1,078.63
07-09-1024 equalizer-battery		\$863.63		
(1.000)				
Miscellaneous Parts		\$0		
74 - PHIPPS, KEVIN (4.30)			\$215.00	
	Labor Comments: Batts were not charging correctly. Equalizer inop. Looked for another equalizer here and Holyoke--no or too small. Recieved equalizer, mounted into bus and hooked uip all cables. Started bus and checked charging voltage===14.1vdc/28.2vdc--perfect.			
Miscellaneous Labor			\$0	
Other			\$0	
35:Instrument & Gauges		\$0	\$90.00	\$0.00
Miscellaneous Parts		\$0		\$90.00
74 - PHIPPS, KEVIN (1.80)			\$90.00	
	Labor Comments: Nobody knew a thing about a module being good or not and guess what-it ain't. tore the drivers area apart and unhooked module then hooked it up to "unkown" one and hi beam indicator did not work. Either order a new one or have "spare" repaired?????????????who knows.....			
	Installed "swing dash" sent old dash out for repair.			
Miscellaneous Labor			\$0	
Other			\$0	
41:A/C & Heating		\$0	\$50.00	\$0.00
Miscellaneous Parts		\$0		\$50.00
74 - PHIPPS, KEVIN (1.00)			\$50.00	
	Labor Comments: A/C system works fine, aux heater works fine. Warms up and cools down as suppose to. Improper voltage caused system to shut down.			
Miscellaneous Labor			\$0	
Other			\$0	
46:Exhaust System		\$594.29	\$262.50	\$0.00
08-20-1014 isolator (3.000)		\$82.74		\$856.79
08-20-1024 muffler (1.000)		\$495.59		
19-4-182 clamp-exh elbow and tailpipe (1.000)		\$15.96		
Miscellaneous Parts		\$0		
74 - PHIPPS, KEVIN (5.25)			\$262.50	
	Labor Comments: Install new exhaust, torch off old brackets and attach new isolators to brackets. Install into bus. Make tailpipe from pipe here.			
Miscellaneous Labor			\$0	
Other			\$0	
50:Accessories		\$139.43	\$17.50	\$0.00
Pillsbury: Belt Alternator MCI		\$17.59		\$156.93
EL3: 08-27-1018 (1.000)				
Pillsbury: Belt, A/C, MCI, E-Coach: 08-27-1029 (1.000)		\$33.74		
Pillsbury: Belt Alternator MCI		\$36.44		
Motor Coach: 8L-27-132 (1.000)				
Pillsbury: Belt EL3:		\$51.66		
08-27-1002 (1.000)				
Miscellaneous Parts		\$0		
74 - PHIPPS, KEVIN (0.35)			\$17.50	
	Labor Comments: Assemble spare belts for bus (4)			

5/7/2019

Work Order Detail

Miscellaneous Labor		\$0			
Other				\$0	
78:Doors Entrance / Exit	\$217.26	\$119.00	\$0.00		\$336.26
Pillsbury: Lock/Keys Kit EL3	\$217.26				
MCI: 3R-29-61 (3.000)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (2.38)		\$119.00			
Labor Comments: 78 - Removed and replaced the three baggage door locks that didn't work. Lubed up all the door locks.					
Miscellaneous Labor		\$0			
Other				\$0	
FF:Fuel Filter	\$8.38	\$116.00	\$0.00		\$124.38
Pillsbury: Filter Fuel: 3118 (1.000)	\$4.02				
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)	\$4.36				
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (2.32)		\$116.00			
Labor Comments: Replace alt oil drain line; tighten belts; fuel filters					
Miscellaneous Labor		\$0			
Other				\$0	
PU:Pick-up & Delivery	\$0	\$115.00	\$0.00		\$115.00
Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (2.30)		\$115.00			
Labor Comments: Go to charter and pick up bus. Batts dead, had to charge.					
0081 - WOLF, PATRICK (0.00)		\$0.00			
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$2,884.13	\$1,829.50	\$0	\$0
					<u>\$4,713.63</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 380,191.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
8112	10/02/2012	10/03/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
16:Drive Train		\$0	\$84.00		\$0.00	\$84.00

Work Comments: Pinion seal replacement. Fleetpride has provided seal and yoke nut for this warranty repair.

Miscellaneous Parts	\$0				
74 - PHIPPS, KEVIN (1.68)		\$84.00			
Labor Comments: Replace diff pinion seal as per warranty by Fleetpride.					
Miscellaneous Labor		\$0			
Other				\$0	

\$0	\$0	\$84.00	\$0	\$0	<u>\$84.00</u>
-----	-----	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
8326	10/09/2012	10/12/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$149.00		\$0.00	\$149.00

Maintenance Requested: 3629 - 10/08/2012 - kneeling inop - see comments

Requestor Notes: Knealt bus for loading and the bus raised from kneelbut kept beeping and kneel flashed on dash when I started leaving with passengers. Eventually, beeping stopped but kneel kept flashing on dash beeping started again.

The bus seemed to be lower and leaning on the door side after a shile when I returned to garage to switch busses it would not lower so parked outside.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
6030 - STRICKER, DJ (2.98) \$149.00

Labor Comments: Went to Hoyleoke shop to check kneeling problem with 527. Checked kneeler and the suspension system was stuck in kneel. Removed power from module and tested OK.

NOTE: this bus is waiting for the new ECAS module ordered 2wks ago.

Miscellaneous Labor \$0
Other \$0

\$0 \$0 \$149.00 \$0 \$0 \$149.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 449,825.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
9159	11/08/2012	11/11/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
BD:Break Down		\$0	\$109.00		\$0.00	\$109.00

Work Comments: BD - Drove to the guthrie With the srvice truck and trouble shoot the no start issue. Got the bus running and fallowed bak to the shop.

Miscellaneous Parts \$0
0081 - WOLF, PATRICK (2.18) \$109.00
Miscellaneous Labor \$0
Other \$0

\$0 \$0 \$109.00 \$0 \$0 \$109.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 449,825.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
9165	11/08/2012	11/09/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$25.00	\$241.50		\$0.00	\$266.50
Pillsbury: SWITCH/		\$25.00				
COMMUTATEUR						
INTERRUPTOR: KS6378						
(1.000)						

Miscellaneous Parts \$0
0081 - WOLF, PATRICK (1.23) \$61.50

Labor Comments: 30 - put the battery box back together. Took the bus back to Hoyoke. Went to ACe and had keys made for the new ignition switch.

6151 - KRASKA, JOHN (2.48) \$124.00

Labor Comments: Removed master disconnect switch from spare mci out back and put it in this bus, that wasnt the problem so i put the other back in the spare bus.

6030 - STRICKER, DJ (1.12) \$56.00

Labor Comments: Install new switch and turnler

Miscellaneous Labor \$0
Other \$0

95:Service Calls		\$0	\$207.50		\$0.00	\$207.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.15)			\$207.50			

Labor Comments: 95 - Took Bus 525 up to the Target center and switched out with the driver. Brought 527 back to Holyoke and disabled the tag steering fault light and beeper.

5/7/2019

Work Order Detail

Miscellaneous Labor
Other

\$0

\$0

\$0	\$25.00	\$449.00	\$0	\$0	<u>\$474.00</u>
-----	---------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 451,722.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
9722	12/04/2012	12/13/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$25.00		\$0.00	\$25.00

Maintenance Requested: 4318 - 12/03/2012 - fuel door driver side came off

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
77 - SCHNEIDER, NICHOLAS			\$25.00			
(0.50)						
Miscellaneous Labor			\$0			
Other					\$0	

Shop Costs						\$25.00
	\$0	\$0	\$25.00	\$0	\$0	<u>\$50.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 452,521.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
10118	12/18/2012	12/19/2012	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$81.10	\$0		\$0.00	\$81.10

Work Comments: Fluids for Lugage Bay

Pillsbury: ATF (Synthetic) Bulk		\$34.60				
Quart: ATF Synthetic Bulk						
Pillsbury (10.000)						
Pillsbury: Fluid Coolant Bulk		\$12.10				
50/50 After Dilution: A/F 50/50						
Green BULK (2.500)						
Pillsbury: Oil Bulk in Quarts:		\$34.40				
Oil 15W-40 Bulk (10.000)						
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$126.34	\$48.50		\$0.00	\$174.84
Pillsbury: AD-IP DLU Air Dryer		\$66.35				
Valve Purge kit: K022105K						
(1.000)						
Pillsbury: AD-IP Air Dryer		\$59.99				
Desiccant Cartridge Bendix:						
109493BXR (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.97)			\$48.50			
Labor Comments: O/H air dryer						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$41.50		\$0.00	\$41.50
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.83)			\$41.50			

5/7/2019

Work Order Detail

Miscellaneous Labor
Other

\$0

\$0

\$0	\$207.44	\$90.00	\$0	\$0	<u>\$297.44</u>
-----	----------	---------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 453,460.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
10975	01/23/2013	01/24/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$580.23	\$423.50		\$0.00	\$1,003.73

Maintenance Requested: 4856 - 01/23/2013 - wont go into coach ride

Requestor Notes:

Technician Response:

Maint Req Status: Completed

S4460550570 (1.000)

\$580.23

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (8.47)

\$423.50

Labor Comments: 21 - Took parts to Holyoke. Installed the new ECAS modual. Started the bus to check if the new modual worked correctly and right away the ride fault light was on. hooked the old muadual back up and brought the bus back to the shop. Reprogramed the ECAS modual. checked it again. The Recover switch wouldn't work. Checked all the peramiters in the computer and found out the switch was telling the modual to lower insted of recover. Wnet thru the wiring diagrams and found that the kneel, raise and lower wires all ran thru this one switch. Removed the switch from 527 and from 529 and tried the other switched and it woked fine. Installed the switchinto 527 and ordered a new switch for 529. Returned the bus to Holyoke garage.

Miscellaneous Labor
Other

\$0

\$0

\$0	\$580.23	\$423.50	\$0	\$0	<u>\$1,003.73</u>
-----	----------	----------	-----	-----	-------------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 455,634.0

Location:

Department:

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
12046	03/01/2013	03/01/2013	Closed	0.00	

Description: Bus Graphics

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Installation of Graphics		\$2,100.00	\$0		\$0.00	\$2,100.00

Vinyl for City Tour Bus (1.000)

\$750.00

Install for City Tour Bus

\$1,250.00

Design work (1.000)

\$100.00

Miscellaneous Parts

\$0

Miscellaneous Labor

\$0

Other

\$0

\$0	\$2,100.00	\$0	\$0	\$0	<u>\$2,100.00</u>
-----	------------	-----	-----	-----	-------------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 465,522.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
12566	03/20/2013	03/29/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

Inspection Diesel				
LOF:Lube, Oil, Filter	\$117.67	\$835.00	\$0.00	\$952.67
Pillsbury: Filter Oil MCI D4500	\$15.96			
w/Detroit Diesel 60 Series:				
1971MP (2.000)				
Pillsbury: Oil Analysis Kit:	\$8.75			
Sample Kit (1.000)				
Pillsbury: Bulb 12v Amber	\$2.20			
Parking/Turn Signal: 3157NA				
(2.000)				
Pillsbury: Oil Bulk in Quarts:	\$85.47			
Oil 15W-40 Bulk (37.000)				
Pillsbury: Fluid Windshield	\$1.44			
Washer Fluid BULK/Gal After				
Dilution: W/W Fluid BULK				
(1.000)				
Pillsbury: Filter Media: 4WZ68	\$3.85			
(7.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (6.10)		\$305.00		
Labor Comments: PM - Performed the service and safty check as per the attatched sheet.				
155 - HOUSLEY, ANTHONY		\$530.00		
(10.60)				
Labor Comments: did a oil change and replaced 2 light bulbs thaty were burnt out or just not working				
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$0	\$2.50	\$0.00	\$2.50
Maintenance Requested: 5387 - 03/05/2013 - RH turn signal lamp middle not working				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.05)		\$2.50		
Labor Comments: 36 -- Replaced the bulbs billed on the PM				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$0	\$65.00	\$0.00	\$65.00
Maintenance Requested: 4768 - 01/16/2013 - low oil pressure light flased on and off				
Requestor Notes:				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (1.30)		\$65.00		
Labor Comments: 40 - Checked the oil Presure, Stays around 50 on low Idle. No codes in the ECM.				
Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$188.47	\$605.50	\$0.00	\$793.97
Pillsbury: Air Bag EL3:	\$163.67			
12-01-1048 (1.000)				
440433-131280 brass fitting	\$24.80			
(4.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (7.30)		\$365.00		
Labor Comments: 49 - Replumbed the shop air fitting to the back corner of the bus so they are all alike.				
Removed and replaced the leaking air fittings at the front left air bag. Removed and replaced the right front air bag and fittings.(all leaking)				
155 - HOUSLEY, ANTHONY		\$240.50		
(4.81)				
Labor Comments: replaced a air bage and new nuts and washers on along with new copper fittings on.				
replaced it because it was leaking and so was the fitting on the air bage				
Miscellaneous Labor		\$0		
Other			\$0	
75:Windows/windshields	\$0	\$45.00	\$0.00	\$45.00
Maintenance Requested: 4990 - 02/02/2013 - windshield washer not working, fluid is full				
Requestor Notes:				

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (0.90) \$45.00

Labor Comments: 75 - Checked the windshield washers and they worked fine. No problem found.

Miscellaneous Labor \$0

Other \$0

FF:Fuel Filter \$8.59 \$0 \$0.00 \$8.59

Pillsbury: Filter Fuel: 3118 \$4.23

(1.000)

Pillsbury: Filter, Fuel, MCI: \$4.36

3120 (1.000)

Miscellaneous Parts \$0

Miscellaneous Labor \$0

Other \$0

\$0 \$314.73 \$1,553.00 \$0 \$0 \$1,867.73

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 457,649.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
13469	04/25/2013	04/25/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$7.06	\$222.50		\$0.00	\$229.56

Pillsbury: Freon R134A per \$7.06

Lb.: R134A (2.000)

Miscellaneous Parts \$0

74 - PHIPPS, KEVIN (4.45) \$222.50

Labor Comments: Check brushes and A/C op; topped off system with 2 lbs. System works well.

Miscellaneous Labor \$0

Other \$0

PU:Pick-up & Delivery \$0 \$23.50 \$0.00 \$23.50

Miscellaneous Parts \$0

74 - PHIPPS, KEVIN (0.47) \$23.50

Miscellaneous Labor \$0

Other \$0

\$0 \$7.06 \$246.00 \$0 \$0 \$253.06

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 458,111.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
14134	05/17/2013	05/21/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$40.00		\$0.00	\$40.00

Work Comments: engine noise

Miscellaneous Parts \$0

157 - BROIN, DOUGLAS \$40.00

Labor Comments: went on service call to look at noise from engine.no noise found but charter thinks it may be PA feed back noise. We will check out problem when they have time to let us have the bus

Miscellaneous Labor \$0

Other \$0

\$0 \$0 \$40.00 \$0 \$0 \$40.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 458,111.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
14319	05/24/2013	05/24/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$1.50		\$0.00	\$1.50
Maintenance Requested: 5731 - 04/09/2013 - MISSING PANELS INSIDE THE LAST BAY						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.03)			\$1.50			
Labor Comments: There are no panels seperating baggage bays, only those added to some buses by previous owners						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$1.50	\$0	\$0	\$1.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 459,014.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
14589	06/05/2013	06/07/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$220.58	\$323.00		\$0.00	\$543.58
Maintenance Requested: 6370 - 06/03/2013 - Vehicle would not raise into high ride						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
12-01-1090 steer bellow (1.000)		\$220.58				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (6.46)			\$323.00			
Labor Comments: 21 -- Removed and replced the right front air bag.						
Miscellaneous Labor			\$0			
Other					\$0	
79:Lavatory		\$19.71	\$46.50		\$0.00	\$66.21
Maintenance Requested: 5730 - 04/09/2013 - TOILET IS LEAKING FROM TOP TANK						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Young Building: Toilet Dump		\$19.71				
Valve: 17K-5-51 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.93)			\$46.50			
Labor Comments: 79 - Removed and replaced the upper dump valve.						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery		\$0	\$39.00		\$0.00	\$39.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.78)			\$39.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$240.29	\$408.50	\$0	\$0	\$648.79

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Work Order Detail

Miles: 459,014.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
14677	06/07/2013	06/12/2013	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
22:Tires		\$735.44	\$55.00		\$0.00	\$790.44
Pillsbury: Tire New Virgin		\$735.44				
FS400: 315/80R 22.5 New						
Virgin Tire (2.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.10)			\$55.00			
Labor Comments: 22 -- Removed and replaced both front tires.						
Miscellaneous Labor			\$0			
Other					\$0	
95:Service Calls		\$0	\$82.50		\$0.00	\$82.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.65)			\$82.50			
Labor Comments: Took the service truck up to the MOA. Checked out the right front tire. followed 5527 back to the shop.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$735.44	\$137.50	\$0	\$0	\$872.94

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 460,167.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
14934	06/19/2013	06/25/2013	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
13:Brakes		\$22.44	\$231.50		\$0.00	\$253.94
Maintenance Requested: 6608 - 06/20/2013 - brakes squeak bad during tour						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Sensor, ABS, 90,		\$22.44				
Brake (gillig also): R955342						
(1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.63)			\$231.50			
Labor Comments: 13 - Lifted the bus in the air . checked all the brakes. The pads and rotors are all in good shape, no oil on any of them. Couldn,t get the brakes to squek on my 2 differant road tests.						
Removed and replaced a broken ABS sensor.						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$85.00		\$0.00	\$85.00
Maintenance Requested: 6627 - 06/23/2013 - a/c was intermittent and abs light on						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.70)			\$85.00			
Labor Comments: 41 -- Checked out the A/C system. Cooled the bus down from 81 to 64 in just 20 min. It has a full freon charge. Works good.						
Miscellaneous Labor			\$0			
Other					\$0	
DO:DOT Inspection		\$0	\$150.00		\$0.00	\$150.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (3.00)			\$150.00			

5/7/2019

Work Order Detail

Miscellaneous Labor		\$0			
Other				\$0	
PU:Pick-up & Delivery	\$0	\$27.50		\$0.00	\$27.50
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (0.55)		\$27.50			
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$22.44	\$494.00	\$0	\$0
					<u>\$516.44</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 460,710.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15129	06/26/2013	07/03/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$318.84	\$911.00		\$0.00	\$1,229.84
16g-2-64 plate assy, valve (2.000)		\$145.74				
16g-2-26 plate assy, valve (1.000)		\$113.13				
Pillsbury: Viscosity 32 oz: PAG		\$59.97				
Oil CQP100-32 (3.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK			\$911.00			

Labor Comments: 41 -- Checked out the A/C system. Found and repaired four bare spotts in the wiring at tthe compressor. Removed 2 pounds of freon from the system. Found the compressor surging presure so I rebuilt all three heads. Replaced all the reed valves. Then found the fans not operating correctly. Removed and rplaced the fan relay. The relay was a used part. then topped off the freon in the system.

Miscellaneous Labor			\$0			
Other					\$0	
75:Windows/windshields	\$0		\$103.50		\$0.00	\$103.50
Miscellaneous Parts	\$0					
6151 - KRASKA, JOHN (2.07)			\$103.50			
Labor Comments: Installed used window in door						
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery	\$0		\$25.00		\$0.00	\$25.00
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.50)			\$25.00			
Labor Comments: Return to hoke						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$318.84	\$1,039.50	\$0	\$0	\$1,358.34

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 462,760.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15450	07/19/2013	08/19/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$139.44	\$461.50		\$0.00	\$600.94
Work Comments: A/C is inop						
Pillsbury: Carrier Front Seal		\$84.00				
Kit O5G A/C Compressor						
MCID4500: 16L-2-112 (1.000)						
Pillsbury: Freon R134A per		\$55.44				

Lb.: R134A (22.000)						
Miscellaneous Parts	\$0					
157 - BROIN, DOUGLAS		\$220.00				
Labor Comments: Found system is empty. found compressor front seal is bad. Removed and replaced front seal and filled system.						
7050 - STRAND, MATTHEW (4.83)		\$241.50				
Labor Comments: replaced front seal on ac compressor						
Miscellaneous Labor		\$0				
Other				\$0		
70:Body Sheet Metal	\$0	\$442.50		\$0.00		\$442.50
Miscellaneous Parts	\$0					
77 - SCHNEIDER, NICHOLAS (8.85)		\$442.50				
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$139.44	\$904.00	\$0	\$0	<u>\$1,043.44</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 462,979.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15505	07/25/2013	07/26/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$22.50		\$0.00	\$22.50

Work Comments: Check A/C

Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.45)			\$22.50			
Labor Comments: Ambient=80; inside garage; P/R blowers only--auto on; freon at lower sight glass; good air flow; 61-R; 62-L; ran 30 mins.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$22.50	\$0	\$0	<u>\$22.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 464,773.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15663	08/06/2013	08/13/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$1,470.88	\$334.50		\$0.00	\$1,805.38

Pillsbury: Tire New Virgin
FS400: 315/80R 22.5 New
Virgin Tire (4.000)

Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (3.92)			\$196.00			

Labor Comments: put new drive tires on

157 - BROIN, DOUGLAS			\$138.50			
Miscellaneous Labor			\$0			
Other					\$0	
40:Engine		\$29.66	\$1,018.00		\$0.00	\$1,047.66

Work Comments: Greeted by "note" this AM--"will crank but will not start.please look at."

Pillsbury: Belt Alternator MCI	\$17.59					
EL3: 08-27-1018 (1.000)						
Pillsbury: Governor Air	\$12.07					
Compressor D-2: 0R275491						

X (1.000)							
Miscellaneous Parts		\$0					
74 - PHIPPS, KEVIN (1.28)			\$64.00				
Labor Comments: Popped right off..... 77-P100-0= Oil psi hi (voltage spike?); 41-S21-0= Too many SRS (missing TRS)							
7050 - STRAND, MATTHEW (8.33)			\$416.50				
Labor Comments: replaced compressor and srs and trs sensors had to remove a lot to get compressor and sensors out and replaced govenor							
157 - BROIN, DOUGLAS (10.75)			\$537.50				
Miscellaneous Labor			\$0				
Other					\$0		
49:Air System	\$698.38	\$5.00		\$0.00		\$703.38	
08929299 gasket (2.000)	\$6.62						
Pillsbury: Gasket Fuel Pump, Detroit Series 60: 23505248 (1.000)	\$1.14						
Pillsbury: Drive Coupler: 23505249 (1.000)	\$5.84						
Pillsbury: Air Compressor: R23522123 (1.000)	\$556.50						
08929387 sensor assy (1.000)	\$63.11						
08929388 sensor (1.000)	\$53.23						
C5205X16 fitting (2.000)	\$11.94						
Miscellaneous Parts	\$0						
7050 - STRAND, MATTHEW (0.10)		\$5.00					
Labor Comments: same as engine comments							
157 - BROIN, DOUGLAS			\$0.00				
Miscellaneous Labor			\$0				
Other					\$0		
	\$0	\$2,198.92	\$1,357.50	\$0	\$0		<u>\$3,556.42</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 465,522.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
15792	08/19/2013	08/19/2013	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
PU:Pick-up & Delivery			\$0	\$42.50		\$0.00	\$42.50
Miscellaneous Parts			\$0				
0079 - SHORTER, CHAD (0.85)				\$42.50			
Labor Comments: Took bus from holyoke to pils for winshields to be fixed.							
Miscellaneous Labor				\$0			
Other						\$0	
	\$0	\$0	\$42.50	\$0	\$0		<u>\$42.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 466,088.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
15795	08/19/2013	08/19/2013	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting			\$49.84	\$8.50		\$0.00	\$58.34

Pillsbury: Light Amber Marker, EL3: 07-07-1012 (1.000)	\$40.88					
Pillsbury: Lens: 07-07-1011 (1.000)	\$8.96					
Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (0.17)		\$8.50				
Labor Comments: 36 -- Removed and replaced a broken marker light and lens.						
Miscellaneous Labor		\$0				
Other				\$0		
75:Windows/windshields	\$408.29	\$370.50		\$0.00		\$778.79
Pillsbury: Glass Windshield Front LH w/Mask MCI EL3: 03-27-1325 (1.000)	\$188.00					
Pillsbury: Glass Windshield Front RH w/Mask MCI EL3: 03-27-1326 (1.000)	\$188.00					
Pillsbury: Wiper Blade MCI EL3: 03-34-1177 (1.000)	\$32.29					
Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (4.10)		\$205.00				
74 - PHIPPS, KEVIN (3.31)		\$165.50				
Labor Comments: Install new windshields; center marker and lens above, and Rt wiper, due to damage.						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$458.13	\$379.00	\$0	\$0	<u>\$837.13</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 465,522.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15806	08/19/2013	08/23/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$208.05	\$126.50		\$0.00	\$334.55

Maintenance Requested: 6856 - 08/16/2013 - see comments

Requestor Notes: drivers air conditioning does not blow on low or medium, high only.

Technician Response:

Maint Req Status: Completed

Pillsbury: Blower Parcel rack	\$208.05					
Heater MCI D4500: 16L-14-68 (1.000)						
Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (2.53)		\$126.50				
Labor Comments: 41 -- Trouble shoot def blowernot working on low & med. Removed and replaced the left blower motor.						
Miscellaneous Labor		\$0				
Other				\$0		
CFR:Coolant Filter Replacement	\$30.98	\$125.00		\$0.00		\$155.98
Pillsbury: Filter Coolant w/Full Charge MCI D4500 w/ Detroit 60 Series Engine: 4088 (1.000)	\$30.98					
Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (2.50)		\$125.00				
Miscellaneous Labor		\$0				
Other				\$0		
PS:Power Steering Flush	\$102.74	\$115.50		\$0.00		\$218.24
Pillsbury: Element Power steering reservoir: 11-08-1074 (1.000)	\$9.64					
Pillsbury: Fluid ATF Bulk: ATF Dexron VI bulk (10.700)	\$46.55					

Pillsbury: Fluid ATF Bulk: ATF
Dexron VI bulk (10.700)

\$46.55

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (1.53)

\$76.50

Labor Comments: PS -- Removed and rplaced the filter. Flushed till clean. Reassembled and topped off
the system.

74 - PHIPPS, KEVIN (0.78)

\$39.00

Miscellaneous Labor

\$0

Other

\$0

\$0	\$341.77	\$367.00	\$0	\$0	<u>\$708.77</u>
-----	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 466,419.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15952	08/27/2013	08/30/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
LOF:Lube, Oil, Filter		\$102.27	\$254.00		\$0.00	\$356.27

Pillsbury: Oil Bulk in Quarts:

\$85.47

Oil 15W-40 Bulk (37.000)

Pillsbury: Filter Oil MCI D4500

\$16.80

w/Detroit Diesel 60 Series:

1971MP (2.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$254.00

(5.08)

Labor Comments: did full service, looked over it a little more cause we havent touched it in awhile, found
few things wrong and no triangles

Miscellaneous Labor

\$0

Other

\$0

\$0	\$102.27	\$254.00	\$0	\$0	<u>\$356.27</u>
-----	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 466,419.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
15958	08/27/2013	08/30/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$80.02	\$87.50		\$0.00	\$167.52

Pillsbury: Draglink End LH

\$80.02

EL3 MCI: 11-04-1006 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$87.50

(1.75)

Labor Comments: put new tie rod on where the nuckle and steering arm are

Miscellaneous Labor

\$0

Other

\$0

41:A/C & Heating

\$0

\$61.00

\$0.00

\$61.00

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$61.00

(1.22)

Labor Comments: put blower motor back in after seeing if i could change brushes and found you cant

Miscellaneous Labor

\$0

Other

\$0

49:Air System

\$0

\$237.00

\$0.00

\$237.00

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$237.00

(4.74)	Labor Comments: found air leak and replaced brass fitting					
Miscellaneous Labor			\$0			
Other					\$0	
HUB:Hub Service	\$6.54	\$66.50		\$0.00		\$73.04
Pillsbury: Oil Gear Synthetic:	\$6.54					
Oil Gear 75W-90 BULK in quarts (2.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$66.50				
(1.33)	Labor Comments: changed hub oil					
Miscellaneous Labor			\$0			
Other					\$0	
PU:Pick-up & Delivery	\$0	\$93.50		\$0.00		\$93.50
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$93.50				
(1.87)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$86.56	\$545.50	\$0	\$0	<u>\$632.06</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 465,522.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
15963	08/28/2013	08/28/2013	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>	
36:Lighting		\$19.34	\$43.50		\$0.00	\$62.84	
Young Building: Light Side		\$13.99					
Marker MCI: 53063 (1.000)							
Young Building: Pigtail: 66900 (1.000)		\$5.35					
Miscellaneous Parts		\$0					
74 - PHIPPS, KEVIN (0.87)			\$43.50				
Miscellaneous Labor			\$0				
Other					\$0		
	\$0	\$19.34	\$43.50	\$0	\$0	<u>\$62.84</u>	

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 468,174.0

Location: HBG

Department: HBG1-Accounting

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
16315	09/18/2013	09/18/2013	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>	
36:Lighting		\$0	\$25.00		\$0.00	\$25.00	
Miscellaneous Parts		\$0					
0079 - SHORTER, CHAD (0.50)			\$25.00				
Labor Comments: Driver came in with side light out, didn't have light, stole light from another coach (5522) to get him going, will replace light later.							
Miscellaneous Labor			\$0				
Other					\$0		
	\$0	\$0	\$25.00	\$0	\$0	<u>\$25.00</u>	

VIN: 1M8TRMPA6WP060245

License Plate:

5527: 1998 MCI EL3

Miles: 469,410.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
16683	10/17/2013	10/22/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$397.48	\$593.50		\$0.00	\$990.98
Pillsbury: Bellow ASM-Air, TRL.		\$225.13				
Axle, EL3: 12-03-1029 (1.000)						
relay valve (1.000)		\$172.35				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$131.00			
(2.62)						
Labor Comments: helped with relay valve						
157 - BROIN, DOUGLAS			\$462.50			
Labor Comments: removed and replaced a relay valve and L/R tag air bag.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$397.48	\$593.50	\$0	\$0	\$990.98

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 470,710.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
17123	11/27/2013	12/31/2013	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$504.84	\$312.00		\$0.00	\$816.84
Work Comments: ignition parts ordered						
W-14846C electrode , ignition		\$17.46				
(1.000)						
07-06-1001 solenoid-fan		\$269.41				
control 12v (1.000)						
470716 webasto nozzle		\$49.22				
(2.000)						
freight (10.000)		\$10.00				
W-14845C ignition coil 24V		\$158.75				
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$239.00			
(4.78)						
Labor Comments: put igniton parts into the webasto						
157 - BROIN, DOUGLAS			\$73.00			
Labor Comments: ordered parts for wabasto						
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$27.31	\$178.50		\$0.00	\$205.81
Work Comments: fan sol orderd.						
Pillsbury: Valve Drain Air Tank:		\$13.45				
4R-19-130 (2.000)						
Pillsbury: Shut Off Cock 1/4":		\$13.86				
V402-4 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$156.00			
(3.12)						
Labor Comments: put alcohol in the system						
157 - BROIN, DOUGLAS			\$22.50			
Labor Comments: added alcohol to air system						
Miscellaneous Labor			\$0			
Other					\$0	

\$0.00 \$532.15 \$490.50 \$0 \$0 \$1,022.65

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 471,823.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
17740	01/31/2014	02/11/2014	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
13:Brakes		\$42.76	\$94.00		\$0.00	\$136.76
Pillsbury: Sensor, ABS, 90, Brake (gillig also): R955342 (1.000)		\$42.76				
Miscellaneous Parts 7050 - STRAND, MATTHEW (1.88)		\$0	\$94.00			
Labor Comments: ABS sensor had a code and it faultd as open sensor, replaced sensor went off, also heard a wind noise on the road test and fixed that						
Miscellaneous Labor			\$0			
Other					\$0	
38:Audio / Video Surveillance System		\$0	\$176.00		\$0.00	\$176.00
Miscellaneous Parts 7050 - STRAND, MATTHEW (1.77)		\$0	\$88.50			
Labor Comments: installed a window fan for the drivers window, and installed a camera, fan part number is not in the system 7200m						
157 - BROIN, DOUGLAS			\$87.50			
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$170.28	\$51.00		\$0.00	\$221.28
Pillsbury: AD-IP Air Dryer Desiccant Cartridge Bendix: 109493BXR (1.000)		\$52.95				
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$117.33				
Miscellaneous Parts 7050 - STRAND, MATTHEW (1.02)		\$0	\$51.00			
Labor Comments: did a air drier service						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$213.04	\$321.00	\$0	\$0	<u>\$534.04</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 479,383.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
18122	03/06/2014	04/07/2015	Closed	0.00	

Detail	Discounts	Parts	Labor	Tires	Other	Total
25:Transmission (Auto)		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
30:Electrical		\$357.90	\$34.00		\$0.00	\$391.90
Pillsbury: Battery 1400CCA Top Post Heavy Duty Workaholic: 8D-MHD(7271)		\$357.90				
Miscellaneous Parts 157 - BROIN, DOUGLAS		\$0	\$34.00			

Labor Comments: installed new batt						
Miscellaneous Labor			\$0			
Other					\$0	
A/C:Prep	\$88.86	\$168.50		\$0.00		\$257.36
Pillsbury: Freon R134A per	\$88.86					
Lb.: R134A (29.000)						
Miscellaneous Parts	\$0					
157 - BROIN, DOUGLAS		\$168.50				
Labor Comments: charged a/c system						
Miscellaneous Labor		\$0				
Other				\$0		
CR:Creep	\$0	\$59.50		\$0.00		\$59.50
Miscellaneous Parts	\$0					
157 - BROIN, DOUGLAS		\$59.50				
Labor Comments: inspected bus						
Miscellaneous Labor		\$0				
Other				\$0		
FF:Fuel Filter	\$0	\$0		\$0.00		\$0.00
Miscellaneous Parts	\$0					
157 - BROIN, DOUGLAS		\$0.00				
0081 - WOLF, PATRICK (0.00)		\$0.00				
Labor Comments: FF -- Fuel filter just replaced on 7-9-14						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$446.76	\$262.00	\$0	\$0	<u>\$708.76</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 473,214.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
18620	04/21/2014	04/22/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$0	\$10.00		\$0.00	\$10.00

Maintenance Requested: 7732 - 04/11/2014 - Engine brake light stays on

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$10.00				
(0.20)						

Labor Comments: no problem found

Miscellaneous Labor		\$0				
Other				\$0		
72:Body Misc	\$0	\$10.00		\$0.00		\$10.00

Maintenance Requested: 7733 - 04/11/2014 - White strip on top step loose

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$10.00				
(0.20)						

Labor Comments: re sealed it to the floor

Miscellaneous Labor		\$0				
Other				\$0		

\$0	\$0	\$20.00	\$0	\$0	<u>\$20.00</u>
-----	-----	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 474,410.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
18892	05/14/2014	06/10/2014	Closed	0.00		
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$45.54	\$46.00		\$0.00	\$91.54
Pillsbury: Sensor 5.8' Kit:		\$45.54				
R955338 (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$17.50			
7050 - STRAND, MATTHEW			\$28.50			
(0.57)						
Labor Comments: replaced sensor						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$14.26	\$641.50		\$0.00	\$655.76
640901040726 90 degree		\$14.26				
elbow (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$641.50			
(12.83)						
Labor Comments: tried to fix condensor leak						
Miscellaneous Labor			\$0			
Other					\$0	
AF:Air Filter Replacement		\$39.99	\$0		\$0.00	\$39.99
Pillsbury: Filter Air: 6741		\$39.99				
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: replaced air filter during lof						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$372.83	\$151.50		\$0.00	\$524.33
Pillsbury: Filter Oil MCI D4500		\$15.96				
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Analysis Kit:		\$8.75				
Sample Kit (1.000)						
Pillsbury: Oil Bulk in Quarts:		\$348.12				
Oil 15W-40 Bulk (36.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$151.50			
(3.03)						
Labor Comments: lof						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$472.62	\$839.00	\$0	\$0	\$1,311.62

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 474,666.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
19004	05/22/2014	06/16/2014	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating			\$89.69	\$805.50		\$0.00	\$895.19
Pillsbury: Filter Dryer EL3:			\$48.74				
16-04-1004 (1.000)							
Pillsbury: Freon R134A per			\$40.95				
Lb.: R134A (13.000)							
Miscellaneous Parts			\$0				

5/7/2019

Work Order Detail

7050 - STRAND, MATTHEW
(7.96)

\$398.00

Labor Comments: swapped condensor, heater core unit and got a/c running

157 - BROIN, DOUGLAS

\$407.50

Labor Comments: installed used condensor assy from ABC

Miscellaneous Labor
Other

\$0

\$0

\$0 \$89.69 \$805.50 \$0 \$0 \$895.19

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 475,871.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19112	06/06/2014	06/16/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$116.34	\$318.00		\$0.00	\$434.34
08929387 sensor assy (1.000)		\$63.11				
08929388 m-sensor (1.000)		\$53.23				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (6.36)			\$318.00			
Labor Comments: 40 -- Removed and replaced the TRS and SRS sensors.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$116.34	\$318.00	\$0	\$0	<u>\$434.34</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 475,811.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19178	06/13/2014	06/16/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$25.58	\$38.50		\$0.00	\$64.08
Work Comments: Install fluids as needed in rear storage area.						
Pillsbury: Dexron VI ATF		\$23.16				
Quarts: ATF Dexron VI (4.000)						
Pillsbury: Oil Bulk in Quarts:		\$2.42				
Oil 15W-40 Bulk (1.000)						
Miscellaneous Parts		\$0				
73 - PAVEK, MICHAEL (0.77)			\$38.50			
Labor Comments: Done.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$25.58	\$38.50	\$0	\$0	<u>\$64.08</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 475,872.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19200	06/18/2014	06/19/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$540.43	\$304.00		\$0.00	\$844.43
Work Comments: Plastic on hub cap melted, spewing oil out.						

Pillsbury: Hub Cap w/ Lube \$37.64
 Window Steer Axle MCI
 D4500: 343-4176 (1.000)
 Pillsbury: Oil Gear Synthetic: \$3.27
 Oil Gear 75W-90 BULK in
 quarts (1.000)
 Pillsbury: Cover Lug Nut MCI \$22.70
 D4500 (Hug-A-Lug): 001812
 (10.000)
 Pillsbury: MCI Caliper Kit LHS: \$476.82
 04-01-1041 (1.000)
 Miscellaneous Parts \$0
 74 - PHIPPS, KEVIN (2.15) \$107.50

Labor Comments: Replace bad cap and fill with oil. Checked brake and found (L tag) the caliper to be
 siezed

7050 - STRAND, MATTHEW \$196.50
 (3.93)

Labor Comments: Rebuilt the caliper because it was stuck causing the brakes to over heat and melt the
 hub

Miscellaneous Labor \$0
 Other \$0

\$0 \$540.43 \$304.00 \$0 \$0 \$844.43

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 477,183.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19304	06/26/2014	06/27/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$29.00		\$0.00	\$29.00

Maintenance Requested: 8039 - 06/26/2014 - Driver Side low beam headlight out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

used 9006 bulb. not in \$0.00
 inventory (1.000)
 Miscellaneous Parts \$0

157 - BROIN, DOUGLAS \$29.00

Labor Comments: Removed and replaced L/F headlamp low beam bulb

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$29.00 \$0 \$0 \$29.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 477,183.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19313	06/27/2014	06/30/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
12:Axles (rear)		\$0	\$232.00		\$0.00	\$232.00

Miscellaneous Parts \$0

7050 - STRAND, MATTHEW \$123.50
 (2.47)

Labor Comments: Studs on the rear axle broke, had to drill and extract them out, gasket was leaking

0142 - GALLINGER, CHAD \$108.50
 (2.17)

Labor Comments: replaced 8 studs and nuts searched fur magic red knob in bus super john showed

me where it is went on road test all good

Miscellaneous Labor
Other

\$0

\$0

\$0	\$0	\$232.00	\$0	\$0	<u>\$232.00</u>
-----	-----	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 478,506.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19398	07/09/2014	07/10/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
48:Fuel System						
Pillsbury: Filter, Fuel, MCI:		\$4.08	\$12.50		\$0.00	\$16.58
3120 (1.000)		\$4.08				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$12.50			
(0.25)						
Labor Comments: fuel filter was leaking, replaced it						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$4.08	\$12.50	\$0	\$0	<u>\$16.58</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 479,820.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
201485	07/18/2014	07/21/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
DO:DOT Inspection		\$0	\$50.00		\$0.00	\$50.00
Work Comments: Perform MN DOT inspection						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.00)			\$50.00			
Labor Comments: Dot unit						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$50.00	\$0	\$0	<u>\$50.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 481,405.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19613	07/29/2014	08/08/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$77.94	\$151.50		\$0.00	\$229.44
Maintenance Requested: 8123 - 07/29/2014 - Problems entry door						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
03-10-1026 valve-quick		\$38.97				
release (1.000)						
03-10-1026 valve-quick		\$38.97				
release (1.000)						
Miscellaneous Parts		\$0				

157 - BROIN, DOUGLAS

\$151.50

Labor Comments: found bad latch sol. installed used part from old door module.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$77.94	\$151.50	\$0	\$0	<u>\$229.44</u>
-----	---------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 481,405.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19693	08/04/2014	08/05/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 8128 - 07/31/2014 - Main door slow to open

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$0.00

Labor Comments: fixed door on pervious work order, closing the maintence request.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$0	\$0	\$0	<u>\$0.00</u>
-----	-----	-----	-----	-----	---------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 481,405.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19785	08/12/2014	10/02/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$51.50		\$0.00	\$51.50

Maintenance Requested: 8198 - 08/28/2014 - Bottom step tread is loose

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$51.50

Labor Comments: Reinstalled lower step tread

Miscellaneous Labor

\$0

Other

\$0

78:Doors Entrance / Exit		\$848.07	\$28.50		\$0.00	\$876.57
--------------------------	--	----------	---------	--	--------	----------

Maintenance Requested: 8148 - 08/11/2014 - Entry door needs adjustment

Requestor Notes:

Technician Response:

Maint Req Status: Completed

04-23-1090 module-entrance
door (1.000)

\$848.07

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$28.50

Labor Comments: Installed new quick release valve for door latch.

Miscellaneous Labor

\$0

Other

\$0

CFR:Coolant Filter Replacement		\$10.33	\$31.50		\$0.00	\$41.83
--------------------------------	--	---------	---------	--	--------	---------

Pillsbury: Filter Coolant

\$10.33

(Charge) Cummins ISC/ISL,

CAT C-13: 4074 (1.000)

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

Labor Comments: Replaced coolant filter \$31.50

Miscellaneous Labor \$0

Other \$0

\$0.00	\$858.40	\$111.50	\$0	\$0	<u>\$969.90</u>
--------	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 482,923.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19902	08/21/2014	08/26/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$30.56	\$21.00		\$0.00	\$51.56

Pillsbury: Switch Rocker Door

\$30.56

EL3: 07-19-1016 (1.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (0.42)

\$21.00

Labor Comments: Install new door switch in dash

Miscellaneous Labor \$0

Other \$0

\$0	\$30.56	\$21.00	\$0	\$0	<u>\$51.56</u>
-----	---------	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 482,923.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
19936	08/25/2014	08/26/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$0	\$36.50		\$0.00	\$36.50

Maintenance Requested: 8186 - 08/23/2014 - see comments

Requestor Notes: Nail/staple or something is embedded in the top outside portion of the passenger rear tire. The nail/staple is located almost in line with the "ALCOA" emblem on the rim, just follow it straight up to the top of the tire.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0

7050 - STRAND, MATTHEW \$36.50

(0.73)

Labor Comments: pulled a sharp rock out of it, checked it with soapy water and checked air pressure

Miscellaneous Labor \$0

Other \$0

\$0	\$0	\$36.50	\$0	\$0	<u>\$36.50</u>
-----	-----	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 482,923.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
198984	09/03/2014	09/30/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
LOF:Lube, Oil, Filter		\$120.85	\$84.00		\$0.00	\$204.85

Pillsbury: Oil Analysis Kit:

\$9.25

Sample Kit (1.000)

Pillsbury: Filter Oil MCI D4500

\$14.80

w/Detroit Diesel 60 Series:
197 TWP (2.000)

Pillsbury: Oil Bulk in Quarts:

\$96.80

Oil 15W-40 Bulk (40.000)

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$84.00

Labor Comments: service engine

Miscellaneous Labor

\$0

Other

\$0

\$0	\$120.85	\$84.00	\$0	\$0	<u>\$204.85</u>
-----	----------	---------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 486,256.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199169	09/17/2014	09/29/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$302.50	\$150.00		\$0.00	\$452.50

Maintenance Requested: 8255 - 09/15/2014 - Windshield crack

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Glass Windshield

\$302.50

Front LH w/Mask MCI EL3:

03-27-1325 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$61.00

(1.22)

Labor Comments: installed driver windsheild

157 - BROIN, DOUGLAS

\$89.00

Labor Comments: Installed L/F windshield

Miscellaneous Labor

\$0

Other

\$0

\$0	\$302.50	\$150.00	\$0	\$0	<u>\$452.50</u>
-----	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 486,798.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199248	09/24/2014	09/29/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$0	\$84.00		\$0.00	\$84.00

used 22.5 tire (1.000)

\$0.00

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$84.00

Labor Comments: Found nail in tire. removed L/R tag tire and patched. when reinstalling tire the side wall started to rip so i installed a good used tire.

Miscellaneous Labor

\$0

Other

\$0

41:A/C & Heating

\$69.30

\$271.00

\$0.00

\$340.30

Pillsbury: Freon R134A per

\$69.30

Lb.: R134A (22.000)

Miscellaneous Parts

\$0

157 - BROIN, DOUGLAS

\$271.00

Labor Comments: Removed 6 lbs of freon and added nitrogen to find leak. replaced unloader gasket and retested. All was fine.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$69.30 \$355.00 \$0 \$0 \$424.30

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 487,801.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199447	10/13/2014	10/14/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$6.80	\$203.50		\$0.00	\$210.30
Pillsbury: Headlight Halogen		\$6.80				
Low Beam: 9006 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.07)			\$203.50			
Labor Comments: 36 -- Removed and replaced the right low beam head light.						
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$6.80 \$203.50 \$0 \$0 \$210.30

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 487,685.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199469	10/13/2014	10/20/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$124.61	\$100.00		\$0.00	\$224.61
Pillsbury: Switch ASM-Joystick,		\$124.61				
Mirror: 07-08-1891 (1.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$100.00			
Labor Comments: mirror inop and new switch didnt work. ordered another switch and all is working fine at this time.						
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$124.61 \$100.00 \$0 \$0 \$224.61

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 487,801.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199564	10/21/2014	10/22/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$4.12	\$11.50		\$0.00	\$15.62

Maintenance Requested: 8390 - 10/21/2014 - Door side fog light out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Bulb 12 Volt	\$4.12					
Mini Fog/Driving: BP1255/H3 (1.000)						
Miscellaneous Parts	\$0					
157 - BROIN, DOUGLAS			\$11.50			
Labor Comments: installed new bulb in r/f foglamp						
Miscellaneous Labor			\$0			

Other

\$0

\$0.00	\$4.12	\$11.50	\$0	\$0	<u>\$15.62</u>
--------	--------	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 488,246.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
199775	11/06/2014	11/10/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories		\$493.99	\$215.00		\$0.00	\$708.99
Pillsbury: cable,dvd 14 pin to e		\$30.50				
interm adapter: 511957						
(1.000)						
Pillsbury: Dvd Player,advanced		\$463.49				
system 12/24V: 710088						
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$215.00			
(4.30)						
Labor Comments: got the dvd player working correctly and cleaned the electrical mess up top and rewired the monitors to system that works						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$93.33	\$250.00		\$0.00	\$343.33
Pillsbury: Door seal:		\$62.06				
03-31-1188 (1.000)						
Pillsbury: Cover Assy, keypad		\$31.27				
silver: 11-02-1067 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$63.50			
(1.27)						
Labor Comments: put new radiator door seal on, adjusted the radiator door						
157 - BROIN, DOUGLAS			\$186.50			
Labor Comments: relocated emergency equipment and install new steering wheel pad.						
Miscellaneous Labor			\$0			
Other					\$0	
95:Service Calls		\$0	\$103.50		\$0.00	\$103.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$103.50			
(2.07)						
Labor Comments: had to run up to minnehaha falls and tighten up mirror						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$0	\$387.50		\$0.00	\$387.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$154.00			
(3.08)						
Labor Comments: went throught the bus and fixed litte things on it and creeped it good for its upcoming trip, also got new monitors coming for it						
157 - BROIN, DOUGLAS			\$233.50			
Labor Comments: check over entire bus for big trip						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$587.32	\$956.00	\$0	\$0	<u>\$1,543.32</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 488,363.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

5/7/2019

Work Order Detail

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
199917	11/20/2014	12/14/2014	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
73:Seats			\$0	\$134.00		\$0.00	\$134.00
Work Comments: Flipped 4 rows of seats and installed 4 tabs							
Miscellaneous Parts			\$0				
0423 - KRANZ, DANIEL (2.68)				\$134.00			
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$0	\$134.00	\$0	\$0	\$134.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 488,363.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
199928	11/21/2014	12/14/2014	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories			\$0	\$128.50		\$0.00	\$128.50
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$128.50			
(2.57)							
	Labor Comments: took dvd monitors out of 530 and put them in 527 for its upcoming trip						
Miscellaneous Labor				\$0			
Other						\$0	
84:Decals / Placards			\$26.54	\$10.00		\$0.00	\$36.54
Pillsbury: decal-emergency			\$13.86				
exit lh: 03-15-1429 (2.000)							
Pillsbury: Decal " Passenger			\$12.68				
window release": 03-15-1427							
(2.000)							
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$10.00			
	Labor Comments: installed missing window decals.						
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$26.54	\$138.50	\$0	\$0	\$165.04

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 488,993.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
200035	12/04/2014	12/14/2014	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating			\$0	\$47.50		\$0.00	\$47.50
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$47.50			
(0.95)							
	Labor Comments: webasto tune up						
Miscellaneous Labor				\$0			
Other						\$0	
72:Body Misc			\$0	\$76.50		\$0.00	\$76.50
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$76.50			
	Labor Comments: Filled all extra fluids, checked block heater and checked over bus for winter weather.						
Miscellaneous Labor				\$0			
Other						\$0	

\$0 \$0 \$124.00 \$0 \$0 \$124.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 488,993.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200047	12/05/2014	12/14/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
73:Seats		\$0	\$111.00		\$0.00	\$111.00

Work Comments: flipped 4 rows of seats back and uninstalled the 4 tables

Miscellaneous Parts		\$0				
0423 - KRANZ, DANIEL (2.22)			\$111.00			
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$0 \$111.00 \$0 \$0 \$111.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 488,993.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200048	12/05/2014	12/14/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 8539 - 12/05/2014 - Major problem with baggage door

Requestor Notes: LH rear baggage door wouldn't stay up, then wouldn't go down (unlock) Drive had to unbolt the eye bolt to get the door to come down.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			

Labor Comments: Doug went thru them yesterday

Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$0 \$0 \$0 \$0 \$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 489,095.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200133	12/12/2014	12/15/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$29.88	\$39.00		\$0.00	\$68.88

Pillsbury: Sleeve, Nylon for Windows: 03-27-1138 (2.000)

Pillsbury: Striker Assy-side \$28.58

sash: 03-27-1137 (2.000)

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.78)			\$39.00			

Labor Comments: window would not shut correctly, strikers worn out

Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$29.88 \$39.00 \$0 \$0 \$68.88

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 489,095.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200157	12/15/2014	12/15/2014	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories		\$0	\$44.00		\$0.00	\$44.00

Maintenance Requested: 8565 - 12/15/2014 - Middle DVD Screen doesn't work

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$44.00
 (0.88)

Labor Comments: bad connection, fixed wiring til i get right adapter

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$44.00 \$0 \$0 \$44.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 489,095.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
200531	01/20/2015	01/24/2015	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$354.10	\$35.00		\$0.00	\$389.10

Pillsbury: Battery 1400CCA \$354.10

Top Post Heavy Duty

Workaholic: 8D-MHD(7271)

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$35.00
 (0.70)

Labor Comments: bus sat for nearly 40 days without moving, swapped batteries out, and recharged old batteries and gonna test to see if they hold charge

Miscellaneous Labor \$0
 Other \$0

41:A/C & Heating		\$430.25	\$56.00		\$0.00	\$486.25
------------------	--	----------	---------	--	--------	----------

megatech temperature \$430.25

controller (1.000)

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$56.00
 (1.12)

Labor Comments: stoled heating controller out of this bus, replaced it

Miscellaneous Labor \$0
 Other \$0

50:Accessories		\$0	\$386.50		\$0.00	\$386.50
----------------	--	-----	----------	--	--------	----------

Work Comments: dash cluster stays on after bus is shut down

07-08-119 (1.000) \$0.00

referbished dash cluster \$0.00

(1.000)

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$269.00
 (5.38)

Labor Comments: fixed two e windows they werent latching, replaced strikers, fixed rattles, took for test drive, fixed electrical problem with the dash, had to switch clusters out,and rewired

dvd player, still waiting on parts for it, dash cost was 850 computer would not let me enter it

157 - BROIN, DOUGLAS		\$117.50			
Labor Comments: Installed used reberbished dash cluster					
Miscellaneous Labor		\$0			
Other				\$0	
75:Windows/windshields	\$57.16	\$110.00	\$0.00		\$167.16
Work Comments: 2 E-windows are loose.					
Pillsbury: Striker Assy-side sash: 03-27-1137 (4.000)	\$57.16				
Miscellaneous Parts	\$0				
157 - BROIN, DOUGLAS		\$110.00			
Labor Comments: Replaced 4 window strickers					
Miscellaneous Labor		\$0			
Other				\$0	
AD:Air Drier Service	\$113.20	\$65.00	\$0.00		\$178.20
Pillsbury: AD-IP Air Dryer	\$46.48				
Desiccant Cartridge Bendix: 109493BXR (1.000)					
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)	\$66.72				
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW (1.30)		\$65.00			
Labor Comments: rebuilt the air drier					
Miscellaneous Labor		\$0			
Other				\$0	
CR:Creep	\$0	\$126.50	\$0.00		\$126.50
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW (2.53)		\$126.50			
Labor Comments: looked over bus and steam cleaned it really good					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$954.71	\$779.00	\$0	\$0
					<u>\$1,733.71</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 586,644.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
201183	03/10/2015	03/21/2015	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting			\$44.09	\$53.50		\$0.00	\$97.59
Work Comments: Back up lights not all lit up							
Pillsbury: Light led 2 system			\$38.99				
back up: 4060C (1.000)							
Pillsbury: Light Rim Mount:			\$2.90				
91740 (2.000)							
Pillsbury: Pigtail: 94993			\$2.20				
(2.000)							
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$53.50			
Labor Comments: repaired wiring and replaced one BU light assy.							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$44.09	\$53.50	\$0	\$0	\$97.59

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 586,644.0

Work Order Detail

Recall:		Location: PBG Campaign #		Department: PBG5-Charter Date:			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
201299	03/19/2015	03/30/2015	Closed	0.00			
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38:Audio / Video Surveillance System			\$0	\$39.00		\$0.00	\$39.00
Work Comments: R/F DVD monitor not working							
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$39.00			
Labor Comments: Repaired wiring for monitor							
Miscellaneous Labor				\$0			
Other						\$0	
78:Doors Entrance / Exit			\$0	\$130.00		\$0.00	\$130.00
Work Comments: entrance door is leaking air							
Miscellaneous Parts			\$0				
157 - BROIN, DOUGLAS				\$130.00			
Labor Comments: repaired leaking air valves in door module with used parts from parts room.							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$0	\$169.00	\$0	\$0	\$169.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 586,644.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:		
WO #	Open Date	Close Date	Status	Downtime	Accident	
201374	03/26/2015	04/09/2015	Closed	0.00		
Detail	Discounts	Parts	Labor	Tires	Other	Total
38:Audio / Video Surveillance System		\$671.94	\$1,915.00		\$0.00	\$2,586.94
Work Comments: speakers and dvd system						
TA484L slide on terminal 2		\$5.76				
boxes (2.000)						
STP481 slide on terminal		\$7.00				
(50.000)						
STP484 slide on terminal		\$8.50				
(50.000)						
Pillsbury: microphone rubber		\$205.88				
coated 10' cord w/connector:						
7I-8-1310 (1.000)						
Pillsbury: Radio CD-2000,AM/		\$394.00				
FM/CD,MOD ADV: 710338						
(1.000)						
Pillsbury: cable,dvd 14 pin to e		\$30.50				
interm adapter: 511957						
(1.000)						
Pillsbury: cable(E) vcm to vcp		\$20.30				
3ft: 511074 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$961.00			
(19.22)						
Labor Comments: replaced every speaker and tweeter and got dvd system going and mic						
157 - BROIN, DOUGLAS			\$954.00			
(19.08)						
Labor Comments: Installed all new speakers, mic, radio and redid the wiring						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$78.75	\$81.00		\$0.00	\$159.75
Work Comments: filled a/c						
Pillsbury: Freon R134A per		\$78.75				
Lb.: R134A (25.000)						
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW (1.62)		\$81.00				
Labor Comments: a/c system empty filled it with 25 lbs for the weeked						
Miscellaneous Labor		\$0				
Other				\$0		
72:Body Misc	\$28.58	\$87.00		\$0.00		\$115.58
Pillsbury: Striker Assy-side sash: 03-27-1137 (2.000)	\$28.58					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (1.74)		\$87.00				
Labor Comments: installed new strikers on the 2nd window back driverside, complaints about whistling noise thru it						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$779.27	\$2,083.00	\$0	\$0	<u>\$2,862.27</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 586,644.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
201489	04/07/2015	04/07/2015	Closed	0.00		
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>
38:Audio / Video Surveillance System			\$443.85	\$0		\$0.00
710088 dvd player advanced system (1.000)			\$443.85			
Part Comments: work was done on wo 201374 this wo is for parts only						
Miscellaneous Parts			\$0			
Miscellaneous Labor				\$0		
Other					\$0	
		\$0	\$443.85	\$0	\$0	<u>\$443.85</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 587,136.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
201688	04/23/2015	04/24/2015	Closed	0.00		
Description: fuel filters;etc						
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>
38:Audio / Video Surveillance System			\$0	\$5.00		\$0.00
Miscellaneous Parts			\$0			
74 - PHIPPS, KEVIN (0.10)				\$5.00		
Labor Comments: Add stops to shade rails to keep shade above camera.						
Miscellaneous Labor				\$0		
Other					\$0	
77:Mirrors			\$0	\$33.50		\$0.00
Work Comments: Out of adj						
Miscellaneous Parts			\$0			
74 - PHIPPS, KEVIN (0.67)				\$33.50		
Labor Comments: Adjusted both mirrors						
Miscellaneous Labor				\$0		
Other					\$0	
FF:Fuel Filter			\$8.14	\$115.00		\$0.00
Pillsbury: Filter Fuel: 3118 (1.000)			\$4.06			
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)			\$4.08			
						\$123.14

5/7/2019

Work Order Detail

Miscellaneous Parts
74 - PHIPPS, KEVIN (2.30)

\$0 \$115.00

Labor Comments: Replace fuel filters

Miscellaneous Labor
Other\$0
\$0\$0 \$8.14 \$153.50 \$0 \$0 \$161.64

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 587,360.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
201890	05/07/2015	05/11/2015	Closed	0.00	

Description: write up for radio

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38:Audio / Video Surveillance System		\$0	\$14.00		\$0.00	\$14.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$14.00			
(0.28)						
Labor Comments: radio works just fine						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$14.00	\$0	\$0	<u>\$14.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 587,360.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202060	05/20/2015	05/22/2015	Closed	0.00	

Description: hub service, air filter replacement, creep

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
AF:Air Filter Replacement		\$41.74	\$5.00		\$0.00	\$46.74
Pillsbury: Filter Air: 6741		\$41.74				
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$5.00			
(0.10)						
Labor Comments: replaced air filter						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$0	\$30.00		\$0.00	\$30.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$30.00			
(0.60)						
Labor Comments: crept the bus, fixed one reading light and one foot rests						
Miscellaneous Labor			\$0			
Other					\$0	
HUB:Hub Service		\$23.92	\$68.00		\$0.00	\$91.92
Pillsbury: Oil Gear Synthetic:		\$23.92				
Oil Gear 75W-90 BULK in						
quarts (8.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$68.00			
(1.36)						
Labor Comments: changed the steer and tag hub fluid						
Miscellaneous Labor			\$0			
Other					\$0	
SC:Steam Clean		\$0	\$17.50		\$0.00	\$17.50
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW
(0.35)

\$17.50

Labor Comments: steam cleaned by the fuel tank, possible fuel leak, or they are overfilling it. and
cleaned the engine off

Miscellaneous Labor

\$0

Other

\$0

\$0 \$65.66 \$120.50 \$0 \$0 \$186.16

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 588,268.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
202119	05/27/2015	06/03/2015	Closed	0.00	

Description: A/C Leak

Detail	Discounts	Parts	Labor	Tires	Other	Total
22:Tires		\$13.97	\$150.00		\$0.00	\$163.97

Pillsbury: Tie Down ring-
recessed: B901 (1.000)

\$13.97

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(3.00)

\$150.00

Labor Comments: had to install a spare tire hold on

Miscellaneous Labor

\$0

Other

\$0

31:Charging

\$17.09

\$127.00

\$0.00

\$144.09

Work Comments: 50DN front seal is leaking

Part came from EBG

10524486 part from Egan
(1.000)

\$17.09

Part Comments: Part came from eagan

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(1.76)

\$88.00

Labor Comments: front seal on the 50 dn is leaking, dont have the right seal, got it ordered

157 - BROIN, DOUGLAS

\$39.00

Labor Comments: Removed and replaced the 50DN front seal. We got the part from Dan at Egan

Miscellaneous Labor

\$0

Other

\$0

41:A/C & Heating

\$823.83

\$870.00

\$0.00

\$1,693.83

Work Comments: a/c is leaking out

Pillsbury: Clutch Assy 24vdc:
16-02-1040 (1.000)

\$470.00

Pillsbury: Freon R134A per
Lb.: R134A (26.000)

\$77.30

Pillsbury: Carrier Front Seal
Kit O5G A/C Compressor

\$90.74

MCID4500: 16L-2-112 (1.000)

10549059 nut a/c clutch
(1.000)

\$33.70

10517299 hub, clutch
mounting (1.000)

\$109.31

16j-2-17 nut (1.000)

\$42.78

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(9.00)

\$450.00

Labor Comments: Had to find a/c leak and fix it and charged system

157 - BROIN, DOUGLAS

\$420.00

Labor Comments: A/C had a leak. Found front comp seal leaking and high side service port. tightned
service port, installed new seal and clutch assy. Filled with freon and tested.

Miscellaneous Labor

\$0

Other

\$0

5/7/2019

Work Order Detail

48:Fuel System	\$13.60	\$191.00	\$0.00	\$204.60
Pillsbury: Filter Fuel: 3118	\$4.06			
(1.000)				
Pillsbury: 3/8" Ball Valve:	\$9.54			
63135 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$191.00		
(3.82)				
Labor Comments: fuel filter shut off valve was leaking, had to replace				
Miscellaneous Labor		\$0		
Other			\$0	

\$0.00	\$868.49	\$1,338.00	\$0	\$0	<u>\$2,206.49</u>
--------	----------	------------	-----	-----	-------------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 588,861.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202279	06/10/2015	06/22/2015	Closed	0.00	

Description: Bus leans in garage

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$0	\$57.50		\$0.00	\$57.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$57.50			
(1.15)						

Labor Comments: tried to find air leak, bus leans in the bus, not successful

Miscellaneous Labor		\$0				
Other					\$0	
51:Communications		\$690.05	\$0		\$0.00	\$690.05
750025 mic 16 channel		\$659.70				
wireless (1.000)						
511472 cable 16 channel rcvr		\$17.50				
charger (1.000)						
560604 bracket (1.000)		\$12.85				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$0	\$73.50		\$0.00	\$73.50

Maintenance Requested: 8934 - 06/11/2015 - Water leaks-Rt side, see comments

Requestor Notes: First 3 seats affected, possible under drip rail...

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$73.50			
(1.47)						
Labor Comments: sealed up the roof of the bus						
Miscellaneous Labor			\$0			
Other					\$0	

\$0.00	\$690.05	\$131.00	\$0	\$0	<u>\$821.05</u>
--------	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 588,861.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202286	06/11/2015	06/22/2015	Closed	0.00	

Description: water leaks RF side

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$15.00		\$0.00	\$15.00

Work Comments: Water leaks first 3 RH seats

Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.30)		\$15.00				
Labor Comments: No time to do anything at this time. Wrote up maint req						
Miscellaneous Labor	\$0					
Other					\$0	
	\$0	\$0	\$15.00	\$0	\$0	<u>\$15.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 589,382.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202316	06/15/2015	07/01/2015	Closed	0.00	

Description: mirror

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$0	\$42.50		\$0.00	\$42.50

Work Comments: 77:Mirrors -- Broken road side mirror

Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (0.85)		\$42.50				

Labor Comments: 77:Mirrors -- Broken road side mirror --- Removed and replaced the glass only.
(Used glass)

Miscellaneous Labor	\$0					
Other					\$0	
	\$0	\$0	\$42.50	\$0	\$0	<u>\$42.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 589,816.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202429	06/22/2015	06/30/2015	Closed	0.00	

Description: transmission and etc

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$226.47	\$567.50		\$0.00	\$793.97

Work Comments: Bushing is bad

Pillsbury: Rod Assy-radius drive axle: 12-05-1010 (1.000)	\$226.47					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (5.37)		\$268.50				

Labor Comments: radial arm bushing bad. bolt broke off in the cast body, took a lot of time to drill out and
retap

157 - BROIN, DOUGLAS	\$299.00					
Labor Comments: Rod assy. bolt broke. had to drill and rethread.						
Miscellaneous Labor	\$0					
Other					\$0	

22:Tires		\$1,638.00	\$159.00		\$0.00	\$1,797.00
Pillsbury: Tire, Steer,Toyo M144: 315/80R22.5 (4.000)	\$1,638.00					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (3.18)		\$159.00				

Labor Comments: drive tires were down to a 3, but new tread on

Miscellaneous Labor	\$0					
Other					\$0	
25:Transmission (Auto)	\$0	\$230.00			\$0.00	\$230.00

Work Comments: clunk when down shifting

Miscellaneous Parts	\$0					
---------------------	-----	--	--	--	--	--

157 - BROIN, DOUGLAS			\$84.00			
	Labor Comments: drove and inspected bus to find r/h lower drive axle bushing bad.					
7050 - STRAND, MATTHEW			\$146.00			
(2.92)	Labor Comments: drove to find clunking noise, run several test thru the computer, it was actually suspension, bad radial arm					
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$25.00		\$0.00	\$25.00
	Work Comments: A/c LEAK					
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$25.00			
	Labor Comments: Found a A/C leak at condenser. Needs new condenser. Tom will order..					
Miscellaneous Labor			\$0			
Other					\$0	
48:Fuel System		\$0	\$37.50		\$0.00	\$37.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$37.50			
(0.75)	Labor Comments: possibly found the leak, resealed it, think its because they are overfueling it and the clamp for the drain hose came off due to old age.					
Miscellaneous Labor			\$0			
Other					\$0	
50:Accessories		\$0	\$48.50		\$0.00	\$48.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$48.50			
(0.97)	Labor Comments: installed wireless microphone, still need to fine tune it, parts are on previous work order					
Miscellaneous Labor			\$0			
Other					\$0	
TF:Transmission Flush		\$202.69	\$106.50		\$0.00	\$309.19
Pillsbury: Filter Kit		\$31.61				
Transmission Allison (Short Filter): 7741XE (1.000)						
Pillsbury: Fluid ATF (Synthetic)		\$171.08				
Bulk Quart: ATF Synthetic Bulk (28.000)						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$106.50			
	Labor Comments: Did a tranny service					
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$2,067.16	\$1,174.00	\$0	\$0
						<u>\$3,241.16</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 590,530.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202599	07/09/2015	07/15/2015	Closed	0.00	

Description: a/c

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$79.24	\$263.50		\$0.00	\$342.74
	Work Comments: a/c inop					
Pillsbury: Freon R134A per Lb.: R134A (28.000)		\$79.24				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$138.50			
(2.77)	Labor Comments: added freon to system					
157 - BROIN, DOUGLAS			\$125.00			

Labor Comments: refilled system until we get a new condensor

Miscellaneous Labor						\$0
Other						\$0
	\$0	\$79.24	\$263.50	\$0	\$0	<u>\$342.74</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 592,105.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202663	07/15/2015	07/27/2015	Closed	0.00	

Description: LOF/ Coolant pump/ Fan clutch

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
43: Cooling		\$1,675.95	\$191.50		\$0.00	\$1,867.45
Work Comments: fan clutch is bad						
Pillsbury: Coolant Pump MCI		\$593.30				
EL3: 16-16-1101 (1.000)						
228006 fan clutch (1.000)		\$1,082.65				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$19.00			
(0.38)						
Labor Comments: coolant pump and fan clutch junk						
161 - SPARKS, MICHAEL			\$80.00			
(1.60)						
Labor Comments: R&R leaking coolant pump. Filled coolant back up to correct level.						
157 - BROIN, DOUGLAS			\$92.50			
Labor Comments: Installed new fan clutch assy.						
Miscellaneous Labor			\$0			
Other					\$0	
DO: DOT Inspection		\$2.00	\$87.50		\$0.00	\$89.50
Sticker (1.000)		\$2.00				
Part Comments: dot sticker 2.00 \$						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$48.50			
(0.97)						
Labor Comments: did a dot on it						
157 - BROIN, DOUGLAS			\$39.00			
Labor Comments: helped with DOT						
Miscellaneous Labor			\$0			
Other					\$0	
LOF: Lube, Oil, Filter		\$120.05	\$147.50		\$0.00	\$267.55
Pillsbury: Filter Oil MCI D4500		\$14.80				
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Analysis Kit:		\$9.25				
Sample Kit (1.000)						
Pillsbury: Oil Bulk in Quarts:		\$96.00				
Oil 15W-40 Bulk (40.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$147.50			
(2.95)						
Labor Comments: did a complete service						
Miscellaneous Labor			\$0			
Other					\$0	
PMI: Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$1,798.00	\$426.50	\$0	\$0	<u>\$2,224.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 591,074.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202703	07/17/2015	07/21/2015	Closed	0.00	

Description: paper work in windshield

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$97.50		\$0.00	\$97.50
Work Comments: 75 -- Drivers paperwork slid between the dash and the windshield						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.95)			\$97.50			
Labor Comments: 75 -- Drivers paperwork slid between the dash and the windshield ---- Removed the plexy glass below the windshield and pulled the drivers paperwork out . Renistalled the wipers, the plexy glass and the lock strip. Siliconed around the wipers to keep the water out.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$97.50	\$0	\$0	<u>\$97.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 592,104.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202780	07/24/2015	07/29/2015	Closed	0.00	

Description: lighting and A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$16.00		\$0.00	\$16.00
Work Comments: check all floor blue lights						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$16.00			
Labor Comments: Adjusted all floor blue lights.						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$0	\$160.00		\$0.00	\$160.00
Work Comments: not cooling						
Miscellaneous Parts		\$0				
157 - BROIN, DOUGLAS			\$160.00			
Labor Comments: Removed all freon and did a full recharge						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$176.00	\$0	\$0	<u>\$176.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 592,105.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202807	07/28/2015	07/29/2015	Closed	0.00	

Description: door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$35.05	\$60.00		\$0.00	\$95.05
Pillsbury: Switch Toggle		\$35.05				
Exterior Door Control MCI						
D4500: 7L-8-553 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.20)			\$60.00			

Labor Comments: Replace outside toggle for ent door.

Miscellaneous Labor

\$0

Other

\$0

\$0.00	\$35.05	\$60.00	\$0	\$0	<u>\$95.05</u>
--------	---------	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 592,792.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202824	07/29/2015	08/03/2015	Closed	0.00	

Description: Door Not Opening Properly

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$109.00		\$0.00	\$109.00

Work Comments: see wo #19785 for billing of 04-29-1090

04-29-1090 (1.000) \$0.00

Part Comments: we had this on our shelf back by our bay its for the door air system. billed to wo #19785 was never installed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$109.00

(2.18)

Labor Comments: found out it was the door air module, replace it and tested door

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$109.00	\$0	\$0	<u>\$109.00</u>
-----	-----	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 592,839.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
202879	08/03/2015	08/05/2015	Closed	0.00	

Description: A/C too cold?

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$33.50		\$0.00	\$33.50

Maintenance Requested: 8982 - 07/31/2015 - Air Controls not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$33.50

(0.67)

Labor Comments: Checked over the A/C because of complaints of it being to cold. It seems to be working just fine, tested it at its coldest and in the upper seventies, the bus keeps the climate you want

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$33.50	\$0	\$0	<u>\$33.50</u>
-----	-----	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 594,885.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203081	08/24/2015	08/28/2015	Closed	0.00	

Description: 49-air leaks

5/7/2019

Work Order Detail

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$472.17	\$481.50		\$0.00	\$953.67
Pillsbury: Valve Assy, suspension, aux MCI EL3: 800174 (1.000)		\$154.94				
04-19-1004 air tank (2.000)		\$217.28				
RO30612 cut off valve (1.000)		\$99.95				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (9.63)			\$481.50			
Labor Comments: Replace leaking valve on RR susp. Found both R side susp tanks to be rusted through at brackets, got 2 from C&J,s and installed.						
Miscellaneous Labor			\$0			
Other					\$0	
79:Lavatory		\$137.32	\$56.00		\$0.00	\$193.32
Pillsbury: Valve Slide, lavatory: 17-05-1095 (1.000)		\$41.47				
645 hose (3.000)		\$95.85				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.12)			\$56.00			
Labor Comments: Replace leaking lav valve. New hose.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$609.49	\$537.50	\$0	\$0	<u>\$1,146.99</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 593,870.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203133	08/28/2015	08/31/2015	Closed	0.00	

Description: int lights

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
24volt module-used-# 07-18-1004		\$0	\$201.00		\$0.00	\$201.00
Work Comments: LH rear bank of int lights in aisle and windows out.						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (4.02)			\$201.00			
Labor Comments:						
Found rubbed through wire for aisle lights--repaired; bad output on relay module--replaced.						
Miscellaneous Labor			\$0			
Other					\$0	
int lights-see comm...		\$0	\$1.00		\$0.00	\$1.00
Maintenance Requested: 9024 - 08/28/2015 - int lights-see comm...						
Requestor Notes: LH aisle and window lights out both banks of 4. WO# 203133						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.02)			\$1.00			
Labor Comments: DONE.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$202.00	\$0	\$0	<u>\$202.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 595,310.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203243	09/04/2015	09/14/2015	Closed	0.00	

<u>Detail</u>	Description: A/C	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating			\$22.64	\$125.00		\$0.00	\$147.64
Work Comments: 41 -- A/C system low on freon							
Pillsbury: Freon R134A per			\$22.64				
Lb.: R134A (8.000)							
Miscellaneous Parts			\$0				
0081 - WOLF, PATRICK (2.50)				\$125.00			
Labor Comments: 41 -- A/C system low on freon ---- Top off the A/C system with freon.							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$22.64	\$125.00	\$0	\$0	<u>\$147.64</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 596,474.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203486	09/23/2015	09/23/2015	Closed	0.00	

Description: glass repair

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00
Repair, Inv. # 2784622, Desc:						
glass repair						
75:Windows/windshields		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$0	\$0	\$35.00	<u>\$35.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 596,868.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203551	09/29/2015	09/30/2015	Closed	0.00	

Description: Smell exhaust inside bus; tag brakes

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$1,457.52	\$669.00		\$0.00	\$2,126.52
Work Comments: Slide boots torn on caliper						
Pillsbury: Pad Fitting Kit; 1 per		\$110.30				
axle; EL3: 04-01-1008 (1.000)						
Pillsbury: Kit Spreader MCI		\$164.69				
EL3: 04-01-1014 (1.000)						
Pillsbury: Pads brake EL3:		\$226.11				
04-01-1019 (1.000)						
Pillsbury: Guide Pin Kit,		\$168.40				
Caliper;EL3: 04-01-1046						
(1.000)						
Pillsbury: Dust Boot Kit;		\$16.32				
Caliper; EL3: 04-01-1012						
(1.000)						
Pillsbury: Adjuster LH:		\$154.60				
04-01-1049 (1.000)						
Pillsbury: MCI Caliper Kit RHS:		\$490.61				
04-01-1042 (1.000)						
04-01-1050 kit-adjuster R		\$126.49				
(1.000)						
Miscellaneous Parts		\$0				

5/7/2019

Work Order Detail

74 - PHIPPS, KEVIN (13.38)			\$669.00			
Labor Comments: Major O/H of L tag caliper and R tag caliper, torque wheels at 475 ft lbs.						
Miscellaneous Labor			\$0			
Other					\$0	
46:Exhaust System	\$1,503.30	\$184.00		\$0.00		\$1,687.30
Work Comments: Needs flex pipe asm.						
08-20-1001 pipe-exhaust s60 flexible (1.000)	\$1,503.30					
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (3.68)		\$184.00				
Labor Comments: Waiting for OK to order pipe asm=\$1500						
Miscellaneous Labor		\$0				
Other				\$0		
49:Air System	\$0	\$145.00		\$0.00		\$145.00
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (2.90)		\$145.00				
Labor Comments: Air leaks, brake valve, bioth tag chambers--parts ordered						
Miscellaneous Labor		\$0				
Other				\$0		
CFR:Coolant Filter Replacement	\$5.34	\$16.00		\$0.00		\$21.34
Pillsbury: Filter Coolant	\$5.34					
Cummins ISM: 4071 (1.000)						
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.32)		\$16.00				
Labor Comments: Change out coolant filter						
Miscellaneous Labor		\$0				
Other				\$0		
CR:Creep	\$0	\$11.50		\$0.00		\$11.50
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.23)		\$11.50				
Miscellaneous Labor		\$0				
Other				\$0		
RT:Road Test	\$0	\$30.00		\$0.00		\$30.00
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.60)		\$30.00				
Miscellaneous Labor		\$0				
Other				\$0		
SC:Steam Clean	\$0	\$45.00		\$0.00		\$45.00
Miscellaneous Parts	\$0					
74 - PHIPPS, KEVIN (0.90)		\$45.00				
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$2,966.16	\$1,100.50	\$0	\$0	<u>\$4,066.66</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 597,769.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
203776	10/15/2015	10/16/2015	Closed	0.00	

Description: buff

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$450.00		\$0.00	\$450.00
Work Comments: i buff all buss with #1compunt and #2						
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS (9.00)			\$450.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$450.00	\$0	\$0	<u>\$450.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 597,945.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
203843	10/20/2015	10/20/2015	Closed	0.00	

Description: A/C

Detail	Discounts	Parts	Labor	Tires	Other	Total
41:A/C & Heating		\$140.20	\$345.00		\$0.00	\$485.20

Maintenance Requested: 9212 - 10/19/2015 - Air not cooling

Requestor Notes:

Technician Response: 41

Maint Req Status: Completed

Pillsbury: Freon R134A per

\$62.26

Lb.: R134A (22.000)

Pillsbury: Viscosity 32 oz: PAG

\$77.94

Oil CQP100-32 (3.800)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (6.90)

\$345.00

Labor Comments: 41 -- A/C not working ---- Filled the compressor with A/C oil. Refilled the A/C system with 134a.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$140.20	\$345.00	\$0	\$0	\$485.20
-----	----------	----------	-----	-----	----------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 598,171.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
203933	10/28/2015	10/29/2015	Closed	0.00	

Description: brake valve R14

Detail	Discounts	Parts	Labor	Tires	Other	Total
49:Air System		\$227.97	\$166.00		\$0.00	\$393.97

Work Comments: Installed new R14 valve-- part is on some other WO?

04-11-1003 valve assy-

\$146.55

emergency relay (1.000)

4R-22-38 valve assy-check

\$81.42

1/2" (3.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (3.32)

\$166.00

Labor Comments: Install new valve.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$227.97	\$166.00	\$0	\$0	\$393.97
-----	----------	----------	-----	-----	----------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 598,357.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
204028	11/06/2015	11/19/2015	Closed	0.00	

Description: PMI & List

Detail	Discounts	Parts	Labor	Tires	Other	Total
13:Brakes		\$19.04	\$33.50		\$0.00	\$52.54

Pillsbury: Crimp Fitting

\$19.04

Female swivel JIC 1/2: FG-

JCFX-1010 (2.000)

Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$33.50		
(0.67)				
Labor Comments: Made new right side front brake line				
Miscellaneous Labor		\$0		
Other			\$0	
20:Steering	\$181.58	\$111.00	\$0.00	\$292.58
Pillsbury: Draglink End RH	\$90.79			
EL3 MCI: 11-04-1005 (1.000)				
Pillsbury: Draglink End LH	\$90.79			
EL3 MCI: 11-04-1006 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$111.00		
(2.22)				
Labor Comments: replaced both tie rods on the drag link				
Miscellaneous Labor		\$0		
Other			\$0	
21:Suspension	\$890.84	\$621.00	\$0.00	\$1,511.84
Pillsbury: Rod Assy-radius	\$231.00			
drive axle: 12-05-1010 (1.000)				
Pillsbury: Bushing V link:	\$74.76			
12-05-1033PK (2.000)				
Pillsbury: V-Link EL3 MCI:	\$585.08			
12-05-1211 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$253.50		
(5.07)				
Labor Comments: replaced Vlink and radial arm				
0081 - WOLF, PATRICK (6.22)		\$311.00		
Labor Comments: 21 -- Drive axle v-link bad ---- Heated up and removed the v-link bolts. Cleaned out the threads with a tap. Mounted the new v-nk into place,toqued the bolts and bent over all the lock tabs.				
0146 - SHIPPY, CURTIS (1.13)		\$56.50		
Labor Comments: Fixed bolt hole treads that were bad on the "V"-link				
Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$0	\$111.50	\$0.00	\$111.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$111.50		
(2.23)				
Labor Comments: air leak out of an plastic air manifold, replaced it with brass				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$0	\$157.50	\$0.00	\$157.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$157.50		
(3.15)				
Labor Comments: did a PMI				
Miscellaneous Labor		\$0		
Other			\$0	
RT:Road Test	\$0	\$0	\$0.00	\$0.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$0.00		
(0.00)				
Labor Comments: did not get to a road test, but they drove it that weekend				
Miscellaneous Labor		\$0		
Other			\$0	
SC:Steam Clean	\$0	\$13.50	\$0.00	\$13.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$13.50		
(0.27)				
Labor Comments: Possible fuel leak or its the freon thats making a mess underneath the mid of the bus, probably third time ive cleaned it and it seems to be getting better each time.				
Miscellaneous Labor		\$0		
Other			\$0	

\$0 \$1,091.46 \$1,048.00 \$0 \$0 \$2,139.46

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 598,710.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204203	11/18/2015	11/19/2015	Closed	0.00	

Description: FF, Road Test

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
FF:Fuel Filter		\$8.14	\$16.50		\$0.00	\$24.64
Pillsbury: Filter Fuel: 3118 (1.000)		\$4.06				
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)		\$4.08				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.33)			\$16.50			
Labor Comments: Changed FF						
Miscellaneous Labor			\$0			
Other					\$0	
RT:Road Test		\$0	\$15.00		\$0.00	\$15.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.30)			\$15.00			
Labor Comments: took on road test I didnt get to last week. Drove good but it was really windy out						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$8.14	\$31.50	\$0	\$0	<u>\$39.64</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 598,710.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204232	11/20/2015	11/23/2015	Closed	0.00	

Description: check heat

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$31.00		\$0.00	\$31.00
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.62)			\$31.00			
Labor Comments: Aux heater, fans all worked well; good air flow; air heating up.						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$0	\$71.00		\$0.00	\$71.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.42)			\$71.00			
Labor Comments: Checked over radio/dvd/pa systems. Fixed DVD Monitor.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$102.00	\$0	\$0	<u>\$102.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 598,710.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

5/7/2019

Work Order Detail

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204235	11/20/2015	11/23/2015	Closed	0.00	

Description: tables install

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$158.50		\$0.00	\$158.50
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (3.17)			\$158.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$158.50	\$0	\$0	<u>\$158.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 599,427.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204493	12/11/2015	12/15/2015	Closed	0.00	

Description: Code 50

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories		\$0	\$58.50		\$0.00	\$58.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.17)			\$58.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$58.50	\$0	\$0	<u>\$58.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 599,427.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204494	12/11/2015	12/15/2015	Closed	0.00	

Description: Drivers Fan, Replaced DVD Monitor

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield Repair, Inv. # 2784826					\$35.00	\$35.00
50:Accessories		\$28.49	\$53.50		\$0.00	\$81.99
Pillsbury: Fan Metal W/ Bergstrom Base: TAD000093 (1.000)		\$28.49				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.07)			\$53.50			
Labor Comments: replaced the drivers fan, and replaced a DVD monitor. Something goofy happened with the previous work order i opened on this bus						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$28.49	\$53.50	\$0	\$35.00	<u>\$116.99</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 599,625.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204587	12/18/2015	12/24/2015	Closed	0.00	

Description: High Beam Indicator Out

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$70.00		\$0.00	\$70.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.40)			\$70.00			
Labor Comments: high beam indicator does not come out, switched out the piano module and now it works						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$70.00	\$0	\$0	<u>\$70.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 599,625.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204600	12/21/2015	12/24/2015	Closed	0.00	

Description: Module was bad

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
37:Warning, Strobe, 8-Ways		\$0	\$167.50		\$0.00	\$167.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.35)			\$167.50			
Labor Comments: the main controller module i replaced from 5522 was bad, but the old one back in. It just does not have a high beam indicator. Test drove three times and got tommy the part number, to try and get another one coming						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$167.50	\$0	\$0	<u>\$167.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 599,625.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204706	01/04/2016	01/05/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$388.00		\$0.00	\$388.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (7.76)			\$388.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$388.00	\$0	\$0	<u>\$388.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 599,813.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204754	01/06/2016	01/18/2016	Closed	0.00	

Description: Electrical and Air Drier

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$111.50		\$0.00	\$111.50
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW (2.23)			\$111.50			
Labor Comments: still trying to figure out the high beam indicator not working problem						
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service	\$113.20	\$73.50		\$0.00		\$186.70
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)	\$66.72					
Pillsbury: AD-IP Air Dryer Desiccant Cartridge Bendix: 109493BXR (1.000)	\$46.48					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (1.47)		\$73.50				
Labor Comments: Air Drier Service						
Miscellaneous Labor		\$0				
Other				\$0		
CR:Creep	\$0	\$50.00		\$0.00		\$50.00
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (1.00)		\$50.00				
Labor Comments: shot alcohol into the system and looked bottom side and fluids over. and added anti gel to the fuel						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$113.20	\$235.00	\$0	\$0	<u>\$348.20</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 600,299.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
204976	01/22/2016	02/01/2016	Closed	0.00	

Description: V-link,air bag

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$214.96	\$246.00		\$0.00	\$460.96

Work Comments: 21 -- Both bolts on one side of the v broken off.

Sliced a hole thru the same airbag.

Pillsbury: Spring Air Bag, Drive

\$140.20

Axle: 12-03-1041 (1.000)

Pillsbury: Bushing V link:

\$74.76

12-05-1033PK (2.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (4.92)

\$246.00

Labor Comments: 21 -- Both bolts on one side of the v broken off. ---- Removed the other half of the
v-link. Extracted the broken bolts. Installed new bushings and bolts. Had to make new
lock tabs.

Sliced a hole thru the same airbag. ---- Removed and replaced the punctured air
bag.

Miscellaneous Labor

\$0

Other

\$0

\$0.00	\$214.96	\$246.00	\$0	\$0	<u>\$460.96</u>
--------	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 600,630.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
-------------	------------------	-------------------	---------------	-----------------	-----------------

5/7/2019

Work Order Detail

205081 02/01/2016 02/03/2016 Closed 0.00

Description: BB Locks

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00
Repair, Inv. # 2784885						
72:Body Misc		\$480.60	\$181.50		\$0.00	\$662.10
Pillsbury: Lock/Keys Kit EL3		\$480.60				
MCI: 3R-29-61 (6.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (3.63)			\$181.50			
Labor Comments: Install new locks in baggage doors; adjust and lube linkages. Add pull cords						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$480.60	\$181.50	\$0	\$35.00	<u>\$697.10</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 600,630.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205170	02/08/2016	02/12/2016	Closed	0.00	

Description: cond unit changeout; air; trans

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$6.02	\$155.50		\$0.00	\$161.52
Pillsbury: Fluid ATF (Synthetic)		\$6.02				
Bulk Quart: ATF Synthetic Bulk (2.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (3.11)			\$155.50			
Labor Comments: Replaced retarder solenoid on accumulator. Test drove--works great						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$122.50	\$595.00		\$0.00	\$717.50
Work Comments: Condensor core leaking						
Foam Tape (1.000)		\$14.98				
Pillsbury: Freon R134A per Lb.: R134A (24.000)		\$67.92				
G33710-0404 coupling		\$24.58				
PT307 connector (1.000)		\$15.02				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (11.90)			\$595.00			
Labor Comments: Replaced core asm with that taken from 522; pressure checked core and system--OK; cleaned and fastened cables and harness; vac'd and filled system. Run and check--OK						
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$17.38	\$216.50		\$0.00	\$233.88
Work Comments: Rapid cycling of air dryer purge valve.						
Pillsbury: Governor Air Compressor D-2: 0R275491 X (1.000)		\$17.38				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (4.33)			\$216.50			
Labor Comments: Found governor to be loose. Replaced with new and with longer bolts. Cleaned fittings and put all back together						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$145.90	\$967.00	\$0	\$0	<u>\$1,112.90</u>

VIN: 1M8TRMPA6WP060245

License Plate:

5527: 1998 MCI EL3

Miles: 601,193.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205335	02/18/2016	02/20/2016	Closed	0.00	

Description: lights,tire,belt

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$0	\$16.00		\$0.00	\$16.00

Work Comments: 22 -- Right front tire wear.

Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (0.32)			\$16.00			

Labor Comments: 22 -- Right front tire wear. ---- Checked out the right front tire. Has a little excessive wear on the outer edge like all the buses but well within specs. for being lega

Miscellaneous Labor			\$0			
Other					\$0	

36:Lighting		\$21.28	\$98.50		\$0.00	\$119.78
-------------	--	---------	---------	--	--------	----------

Work Comments: 36 -- Right side turn lamp out.

Pillsbury: Light Non LED		\$21.28				
Amber Side Marker/Turn MCI						
EL3: 07-07-1003 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.97)			\$98.50			

Labor Comments: 36 -- Right side turn lamp out. ---- The lens was on upsidedown. tried a new bulb but had to replace the assy. all corroded. Also switched two other lenses right side up.

Miscellaneous Labor			\$0			
Other					\$0	

40:Engine		\$57.10	\$43.50		\$0.00	\$100.60
-----------	--	---------	---------	--	--------	----------

Work Comments: 40 -- Fan belt worn

Pillsbury: Belt EL3:		\$57.10				
08-27-1002 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.87)			\$43.50			

Labor Comments: 40 -- Fan belt worn ---- Removed and replaced the fan belt.

Miscellaneous Labor			\$0			
Other					\$0	

	\$0	\$78.38	\$158.00	\$0	\$0	\$236.38
--	-----	---------	----------	-----	-----	----------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 601,192.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205347	02/18/2016	02/20/2016	Closed	0.00	

Description: dirty evap filters

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$4.72	\$55.00		\$0.00	\$59.72

Pillsbury: Filter Media: 4WZ68		\$4.72				
(8.000)						

Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.10)			\$55.00			

Labor Comments: Install new filter media

Miscellaneous Labor			\$0			
Other					\$0	

	\$0	\$4.72	\$55.00	\$0	\$0	\$59.72
--	-----	--------	---------	-----	-----	---------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 601,340.0

Recall: Location: PBG Campaign # Department: PBG5-Charter Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
205434	02/25/2016	02/27/2016	Closed	0.00		
Description: Lighting/ Creep						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$56.50		\$0.00	\$56.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$56.50			
(1.13)						
Labor Comments: rewired the left front fog light						
replaced reading lamp						
replaced bathroom telltale lights						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$0	\$13.50		\$0.00	\$13.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$13.50			
(0.27)						
Labor Comments: crept the bus						
replaced cup holders that were broken						
Miscellaneous Labor			\$0			
Other					\$0	
SC:Steam Clean		\$0	\$32.50		\$0.00	\$32.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$32.50			
(0.65)						
Labor Comments: Cleaned the engine.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$102.50	\$0	\$0	\$102.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 601,340.0

Recall: Location: PBG Campaign # Department: PBG5-Charter Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
205440	02/25/2016	02/27/2016	Closed	0.00		
Description: REPAIR REAR BUMPER CORNERS AND LEFT FENDER						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$84.00		\$0.00	\$84.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (1.68)			\$84.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$84.00	\$0	\$0	\$84.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 601,645.0

Recall: Location: PBG Campaign # Department: PBG5-Charter Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
205632	03/08/2016	03/28/2016	Closed	0.00		
Description: LOF						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00
Repair, Inv. # 2784981						
LOF:Lube, Oil, Filter		\$111.25	\$195.00		\$0.00	\$306.25
Pillsbury: Oil Bulk in Quarts:		\$86.40				

Oil 15W-40 Bulk (40.000)						
Pillsbury: Filter Oil MCI D4500	\$15.10					
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Analysis Kit:	\$9.75					
Sample Kit (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW				\$195.00		
(3.90)						
Labor Comments: Did a LOF						
Miscellaneous Labor				\$0		
Other					\$0	
PMI:Preventative Maintenance Inspection	\$0	\$0		\$0.00		\$0.00
Miscellaneous Parts	\$0					
Miscellaneous Labor				\$0		
Other					\$0	
	\$0	\$111.25	\$195.00	\$0	\$35.00	<u>\$341.25</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 601,930.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
205909	03/30/2016	03/30/2016	Closed	0.00	

Description: Charging

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$350.30	\$38.50		\$0.00	\$388.80
Pillsbury: Battery 1400CCA		\$350.30				
Top Post Heavy Duty						
Workaholic: 8D-MHD(7271)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$38.50			
(0.77)						
Labor Comments: Ceaser said he has to jump this bus everytime, Checked the charging, everything checked out. Checked Batteries, did not check out okay, replaced them, also going to see if NAPA will warrenty other batteries since they are not that old						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$350.30	\$38.50	\$0	\$0	<u>\$388.80</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 602,105.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206253	04/27/2016	04/29/2016	Closed	0.00	

Description: Air Filter Replacement

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
AF:Air Filter Replacement		\$41.74	\$9.00		\$0.00	\$50.74
Pillsbury: Filter Air: 6741		\$41.74				
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$9.00			
(0.18)						
Labor Comments: replaced air filter						
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$41.74 \$9.00 \$0 \$0 \$50.74

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 602,105.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206254	04/27/2016	04/27/2016	Closed	0.00	

Description: tumbler assy

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
50:Accessories		\$480.60	\$0		\$0.00	\$480.60
3R-29-61 tumbler assy-lock (6.000)		\$480.60				
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$480.60	\$0	\$0	\$0	<u>\$480.60</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 602,694.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206548	05/19/2016	05/19/2016	Closed	0.00	

Description: BU alarm

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$35.00	\$35.00
Repair, Inv. # 2785125, Desc: Chipped Glass Repair						
Install Back-up Alarm		\$17.83	\$39.00		\$0.00	\$56.83
Maintenance Requested: 9889 - 04/21/2016 - Install Back-up Alarm						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Back Up Alarm: 56012 (1.000)		\$17.83				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.78)			\$39.00			
Labor Comments: Install BU alarm						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$17.83	\$39.00	\$0	\$35.00	<u>\$91.83</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 603,907.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206755	06/07/2016	06/08/2016	Closed	0.00	

Description: Steer tires

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$790.00	\$165.00		\$0.00	\$955.00
Pillsbury: Tire, Steer,Toyo M144: 315/80R22.5 (2.000)		\$790.00				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (3.30)			\$165.00			
Labor Comments: Mount and balance 2 new steers; 475 ft lbs; 110 psi						
Miscellaneous Labor			\$0			

Other

\$0

\$0	\$790.00	\$165.00	\$0	\$0	<u>\$955.00</u>
-----	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 604,473.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206880	06/20/2016	06/29/2016	Closed	0.00	

Description: L headlamps inop

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$110.50		\$0.00	\$110.50

Maintenance Requested: 10159 - 06/20/2016 - Driver side head light out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0	
74 - PHIPPS, KEVIN (2.21)		\$110.50

Labor Comments: Tried new bulb--not it; hi beam out also....

Only 8 vdc at bulbs... Found poor ground connection at terminal sockey at P-91, replaced socket connector.

Miscellaneous Labor	\$0	
Other		\$0

\$0	\$0	\$110.50	\$0	\$0	<u>\$110.50</u>
-----	-----	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 604,699.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
206955	06/27/2016	06/29/2016	Closed	0.00	

Description: drivers windscreen

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$387.60	\$157.00		\$0.00	\$544.60

Maintenance Requested: 10132 - 06/13/2016 - Small crack on top windshield

Requestor Notes: Rock hit windshield above driver

Technician Response:

Maint Req Status: Completed

Pillsbury: Glass Windshield	\$387.60	
Front RH w/Mask MCI EL3:		
03-27-1326 (1.000)		
Miscellaneous Parts	\$0	
74 - PHIPPS, KEVIN (2.02)		\$101.00

Labor Comments: Switch out drivers w/s

0081 - WOLF, PATRICK (1.12)		\$56.00
-----------------------------	--	---------

Labor Comments: 75 -- Switch out drivers w/s

Miscellaneous Labor	\$0	
Other		\$0

\$0	\$387.60	\$157.00	\$0	\$0	<u>\$544.60</u>
-----	----------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 606,501.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207130	07/14/2016	07/14/2016	Closed	0.00	

Description: RR turn inop						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$14.00		\$0.00	\$14.00
Work Comments: RR turn inop						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.28)			\$14.00			
Labor Comments: Found disconnected, cleaned, greased and reconnected with zip tie.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$14.00	\$0	\$0	\$14.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 607,309.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207244	07/22/2016	07/26/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$23.97	\$11.00		\$0.00	\$34.97
Pillsbury: Headlight Halogen		\$2.69				
Low Beam: 9006 (1.000)						
Pillsbury: Light Non LED		\$21.28				
Amber Side Marker/Turn MCI						
EL3: 07-07-1003 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.22)			\$11.00			
Labor Comments: new bulb in LH headlamp; new light asm in LR side marker						
Miscellaneous Labor			\$0			
Other					\$0	
52:Electrical Accessories		\$10.75	\$98.50		\$0.00	\$109.25
Pillsbury: plug kit-conn:		\$5.32				
155-2271 (1.000)						
Pillsbury: Receptacle:		\$5.43				
102-8804 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (1.97)			\$98.50			
Labor Comments: Run wiring for WIFI						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$34.72	\$109.50	\$0	\$0	\$144.22

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 607,615.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207254	07/25/2016	07/26/2016	Closed	0.00	

Description: PMI with list; DOT						
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$336.41	\$140.00		\$0.00	\$476.41
Pillsbury: Pads brake EL3:		\$226.11				
04-01-1019 (1.000)						
Pillsbury: Pad Fitting Kit; 1 per axle; EL3: 04-01-1008 (1.000)		\$110.30				
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (2.80)			\$140.00			
Labor Comments: Mic'd rotors=1.65 plus (1.61 min); install new pads and hardware; torque wheels to 475 ft lbs						
Miscellaneous Labor			\$0			

Other			\$0	
22:Tires	\$0	\$48.50	\$0.00	\$48.50
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.97)		\$48.50		
Labor Comments: Install used retread on L tag; 11/32nds; 100 psi; 475 ft lbs				
Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$227.32	\$27.50	\$0.00	\$254.82
Pillsbury: Light Amber Marker,	\$138.42			
EL3: 07-07-1012 (3.000)				
Pillsbury: Lens: 07-07-1011	\$9.90			
(1.000)				
Pillsbury: Light MCI	\$79.00			
Conversion LED Red:				
GG77093 (2.000)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.55)		\$27.50		
Labor Comments: Replace all 3 front upper marker lights as they were mostly burnt out; both tail/stop as each had LED's burnt out				
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$76.17	\$97.50	\$0.00	\$173.67
Work Comments: Rear cond fan inop				
16-04-1204 24v relay (1.000)	\$76.17			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (1.95)		\$97.50		
Labor Comments: Replaced bad 24v relay--sticking; hosed core out				
Miscellaneous Labor		\$0		
Other			\$0	
DO:DOT Inspection	\$2.00	\$31.00	\$0.00	\$33.00
Annual sticker \$2 (1.000)	\$2.00			
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (0.62)		\$31.00		
Labor Comments: Perform annual inspection				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$30.09	\$238.00	\$0.00	\$268.09
Work Comments: 6 P/R hinge pins/springs loose-X				
2 Reading lights out-X				
1 footrest loose-X				
RF side marker loose-X				
Roll pin in PP2 valve protruding-X				
Ramp screws loose-X				
Replace 1 cup holder-X				
Add nut with washer to cradle bolt-X				
Tighten 2 trans mounting bolts-L side-X				
Needs drive brake pads-X				
Needs L tag tire-X				
Replace all 3 upper front marker lights-X				
Rear condensor fan inop-X				
Both rear tail/stop LED's out-X				
Pillsbury: Lens, Overhead	\$8.34			
light, MCI: 03-08-1169 (1.000)				
Pillsbury: Light Bulb Pass.	\$2.00			
Sevice Module 28V 10W:				
03-08-1162 (2.000)				
Pillsbury: Filter Media: 4WZ68	\$13.52			
(8.000)				
Pillsbury: Fluid ATF (Synthetic)	\$3.02			
Bulk Quart: ATF Synthetic Bulk				
(0.500)				
Pillsbury: Oil Bulk in Quarts:	\$3.21			
Oil 15W-40 Bulk (1.500)				
Miscellaneous Parts	\$0			
74 - PHIPPS, KEVIN (4.76)		\$238.00		

Labor Comments: Perform PMI and list noted in heading.
Top off PS and engine oil

Miscellaneous Labor						\$0
Other						\$0
	\$0	\$671.99	\$582.50	\$0	\$0	<u>\$1,254.49</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 607,614.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207274	07/26/2016	07/26/2016	Closed	0.00	

Description: engine; body misc

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$13.50		\$0.00	\$13.50

Work Comments: Check engine light on

Miscellaneous Parts	\$0	
74 - PHIPPS, KEVIN (0.27)		\$13.50

Labor Comments: Caused by pressure washing, blew dry around ECM and cleared codes--OK

Miscellaneous Labor	\$0	
Other		\$0

72:Body Misc	\$0	\$61.00	\$0.00	\$61.00
--------------	-----	---------	--------	---------

Work Comments: Rad and cond doors not latching

Miscellaneous Parts	\$0	
74 - PHIPPS, KEVIN (1.22)		\$61.00

Labor Comments: Rad door--sprayed latch asm and loosened the latches--OK; cond door missing latch
stud-took one off 522, cut hole under rail to fit washer and nut up to stud bolt.

Miscellaneous Labor	\$0	
Other		\$0

RT:Road Test	\$0	\$17.50	\$0.00	\$17.50
--------------	-----	---------	--------	---------

Miscellaneous Parts	\$0	
74 - PHIPPS, KEVIN (0.35)		\$17.50

Labor Comments: Check cruise and retarder--Good

Miscellaneous Labor	\$0	
Other		\$0

\$0	\$0	\$92.00	\$0	\$0	<u>\$92.00</u>
-----	-----	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 607,615.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207279	07/26/2016	07/27/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$9.46	\$31.50		\$0.00	\$40.96

Work Comments: 36 -- Both Lic. plate lightbases broken ---- Removed and replaced both lamp
bases.

Pillsbury: Kit Bracket	\$9.46	
Hardware Mount: 15414		

Miscellaneous Parts	\$0	
0081 - WOLF, PATRICK (0.63)		\$31.50

Miscellaneous Labor	\$0	
Other		\$0

\$0	\$9.46	\$31.50	\$0	\$0	<u>\$40.96</u>
-----	--------	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 607,739.0

		Recall:	Location: PBG Campaign #		Department: PBG5-Charter Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
207327	07/29/2016	07/29/2016	Closed	0.00			
Description: Lavatory Coupler							
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory			\$33.79	\$20.00		\$0.00	\$53.79
Pillsbury: Coupling End, Lav			\$33.79				
MCI: 17B-5-50 (1.000)							
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW				\$20.00			
(0.40)							
Labor Comments: replaced coupler							
Miscellaneous Labor				\$0			
Other						\$0	
		\$0	\$33.79	\$20.00	\$0	\$0	\$53.79

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,189.0

Location: PBG

Department: PBG5-Charter

		Recall:	Campaign #		Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
207365	08/02/2016	08/02/2016	Closed	0.00			
Description: Door Lock							
<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>	
78:Doors Entrance / Exit		\$0	\$5.00		\$0.00	\$5.00	
Maintenance Requested: 10307 - 08/01/2016 - Pass door manual lock knob fell off							
Requestor Notes:							
Technician Response:							
Maint Req Status: Completed							
Miscellaneous Parts		\$0					
7050 - STRAND, MATTHEW			\$5.00				
(0.10)							
Labor Comments: ordered parts for it							
Miscellaneous Labor			\$0				
Other					\$0		
		\$0	\$0	\$5.00	\$0	\$5.00	

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,189.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:			
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
207383	08/03/2016	08/09/2016	Closed	0.00			
Description: Alt belt/ pulley failed							
<u>Detail</u>	<u>Discounts</u>		<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging			\$353.96	\$102.50		\$0.00	\$456.46
Pillsbury: Oil Gear Synthetic:			\$1.56				
Oil Gear 75W-90 BULK in quarts (0.500)							
Pillsbury: Belt Serpentine (EL3): 25-060295 (1.000)			\$14.09				
Pillsbury: Belt Alternator MCI Motor Coach: 8L-27-132 (1.000)			\$38.36				
RO31769 Idler Pulley (1.000)			\$299.95				
Miscellaneous Parts			\$0				
74 - PHIPPS, KEVIN (0.92)				\$46.00			

Labor Comments: 31--Removed failed pulley asm; replaced small alt belt with new, set up for Pat to finish when part came in.

0081 - WOLF, PATRICK (1.13)

\$56.50

Labor Comments: 31 -- Attached the rebuilt pulley assy. Torqued all bolts to specs. Checked the charging system and HVAC. both good. Filled the fan gear box with gear lube.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$353.96 \$102.50 \$0 \$0 \$456.46

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,928.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207449	08/09/2016	08/09/2016	Closed	0.00	

Description: Charging

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 10312 - 08/04/2016 - Charging system

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: Closing Maintenance Request. Was finished on work order 207383

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$0 \$0 \$0 \$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,928.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207463	08/10/2016	08/11/2016	Closed	0.00	

Description: drivers head light

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$2.69	\$16.50		\$0.00	\$19.19

Work Comments: drivers side low beam head light out.

Pillsbury: Headlight Halogen

\$2.69

Low Beam: 9006 (1.000)

Miscellaneous Parts

\$0

6036 - CORNFORTH,

\$16.50

MICHAEL (0.33)

Labor Comments: replaced drivers side low beam head light.

MC

Miscellaneous Labor

\$0

Other

\$0

\$0 \$2.69 \$16.50 \$0 \$0 \$19.19

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,928.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207480	08/11/2016	08/18/2016	Closed	0.00	

Description: dents on middle side comparmnt doors

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$890.00		\$0.00	\$890.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (17.80)			\$890.00			
Miscellaneous Labor			\$0			
Other					\$0	
70:Body Sheet Metal		\$650.00	\$0		\$0.00	\$650.00
5522 old door (1.000)		\$650.00				
Part Comments: old door pull paint						
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$650.00	\$890.00	\$0	\$0	<u>\$1,540.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 609,578.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207518	08/15/2016	08/16/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$249.00		\$0.00	\$249.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (4.98)			\$249.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$249.00	\$0	\$0	<u>\$249.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 609,578.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207520	08/15/2016	08/16/2016	Closed	0.00	

Description: Door Latch, Maintence Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 10322 - 08/11/2016 - Driver side headlight out on low beam						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: already repaired						
Miscellaneous Labor			\$0			
Other					\$0	
73:Seats		\$0	\$19.00		\$0.00	\$19.00
Maintenance Requested: 10310 - 08/03/2016 - A sharp piece of plastic is sticking out on panel						
Requestor Notes: Drivers side / 10 seats back aisle seat on the side panel. There is a sharp						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$19.00			
(0.38)						
Labor Comments: fixed seat the screw busted off allowing a sharp piece of meatal to show.						
Miscellaneous Labor			\$0			
Other					\$0	

78:Doors Entrance / Exit	\$152.86	\$57.50		\$0.00	\$210.36
03-32-1042 Handle-Sedan	\$104.43				
Door (1.000)					
3G-32-612M138 Knob-Manuel	\$48.43				
Release, Grey (1.000)					
Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW		\$57.50			
(1.15)					
Labor Comments: replaced door latch					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$152.86	\$76.50	\$0	\$0
					<u>\$229.36</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 609,578.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207571	08/17/2016	08/17/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$7.77	\$17.50		\$0.00	\$25.27
Pillsbury: Mirror Convex:		\$7.77				
28032 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.35)			\$17.50			
Labor Comments: Replace drivers convex mirror						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$7.77	\$17.50	\$0	\$0	<u>\$25.27</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207773	09/01/2016	09/01/2016	Closed	0.00	

Description: FF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
FF:Fuel Filter		\$8.40	\$31.50		\$0.00	\$39.90
Pillsbury: Filter Fuel: 3118		\$4.19				
(1.000)						
Pillsbury: Filter, Fuel, MCI:		\$4.21				
3120 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$31.50			
(0.63)						
Labor Comments: FF Replacement						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$8.40	\$31.50	\$0	\$0	<u>\$39.90</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207892	09/10/2016	09/12/2016	Closed	0.00	

Description: Leaking Hub Cover

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$42.28	\$25.00		\$0.00	\$67.28
Pillsbury: Hub Cap w/ Lube		\$39.16				
Window Steer Axle MCI						
D4500: 343-4176 (1.000)						
Pillsbury: Oil Gear Synthetic:		\$3.12				
Oil Gear 75W-90 BULK in quarts (1.000)						
Part Comments: They need to send a memo out when they change the names of parts. Use to be able to type in gear oil and choose, now it brings you straight to 80w-140.						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.50)			\$25.00			
Labor Comments: Driver came in, showed me the LF steer tires was spitting out fluid. Looked at it and detrmined the hub was proly over heating from heavy use of brakes in the cities. Replaced the hub covera nd filled with oil						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$42.28	\$25.00	\$0	\$0	<u>\$67.28</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207922	09/12/2016	09/12/2016	Closed	0.00	

Description: Coolant Filter

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CFR:Coolant Filter Replacement		\$5.64	\$46.00		\$0.00	\$51.64
Pillsbury: Filter Coolant		\$5.64				
Cummins ISM: 4071 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.92)			\$46.00			
Labor Comments: replaced the coolant filter						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$5.64	\$46.00	\$0	\$0	<u>\$51.64</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207926	09/12/2016	09/13/2016	Closed	0.00	

Description: Tag Hub Leaking

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$70.52	\$27.50		\$0.00	\$98.02
Pillsbury: Hub Cap w/ Lube		\$39.16				
Window Steer Axle MCI						
D4500: 343-4176 (1.000)						
Pillsbury: Hub Cap, Stainless		\$10.08				
Steel: MW1273 (1.000)						
Pillsbury: Light Non LED		\$21.28				
Amber Side Marker/Turn MCI						
EL3: 07-07-1003 (1.000)						
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW
(0.55)

\$27.50

Labor Comments: Right Tag hub was also leaking, they must of been doing heavy braking, replaced it
also replaced a side marker lamp assembly

Miscellaneous Labor
Other

\$0

\$0

\$0.00 \$70.52 \$27.50 \$0 \$0 \$98.02

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,226.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207959	09/14/2016	09/14/2016	Closed	0.00	

Description: R3 bay door latch; R tag tire

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$174.76	\$98.50		\$0.00	\$273.26

Pillsbury: Tire TB Recap Tag:
315/80R 22.5 TB Recap Tag
(1.000)

\$174.76

Miscellaneous Parts
74 - PHIPPS, KEVIN (1.97)

\$0

\$98.50

Labor Comments: Change out R tag tire--out of balance and cupping; mount and balanced new retread;
torqued wheel to 475 ft lbs; 100 psi

Miscellaneous Labor
Other

\$0

\$0

72:Body Misc

\$0

\$42.50

\$0.00

\$42.50

Maintenance Requested: 10418 - 09/14/2016 - 3rd luggage bay doesn't lock open

Requestor Notes: Drivers speakers don't work

Low tire tread on rear tag axel

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts
74 - PHIPPS, KEVIN (0.85)

\$0

\$42.50

Labor Comments: R3 bay door missing latch. Body shop did not finish the job. Took parts off 522 and
made it work.

Miscellaneous Labor
Other

\$0

\$0

\$0 \$174.76 \$141.00 \$0 \$0 \$315.76

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,226.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207980	09/15/2016	09/15/2016	Closed	0.00	

Description: Charging, Mirrors

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$65.00		\$0.00	\$65.00

Miscellaneous Parts
7050 - STRAND, MATTHEW
(1.30)

\$0

\$65.00

Labor Comments: Bus came back not charging, Found the feild wire was rotted off, replaced end and
hooked up and took for test drive.

Miscellaneous Labor
Other

\$0

\$0

77:Mirrors

\$0

\$24.00

\$0.00

\$24.00

Miscellaneous Parts
7050 - STRAND, MATTHEW

\$0

\$24.00

5/7/2019

Work Order Detail

(0.48)

Labor Comments: shined the drivers mirrors up, got rid of some of the oxidation from the well water

Miscellaneous Labor

\$0

Other

\$0

\$0

\$0

\$89.00

\$0

\$0

\$89.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,434.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

208024

09/19/2016

09/20/2016

Closed

0.00

Description: La v issues; Hub srvc

DetailDiscountsPartsLaborTiresOtherTotal

79:Lavatory

\$0

\$89.50

\$0.00

\$89.50

Maintenance Requested: 10423 - 09/16/2016 - Coach Restroom Issues

Requestor Notes: Driver reported that the toilet/tank smells even when fresh solution is added to tank.

When flushing the system it seems to be clogged.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$13.50

(0.27)

Labor Comments: was going to get set up on working on this bus, but got pulled off to do DOTs in Burnsville

74 - PHIPPS, KEVIN (1.52)

\$76.00

Labor Comments: Water free flowing OK; exhaust fan not able to blow through noise suppressor--fixed that. Turned fittings to unkink lines for exterior flushing

Miscellaneous Labor

\$0

Other

\$0

HUB:Hub Service

\$18.00

\$61.50

\$0.00

\$79.50

Pillsbury: Oil Gear 80W-140

\$18.00

Synthetic Mobil Delvac: Gear

oil 80W-140 in pints (6.000)

Miscellaneous Parts

\$0

74 - PHIPPS, KEVIN (1.23)

\$61.50

Labor Comments: Service hubs

Used 80/140 gear lube

Miscellaneous Labor

\$0

Other

\$0

\$0

\$18.00

\$151.00

\$0

\$0

\$169.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,434.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

208048

09/20/2016

09/20/2016

Closed

0.00

Description: Lighting

DetailDiscountsPartsLaborTiresOtherTotal

36:Lighting

\$0

\$18.50

\$0.00

\$18.50

Maintenance Requested: 10444 - 09/20/2016 - right running light go's on an off

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$18.50

(0.37)

Labor Comments: replaced mid rightside marker light bulb 3157

5/7/2019

Work Order Detail

Miscellaneous Labor
Other

\$0

\$0

\$0	\$0	\$18.50	\$0	\$0	\$18.50
-----	-----	---------	-----	-----	---------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 612,380.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208233	09/28/2016	09/28/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
	\$0	\$0	\$0	\$0	\$0	\$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 612,380.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208237	09/28/2016	09/28/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$0		\$0.00	\$0.00

Description: baggage light stays on

Maintenance Requested: 10470 - 09/26/2016 - Baggage door lites stay on when the doors are clos

Requestor Notes: closed and latched

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW	\$0.00
(0.00)	

Labor Comments: Missing the magnetic switch, roobbed one off of the parts bus down below

Miscellaneous Labor	\$0
Other	\$0

\$0	\$0	\$0	\$0	\$0	\$0.00
-----	-----	-----	-----	-----	--------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 612,380.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208244	09/28/2016	09/29/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$60.00		\$0.00	\$60.00

Description: Roof Leak

Maintenance Requested: 10457 - 09/22/2016 - Multiple water leaks above drivers seat.

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW	\$60.00
(1.20)	

Labor Comments: got on the roof and siliconed possible water leak locations

Miscellaneous Labor	\$0
Other	\$0

\$0	\$0	\$60.00	\$0	\$0	\$60.00
-----	-----	---------	-----	-----	---------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,131.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208324	10/04/2016	10/06/2016	Closed	0.00	

Description: Cradle bolt; sm alt

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Missing cradle bolt-road side rear		\$0	\$342.50		\$0.00	\$342.50

Maintenance Requested: 10511 - 10/03/2016 - Missing cradle bolt-road side rear

Requestor Notes:

Technician Response:

Maint Req Status: Completed

34 SI 24v 90amp reman from Schelen (1.000)	\$0.00
--	--------

Part Comments: Only one on shelf at this time

Miscellaneous Parts	\$0
74 - PHIPPS, KEVIN (6.15)	\$307.50

Labor Comments: Remove broken cradle bolt, siezed in tube; remove 34SI alt and brackets--badly worn--found good used lower bracket and reman alt to install

0146 - SHIPPY, CURTIS (0.70)	\$35.00
------------------------------	---------

Labor Comments: Cut and weld new bolt tube into frame

Miscellaneous Labor	\$0
Other	\$0

\$0	\$0	\$342.50	\$0	\$0	<u>\$342.50</u>
-----	-----	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,132.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208374	10/06/2016	10/10/2016	Closed	0.00	

Description: LOF, Webasto Tune Up

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$30.72	\$226.50		\$0.00	\$257.22

Pillsbury: Nozzle (0.65 GPH
80H)wabasto: WE470716
(1.000)

Pillsbury: Electrode Ignition	\$12.75
-------------------------------	---------

dw-thermo wabasto:
WE14846D (1.000)

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW (4.53)	\$226.50

Labor Comments: tuned up the webasto. Broke a bolt, had to extract it and then heli coil it. coudnt get the webasto program to hook up. finally go it hooked up. Got it out of interlock and fixed fault. Ran the heater.

Miscellaneous Labor	\$0
Other	\$0

LOF:Lube, Oil, Filter	\$104.90	\$155.00	\$0.00	\$259.90
-----------------------	----------	----------	--------	----------

Pillsbury: Oil Bulk in Quarts:

Oil 15W-40 Bulk (38.000)	\$79.80
--------------------------	---------

Pillsbury: Filter Oil MCI D4500	\$15.10
---------------------------------	---------

w/Detroit Diesel 60 Series:
1971MP (2.000)

Pillsbury: Oil Analysis Kit:	\$10.00
------------------------------	---------

Sample Kit (1.000)

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW (3.10)	\$155.00

7050 - STRAND, MATTHEW
(3.10)

5/7/2019

Work Order Detail

Miscellaneous Labor	Labor Comments: serviced the bus		\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
	Labor Comments: Service					
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$135.62	\$381.50	\$0	\$0
						<u>\$517.12</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,892.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208995	11/17/2016	11/18/2016	Closed	0.00	

Description: Battery Draw

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$141.50		\$0.00	\$141.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$141.50			
(2.83)						
	Labor Comments: searching for a draw, found a baggage bay light that was not turning off.					
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$141.50	\$0	\$0	<u>\$141.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,892.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209022	11/18/2016	11/25/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
73:Seats		\$0	\$38.50		\$0.00	\$38.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.77)			\$38.50			
	Labor Comments: moved seats so tables could be installed for customer.					
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$38.50	\$0	\$0	<u>\$38.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 831,828.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209154	12/01/2016	12/02/2016	Closed	0.00	

Description: Air Gauges

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$750.00	\$159.00		\$0.00	\$909.00

Maintenance Requested: 10727 - 11/23/2016 - Air Guages read low

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: IP instrument \$750.00
 cluster: 07-08-119 (1.000)
 Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$159.00
 (3.18)

Labor Comments: dash gauges were not reading correct, switched out dash and bumped up the air governor to 115 psi. Also fixed a couple loose rivets

Miscellaneous Labor \$0
 Other \$0

\$0 \$750.00 \$159.00 \$0 \$0 \$909.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 832,058.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209324	12/12/2016	12/12/2016	Closed	0.00	

Description: Radio

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 10765 - 12/08/2016 - See notes

Requestor Notes: Driver didn't set Parking Brake. Bus rolled into parked school bus. Dent in front bumper on driver side. Kathryn has been notified.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$0.00
 (0.00)

Labor Comments: this doesnt need to be a write up, notify the bodyshop

Miscellaneous Labor \$0
 Other \$0
 Radio/DVD/PA:Radio repair \$0 \$6.00 \$0.00 \$6.00

Maintenance Requested: 10801 - 12/12/2016 - Advanced REI Head Unit above Stero does not power

Requestor Notes: Advanced REI Head Unit above Stero does not power up

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$6.00
 (0.12)

Labor Comments: unit does power up

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$6.00 \$0 \$0 \$6.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 832,149.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209694	01/11/2017	01/17/2017	Closed	0.00	

Description: Air Drier, Low Air Buzzer

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
37:Warning, Strobe, 8-Ways		\$0	\$95.00		\$0.00	\$95.00

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$95.00
 (1.90)

Labor Comments: the low air buzzer was not working. I messed with some wiring and unplugged and plugged somethings in and it started to work. I ordered one for stock incase this one does go out again

5/7/2019

Work Order Detail

Miscellaneous Labor		\$0				
Other					\$0	
AD:Air Drier Service	\$119.70	\$126.50		\$0.00		\$246.20
Pillsbury: Purge Valve Repair	\$66.72					
Kit, AD-IP: K022105 (1.000)						
Pillsbury: AD-IP Air Dryer	\$52.98					
Desiccant Cartridge Bendix:						
109493BXR (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$126.50				
(2.53)						
Labor Comments: jump started 2 buses rebuilt the air drier. checked brake stroke						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$119.70	\$221.50	\$0	\$0	<u>\$341.20</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 832,422.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
209811	01/19/2017	01/20/2017	Closed	0.00			
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield						\$35.00	\$35.00
Repair, Inv. # 2785612							
77:Mirrors			\$0	\$41.50		\$0.00	\$41.50
Miscellaneous Parts			\$0				
9127 - JACOBS, ANDREW				\$41.50			
(0.83)							
Labor Comments: found both mirror arms loose readjust with driver to where needs to be tighten all bolts for the arms down							
Miscellaneous Labor				\$0			
Other						\$0	
	\$0	\$0	\$41.50	\$0	\$35.00		<u>\$76.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 836,073.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>		
210689	03/24/2017	03/24/2017	Closed	0.00			
Description: RV A/F							
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory			\$160.34	\$0		\$0.00	\$160.34
Pillsbury: Fluid Antifreeze RV:			\$160.34				
A/F RV BULK (31.500)							
Part Comments: Added over winter for bathroom charge filled by wash stall. JS.							
Miscellaneous Parts			\$0				
Miscellaneous Labor				\$0			
Other						\$0	
	\$0	\$160.34	\$0	\$0	\$0		<u>\$160.34</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 837,323.0

Location: PBG

Department: PBG5-Charter

	Recall:	Campaign #			Date:
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
210892	04/07/2017	04/20/2017	Closed	0.00	

Description: PMI, List

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$824.95	\$302.50		\$0.00	\$1,127.45
Pillsbury: Brake Chamber,		\$282.75				
Tag, LH EL3: MJS1724ET057						
(1.000)						
Pillsbury: Pads brake EL3:		\$243.75				
04-01-1019 (1.000)						
Pillsbury: Brake Chamber, Tag		\$298.45				
RH, EL3: T04-1246 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$302.50			
(6.05)						
Labor Comments: Front brake pads						
found were the air was back feeding into the system. thru the tags parking brake						
replaced both tag brake chambers						
installled new head lights						
Miscellaneous Labor			\$0			
Other					\$0	
25:Transmission (Auto)		\$184.88	\$0		\$0.00	\$184.88
Pillsbury: Speedi-Sleeve		\$126.24				
Allison B500 Output: 99473						
(1.000)						
Pillsbury: Seal Rear		\$58.64				
Transmission Output Allison						
B500: 29552705 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: transmission seal leaking, replaced seal and speedy sleeve						
Time is combined with brakes, did not punch over						
Miscellaneous Labor			\$0			
Other					\$0	
35:Instrument & Gauges		\$0	\$114.00		\$0.00	\$114.00
Maintenance Requested: 11223 - 03/18/2017 - bright light indicator light not working						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$114.00			
(2.28)						
Labor Comments: no high beam indicator lamp. found the piano module it bad, have a used one that						
one is bad for other reasons. sending that one to 3g to be rebuilt						
Miscellaneous Labor			\$0			
Other					\$0	
35:Instrument & Gauges		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11103 - 02/23/2017 - highbeam indicator on dash inop.						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$158.95	\$26.00		\$0.00	\$184.95
Pillsbury: Light Amber Marker,		\$46.14				
EL3: 07-07-1012 (1.000)						
Pillsbury: Light Bulb 12 Volt		\$6.39				
Mini Fog/Driving: BP1255/H3						
(1.000)						

Pillsbury: Fog Lamp RH, Dual Halagon, EL3: 07-07-1026 (see note) (1.000)	\$106.42			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.52)		\$26.00		
Labor Comments: fog lamp out and right side marker lamp not blinking on hazards				
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$21.98	\$12.50	\$0.00	\$34.48
Pillsbury: Gauge Sight MCI Surge Tank: 6R-14-60 (1.000)	\$21.98			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.25)		\$12.50		
Labor Comments: replaced coolant sight glass tightened up a couple coldwater leaks				
Miscellaneous Labor		\$0		
Other			\$0	
48:Fuel System	\$0	\$319.00	\$0.00	\$319.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (6.38)		\$319.00		
Labor Comments: fuel tank was overfilled and leaked out underneath the matting for the floor in the 3rd bag bay. Had to take out mat, clean the bay and then scrap the molding off. Reinstalled mat and riveted and screwed down and silicone to preven thsi again. Also cleaned the tank up and tightened some clamps. powerwashed underside of the tank				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$187.88	\$150.00	\$0.00	\$337.88
Pillsbury: Latch Front bumper: 03-21-1046 (1.000)	\$19.73			
Pillsbury: Bracket Striker: 03-21-1080 (1.000)	\$148.41			
03-21-1042 Cable-Release, Bumper (1.000)	\$19.74			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (3.00)		\$150.00		
Labor Comments: Front bumper needed new latch and latch assembly also needs new cable that is ordered put new step tread on the steps replaced screws in body that were rusted out				
Miscellaneous Labor		\$0		
Other			\$0	
79:Lavatory	\$383.04	\$33.50	\$0.00	\$416.54
Pillsbury: Kit, Lav Retro Fit: T17-1107A (1.000)	\$383.04			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.67)		\$33.50		
Labor Comments: installed new lavatory dump valve kit				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$0	\$160.50	\$0.00	\$160.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (3.21)		\$160.50		
Labor Comments: PMI				
Miscellaneous Labor		\$0		
Other			\$0	
RT:Road Test	\$0	\$26.00	\$0.00	\$26.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$26.00		

(0.52)

Labor Comments: road test

Miscellaneous Labor

\$0

Other

\$0

SC:Steam Clean

\$0

\$27.50

\$0.00

\$27.50

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$27.50

(0.55)

Labor Comments: steam clean

Miscellaneous Labor

\$0

Other

\$0

\$0.00

\$1,761.68

\$1,171.50

\$0

\$0

\$2,933.18

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 837,737.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

211152

04/26/2017

05/02/2017

Closed

0.00

Description: A/C: pre System for Summer

DetailDiscountsPartsLaborTiresOtherTotal

A/C:Prep

\$1,345.04

\$425.50

\$0.00

\$1,770.54

Work Comments: A/C: pre System for Summer

Pillsbury: Headlight, LED, MCI:

\$77.14

9705K (1.000)

Pillsbury: Headlight, LED, MCI:

\$77.14

9706K (1.000)

Pillsbury: Water Valve repair

\$427.76

kit, EL3: 16-06-1025 (2.000)

Pillsbury: A/C control module

\$763.00

(1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (8.51)

\$425.50

Labor Comments: A/C: pre System for Summer ----- Pulled the panels off. removed the motor brush caps and checked all brushes on the condensor and evap. motors. All ok. Rebuilt the left heat valve. Blew the brush dust out of the motors. washed out all the dirt from the condensor, radiator and the CAC. Put everything back together.

Miscellaneous Labor

\$0

Other

\$0

\$0

\$1,345.04

\$425.50

\$0

\$0

\$1,770.54

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,010.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

211302

05/05/2017

05/08/2017

Closed

0.00

Description: Bay Lamp

DetailDiscountsPartsLaborTiresOtherTotal

78:Doors Entrance / Exit

\$1.16

\$0

\$0.00

\$1.16

Maintenance Requested: 11374 - 05/05/2017 - Baggage Doors light is on dash

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Bulb 24V

\$1.16

Above Stepwell MCI D4500:

1203 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

5/7/2019

Work Order Detail

(0.00)

Labor Comments: baggage light on dash, sensor was missing. Siliconed a used one in

Miscellaneous Labor

\$0

Other

\$0

\$0	\$1.16	\$0	\$0	\$0	\$1.16
-----	--------	-----	-----	-----	--------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,010.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211330	05/08/2017	05/10/2017	Closed	0.00	

Description: Chip In Windsheild

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$40.00	\$40.00
Repair, Inv. # 2785770						
75:Windows/windshields		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 11380 - 05/06/2017 - Chip in windshield left side

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: put on board for mike the glass guy to look at

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$0	\$0	\$40.00	\$40.00
-----	-----	-----	-----	---------	---------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,010.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211477	05/17/2017	05/23/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Rear outside dual tire looks a little low.		\$0	\$48.50		\$0.00	\$48.50

Maintenance Requested: 11412 - 05/17/2017 - Rear outside dual tire looks a little low.

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

9127 - JACOBS, ANDREW

\$28.50

(0.57)

Labor Comments: found tire pressure low handed off to allen

9128 - DIAZ, ALLEN (0.40)

\$20.00

Labor Comments: tightened up the valve stem

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$48.50	\$0	\$0	\$48.50
-----	-----	---------	-----	-----	---------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,845.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211547	05/24/2017	05/26/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$64.00		\$0.00	\$64.00
Maintenance Requested: 11418 - 05/20/2017 - Driver States that there is an oil per DOT Inspec						
Requestor Notes: 1) Driver States that there is an oil per DOT Inspection						
2) Driver states that the brakes Squeel						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$64.00			
(1.28)						
Labor Comments: no oil leaks that are dripping. Multiple slow oil leaks like front and rear main seals,						
Cam Seal, Trans Bell housing seal.						
Steam cleaned the engine.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$64.00	\$0	\$0	<u>\$64.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 839,139.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211650	06/01/2017	06/02/2017	Closed	0.00	

Description: Window Latches, Buzzer

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
37:Warning, Strobe, 8-Ways		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11436 - 05/26/2017 - low air pressure warning buzzer inop						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: intermittent problem, will look into it						
Miscellaneous Labor			\$0			
Other					\$0	
75:Windows/windshields		\$0	\$17.50		\$0.00	\$17.50
Maintenance Requested: 11443 - 05/31/2017 - 5 windows will not lock						
Requestor Notes: 1st 3 on right/ 2nd 2 on drivers side						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$17.50			
(0.35)						
Labor Comments: They were not shut properly when opened by the DOT for its random inspection						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$17.50	\$0	\$0	<u>\$17.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 839,139.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211688	06/05/2017	06/06/2017	Closed	0.00	

Description: Tag Tire

5/7/2019

Work Order Detail

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$353.68	\$83.50		\$0.00	\$437.18
Maintenance Requested: 11452 - 06/03/2017 - Right Rear Tag tire looks low check PSI						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Hub Cap, Stainless		\$10.08				
Steel: MW1273 (1.000)						
9705K LED Headlight (1.000)		\$84.42				
9706K LED Headlight (1.000)		\$84.42				
Pillsbury: Tire TB Recap Drive:		\$174.76				
315/80R 22.5 TB Recap Drive						
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$83.50			
(1.67)						
Labor Comments: tag tire had a nail in it. replaced it						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$353.68	\$83.50	\$0	\$0	\$437.18

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 839,685.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211755	06/08/2017	06/14/2017	Closed	0.00	

Description: Air Filter, FF, A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$387.75	\$252.50		\$0.00	\$640.25
Pillsbury: Valve, Electric		\$111.13				
Unloader: 10610656 (1.000)						
Pillsbury: Coil Unloader, 24		\$72.84				
volt: 16-02-1020 (1.000)						
03-29-1612 Cable Assy		\$40.32				
(1.000)						
Pillsbury: Spring-large		\$23.31				
baggage door: 03-29-1170						
(1.000)						
Pillsbury: Plate Assembly, 05G		\$140.15				
Compressor: 16G-2-64						
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$252.50			
(5.05)						
Labor Comments: While running the a/c, I could hear a leak a the compressor.						
Couldnt find it but could hear it, when I put my hand on the unloader.						
Shut off the kings valve sucked down the compressor and changed the unloader and solenoid						
Fill compressor back up and ran system. Still internal leaking.						
Shut of kings valves and sucked down the compressor,						
Pulled the head valve off, found parts bad. Replaced them						
ran system, no internal leaking.						
Miscellaneous Labor			\$0			
Other					\$0	
AF:Air Filter Replacement		\$42.21	\$41.00		\$0.00	\$83.21
Pillsbury: Filter Air: 6741		\$42.21				
(1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$41.00			
(0.82)						
Labor Comments: replaced air filter						

replaced FF
checked oils
ran A/C

Miscellaneous Labor		\$0				
Other				\$0		
FF:Fuel Filter	\$8.53	\$0		\$0.00		\$8.53
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)	\$4.34					
Pillsbury: Filter Fuel: 3118 (1.000)	\$4.19					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (0.00)		\$0.00				
Labor Comments: replaced FF						
Miscellaneous Labor		\$0				
Other				\$0		
	\$0	\$438.49	\$293.50	\$0	\$0	<u>\$731.99</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 840,513.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211878	06/20/2017	06/20/2017	Closed	0.00	

Description: Fast Idle, Latch

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$51.50		\$0.00	\$51.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.03)			\$51.50			

Labor Comments: Driver said everytime they put the bus in high idle it shut down. Pulled bus in and could not duplicate problem, Bus needed to go out.
Found the front latch on the front bumper not holding, tired to readjust, needs new striker

Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$0	\$51.50	\$0	\$0	<u>\$51.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 840,513.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211888	06/20/2017	06/21/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
PM:Preventative Maintenance		\$0	\$50.00		\$0.00	\$50.00
Miscellaneous Parts		\$0				
9128 - DIAZ, ALLEN (1.00)			\$50.00			

Labor Comments: sewer pipe was leaking from clap

Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$0	\$50.00	\$0	\$0	<u>\$50.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 840,979.0

Location: PBG

Department: PBG5-Charter

<u>WO #</u>	<u>Open Date</u>	Recall:	<u>Close Date</u>	Campaign #	<u>Status</u>	<u>Downtime</u>	Date: <u>Accident</u>
211934	06/24/2017		06/27/2017		Closed	0.00	

Description: check bus

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$16.50		\$0.00	\$16.50
Miscellaneous Parts		\$0				
9127 - JACOBS, ANDREW			\$16.50			
(0.33)						
Labor Comments: check engine oil level						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$16.50	\$0	\$0	<u>\$16.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 841,570.0

Location: PBG

Department: PBG5-Charter

<u>WO #</u>	<u>Open Date</u>	Recall:	<u>Close Date</u>	Campaign #	<u>Status</u>	<u>Downtime</u>	Date: <u>Accident</u>
211992	06/29/2017		07/05/2017		Closed	0.00	

Description: LOF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$675.47	\$80.00		\$0.00	\$755.47
Pillsbury: Tensioner, Detroit:		\$200.47				
23533015 (1.000)						
RO32715 ACC. Drive (1.000)		\$475.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$80.00			
(1.60)						
Labor Comments: Tensioner and Accesory Drive pulley were bad, Replaced both						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$10.67	\$37.50		\$0.00	\$48.17
Pillsbury: Stricker - Front		\$10.67				
Bumper: 03-21-1047 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$37.50			
(0.75)						
Labor Comments: Front bumper striker was shot, replaced it and adjusted it						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$110.29	\$240.00		\$0.00	\$350.29
Pillsbury: Filter Oil MCI D4500		\$15.56				
w/Detroit Diesel 60 Series:						
1971MP (2.000)						
Pillsbury: Oil Analysis Kit:		\$10.00				
Sample Kit (1.000)						
Pillsbury: Oil Bulk in Quarts:		\$84.73				
Oil 15W-40 Bulk (37.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$240.00			
(4.80)						
Labor Comments: Serviced the Bus, Had a really hard time geting the bus to level out to lift, found leaking valve, tightened it						
Took on Road Test						
Miscellaneous Labor			\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						

Miscellaneous Labor	Labor Comments: Serviced the Bus		\$0			
Other					\$0	
	\$0	\$796.43	\$357.50	\$0	\$0	<u>\$1,153.93</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 841,806.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212069	07/08/2017	07/10/2017	Closed	0.00	

Description: dvd

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$19.00		\$0.00	\$19.00
Miscellaneous Parts		\$0				
9127 - JACOBS, ANDREW			\$19.00			
(0.38)						
Labor Comments: tape up right rear tv screen the clip is broken to hold it up right						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$19.00	\$0	\$0	<u>\$19.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 841,806.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212097	07/11/2017	07/19/2017	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11568 - 07/11/2017 - turn signal indicator on the dash not working						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: worked just fine.						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$0	\$46.50		\$0.00	\$46.50
Maintenance Requested: 11569 - 07/11/2017 - Monitor in the back of the bus will not stay up						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Used Monitor (1.000)		\$0.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$46.50			
(0.93)						
Labor Comments: repalced the broken monitor						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11560 - 07/07/2017 - rear tv screen door side hinges down						
Requestor Notes: passenger air temp can't be controled - it's extremely cold or extremely cold not mater if temp is set at 60 or 80						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW
(0.00)
Miscellaneous Labor
Other

\$0.00

\$0

\$0

\$0 \$0 \$46.50 \$0 \$0 \$46.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,262.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212235	07/20/2017	07/25/2017	Closed	0.00	

Description: DOT,sc,air leak

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$0	\$119.50		\$0.00	\$119.50

Work Comments: 13 -- Air leak at right front brake chamber line.

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (2.39)

\$119.50

Labor Comments: 13 -- Air leak at right front brake chamber line. ---- Pull the end off. cut the line back
and reinstalled the end.

Miscellaneous Labor

\$0

Other

\$0

DO:DOT Inspection

\$0

\$160.00

\$0.00

\$160.00

Work Comments: DOT -- DOT Inspection..

DOT Sticker @ \$2.00

\$0.00

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (3.20)

\$160.00

Labor Comments: DOT -- DOT Inspection.. ---- Performed the Dot Inspection as per MN DOT
Handbook.

Miscellaneous Labor

\$0

Other

\$0

SC:Steam Clean

\$0

\$83.50

\$0.00

\$83.50

Work Comments: SC -- Steam clean ----

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (1.67)

\$83.50

Labor Comments: SC -- Steam clean ---- Steam cleaned the bottom of the bus.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$363.00 \$0 \$0 \$363.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,370.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212265	07/24/2017	07/25/2017	Closed	0.00	

Description: Air System

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$0	\$16.50		\$0.00	\$16.50

Maintenance Requested: 11604 - 07/22/2017 - air break leak. brakes squeak. chips in windshield

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$16.50

(0.33)

Labor Comments: When kneeling the bus the air hose would hit the dump valve and reelase air.

Wrote up the windsheild cracks for the windsheild dude.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$0	\$16.50	\$0	\$0	<u>\$16.50</u>
-----	-----	---------	-----	-----	----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,786.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212309	07/26/2017	07/26/2017	Closed	0.00	

Description: Repair from 7-19-17 incident

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$294.00	\$451.75		\$0.00	\$745.75
replace three skirt panels (3.000)		\$294.00				
Miscellaneous Parts		\$0				
technician (6.95)			\$451.75			
Labor Comments: paint rub rails						
Miscellaneous Labor			\$0			
Other					\$0	
	\$451.75	\$294.00	\$451.75	\$0	\$0	<u>\$745.75</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,971.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212324	07/27/2017	08/07/2017	Closed	0.00	

Description: A/C, Microphone, air leak, lights

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$26.00		\$0.00	\$26.00
Work Comments: 36 -- Right side front turn lamp out.						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.52)			\$26.00			
Labor Comments: 36 -- Right side front turn lamp out. ---- Removed and replaced the bulb (3157 bulb)						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$198.22	\$938.50		\$0.00	\$1,136.72
Work Comments: 41 -- A/C not working						
16-04-1031 Coil (1.000)		\$93.32				
Pillsbury: Transducer		\$65.95				
Pressure MCI D4500:						
16-02-1012 (1.000)						
Pillsbury: Filter Dryer EL3:		\$38.95				
16-04-1004 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK			\$938.50			
Labor Comments: 41 -- A/C not working ---- Trouble shoot NO A/C issue. system keeps shutting down because of low pressure on the suction side of the system. Changed out the pressure transducer on the low side. Found that the liquid solenoid valve wasn't working. The coil was shorted out. Ordered and installed a new coil. topped off the						
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$133.50		\$0.00	\$133.50
Maintenance Requested: 11616 - 07/26/2017 - Bus leaking air when kneeling bus on or off						
Requestor Notes: Bus isn't signaling that air is low at 60psi						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				

0081 - WOLF, PATRICK (2.67)

\$133.50

Labor Comments: 49 -- Leaking air when kneeling thr bus. ---- The right front brake line is catching on the air tank bleeder. Turned the brake line so it wouldn't catch.

Miscellaneous Labor

\$0

Other

\$0

Radio/DVD/PA:Radio repair

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 11624 - 07/26/2017 - microphone not working. A/C not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (0.00)

\$0.00

Labor Comments: PA -- microphone notworking. ---- Works fine for me. Maybe someone should train the drivers.
A/C not working is below in 41

Miscellaneous Labor

\$0

Other

\$0

\$0 \$198.22 \$1,098.00 \$0 \$0 \$1,296.22

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,971.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

212509

08/07/2017

08/07/2017

Closed

0.00

Description: Bathroom Lock

DetailDiscountsPartsLaborTiresOtherTotal

79:Lavatory

\$0

\$16.00

\$0.00

\$16.00

Maintenance Requested: 11705 - 08/05/2017 - bathroom door won't lock-no light inside

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(0.32)

\$16.00

Labor Comments: fixed the bathroom lock door jam

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$16.00 \$0 \$0 \$16.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,971.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

212515

08/07/2017

08/07/2017

Closed

0.00

Description: Radio/PA

DetailDiscountsPartsLaborTiresOtherTotal

Radio/DVD/PA:Radio repair

\$0

\$91.00

\$0.00

\$91.00

USED AMP For MCI (1.000)

\$0.00

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(1.82)

\$91.00

Labor Comments: Found the Amp was not powering up. Repalced with a used one.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$91.00 \$0 \$0 \$91.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 845,135.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212766	08/21/2017	09/05/2017	Closed	0.00	

Description: High beam indicator not working

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
33:Horn & Alarm		\$0	\$436.50		\$0.00	\$436.50

Work Comments: 33 -- Beepers keep going off, no Idiot lights light up.

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (8.73)

\$436.50

Labor Comments: 33 -- Beepers keep going off, no Idiot lights light up. ---- Worked with the tech. at

3-G trying to figure out what the problem is from . Switched out seven of the nine moduals in the bus. Still no diffarence. Had to leave the Piano modual that keeps the beepers on, so the high beam indicator light works. Sent the old piano modual in to 3-G for repairs. Waiting on new parts.

Miscellaneous Labor

\$0

Other

\$0

36:Lighting

\$0

\$166.00

\$0.00

\$166.00

Work Comments: 36 -- High beam indicator not working

Used piano modual from C&J

\$0.00

(1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (3.32)

\$166.00

Labor Comments: 36 -- High beam indicator not working ---- Removed and replaced the piono modual .

Miscellaneous Labor

\$0

Other

\$0

CFR:Coolant Filter Replacement

\$5.64

\$18.50

\$0.00

\$24.14

Work Comments: CFR -- Coolant filter replacement

Pillsbury: Filter Coolant

\$5.64

Cummins ISM: 4071 (1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (0.37)

\$18.50

Labor Comments: CFR -- Coolant filter replacement ---- Removed and replaced the coolant filter.

Miscellaneous Labor

\$0

Other

\$0

Radio/DVD/PA:Radio repair

\$0

\$155.00

\$0.00

\$155.00

Maintenance Requested: 11733 - 08/08/2017 - Remote mic not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (3.10)

\$155.00

Labor Comments: Radio repair -- Remote mic not working ---- Charged up the mic. the mic. still will not turn. We need to send it in for repairs or buy a new one.

Miscellaneous Labor

\$0

Other

\$0

\$0	\$5.64	\$776.00	\$0	\$0	<u>\$781.64</u>
-----	--------	----------	-----	-----	-----------------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 845,327.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212921	08/30/2017	09/06/2017	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$122.58	\$90.00		\$0.00	\$212.58

Maintenance Requested: 11942 - 08/29/2017 - see comments

Requestor Notes: Outside white L & R turn lights not working

Coolant was low

window is loose at seat 31

Amber round light outside the door is out

Technician Response:

Maint Req Status: Completed

Pillsbury: Cornering Light, \$122.58

LED, MCI: 07-07-1476 (1.000)

Miscellaneous Parts \$0

7050 - STRAND, MATTHEW \$90.00

(1.80)

Labor Comments: replaced a bunch of lights and got some kneeling lights ordered

Miscellaneous Labor \$0

Other \$0

Radio/DVD/PA:Radio repair \$0 \$41.50 \$0.00 \$41.50

Miscellaneous Parts \$0

7050 - STRAND, MATTHEW \$41.50

(0.83)

Labor Comments: ordered parts to fix the wireless microphone.

Miscellaneous Labor \$0

Other \$0

\$0.00 \$122.58 \$131.50 \$0 \$0 \$254.08

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 845,327.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212997	09/05/2017	09/06/2017	Closed	0.00	

Description: Lav Handle, Engine Temp

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
35:Instrument & Gauges		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 11984 - 09/02/2017 - Engine temp gauge not working right.

Requestor Notes: Engine temp gauge not working right. Run in red. Water ok, belt ok, functioning ok-shop on Sat said ok to run.

Nut for dump handle missing for restroom dump

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0

7050 - STRAND, MATTHEW \$0.00

(0.00)

Labor Comments: its not overheating, the gauge is 10-20 degrees over the actual engine temp.

Will see what Jacob wants to do.

Miscellaneous Labor \$0

Other \$0

79:Lavatory \$0 \$0 \$0.00 \$0.00

Maintenance Requested: 11982 - 09/02/2017 - red handle to dump valve is lose

Requestor Notes: red handle to dump valve is lose. Found laying in compartment when I dumped. Needs tightening

Also needs water in toilet-no bucket, looked for bucket. Couldn't find. No one in cleaning area to Fri at 3pm. Can't reach the water valve-someone please fill.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0

7050 - STRAND, MATTHEW \$0.00

(0.00)

Labor Comments: put the handle and new nut on

Miscellaneous Labor \$0

Other

\$0

\$0	\$0	\$0	\$0	\$0	\$0.00
-----	-----	-----	-----	-----	--------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213225	09/18/2017	09/22/2017	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$850.00	\$85.00		\$0.00	\$935.00

Maintenance Requested: 60230 - 09/16/2017 - bus shut off while driving residential street and

Requestor Notes: 1) Tag driver side needs to be looked at. Inside tread is wearing and feels like blots are starting to come through

2) Side marker line passenger (this is hard to make out the handwriting, so I'm guessing here) in front lost-Mechanic changed out light and 1 side is loose....?

3) Bus turned itself off while carrying passengers down street.

4) Water temp gauge is running very high-might want to take a look

Technician Response:

Maint Req Status: Completed

07-08-119 engine cluster

\$850.00

(1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$85.00

(1.70)

Labor Comments: Fixed the light I think they were talking about.

Checked the codes, one for low coolant and that would have shut the bus down.

Someone must have filled it back up.

Tag tires are perfect.

Replaced the Cluster, so the coolant read the right temp

Miscellaneous Labor

\$0

Other

\$0

\$0	\$850.00	\$85.00	\$0	\$0	\$935.00
-----	----------	---------	-----	-----	----------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213302	09/21/2017	09/22/2017	Closed	0.00	

Description: Coolant Sensor, Engine Kill Switch

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
quit running while en route		\$109.47	\$157.50		\$0.00	\$266.97

Maintenance Requested: 60276 - 09/20/2017 - quit running while en route

Requestor Notes: bus engine quit running on 94 at 694. NOT FUN sat a minute and restarted.

This happened last weekend as well, when Tom Gillen drove it for a TCHTRachel

Transmission clunks and jerks bus frequently when you take foot of gas pedal

Technician Response:

Maint Req Status: Completed

Pillsbury: Sensor Coolant

\$29.12

Engine Shut-Down MCI

D4500 w/ Detroit Series 60:

7L-8-1124 (1.000)

Pillsbury: Sensor Coolant

\$61.04

Surge Tank: 07-08-1119

(1.000)

5/7/2019

Work Order Detail

Pillsbury: Fluid DELO \$16.00
 Antifreeze ELC BULK: A/F
 Chevron DELO 50/50 BULK
 (2.000)
 Pillsbury: Connector, \$3.31
 ThermoKing: 445835 (1.000)
 Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$157.50
 (3.15)

Labor Comments: Code for coolant level keeps popping up, changed the coolant sensors. Stripped out the one, so I had fun fixing that.

Engine kill switch in the battery box had loose connections. tightened them up

Miscellaneous Labor \$0
 Other \$0

\$0 \$109.47 \$157.50 \$0 \$0 \$266.97

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
213341	09/25/2017	09/25/2017	Closed	0.00	

Description: Already Fixed??

Detail	Discounts	Parts	Labor	Tires	Other	Total
40:Engine		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 60303 - 09/23/2017 - bus shuts off when en route-multiple times

Requestor Notes: Bus STOPPED RUNNING TWICE on the road doing the city tour

Pipes leak toilet water (in the dump door)

Bus needs a new microphone0the mic doesn't always pick up the guides voice and also comes disconnected

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$0.00
 (0.00)

Labor Comments: Old request already fixed.

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$0 \$0 \$0 \$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
213480	10/03/2017	10/04/2017	Closed	0.00	

Description: Engine Sensors, Wireless Microphone

Detail	Discounts	Parts	Labor	Tires	Other	Total
31:Charging		\$0	\$25.00		\$0.00	\$25.00

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$25.00
 (0.50)

Labor Comments: Bus would not start, Code for SRS and TRS Sensors, Got it started and into the garage.

Miscellaneous Labor \$0
 Other \$0

40:Engine \$116.34 \$125.00 \$0.00 \$241.34
 Pillsbury: Sensor Assy (trs): \$53.23

5/7/2019

Work Order Detail

08929388 (1.000)
 Pillsbury: Sensor Assy (SRS):
 08929387 (1.000)
 Miscellaneous Parts
 7050 - STRAND, MATTHEW
 (2.50)

\$63.11

\$0

\$125.00

Labor Comments: Replaced the TRS and SRS engine sensors.

Miscellaneous Labor
 Other

\$0

\$0

Radio/DVD/PA:Radio repair

\$0

\$21.50

\$0.00

\$21.50

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
 (0.43)

\$21.50

Labor Comments: Got the wireless microphone back from REI, installed back into bus.

Miscellaneous Labor
 Other

\$0

\$0

\$0.00

\$116.34

\$171.50

\$0

\$0

\$287.84

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 978,762.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

213664

10/12/2017

10/13/2017

Closed

0.00

Description: PMI, Drag Link

DetailDiscountsPartsLaborTiresOtherTotal

20:Steering

\$94.65

\$56.00

\$0.00

\$150.65

Pillsbury: Draglink End RH

\$94.65

EL3 MCI: 11-04-1005 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
 (1.12)

\$56.00

Labor Comments: Replaced a bad drag link.

Miscellaneous Labor
 Other

\$0

\$0

PMI:Preventative Maintenance Inspection

\$183.34

\$226.00

\$0.00

\$409.34

Pillsbury: Filter Frame, Main

\$183.34

Evap, EL3: 16-06-1093

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
 (4.52)

\$226.00

Labor Comments: PMI

Miscellaneous Labor
 Other

\$0

\$0

\$0

\$277.99

\$282.00

\$0

\$0

\$559.99

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 978,827.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

213694

10/16/2017

10/16/2017

Closed

0.00

Description: Mirror

DetailDiscountsPartsLaborTiresOtherTotal

72:Body Misc

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 60537 - 10/14/2017 - body work needed

Requestor Notes: today the bus scraped garage door frame as putting coach away-approx 4' long
 above 1st and 2nd luggage doors.

Technician Response:

Work Order Detail

5527: 1998 MCI EL3

License Plate:

Location: PBG

Department: PBG5-Charter

Campaign #

Date:

Description: Webasto Service

5527: 1998 MCI EL3

License Plate:

Location: PBG

Department: PBG5-Charter

Campaign #

Date:

Description: repair scratches of passenger side and polish

5527: 1998 MCI EL3

License Plate:

Miles: 979.146.0

Work Order Detail

Recall:		Location: PBG Campaign #		Department: PBG5-Charter Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
213835	10/24/2017	10/24/2017	Closed	0.00		
Description: Lavatory						
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>
79:Lavatory			\$0	\$83.50		\$0.00
Miscellaneous Parts			\$0			
7050 - STRAND, MATTHEW				\$83.50		
(1.67)						
Labor Comments: Lavatory, When charging the bus with water, the gasket on the inside was leaking, causing water to drop in the engine compartment. Looking like a leak. Resealed it with RTV.						
Miscellaneous Labor				\$0		
Other						\$0
		\$0	\$0	\$83.50	\$0	\$0
						\$83.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 979,325.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
213985	11/02/2017	11/02/2017	Closed	0.00		
Description: Mirror						
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u> <u>Total</u>
267 - Superglass Windshield						\$40.00 \$40.00
Repair, Inv. # 2786162						
267 - Superglass Windshield						\$40.00 \$40.00
Repair, Inv. # 2786033, PO #						
5527, Desc: Chip Repair						
77:Mirrors			\$0	\$3.50		\$0.00 \$3.50
Maintenance Requested: 60703 - 11/02/2017 - driver side mirror plastic frame broken						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts			\$0			
7050 - STRAND, MATTHEW				\$3.50		
(0.07)						
Labor Comments: not a safety concern						
Miscellaneous Labor				\$0		
Other						\$0
		\$0	\$0	\$3.50	\$0	\$80.00 \$83.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,044.0

Location: PBG

Department: PBG5-Charter

Recall:		Campaign #		Date:		
<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>	
214216	11/20/2017	11/20/2017	Closed	0.00		
Description: Mirror						
<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>
77:Mirrors			\$723.76	\$47.50		\$0.00
Maintenance Requested: 60854 - 11/18/2017 - Left mirror housing damaged, needs adjustment *com						
Requestor Notes: Service door is out of alignment at top. Closes hard						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Mirror Head:			\$723.76			
03-22-1053 (2.000)						
Miscellaneous Parts			\$0			

7050 - STRAND, MATTHEW
(0.95)

\$47.50

Labor Comments: Mirror head damaged. Replaced it and adjusted it.

Miscellaneous Labor
Other

\$0

\$0

\$0 \$723.76 \$47.50 \$0 \$0 \$771.26

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,260.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214406	12/04/2017	12/05/2017	Closed	0.00	

Description: Radio

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$21.50		\$0.00	\$21.50

Maintenance Requested: 60931 - 12/02/2017 - Radio-CD player-Mic Quick working completely halfw

Requestor Notes: Radio-CD player-Mic Quick working completely halfway though x-mas lights tour. If
turned off the unit above the radio, the CD would play a few seconds then quit playing-
cordless mic and regular mic also would not work

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts
7050 - STRAND, MATTHEW
(0.43)

\$0

\$21.50

Labor Comments: Looked over the bus and found everything to be operational, left the radio on outside
with the bus running for 3 hours and the mic and everything continued to work

Miscellaneous Labor
Other

\$0

\$0

\$0 \$0 \$21.50 \$0 \$0 \$21.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,348.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214461	12/06/2017	12/08/2017	Closed	0.00	

Description: drive tire

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$1,500.00	\$235.00		\$0.00	\$1,735.00

Work Comments: 22 -- Drive tires need replacing.

Pillsbury: Tire, Steer,Toyo

\$1,500.00

M144: 315/80R22.5 (4.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (4.70)

\$235.00

Labor Comments: 22 -- Drive tires need replacing. ----- Removed and replaced all four drive tires.

Dimount and remount. Balanced, and torqued lug nuts to 450 LBS.

Miscellaneous Labor
Other

\$0

\$0

\$0 \$1,500.00 \$235.00 \$0 \$0 \$1,735.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,348.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214570	12/12/2017	12/13/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$134.64	\$424.50		\$0.00	\$559.14
Work Comments: 21 -- Rubber bumpers for drive and tag axles are shot.						
Pillsbury: Stop-Bump, Drive		\$134.64				
Axle: 12-03-1025 (4.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (8.49)			\$424.50			
Labor Comments: 21 -- Rubber bumpers for drive and tag axles are shot. ----- Removed and replaced all the bad rubber bumpers.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$134.64	\$424.50	\$0	\$0	<u>\$559.14</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,429.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214793	12/27/2017	12/27/2017	Closed	0.00	

Description: Air System, Air Drier

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$33.50		\$0.00	\$33.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.67)			\$33.50			
Labor Comments: Checked the rear torque arms. Bushings wearing but are still good.						
Miscellaneous Labor			\$0			
Other					\$0	
31:Charging		\$0	\$13.50		\$0.00	\$13.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.27)			\$13.50			
Labor Comments: Charging the bus. Dead in the washstall, had to jump start.						
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$46.50		\$0.00	\$46.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.93)			\$46.50			
Labor Comments: Drained air and filled with air conditioning alcohol.						
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$186.21	\$91.00		\$0.00	\$277.21
Pillsbury: AD-IP Air Dryer		\$57.25				
Desiccant Cartridge Bendix: 109493BXR (1.000)						
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$64.48				
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$64.48				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.82)			\$91.00			
Labor Comments: Air drier service.						
Helped driver with check engine lights on 2177 and 2178.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$186.21	\$184.50	\$0	\$0	<u>\$370.71</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,697.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214891	01/02/2018	01/04/2018	Closed	0.00	

Description: Radio, Door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$80.10	\$71.00		\$0.00	\$151.10
Pillsbury: Lock/Keys Kit EL3		\$80.10				
MCI: 3R-29-61 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.42)			\$71.00			
Labor Comments: Fuel door latch was not working properly, exchanged the tumblers out. Took for a drive. Door is noisy. Found spot the wind is entering, sealed it and added some weather stripping.						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$394.00	\$26.50		\$0.00	\$420.50
Maintenance Requested: 61190 - 01/01/2018 - radio does not work-entry door does not seal						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Radio CD-2000,AM/ FM/CD,MOD ADV: 710338 (1.000)		\$394.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.53)			\$26.50			
Labor Comments: Swapped radios out to see if that is the ongoing problem.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$474.10	\$97.50	\$0	\$0	<u>\$571.60</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 981,041.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215086	01/12/2018	01/15/2018	Closed	0.00	

Description: Door, Air system

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$141.91	\$186.50		\$0.00	\$328.41
Pillsbury: Drain Valve: 12100 (4.000)		\$31.96				
RO32934 Cut Off Air Valve (Reman) (1.000)		\$109.95				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.73)			\$186.50			
Labor Comments: Bus was leaning really bad in the barn. Sparyed down fittings found the left side air suspension valve was leaking at the casing. Ordered one from C&J. Waited for the part. Test drove a school bus.						
Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$0	\$62.50		\$0.00	\$62.50
Maintenance Requested: 61283 - 01/11/2018 - poke with Jacob on trip. Top of door does not alwa						
Requestor Notes: spoke with Jacob on trip. Top of door does not always close properly. Leaves a gag for						

air 3/4 inch. Can be closed if door is pulled on while closing. Otherwise it latches on top inside plastic cover rather than inside steel catch.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
7050 - STRAND, MATTHEW \$62.50
(1.25)

Labor Comments: Adjusted the lock out a little, but its mainly due to the cold. Door works perfect in the barn or the shop.

Miscellaneous Labor \$0
Other \$0

\$0.00 \$141.91 \$249.00 \$0 \$0 \$390.91

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,921.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215106	01/15/2018	01/15/2018	Closed	0.00	

Description: Entrance Door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$11.50		\$0.00	\$11.50

Maintenance Requested: 61303 - 01/12/2018 - door does not close tightly

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
7050 - STRAND, MATTHEW \$11.50
(0.23)

Labor Comments: Readjusted the door back.

Miscellaneous Labor \$0
Other \$0

\$0 \$0 \$11.50 \$0 \$0 \$11.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 981,548.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215172	01/17/2018	01/25/2018	Closed	0.00	

Description: steering, suspension, entrance door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$174.00		\$0.00	\$174.00

Maintenance Requested: 61380 - 01/21/2018 - turning left steering sluggish/chatters

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
0081 - WOLF, PATRICK (3.48) \$174.00

Labor Comments: 20 -- Maint. req. -- turning left steering sluggish/chatters ----- Checked the steering linkage. both front and back. Didn't find anything wrong. Checked the res. topped it off. Road tested it. Did not feel any sluggish or here andy chattering.

Miscellaneous Labor \$0
Other \$0

21:Suspension \$7.99 \$171.50 \$0.00 \$179.49

Work Comments: 21 -- Complaints about the bus tilting very bad in the front right.

Pillsbury: Drain Valve: 12100 \$7.99

(1.000)

Miscellaneous Parts \$0

5/7/2019

Work Order Detail

0081 - WOLF, PATRICK (3.43)

\$171.50

Labor Comments: 21 -- Complaints about the bus tilting very bad in the front right. Got 6 lifts under the bus and raised it in the air. Checked all the air bags, hoses, tanks ect. Removed and replaced the right tag axle drain valve (leaking).

Miscellaneous Labor

\$0

Other

\$0

78:Doors Entrance / Exit

\$0

\$79.00

\$0.00

\$79.00

Work Comments: 78 -- Compants about the front door upper latch closing on the wrong side of the catch.

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (1.58)

\$79.00

Labor Comments: 78 -- Compants about the front door upper latch closing on the wrong side of the catch. ----- Adjusted the door closed sensor.

Miscellaneous Labor

\$0

Other

\$0

\$0

\$7.99

\$424.50

\$0

\$0

\$432.49

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 982,835.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

215693

02/21/2018

02/22/2018

Closed

0.00

Description: Maintenance Requests

DetailDiscountsPartsLaborTiresOtherTotal

267 - Superglass Windshield

\$40.00

\$40.00

Repair, Inv. # 2786337

40:Engine

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 61628 - 02/14/2018 - oil drip, front end shakes, chip in windshield-->

Requestor Notes: chip in windshield-driver's side-above the synovia tablet

Front end shakes at freeway speed-steering wheel shakes

Engine dripping oil

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Miscellaneous Labor

\$0

Other

\$0

73:Seats

\$0

\$104.00

\$0.00

\$104.00

Maintenance Requested: 61669 - 02/18/2018 - seat 49 and 50 are loose-missing bolts

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$104.00

(2.08)

Labor Comments: Refastened the seat.

Cleaned the oil off the engine, Looks like its leaking from the rocker extentsion.

Took for test drive, Front end seemed fine.

Wrote up the windshield for the glass guy.

Miscellaneous Labor

\$0

Other

\$0

\$0

\$0

\$104.00

\$0

\$40.00

\$144.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 984,258.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

216117 03/19/2018 03/20/2018 Closed 0.00

Description: Camera, Parking Brake Light

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
35:Instrument & Gauges		\$400.00	\$42.50		\$0.00	\$442.50
Maintenance Requested: 61810 - 03/07/2018 - see comments						
Requestor Notes: 1. on board camera in windshield fell down after hitting a pothole						
2. parking brake light doesn't light up						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Interlock Relay		\$400.00				
module: 07-18-1010 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$31.50			
(0.63)						
Labor Comments: Refastened the camera to the windshield.						
0081 - WOLF, PATRICK (0.22)			\$11.00			
Labor Comments: 2. Parking brake light doesn't light up ---- Checked the park brake switch. good.						
Tried a new Interlock module. Now they work fine.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$400.00	\$42.50	\$0	\$0	<u>\$442.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 984,436.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216266	03/28/2018	04/23/2018	Closed	0.00	

Description: LOF,PMI,Diff.,FF,HUB

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
DF:Differential Service		\$117.48	\$179.00		\$0.00	\$296.48
Work Comments: DF. -- Differential service.						
Pillsbury: Oil Gear Synthetic:		\$117.48				
Oil Gear 75W-90 BULK in						
quarts (20.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (3.58)			\$179.00			
Labor Comments: DF. -- Differential service. ----- Drained then refilled with new fluid.						
Miscellaneous Labor			\$0			
Other					\$0	
FF:Fuel Filter		\$8.53	\$0		\$0.00	\$8.53
Work Comments: FF -- Fuel Filters.						
Pillsbury: Filter Fuel: 3118		\$4.19				
(1.000)						
Pillsbury: Filter, Fuel, MCI:		\$4.34				
3120 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Labor Comments: FF -- Fuel Filters. ----- Removed and replaced both fuel filters.						
Miscellaneous Labor			\$0			
Other					\$0	
HUB:Hub Service		\$13.14	\$256.00		\$0.00	\$269.14
Work Comments: HUB -- Hub service						
Pillsbury: Oil Gear Synthetic:		\$13.14				
Oil Gear 75W-90 BULK in						
quarts (2.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (5.12)			\$256.00			
Labor Comments: HUB -- Hub service ----- Drained both steer and both tag axle, Hubs. Refilled with new gear lube.						
Miscellaneous Labor			\$0			

5/7/2019

Work Order Detail

Other LOF:Lube, Oil, Filter	\$106.22	\$108.50	\$0 \$0.00	\$214.72
Work Comments: LOF -- Lube, Oil and Filter				
Pillsbury: Oil Bulk in Quarts:	\$76.59			
Oil 15W-40 Bulk (37.000)				
Pillsbury: Filter Media: 4WZ68 (7.000)	\$4.13			
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)	\$7.00			
Pillsbury: Fluid Windshield Washer Fluid BULK/Gal After Dilution: W/W Fluid BULK (2.000)	\$2.96			
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)	\$15.54			
Miscellaneous Parts 0081 - WOLF, PATRICK (2.17)	\$0	\$108.50		
Labor Comments: LOF -- Lube, Oil and Filter ---- Performed the service and safety check as per the attached sheet.				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$100.00	\$0	\$0.00	\$100.00
Work Comments: PMI -- Preventative maintenance Inspection.				
03-22-1361 Mirror Bracket Arm, LH (1.000)	\$100.00			
Miscellaneous Parts 0081 - WOLF, PATRICK (0.00)	\$0	\$0.00		
Labor Comments: PMI -- Preventative maintenance Inspection. ----- Performed the preventative maintenance and Inspection as per the attached sheet.				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$345.37	\$543.50	\$0
			\$0	\$888.87

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 984,611.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216595	04/18/2018	04/19/2018	Closed	0.00	

Description: 2 -way install

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
51:Communications		\$619.00	\$196.00		\$0.00	\$815.00

Work Comments: 51 -- Install 2-way radio

2way install \$619.00 (1.000) \$619.00

Part Comments: Kit includes:

*HY-MD782U-1 UHF DMR Mobile Radio
 *K-794 Line kit, very thick mount
 *K332 Ground plane disc 6" dia, 3/8" mounting
 *C-BNC58-CR connector, BNC-Male, R858, crimp
 *B4502NS Antenna, UHF, no ground plane with spring
 *HY-IGNITION SENSE accessory plug, ignition sense, hytera MD752/MD662
 (professional wireless)

Miscellaneous Parts \$0
 0081 - WOLF, PATRICK (3.92) \$196.00

Labor Comments: 51 -- Install 2-way radio ---- Installed the 2-Way Radio.

Miscellaneous Labor \$0
 Other \$0

\$0 \$619.00 \$196.00 \$0 \$0 \$815.00

VIN: 1M8TRMPA6WP060245

License Plate:

5527: 1998 MCI EL3

Miles: 985,310.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216821	05/02/2018	05/08/2018	Closed	0.00	

Description: A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 62119 - 04/20/2018 - Steering-woobles Strays

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts
7050 - STRAND, MATTHEW
(0.00)

\$0

\$0.00

Miscellaneous Labor
Other

\$0

\$0

20:Steering

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 62110 - 04/20/2018 - Brke squeaks bus shkes @ 60 steerg off

Requestor Notes: driver seat doesn't raise

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts
7050 - STRAND, MATTHEW
(0.00)

\$0

\$0.00

Labor Comments: Took bus for a road test. Seemed to drive normal.

Seat does go up and down. '

Brakes didnt seem to squeak to bad.

Miscellaneous Labor
Other

\$0

\$0

37:Warning, Strobe, 8-Ways

\$17.83

\$0

\$0.00

\$17.83

Maintenance Requested: 62138 - 04/23/2018 - no back up alarm horn

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Back Up Alarm:
56012 (1.000)
Miscellaneous Parts
7050 - STRAND, MATTHEW
(0.38)

\$17.83

\$0

\$0.00

Labor Comments: Installed new backup alarm.

Miscellaneous Labor
Other

\$0

\$0

41:A/C & Heating

\$471.06

\$0

\$0.00

\$471.06

Pillsbury: Valve Assy, For 5527:
16-02-1034 (1.000)
Pillsbury: oring: 16-02-1041pk
(1.000)

\$5.18

Pillsbury: Filter Dryer EL3:
16-04-1004 (1.000)
Pillsbury: Freon R134A per
Lb.: R134A (20.000)

\$38.95

\$46.60

Miscellaneous Parts
7050 - STRAND, MATTHEW
(5.28)

\$0

\$0.00

Labor Comments: A/C leak out of the kingsvalve on the low side. Replaced the whole fitting. Changed out the filter drier. It held 150 pounds of nitrogen over night. Sucked the system down, held perfect vaccum for 30 mins Cleanded out the condensor and evapartor.. Added 20 pounds of freon to the system. Took for a road test.

Miscellaneous Labor
Other

\$0

\$0

Work Order Detail

\$0 \$488.89 \$0 \$0 \$0 \$488.89

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 985,666.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216952	05/10/2018	05/17/2018	Closed	0.00	

Description: mirrors

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$0	\$6.00		\$0.00	\$6.00

Maintenance Requested: 62251 - 05/09/2018 - Left Mirror arm is loose

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 9131 - CARNEY, JASON (0.12) \$6.00

Labor Comments: tightened up mirror arm and double checked mirror angle for driver

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$6.00 \$0 \$0 \$6.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 986,402.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217187	05/23/2018	05/30/2018	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$859.50		\$0.00	\$859.50
Miscellaneous Parts		\$0				
9106 - MARIN RODRIGUEZ, CLAUDIO (17.19)			\$859.50			
Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$0 \$859.50 \$0 \$0 \$859.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 986,632.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217346	06/05/2018	06/06/2018	Closed	0.00	

Description: Drivers Window

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$25.00		\$0.00	\$25.00

Maintenance Requested: 62246 - 05/08/2018 - driver's side window leaks when it rains

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW (0.50) \$25.00

Labor Comments: Sealed up possible locations of water leaks on the drivers side window

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$25.00 \$0 \$0 \$25.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 987,796.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217473	06/15/2018	06/21/2018	Closed	0.00	

Description: radio and synovia base,P/S Flush,synovia base

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
39:Other Electrical		\$0	\$66.00		\$0.00	\$66.00

Maintenance Requested: 62475 - 06/14/2018 - Synovia unit is loose on dash

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0	
0081 - WOLF, PATRICK (1.32)		\$66.00

Labor Comments: 39 -- Synovia unit is loose on dash ---- Screwed the base back into place.

Miscellaneous Labor	\$0	
Other		\$0

40:Engine	\$0	\$32.50	\$0.00	\$32.50
-----------	-----	---------	--------	---------

Miscellaneous Parts	\$0	
7050 - STRAND, MATTHEW (0.65)		\$32.50

Labor Comments: Bus wouldnt start, Code for SRS. Checked the wiring. Bus fired up. Cleaned the connector and wiring. Bus started just fine after that.

Miscellaneous Labor	\$0	
Other		\$0

49:Air System	\$0	\$36.00	\$0.00	\$36.00
---------------	-----	---------	--------	---------

Miscellaneous Parts	\$0	
7050 - STRAND, MATTHEW (0.72)		\$36.00

Labor Comments: Checked for air leaks. Bus leans to the right. Did not find anything. Possibly small leaks in the air bags.

Miscellaneous Labor	\$0	
Other		\$0

PS:Power Steering Flush	\$83.29	\$144.00	\$0.00	\$227.29
-------------------------	---------	----------	--------	----------

Work Comments: P/S -- Power steering flush

Pillsbury: Fluid ATF (Synthetic) \$72.91

Bulk Quart: ATF Synthetic Bulk (11.500)

Pillsbury: Element Power \$10.38

steering reservoir: 11-08-1074

(1.000)

Miscellaneous Parts	\$0	
0081 - WOLF, PATRICK (2.88)		\$144.00

Labor Comments: P/S -- Power steering flush ---- Disconected the return line and ran fluid thru the p/s system till coming out clean.

Miscellaneous Labor	\$0	
Other		\$0

Radio/DVD/PA:Radio repair	\$0	\$105.00	\$0.00	\$105.00
---------------------------	-----	----------	--------	----------

Maintenance Requested: 62456 - 06/11/2018 - radio and synovia base-see comments

Requestor Notes: radio doesn't work-top unit

Synovia unit is loose-missing a screw in base

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0	
0081 - WOLF, PATRICK (2.10)		\$105.00

Labor Comments: RADIO/DVD/PA -- radio doesn't work-top unit ---- The radio works fine if you turn it on.

39 -- Synovia unit is loose-missing a screw in base ---- Screwed the base back into place.

Miscellaneous Labor	\$0	
Other		\$0

\$0.00 \$83.29 \$383.50 \$0 \$0 \$466.79

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 989,411.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217770	07/10/2018	07/11/2018	Closed	0.00	

Description: polishing wheels

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$61.50		\$0.00	\$61.50
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS			\$61.50			
(1.23)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$61.50	\$0	\$0	<u>\$61.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 989,411.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217792	07/11/2018	07/25/2018	Closed	0.00	

Description: polishing wheels

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$255.00		\$0.00	\$255.00
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS			\$255.00			
(5.10)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$255.00	\$0	\$0	<u>\$255.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 989,680.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217811	07/12/2018	07/25/2018	Closed	0.00	

Description: Engine

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$47.34	\$178.50		\$0.00	\$225.84

Maintenance Requested: 62594 - 07/06/2018 - see comments

Requestor Notes: microphone only works part of time

air conditioning stopped working, came back on after shutting bus down

Bus powered down at stop sign and had to be powered back on. Seemed OK after restarting

The red and amber engine lights came on briefly while idling but then went away

Technician Response:

Maint Req Status: Completed

Pillsbury: Sensor Coolant \$31.82
 Engine Shut-Down MCI
 D4500 w/ Detroit Series 60:
 7L-8-1124 (1.000)
 Pillsbury: Oil Bulk in Quarts: \$15.52

Oil 15W-40 Bulk (7.500)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$178.50

(3.57)

Labor Comments: Engine code for low coolant level. Changed out the sensor. Checked the wiring, retied the wiring up. Found the bus was almost 2 gallons low on coolant. Filled to full mark. Microphone on order..

Replaced the pigtail for the TRS Sensor.

Greased the bus hoping to do a pmi. But charter needed the bus.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$47.34 \$178.50 \$0 \$0 \$225.84

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,275.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #Open DateClose DateStatusDowntimeAccident

218068

07/30/2018

08/27/2018

Closed

0.00

Description: PMI,TF, DOT, Write-ups.

DetailDiscountsPartsLaborTiresOtherTotal

12:Axles (rear)

\$722.87

\$1,914.50

\$0.00

\$2,637.37

Work Comments: 12 -- Drive axle sub-frame rotted out. Air bags shot.

Pillsbury: Shock Absorber,

\$160.06

Drive, MCI: 12-05-1148 (2.000)

Pillsbury: Spring Air Bag, Drive

\$503.62

Axle: 12-03-1041 (4.000)

0301742 Tree D 3/8x1/4

\$15.74

(1.000)

0301796 CYL N/F 1/2x1/4

\$26.69

(1.000)

0301682 Burr Oval DB 3/8x1/4

\$16.76

(1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK

\$1,491.50

Labor Comments: 12 -- Drive axle sub-frame rotted out. Air bags shot. ----- Pulled 522 up to the shop. Removed the entire rear axle assembly. Blocked up the tag axle and pushed it back down to the body shop area. Removed the drive axle from both axle assemblies. Removed the subframe from 527. Mounted the subframe from 522 into 527. Mounted the drive axle from 527 back onto the subframe. Installed two new shocks. installed four new air springs. Had to remove a broken bolt from the frame of the rear boggy assembly. Hooked up all the air lines and ABS sensors. Remounted the leveling valves.

9127 - JACOBS, ANDREW

\$210.50

(4.21)

Labor Comments: help pat pull axle out of burnt bus and put bus back at body shop

0146 - SHIPPY, CURTIS (4.25)

\$212.50

Labor Comments: went out to pills and got a broken bolt out of the trailing arm bracket on a motor coach.

Miscellaneous Labor

\$0

Other

\$0

35:Instrument & Gauges

\$0

\$459.00

\$0.00

\$459.00

Maintenance Requested: 62644 - 07/18/2018 - ISE fleet is not working.

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

9130 - PADEFORD, ERIC

\$459.00

(9.18)

Labor Comments: tried a couple different spare screens had different issues with them put them on jacob's desk to get repaired

removed wire harness feeding synovia and cut out bad section reinstalled and test
drove synovia worked as should
wired in new keyed power

Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$0	\$38.50	\$0.00	\$38.50
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.77)		\$38.50		
Labor Comments: 36 -- Lighting ---- Replaced burnt out bulbs.				
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$0	\$374.00	\$0.00	\$374.00
Maintenance Requested: 62736 - 07/28/2018 - see comment				
Requestor Notes: A/C Stopped working at 1:00 PM with passengers.				
Rebooted a/c once. Did not start working				
Rear PSI dropped into red a couple of times. Less than 100 PSI				
Passenger door not working correctly as previously written up				
Technician Response: 41 -- A/C Stopped working at 1:00 PM with passengers.				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (7.48)		\$374.00		
Labor Comments: 41 -- A/C Stopped working at 1:00 PM with passengers.				
Rebooted a/c once. Did not start working see below Work code 41.				
49 -- Rear PSI dropped into red a couple of times. Less than 100 PSI. This can happen easily in heavy traffic with the bus idling.				
78 -- Passenger door not working correctly as previously written up ---- See work code 78 below.				
0146 - SHIPPY, CURTIS (0.00)		\$0.00		
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$68.68	\$87.50	\$0.00	\$156.18
Maintenance Requested: 62843 - 08/15/2018 - A/C stopped working. See Notes				
Requestor Notes: Driver restarted the bus and the A/C started working for an hour to hour and a half and then quit again.				
Technician Response:				
Maint Req Status: Completed				
Pillsbury: Coil 24 Volt A/C	\$68.68			
Comp. Unloader Valve MCI				
D4500: 16L-10-107 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (1.75)		\$87.50		
Labor Comments: Found a unloader not working. Replaced it and ran system. Freon level was good. Changed filters.				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$22.50	\$0.00	\$22.50
Maintenance Requested: 62653 - 07/18/2018 - overheard bin missing a screw see comments				
Requestor Notes: right side of coach, right side of bin				
Did not say passenger or driver side.....				
Technician Response: 72 -- Door hitting the front bumper.				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.45)		\$22.50		
Labor Comments: 72 -- right side of coach, right side of bin				
Did not say passenger or driver side..... ---- Replaced the missing screw.				
72 -- Door hitting the front bumper. ---- Had to readjust the front bumper				
Miscellaneous Labor		\$0		
Other			\$0	
78:Doors Entrance / Exit	\$122.46	\$395.00	\$0.00	\$517.46
Maintenance Requested: 62730 - 07/27/2018 - see comments				
Requestor Notes: passenger door does not close and latch completely with door toggle switch. Buss stayed in low ride until door is pulled completely closed by hand and than latches closes.				

On pre trip one of the mechanics knew about the problem. He told me to pull door closed until fixed. NO problem doing so during run.

Technician Response: 78 -- passenger door does not close and latch completely with door toggle switch. Buss stayed in low ride until door is pu

Maint Req Status: Completed

Pillsbury: Bearing Mount \$122.46
 hinge: 03-32-1008 (2.000)
 Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$9.00
 (0.18)

Labor Comments: Pulled the bus in and checked the A/C. A/C was working as should

0081 - WOLF, PATRICK (7.72) \$386.00

Labor Comments: 78 -- passenger door does not close and latch completely with door toggle switch.
 Buss stayed in low ride until door is pulled completely closed by hand and than
 latches closes.

On pre trip one of the mechanics knew about the problem. He told me to pull door closed until fixed. NO problem doing so during run. ----- Pulled the front bumperet off. Removed the front door. Pulled the door frame out. Ground out the old bearings and replaced them. Put everything back together.

Miscellaneous Labor \$0
 Other \$0

DO:DOT Inspection \$2.00 \$146.00 \$0.00 \$148.00

Work Comments: DO -- DOT Inspection

DOT Sticker (\$2.00) (1.000) \$2.00
 Miscellaneous Parts \$0
 0081 - WOLF, PATRICK (2.92) \$146.00

Labor Comments: DO -- DOT Inspection ---- Performed the DOT inspection as per the attached sheet.

Miscellaneous Labor \$0
 Other \$0

MS:Misc \$0 \$1.00 \$0.00 \$1.00

Maintenance Requested: 62808 - 08/10/2018 - see comments

Requestor Notes: when filling toilet water sprays out of different areas of the engine-Pat said the hose inside must be leaking/loose
 Synovia not working

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 9130 - PADELFORD, ERIC \$1.00
 (0.02)

Labor Comments: clocked into on accident looking for synovia write up

Miscellaneous Labor \$0
 Other \$0

PMI:Preventative Maintenance Inspection \$0 \$135.00 \$0.00 \$135.00

Work Comments: PMI -- Preventative Maintenance Inspection

Headlights: high/low beam:Pass Horn:Pass Leaks:Pass

Turn signals:Pass

Miscellaneous Parts \$0
 0081 - WOLF, PATRICK (2.70) \$135.00

Labor Comments: PMI -- Preventative Maintenance Inspection ---- Performed the PMI as per the attached sheet.

Miscellaneous Labor \$0
 Other \$0

TF:Transmission Flush \$211.72 \$79.00 \$0.00 \$290.72

Work Comments: TF -- Transmission flush

Pillsbury: Fluid ATF (Synthetic) \$177.52
 Bulk Quart: ATF Synthetic Bulk
 (28.000)

Pillsbury: Filter Kit \$34.20
 Transmission Allison (Short
 Filter): 7741XE (1.000)

Miscellaneous Parts \$0
 0081 - WOLF, PATRICK (1.58) \$79.00

Labor Comments: TF -- Transmission flush

Miscellaneous Labor \$0
 Other \$0

\$0.00 \$1,127.73 \$3,652.00 \$0 \$0 \$4,779.73

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,573.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218504	08/21/2018	08/22/2018	Closed	0.00	

Description: service call, Intake,

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
42:Air Intake		\$0	\$239.00		\$0.00	\$239.00

Work Comments: 42 -- Air Intake

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (4.78)

\$239.00

Labor Comments: 42 -- Air Intake ---- Looked over the turbo again. Pressure tested the CAC and all the boots.

Miscellaneous Labor

\$0

Other

\$0

95:Service Calls

\$0

\$132.50

\$0.00

\$132.50

Work Comments: 95 -- Service call

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (2.65)

\$132.50

Labor Comments: 95 -- Service call ---- Drove up to Hwy 5 And 34th. Looked over the bus. Turbo was ok. dint find anything wrong. Fallowed the driver back to the shop.

Miscellaneous Labor

\$0

Other

\$0

AF:Air Filter Replacement

\$42.00

\$22.50

\$0.00

\$64.50

Work Comments: AF -- Air Filter Replacement

Pillsbury: Filter Air: 6741

\$42.00

(1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (0.45)

\$22.50

Labor Comments: AF -- Air Filter Replacement ---- Removed and replaced the Air Filter.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$42.00 \$394.00 \$0 \$0 \$436.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,573.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218569	08/22/2018	08/28/2018	Closed	0.00	

Description: Turn Signal

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$10.50		\$0.00	\$10.50

Maintenance Requested: 62864 - 08/17/2018 - the right front turn signal and flasher bulb needs

Requestor Notes: to be replaced

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$10.50

(0.21)

Labor Comments: Changed right side front turn signal bulb.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$10.50 \$0 \$0 \$10.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,672.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218615	08/24/2018	08/28/2018	Closed	0.00	

Description: New Wiper Blades

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
58:Wiper/washers		\$73.56	\$0		\$0.00	\$73.56
Pillsbury: Wiper Blade MCI		\$73.56				
EL3: 03-34-1177 (2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: Driver complaint. Replaced wiper blades						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$73.56	\$0	\$0	\$0	<u>\$73.56</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,919.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218678	08/28/2018	09/10/2018	Closed	0.00	

Description: CFR, Write-ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
48:Fuel System		\$0	\$263.50		\$0.00	\$263.50
Maintenance Requested: 62931 - 08/25/2018 - gassy or diesel smell in drivers area after drivin						
Requestor Notes: gassy or diesel smell in drivers area after drivin a while						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (5.27)			\$263.50			
Labor Comments: 48 -- gassy or diesel smell in drivers area after driving a while ---- Removed the panel over the fuel tank. Tightened several bolts into the fuel tank. Steam cleaned the fuel tank area. Put everything back together.						
Miscellaneous Labor			\$0			
Other					\$0	
CFR:Coolant Filter Replacement		\$5.69	\$6.50		\$0.00	\$12.19
Work Comments: CFR -- Coolant filter replacement						
Pillsbury: Filter Coolant		\$5.69				
Cummins ISM: 4071 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.13)			\$6.50			
Labor Comments: CFR -- Coolant filter replacement ---- Removed and replaced the coolant filter.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$5.69	\$270.00	\$0	\$0	<u>\$275.69</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 992,003.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218748	08/30/2018	09/14/2018	Closed	0.00	

Description: White Smoke

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$2,216.39	\$1,539.50		\$0.00	\$3,755.89
Pillsbury: Injector O-Ring 60: RTF26210 (2.000)		\$7.06				
Freight (1.000)		\$15.02				
R23538247 ARM/RLR ASM (1.000)		\$103.59				
R5236977 Injector (1.000)		\$284.19				
23539286 Tube (1.000)		\$30.13				
11506101 Nut (4.000)		\$1.80				
23507438 Stud, Exhaust (4.000)		\$17.44				
08929357 Bolt (9.000)		\$70.02				
23511667 Spacer (11.000)		\$70.73				
23511221 Manifold, Exhaust (1.000)		\$58.11				
23511222 Manifold, Exhaust (1.000)		\$58.90				
23519348 Manifold, Exhaust (1.000)		\$487.18				
23539193 Gasket, Manifold (3.000)		\$25.20				
23511667 Spacer (1.000)		\$6.43				
08929357 Bolt (3.000)		\$36.87				
SCH172743 Turbocharger, New (1.000)		\$750.00				
R23537686 Pump, Fuel (1.000)		\$193.72				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (30.79)			\$1,539.50			

Labor Comments: Bus is blowing out white smoke really bad. Had an exhaust manifold leak. Replaced the manifold and gaskets. During the inspection of the turbo, it showed signs of wear outside of normal patterns. Replaced the turbo and turbo gasket. Found that the fuel pump seemed weak, replaced the fuel pump and the gasket. Installed a clear line from the secondary fuel filter to the back of the head and watched the fuel being pumped into the head. It was not aerated at all. Next we manual cut out the injectors one at a time at the harness by putting a homeade breakout box. Every cylinder change except for cylinder 4. Replaced Injector number 4. During the inspection of the cam and rocker rollers. Cam has wear. The rocker rollers for the exhaust outside of operating specs, replaced them. Still smokes but everything Ive done helps. Took for 1 hour and 45 min test drive and everything drove great, one hiccup. But back into service and see what happens.

Miscellaneous Labor		\$0				
Other					\$0	
51:Communications		\$0	\$47.50		\$0.00	\$47.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.95)			\$47.50			
Labor Comments: Moved the 2-way microphone to the drivers preferred spot. Also moved 4 other buses						
Miscellaneous Labor		\$0				
Other					\$0	

\$0 \$2,216.39 \$1,587.00 \$0 \$0 \$3,803.39

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 992,232.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219169	09/22/2018	09/25/2018	Closed	0.00	

Description: service call

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

5/7/2019

Work Order Detail

40:Engine		\$0	\$0	\$0.00	\$0.00
Maintenance Requested: 63052 - 09/14/2018 - see comments					
Requestor Notes: charge filter light kept coming on					
when filling toilet with water, water comes pouring out all over different area of the engine and tube to dump					
when driving the bus would stop accelerating with foot on pedal and a big cloud of blue smoke came out of the exhaust. I did this a lot					
Technician Response:					
Maint Req Status: Completed					
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW			\$0.00		
(0.00)					
Labor Comments: Took for test drive. Advised that the other 5 injectors should be replaced.					
Miscellaneous Labor		\$0			
Other				\$0	
95:Service Calls		\$0	\$16.50	\$0.00	\$16.50
Work Comments: bus was stalling and smoking					
Miscellaneous Parts		\$0			
0142 - GALLINGER, CHAD			\$16.50		
(0.33)					
Labor Comments: driver called bus was stalling and smoking got 530 ready to swap it out bus was swapped and 527 was parked in Mat's bay driver that swapped bus had no issues when driving from MOA to shop					
Miscellaneous Labor			\$0		
Other				\$0	
	\$0	\$0	\$16.50	\$0	\$0
					<u>\$16.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 992,692.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219333	10/01/2018	10/17/2018	Closed	0.00	

Description: Engine, LOF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$1,883.68	\$1,848.50		\$0.00	\$3,732.18

Maintenance Requested: 63187 - 09/29/2018 - see comments

Requestor Notes: Bus has blue smoke coming out every time gas is pressed

Bus hesitates when driving

Technician Response:

Maint Req Status: Completed

07-01-6001 relay (1.000)	\$51.80
05104701 seal, ring (6.000)	\$18.36
BOSRB5236977 injectors (5.000)	\$1,033.35
freight (1.000)	\$12.50
23511991 gasket (1.000)	\$27.93
23513556 harness injector (1.000)	\$263.11
23522323 harness (1.000)	\$354.51
Pillsbury: Sensor Assy (SRS): 08929387 (1.000)	\$68.89
Pillsbury: Sensor Assy (trs): 08929388 (1.000)	\$53.23
Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW (36.97)	\$1,848.50

Labor Comments: Engine was blowing white smoke really bad. Exhaust manifold leak, replaced manifold, found turbo bad, replaced turbo. Still smoked. Replaced the fuel pump due to shear age, installed a clear line from the secondary filter to the head to watch for air in the fuel. No air, took the CAC out of the equation. Still smokes. Installed a breakout box for the injectors found 4 to be missing. Replaced injector. Still smokes, decided to

do the rest. Reset the injector heights. Found the harness bad, swapped harness and ecms. Still smokes. Injector and Engine harness needed to be replaced. Decided to do both and replace both TRS and SRS sensors. No more smoke, took for really long test drive, sounds and runs better. Installed new harnesses before we pulled engine. Can't replicate the issue anymore. Changed oil and put back in service.

Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter	\$104.06	\$174.00	\$0.00			\$278.06
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)	\$7.00					
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)	\$15.70					
Pillsbury: Oil Bulk in Quarts: Oil 15W-40 Bulk (36.000)	\$81.36					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (3.48)		\$174.00				
Labor Comments: LOF						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0.00	\$1,987.74	\$2,022.50	\$0	\$0	<u>\$4,010.24</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219982	10/31/2018	11/01/2018	Closed	0.00	

Description: Webasto Tune Up, ETC...

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$22.14	\$11.50		\$0.00	\$33.64

Maintenance Requested: 63445 - 10/29/2018 - bulb issue and cable below dash, see comments

Requestor Notes: Flasher not working, left side, behind front wheel. Cable below dash, left of steering column needs to be secured out of the way.

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Non LED	\$22.14					
Amber Side Marker/Turn MCI EL3: 07-07-1003 (1.000)						
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (0.23)		\$11.50				
Labor Comments: Replaced burnt out marker lamp						
Miscellaneous Labor		\$0				
Other					\$0	
41:A/C & Heating	\$19.26	\$76.00			\$0.00	\$95.26
Pillsbury: Electrode Ignition dw-thermo wabasto: WE14846D (1.000)	\$13.01					
Pillsbury: Disk Photo no pre heat thermo: WE88440A (1.000)	\$6.25					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (1.52)		\$76.00				
Labor Comments: Webasto Tune Up						
Miscellaneous Labor		\$0				
Other					\$0	
79:Lavatory	\$0	\$11.00			\$0.00	\$11.00

Maintenance Requested: 63420 - 10/25/2018 - see comments.

Requestor Notes: The toilet is leaking while being filled in three different spots.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$11.00
 (0.22)

Labor Comments: Tightened up connections for lavatory.
 Checked Fluids.

Miscellaneous Labor \$0
 Other \$0

\$0 \$41.40 \$98.50 \$0 \$0 \$139.90

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220311	11/15/2018	11/19/2018	Closed	0.00	

Description: 2-Way not working

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
51:Communications		\$0	\$13.50		\$0.00	\$13.50

Work Comments: 51 -- 2-Way not working

Miscellaneous Parts \$0
 0081 - WOLF, PATRICK (0.27) \$13.50

Labor Comments: 51 -- 2-Way not working ----- 2-way not getting power. Traced the wires back to a
 fuse. Removed and replaced a blown fuse.

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$13.50 \$0 \$0 \$13.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220604	11/29/2018	12/06/2018	Closed	0.00	

Description: Charging

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$105.00		\$0.00	\$105.00

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$105.00
 (2.10)

Labor Comments: Slow charging the batteries.
 Checked Fluids.
 Cleaned out the CAC and Radiator.

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$105.00 \$0 \$0 \$105.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220814	12/10/2018	12/21/2018	Closed	0.00	

Description: Air drier, Charging

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>

5/7/2019

Work Order Detail

31:Charging		\$0	\$106.00	\$0.00	\$106.00
Work Comments: 31 -- Charging					
Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (2.12)			\$106.00		
Labor Comments: 31 -- Charging ---- Load tested the batteries. Both are good. Was told to check for a battery draw. there is a small battery draw for the sonovia and camera systems. Charged the batteries up good.					
Miscellaneous Labor			\$0		
Other				\$0	
AD:Air Drier Service		\$131.56	\$123.50	\$0.00	\$255.06
Work Comments: AD -- Air drier Service					
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$77.16			
Pillsbury: AD-IP Air Dryer		\$54.40			
Desiccant Cartridge Bendix: 109493BXR (1.000)					
Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (2.47)			\$123.50		
Labor Comments: AD -- Air drier Service ---- Pulled the air drier off. Cleaned it all up. Installed a new purge valve and desc. filter. Mounted back on the bus. Checked for good power and ground at the heater wires.					
Miscellaneous Labor			\$0		
Other				\$0	
		\$0	\$131.56	\$229.50	\$0
				\$0	\$361.06

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,869.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221900	01/29/2019	02/01/2019	Closed	0.00	

Description: take off decal

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$220.00		\$0.00	\$220.00
Miscellaneous Parts		\$0				
1004 - PEREZ, YONI (4.40)			\$220.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$220.00	\$0	\$0	\$220.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 994,316.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222309	02/14/2019	03/01/2019	Closed	0.00	

Description: Write - ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$281.00		\$0.00	\$281.00

Maintenance Requested: 64478 - 02/16/2019 - Back end sits up too high - see comments

Requestor Notes: This driver had this bus on an earlier trip and Darlene Helman had it today. Ron thinks it sits up too high and wonders if the blocks that are put between the axle and the frame were accidentally left on the bus the last time it was serviced. He had trouble with it on his earlier trip. Picture from Ron forwarded to Jacob.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
0081 - WOLF, PATRICK (5.62)	\$281.00

Labor Comments: 21 -- This driver had this bus on an earlier trip and Darlene Helman had it today. Ron

thinks it sits up too high and wonders if the blocks that are put between the axle and the frame were accidentally left on the bus the last time it was serviced. He had trouble with it on his earlier trip. Picture from Ron forwarded to Jacob. ----
Recalibrated the ride height.

Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$38.36	\$31.00	\$0.00	\$69.36

Maintenance Requested: 64473 - 02/16/2019 - Rear air pressure fluctuates. See notes.

Requestor Notes: Another driver on this trip, Ron Lischeid, thought that the back end of the bus was riding too high prior to the fluctuations starting.

Technician Response:

Maint Req Status: Completed

Pillsbury: Hose ASM, Front	\$38.36			
Brakes E-Coach: 04-20-1040				
(1.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.62)		\$31.00		

Labor Comments: 49 -- Another driver on this trip, Ron Lischeid, thought that the back end of the bus was riding too high prior to the fluctuations starting. ---- Checked into the rear air PSI. Found the Gauge reading 15 PSI lower than it really is. Trying to get a new dash. Found the right front brake hose broken. Removed and replaced the hose.

Miscellaneous Labor		\$0		
Other			\$0	
52:Electrical Accessories	\$0	\$44.00	\$0.00	\$44.00

Maintenance Requested: 64376 - 02/08/2019 - See comments

Requestor Notes: 1. Stone chip in windshield, right door side, just right of the video camera.
2. Radio (music) won't turn on.
3. Water rinse/refill on lavatory leaks behind the bullshead fitting (inside).

Technician Response: 75 -- . Stone chip in windshield, right door side, just right of the video camera.

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.88)		\$44.00		

Labor Comments: 75 -- . Stone chip in windshield, right door side, just right of the video camera. ---- Wrote up windshield repair on white board.
52 -- . Radio (music) won't turn on. ---- Removed and replaced the radio with a good used one.
79 -- . Water rinse/refill on lavatory leaks behind the bulkhead fitting (inside). ---- Removed the rear panel. found the leak cut the line back a little and refastened.

Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$159.00	\$0.00	\$159.00

Maintenance Requested: 64305 - 02/06/2019 - radio inop, overhead bin broken, see comments

Requestor Notes: radio not working-can't get lower cd player/radio to turn on
overhead bin at 1 and 2 has a broken hinge

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (3.18)		\$159.00		

Labor Comments: 52 -- radio not working-can't get lower cd player/radio to turn on ---- Removed and replaced the radio with a good used one.
72 -- overhead bin at 1 and 2 has a broken hinge ---- Screwed the hing back together.

Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$108.50	\$0.00	\$108.50

Maintenance Requested: 64481 - 02/16/2019 - See comments.

Requestor Notes: 1. Back of bus is raised too high. See previous maintenance request.
2. First overhead on doorside has a screw missing on one hinge so it doesn't work very well.

Technician Response: 21 -- Back of bus is raised too high. See previous maintenance request. ---- Recalibrated the ride height

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (2.17)		\$108.50		

Labor Comments: 21 -- Back of bus is raised too high. See previous maintenance request. ----

Recalibrated the ride height.
72 -- First overhead on doorside has a screw missing on one hinge so it doesn't
work very well. Reattached the screw.

Miscellaneous Labor					\$0	
Other						\$0
75:Windows/windshields		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 64463 - 02/15/2019 - Washer fluid not coming out and reservoir is full.						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Labor Comments: 75 -- Washer fluid not coming out and reservoir is full. ---- Tied the windshield washers and they worked fine. something must have been frozen.						
Miscellaneous Labor			\$0			
Other						\$0
		\$0	\$38.36	\$623.50	\$0	\$0
						<u>\$661.86</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 994,807.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222782	03/07/2019	03/08/2019	Closed	0.00	

Description: Write-ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$4.00		\$0.00	\$4.00

Maintenance Requested: 64726 - 03/06/2019 - See comments.

Requestor Notes: Entire bus leans badly to the right, all the time. Right turns are okay, but left turns are very uncomfortable.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.08)			\$4.00			
Labor Comments: 21 -- Entire bus leans badly to the right, all the time. Right turns are okay, but left turns are very uncomfortable. ---- Calibrated all three ride heights.						
Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$0	\$292.50		\$0.00	\$292.50
Maintenance Requested: 64727 - 03/06/2019 - Right front cargo door latch broken.						
Requestor Notes:						
Technician Response: 78 -- Right front cargo door latch broken.						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (5.85)			\$292.50			
Labor Comments: 78 -- Right front cargo door latch broken. ---- Removed a good cargo door latch from 523 AND INSTALLED IT ON 527.						
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$0	\$296.50	\$0	\$0
						<u>\$296.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 995,091.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223139	03/19/2019	03/20/2019	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$20.00		\$0.00	\$20.00

5/7/2019

Work Order Detail

Miscellaneous Parts
2138 - KREJCE, LUCAS

\$0 \$20.00

Labor Comments: Help pat with fixing and putting in of the window shade

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$20.00 \$0 \$0 \$20.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 995,091.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223263	03/25/2019	03/27/2019	Closed	0.00	

Description: marker light has water in it

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$79.77	\$0		\$0.00	\$79.77
Pillsbury: Light MCI		\$79.00				
Conversion LED Amber: GG77090 (2.000)						
Pillsbury: Reflector Front		\$0.77				
Amber Gillig: 51-09325-001 (1.000)						
Miscellaneous Parts		\$0				
0142 - GALLINGER, CHAD (0.00)			\$0.00			
Labor Comments: replaced front lower side reflectors and L/R marker light						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$79.77	\$0	\$0	\$0	<u>\$79.77</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 995,225.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223389	03/28/2019	04/01/2019	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CR:Creep		\$0	\$184.00		\$0.00	\$184.00
Miscellaneous Parts		\$0				
2138 - KREJCE, LUCAS			\$184.00			
Labor Comments: Crept with Pat replaced license plate light, cleaned off four shocks, and replaced broken and rusted bolts in loose mud flap.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$184.00	\$0	\$0	<u>\$184.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 995,225.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223453	04/02/2019	04/22/2019	Closed	0.00	

Description: Radiator,belts,batteries

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$381.56	\$123.50		\$0.00	\$505.06
Work Comments: 31 -- Bus keeps needing jump start.						

Pillsbury: Battery 1400CCA Top Post Heavy Duty	\$381.56				
Workaholic: 8D-MHD(7271)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (2.47)		\$123.50			
Labor Comments: 31 -- Bus keeps needing jump start. ---- Removed and replaced both batteries.					
Miscellaneous Labor		\$0			
Other				\$0	
43: Cooling	\$33.10	\$841.00		\$0.00	\$874.10
Work Comments: 43 -- Radiator leaking.					
Pillsbury: Holder cup w/ mounting screws black:	\$3.80				
TH2BLK (2.000)					
Pillsbury: Fluid Coolant Bulk	\$29.30				
50/50 After Dilution: A/F 50/50					
Green BULK (5.000)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK		\$801.00			
Labor Comments: 43 -- Radiator leaking. ---- Pulled the radiator out of 5523 and installed it into 527.					
Ran the engine up to temp and topped off the coolant.					
2138 - KREJCE, LUCAS		\$40.00			
Labor Comments: Help Pat move radiators from one bus to 5527.					
Miscellaneous Labor		\$0			
Other				\$0	
Belt: Belt Replacement	\$94.06	\$119.00		\$0.00	\$213.06
Work Comments: Belt -- Belt replacement					
Pillsbury: Belt EL3:	\$57.10				
08-27-1002 (1.000)					
Pillsbury: Belt, A/C, MCI, E-	\$36.96				
Coach: 08-27-1029 (1.000)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (2.38)		\$119.00			
Labor Comments: Belt -- Belt replacement ---- Removed and replaced the fan belt and the A/C belt.					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$508.72	\$1,083.50	\$0	\$0
					<u>\$1,592.22</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 996,016.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
224023	04/24/2019		Completed	0.00	

Description: list

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38: Audio / Video Surveillance System		\$0	\$104.50		\$0.00	\$104.50

Maintenance Requested: 65190 - 04/19/2019 - See comments.

Requestor Notes: 1. PA/wireless microphone doesn't work along with radio//AUX sound don't work. FM radio has power. it's on/working but REI selector doesn't fully power up.

2. Synovia/ISE system doesn't detect or record mileage (odometer or trip distance), nor engine hours/time. GPS does detect motion so ISE records drivers. Standby v. Off duty/break.

Technician Response:

Maint Req Status: Completed

15.4 inch monitor P/N	\$0.00				
T1588IR (1.000)					
Miscellaneous Parts	\$0				
0142 - GALLINGER, CHAD		\$104.50			
(2.09)					

Labor Comments: checked Synovia and video system every thing was working. checked P/A and radio they are working. Found 4 DVD screens not working replaced driver side center screen and ordered 3 more

Miscellaneous Labor	\$0				
---------------------	-----	--	--	--	--

Other			\$0	
40:Engine		\$0	\$126.00	\$0.00 \$126.00
	Maintenance Requested: 65142 - 04/16/2019 - No Power/smokes alot			
	Requestor Notes:			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts		\$0		
0142 - GALLINGER, CHAD			\$126.00	
(2.52)				
	Labor Comments: test drove ran fine			
Miscellaneous Labor			\$0	
Other				\$0
40:Engine		\$0	\$0	\$0.00 \$0.00
	Maintenance Requested: 65080 - 04/09/2019 - no acceleration power. inop fuel gauge			
	Requestor Notes:			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts		\$0		
0142 - GALLINGER, CHAD			\$0.00	
(0.00)				
	Labor Comments: drove fine dash was replaced			
Miscellaneous Labor			\$0	
Other				\$0
40:Engine		\$0	\$0	\$0.00 \$0.00
	Maintenance Requested: 64693 - 03/04/2019 - runs cold, heater, dvds-see comments			
	Requestor Notes: engine runs cold			
	heater will go off-then aux- the en			
	rear air gauge doesn't work			
	DVD players on bus:			
	Drivers side front and rear do work, the middle dvd has no picture			
	Pass side only the front works, middle screen won't come down			
	rear screen doesn't work			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts		\$0		
0142 - GALLINGER, CHAD			\$0.00	
(0.00)				
	Labor Comments: work done on different task			
Miscellaneous Labor			\$0	
Other				\$0
41:A/C & Heating		\$0	\$0	\$0.00 \$0.00
	Maintenance Requested: 65128 - 04/15/2019 - Heat does not work			
	Requestor Notes: Heat does not work			
	smokes really bad			
	has a hard time going up hill			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts		\$0		
0142 - GALLINGER, CHAD			\$0.00	
(0.00)				
	Labor Comments: wrote up for no heat. Heat valves were closed for the summer			
Miscellaneous Labor			\$0	
Other				\$0
49:Air System		\$0	\$316.00	\$0.00 \$316.00
	Maintenance Requested: 65204 - 04/20/2019 - Rear air tanks aren't building to 130			
	Requestor Notes:			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts		\$0		
0142 - GALLINGER, CHAD			\$316.00	
(6.32)				
	Labor Comments: checked air pressure at supply front and rear tanks all were same pressure checked			
	sending units they were o/k installed used dash from parts room and adjusted air			

governor miles on removed dash 996,018 miles on installed dash 846,389

Miscellaneous Labor		\$0				
Other					\$0	
72:Body Misc		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 65186 - 04/18/2019 - See comments.						
Requestor Notes: 1. PA system doesn't power up. AM/FM radio turns on but cannot select any options, ie: "PA", "AUX", "CD", etc.						
2. Door side front luggage bay door won't open.						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0142 - GALLINGER, CHAD				\$0.00		
(0.00)						
Labor Comments: checked baggage door it will open fine all other write ups all ready repaired						
Miscellaneous Labor		\$0				
Other					\$0	
		\$0	\$0	\$546.50	\$0	\$0
						<u>\$546.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,929.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
224162	04/30/2019	05/06/2019	Closed	0.00	

Description: Door switch broken

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$32.85	\$10.00		\$0.00	\$42.85
Work Comments: 78 -- Door switch broken						
Pillsbury: Switch Rocker Door		\$32.85				
EL3: 07-19-1016 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.20)			\$10.00			
Labor Comments: 78 -- Door switch broken ---- Removed and replaced the inner door switch.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$32.85	\$10.00	\$0	\$0	<u>\$42.85</u>