











































































































































































Work Order Detail

Labor Comments: 31--Removed failed pulley asm; replaced small alt belt with new, set up for Pat to finish when part came in.

0081 - WOLF, PATRICK (1.13)

\$56.50

Labor Comments: 31 -- Attached the rebuilt pully assy. Torqued all bolts to specs. Checked the charging system and HVAC. both good. Filled the fan gear box with gear lube.

Miscellaneous Labor  
Other

\$0

\$0

\$0      \$353.96      \$102.50      \$0      \$0      \$456.46

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,928.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207449	08/09/2016	08/09/2016	Closed	0.00	

Description: Charging

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 10312 - 08/04/2016 - Charging system

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
7050 - STRAND, MATTHEW  
(0.00)

\$0

\$0.00

Labor Comments: Closing Maintenance Request. Was finished on work order 207383

Miscellaneous Labor  
Other

\$0

\$0

\$0      \$0      \$0      \$0      \$0      \$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,928.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207463	08/10/2016	08/11/2016	Closed	0.00	

Description: drivers head light

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$2.69	\$16.50		\$0.00	\$19.19

Work Comments: drivers side low beam head light out.

Pillsbury: Headlight Halogen  
Low Beam: 9006 (1.000)  
Miscellaneous Parts  
6036 - CORNFORTH,  
MICHAEL (0.33)

\$2.69

\$16.50

Labor Comments: replaced drivers side low beam head light.

MC

Miscellaneous Labor  
Other

\$0

\$0

\$0      \$2.69      \$16.50      \$0      \$0      \$19.19

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 608,928.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207480	08/11/2016	08/18/2016	Closed	0.00	

Description: dents on middle side compartment doors

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$890.00		\$0.00	\$890.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (17.80)			\$890.00			
Miscellaneous Labor			\$0			
Other					\$0	
70:Body Sheet Metal		\$650.00	\$0		\$0.00	\$650.00
5522 old door (1.000)		\$650.00				
Part Comments: old door pull paint						
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$650.00	\$890.00	\$0	\$0	<u>\$1,540.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 609,578.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207518	08/15/2016	08/16/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$249.00		\$0.00	\$249.00
Miscellaneous Parts		\$0				
82 - BLANCO, VICTOR (4.98)			\$249.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$249.00	\$0	\$0	<u>\$249.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 609,578.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207520	08/15/2016	08/16/2016	Closed	0.00	

Description: Door Latch, Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 10322 - 08/11/2016 - Driver side headlight out on low beam						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: already repaired						
Miscellaneous Labor			\$0			
Other					\$0	
73:Seats		\$0	\$19.00		\$0.00	\$19.00
Maintenance Requested: 10310 - 08/03/2016 - A sharp piece of plastic is sticking out on panel						
Requestor Notes: Drivers side / 10 seats back aisle seat on the side panel. There is a sharp						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$19.00			
(0.38)						
Labor Comments: fixed seat the screw busted off allowing a sharp piece of meatal to show.						
Miscellaneous Labor			\$0			
Other					\$0	

Work Order Detail

78:Doors Entrance / Exit	\$152.86	\$57.50	\$0.00	\$210.36
03-32-1042 Handle-Sedan	\$104.43			
Door (1.000)				
3G-32-612M138 Knob-Manuel	\$48.43			
Release, Grey (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$57.50		
(1.15)				
Labor Comments: replaced door latch				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$152.86	\$76.50	\$0
			\$0	\$229.36

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 609,578.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207571	08/17/2016	08/17/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$7.77	\$17.50		\$0.00	\$25.27
Pillsbury: Mirror Convex:		\$7.77				
28032 (1.000)						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (0.35)			\$17.50			
Labor Comments: Replace drivers convex mirror						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$7.77	\$17.50	\$0	\$0	\$25.27

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207773	09/01/2016	09/01/2016	Closed	0.00	

Description: FF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
FF:Fuel Filter		\$8.40	\$31.50		\$0.00	\$39.90
Pillsbury: Filter Fuel: 3118		\$4.19				
(1.000)						
Pillsbury: Filter, Fuel, MCI:		\$4.21				
3120 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$31.50			
(0.63)						
Labor Comments: FF Replacement						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$8.40	\$31.50	\$0	\$0	\$39.90

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207892	09/10/2016	09/12/2016	Closed	0.00	

Description: Leaking Hub Cover

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$42.28	\$25.00		\$0.00	\$67.28
Pillsbury: Hub Cap w/ Lube		\$39.16				
Window Steer Axle MCI						
D4500: 343-4176 (1.000)						
Pillsbury: Oil Gear Synthetic:		\$3.12				
Oil Gear 75W-90 BULK in quarts (1.000)						
Part Comments: They need to send a memo out when they change the names of parts. Use to be able to type in gear oil and choose, now it brings you straight to 80w-140.						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.50)			\$25.00			
Labor Comments: Driver came in, showed me the LF steer tires was spitting out fluid. Looked at it and detrimined the hub was proly over heating from heavy use of brakes in the cities. Replaced the hub covera nd filled with oil						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$42.28	\$25.00	\$0	\$0	<u>\$67.28</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207922	09/12/2016	09/12/2016	Closed	0.00	

Description: Coolant Filter

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CFR:Coolant Filter Replacement		\$5.64	\$46.00		\$0.00	\$51.64
Pillsbury: Filter Coolant		\$5.64				
Cummins ISM: 4071 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.92)			\$46.00			
Labor Comments: replaced the coolant filter						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$5.64	\$46.00	\$0	\$0	<u>\$51.64</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 610,404.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207926	09/12/2016	09/13/2016	Closed	0.00	

Description: Tag Hub Leaking

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
27:Wheels, Rims, Hubs & Mounts		\$70.52	\$27.50		\$0.00	\$98.02
Pillsbury: Hub Cap w/ Lube		\$39.16				
Window Steer Axle MCI						
D4500: 343-4176 (1.000)						
Pillsbury: Hub Cap, Stainless Steel: MW1273 (1.000)		\$10.08				
Pillsbury: Light Non LED		\$21.28				
Amber Side Marker/Turn MCI						
EL3: 07-07-1003 (1.000)						
Miscellaneous Parts		\$0				



7050 - STRAND, MATTHEW  
(0.55)

\$27.50

Labor Comments: Right Tag hub was also leaking, they must of been doing heavy braking, replaced it also replaced a side marker lamp assembly

Miscellaneous Labor  
Other

\$0

\$0

\$0.00      \$70.52      \$27.50      \$0      \$0      \$98.02

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,226.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207959	09/14/2016	09/14/2016	Closed	0.00	

Description: R3 bay door latch; R tag tire

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$174.76	\$98.50		\$0.00	\$273.26

Pillsbury: Tire TB Recap Tag:  
315/80R 22.5 TB Recap Tag  
(1.000)

\$174.76

Miscellaneous Parts  
74 - PHIPPS, KEVIN (1.97)

\$0

\$98.50

Labor Comments: Change out R tag tire--out of balance and cupping; mount and balanced new retread; torqued wheel to 475 ft lbs; 100 psi

Miscellaneous Labor  
Other

\$0

\$0

72:Body Misc

\$0

\$42.50

\$0.00

\$42.50

Maintenance Requested: 10418 - 09/14/2016 - 3rd luggage bay doesn't lock open

Requestor Notes: Drivers speakers don't work

Low tire tread on rear tag axel

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
74 - PHIPPS, KEVIN (0.85)

\$0

\$42.50

Labor Comments: R3 bay door missing latch. Body shop did not finish the job. Took parts off 522 and made it work.

Miscellaneous Labor  
Other

\$0

\$0

\$0      \$174.76      \$141.00      \$0      \$0      \$315.76

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,226.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
207980	09/15/2016	09/15/2016	Closed	0.00	

Description: Charging, Mirrors

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$65.00		\$0.00	\$65.00

Miscellaneous Parts  
7050 - STRAND, MATTHEW  
(1.30)

\$0

\$65.00

Labor Comments: Bus came back not charging, Found the feild wire was rotted off, replaced end and hooked up and took for test drive.

Miscellaneous Labor  
Other

\$0

\$0

77:Mirrors

\$0

\$24.00

\$0.00

\$24.00

Miscellaneous Parts  
7050 - STRAND, MATTHEW

\$0

\$24.00

(0.48)

Labor Comments: shined the drivers mirrors up, got rid of some of the oxidation from the well water

Miscellaneous Labor  
Other

\$0  
\$0

\$0      \$0      \$89.00      \$0      \$0      \$89.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,434.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208024	09/19/2016	09/20/2016	Closed	0.00	

Description: La v issues; Hub srvc

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$89.50		\$0.00	\$89.50

Maintenance Requested: 10423 - 09/16/2016 - Coach Restroom Issues

Requestor Notes: Driver reported that the toilet/tank smells even when fresh solution is added to tank.  
When flushing the system it seems to be clogged.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
7050 - STRAND, MATTHEW  
(0.27)      \$0      \$13.50

Labor Comments: was going to get set up on working on this bus, but got pulled off to do DOTs in Burnsville

74 - PHIPPS, KEVIN (1.52)      \$76.00

Labor Comments: Water free flowing OK; exhaust fan not able to blow through noise suppressor--fixed that. Turned fittings to unkink lines for exterior flushing

Miscellaneous Labor      \$0  
Other      \$0

HUB:Hub Service      \$18.00      \$61.50      \$0.00      \$79.50

Pillsbury: Oil Gear 80W-140      \$18.00

Synthetic Mobil Delvac: Gear oil 80W-140 in pints (6.000)

Miscellaneous Parts      \$0  
74 - PHIPPS, KEVIN (1.23)      \$61.50

Labor Comments: Service hubs  
Used 80/140 gear lube

Miscellaneous Labor      \$0  
Other      \$0

\$0      \$18.00      \$151.00      \$0      \$0      \$169.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 611,434.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208048	09/20/2016	09/20/2016	Closed	0.00	

Description: Lighting

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$18.50		\$0.00	\$18.50

Maintenance Requested: 10444 - 09/20/2016 - right running light go's on an off

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts      \$0  
7050 - STRAND, MATTHEW      \$18.50  
(0.37)

Labor Comments: replaced mid rightside marker light bulb 3157

Miscellaneous Labor  
Other

\$0

\$0

\$0      \$0      \$18.50      \$0      \$0      \$18.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 612,380.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208233	09/28/2016	09/28/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
	\$0	\$0	\$0	\$0	\$0	\$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 612,380.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208237	09/28/2016	09/28/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$0		\$0.00	\$0.00

Description: baggage light stays on

Maintenance Requested: 10470 - 09/26/2016 - Baggage door lites stay on when the doors are clos

Requestor Notes: closed and latched

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts      \$0  
7050 - STRAND, MATTHEW      \$0.00  
(0.00)

Labor Comments: Missing the magnetic switch, roobbed one off of the parts bus down below

Miscellaneous Labor      \$0  
Other      \$0

\$0      \$0      \$0      \$0      \$0      \$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 612,380.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208244	09/28/2016	09/29/2016	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$60.00		\$0.00	\$60.00

Description: Roof Leak

Maintenance Requested: 10457 - 09/22/2016 - Multiple water leaks above drivers seat.

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts      \$0  
7050 - STRAND, MATTHEW      \$60.00  
(1.20)

Labor Comments: got on the roof and siliconed possible water leak locations

Miscellaneous Labor      \$0  
Other      \$0

\$0      \$0      \$60.00      \$0      \$0      \$60.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,131.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208324	10/04/2016	10/06/2016	Closed	0.00	

Description: Cradle bolt; sm alt

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Missing cradle bolt-road side rear		\$0	\$342.50		\$0.00	\$342.50
Maintenance Requested: 10511 - 10/03/2016 - Missing cradle bolt-road side rear						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
34 SI 24v 90amp reman from Schelen (1.000)		\$0.00				
Part Comments: Only one on shelf at this time						
Miscellaneous Parts		\$0				
74 - PHIPPS, KEVIN (6.15)			\$307.50			
Labor Comments: Remove broken cradle bolt, siezed in tube; remove 34SI alt and brackets--badly worn--found good used lower bracket and reman alt to install						
0146 - SHIPPY, CURTIS (0.70)			\$35.00			
Labor Comments: Cut and weld new bolt tube into frame						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$342.50	\$0	\$0	<u>\$342.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,132.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208374	10/06/2016	10/10/2016	Closed	0.00	

Description: LOF, Webasto Tune Up

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$30.72	\$226.50		\$0.00	\$257.22
Pillsbury: Nozzle (0.65 GPH		\$17.97				
80H)wabasto: WE470716 (1.000)						
Pillsbury: Electrode Ignition dw-thermo wabasto: WE14846D (1.000)		\$12.75				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (4.53)			\$226.50			
Labor Comments: tuned up the webasto. Broke a bolt, had to extract it and then heli coil it. couldnt get the webasto program to hook up. finally go it hooked up. Got it out of interlock and fixed fault. Ran the heater.						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$104.90	\$155.00		\$0.00	\$259.90
Pillsbury: Oil Bulk in Quarts: Oil 15W-40 Bulk (38.000)		\$79.80				
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)		\$15.10				
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)		\$10.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.10)			\$155.00			

Work Order Detail

Miscellaneous Labor	Labor Comments: serviced the bus		\$0				
Other						\$0	
PMI:Preventative Maintenance Inspection			\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts			\$0				
7050 - STRAND, MATTHEW (0.00)				\$0.00			
	Labor Comments: Service						
Miscellaneous Labor				\$0			
Other						\$0	
			\$0	\$135.62	\$381.50	\$0	\$0
							<u>\$517.12</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,892.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
208995	11/17/2016	11/18/2016	Closed	0.00	

Description: Battery Draw

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$141.50		\$0.00	\$141.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.83)			\$141.50			
	Labor Comments: searching for a draw, found a baggage bay light that was not turning off.					
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$0	\$141.50	\$0	\$0
						<u>\$141.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 613,892.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209022	11/18/2016	11/25/2016	Closed	0.00	

Description: moved seats so tables could be installed for customer.

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
73:Seats		\$0	\$38.50		\$0.00	\$38.50
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.77)			\$38.50			
	Labor Comments: moved seats so tables could be installed for customer.					
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$0	\$38.50	\$0	\$0
						<u>\$38.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 831,828.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209154	12/01/2016	12/02/2016	Closed	0.00	

Description: Air Gauges

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$750.00	\$159.00		\$0.00	\$909.00
	Maintenance Requested: 10727 - 11/23/2016 - Air Guages read low					
	Requestor Notes:					
	Technician Response:					
	Maint Req Status: Completed					

Work Order Detail

Pillsbury: IP instrument \$750.00  
 cluster: 07-08-119 (1.000)  
 Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$159.00  
 (3.18)

Labor Comments: dash gauges were not reading correct, switched out dash and bumped up the air governor to 115 psi. Also fixed a couple loose rivets

Miscellaneous Labor \$0  
 Other \$0

\$0 \$750.00 \$159.00 \$0 \$0 \$909.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245 License Plate:

Miles: 832,058.0

Location: PBG Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209324	12/12/2016	12/12/2016	Closed	0.00	

Description: Radio

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 10765 - 12/08/2016 - See notes

Requestor Notes: Driver didn't set Parking Brake. Bus rolled into parked school bus. Dent in front bumper on driver side. Kathryn has been notified.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$0.00  
 (0.00)

Labor Comments: this doesnt need to be a write up, notify the bodyshop

Miscellaneous Labor \$0  
 Other \$0

Radio/DVD/PA:Radio repair \$0 \$6.00 \$0.00 \$6.00

Maintenance Requested: 10801 - 12/12/2016 - Advanced REI Head Unit above Stero does not power

Requestor Notes: Advanced REI Head Unit above Stero does not power up

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$6.00  
 (0.12)

Labor Comments: unit does power up

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$6.00 \$0 \$0 \$6.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245 License Plate:

Miles: 832,149.0

Location: PBG Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209694	01/11/2017	01/17/2017	Closed	0.00	

Description: Air Drier, Low Air Buzzer

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
37:Warning, Strobe, 8-Ways		\$0	\$95.00		\$0.00	\$95.00

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$95.00  
 (1.90)

Labor Comments: the low air buzzer was not working. I messed with some wiring and unplugged and plugged somethings in and it started to work. I ordered one for stock incase this one does go out again

Work Order Detail

Miscellaneous Labor		\$0				
Other					\$0	
AD:Air Drier Service	\$119.70	\$126.50		\$0.00		\$246.20
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)	\$66.72					
Pillsbury: AD-IP Air Dryer Desiccant Cartridge Bendix: 109493BXR (1.000)	\$52.98					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (2.53)		\$126.50				
Labor Comments: jump started 2 buses rebuilt the air drier. checked brake stroke						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$119.70	\$221.50	\$0	\$0	<u>\$341.20</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 832,422.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
209811	01/19/2017	01/20/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield Repair, Inv. # 2785612					\$35.00	\$35.00
77:Mirrors		\$0	\$41.50		\$0.00	\$41.50
Miscellaneous Parts		\$0				
9127 - JACOBS, ANDREW (0.83)			\$41.50			

Labor Comments: found both mirror arms loose readjust with driver to where needs to be tighten all bolts for the arms down

Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$41.50	\$0	\$35.00	<u>\$76.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 836,073.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
210689	03/24/2017	03/24/2017	Closed	0.00	

Description: RV A/F

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$160.34	\$0		\$0.00	\$160.34
Pillsbury: Fluid Antifreeze RV: A/F RV BULK (31.500)		\$160.34				

Part Comments: Added over winter for bathroom charge filled by wash stall. JS.

Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$160.34	\$0	\$0	\$0	<u>\$160.34</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 837,323.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign # Date: WO # Open Date Close Date Status Downtime Accident

210892 04/07/2017 04/20/2017 Closed 0.00

Description: PMI, List

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

13:Brakes		\$824.95	\$302.50		\$0.00	\$1,127.45
Pillsbury: Brake Chamber, Tag, LH EL3: MJS1724ET057 (1.000)						
		\$282.75				
Pillsbury: Pads brake EL3: 04-01-1019 (1.000)						
		\$243.75				
Pillsbury: Brake Chamber, Tag RH, EL3: T04-1246 (1.000)						
		\$298.45				
Miscellaneous Parts						
		\$0				
7050 - STRAND, MATTHEW (6.05)						
			\$302.50			

Labor Comments: Front brake pads

found were the air was back feeding into the system. thru the tags parking brake replaced both tag brake chambers installed new head lights

Miscellaneous Labor			\$0			
Other					\$0	

25:Transmission (Auto)		\$184.88	\$0		\$0.00	\$184.88
Pillsbury: Speedi-Sleeve Allison B500 Output: 99473 (1.000)						
		\$126.24				
Pillsbury: Seal Rear Transmission Output Allison B500: 29552705 (1.000)						
		\$58.64				
Miscellaneous Parts						
		\$0				
7050 - STRAND, MATTHEW (0.00)						
			\$0.00			

Labor Comments: transmission seal leaking, replaced seal and speedy sleeve

Time is combined with brakes, did not punch over

Miscellaneous Labor			\$0			
Other					\$0	

35:Instrument & Gauges		\$0	\$114.00		\$0.00	\$114.00
Maintenance Requested: 11223 - 03/18/2017 - bright light indicator light not working						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts						
		\$0				
7050 - STRAND, MATTHEW (2.28)						
			\$114.00			

Labor Comments: no high beam indicator lamp. found the piano module it bad, have a used one that one is bad for other reasons. sending that one to 3g to be rebuilt

Miscellaneous Labor			\$0			
Other					\$0	

35:Instrument & Gauges		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11103 - 02/23/2017 - highbeam indicator on dash inop.						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)						
			\$0.00			
Miscellaneous Labor						
			\$0			
Other					\$0	

36:Lighting		\$158.95	\$26.00		\$0.00	\$184.95
Pillsbury: Light Amber Marker, EL3: 07-07-1012 (1.000)						
		\$46.14				
Pillsbury: Light Bulb 12 Volt Mini Fog/Driving: BP1255/H3 (1.000)						
		\$6.39				



## Work Order Detail

Pillsbury: Fog Lamp RH, Dual Halagon, EL3: 07-07-1026 (see note) (1.000)	\$106.42			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.52)		\$26.00		
Labor Comments: fog lamp out and right side marker lamp not blinking on hazards				
Miscellaneous Labor		\$0		
Other			\$0	
43:Cooling	\$21.98	\$12.50	\$0.00	\$34.48
Pillsbury: Gauge Sight MCI Surge Tank: 6R-14-60 (1.000)	\$21.98			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.25)		\$12.50		
Labor Comments: replaced coolant sight glass tightened up a couple coldwater leaks				
Miscellaneous Labor		\$0		
Other			\$0	
48:Fuel System	\$0	\$319.00	\$0.00	\$319.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (6.38)		\$319.00		
Labor Comments: fuel tank was overfilled and leaked out underneath the matting for the floor in the 3rd bag bay. Had to take out mat, clean the bay and then scrap the molding off. Reinstalled mat and riveted and screwed down and silicone to preven thsi again. Also cleaned the tank up and tightened some clamps. powerwashed underside of the tank				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$187.88	\$150.00	\$0.00	\$337.88
Pillsbury: Latch Front bumper: 03-21-1046 (1.000)	\$19.73			
Pillsbury: Bracket Striker: 03-21-1080 (1.000)	\$148.41			
03-21-1042 Cable-Release, Bumper (1.000)	\$19.74			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (3.00)		\$150.00		
Labor Comments: Front bumper needed new latch and latch assembly also needs new cable that is ordered put new step tread on the steps replaced screws in body that were rusted out				
Miscellaneous Labor		\$0		
Other			\$0	
79:Lavatory	\$383.04	\$33.50	\$0.00	\$416.54
Pillsbury: Kit, Lav Retro Fit: T17-1107A (1.000)	\$383.04			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.67)		\$33.50		
Labor Comments: installed new lavatory dump valve kit				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$0	\$160.50	\$0.00	\$160.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (3.21)		\$160.50		
Labor Comments: PMI				
Miscellaneous Labor		\$0		
Other			\$0	
RT:Road Test	\$0	\$26.00	\$0.00	\$26.00
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$26.00		

(0.52)

Labor Comments: road test

Miscellaneous Labor		\$0				
Other					\$0	
SC: Steam Clean	\$0	\$27.50		\$0.00		\$27.50
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW		\$27.50				

(0.55)

Labor Comments: steam clean

Miscellaneous Labor		\$0				
Other					\$0	
	\$0.00	\$1,761.68	\$1,171.50	\$0	\$0	<u>\$2,933.18</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 837,737.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211152	04/26/2017	05/02/2017	Closed	0.00	

Description: A/C: pre System for Summer

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
A/C: Prep		\$1,345.04	\$425.50		\$0.00	\$1,770.54

Work Comments: A/C: pre System for Summer

Pillsbury: Headlight, LED, MCI: 9705K (1.000)	\$77.14					
Pillsbury: Headlight, LED, MCI: 9706K (1.000)	\$77.14					
Pillsbury: Water Valve repair kit, EL3: 16-06-1025 (2.000)	\$427.76					
Pillsbury: A/C control module (1.000)	\$763.00					
Miscellaneous Parts 0081 - WOLF, PATRICK (8.51)	\$0		\$425.50			

Labor Comments: A/C: pre System for Summer ----- Pulled the panels off. removed the motor brush caps and checked all brushes on the condensor and evap. motors. All ok. Rebuilt the left heat valve. Blew the brush dust out of the motors. washed out all the dirt from the condensor, radiator and the CAC. Put everything back together.

Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$1,345.04	\$425.50	\$0	\$0	<u>\$1,770.54</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,010.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211302	05/05/2017	05/08/2017	Closed	0.00	

Description: Bay Lamp

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78: Doors Entrance / Exit		\$1.16	\$0		\$0.00	\$1.16

Maintenance Requested: 11374 - 05/05/2017 - Baggage Doors light is on dash

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Bulb 24V Above Stepwell MCI D4500: 1203 (1.000)	\$1.16					
Miscellaneous Parts 7050 - STRAND, MATTHEW	\$0		\$0.00			

(0.00)

Labor Comments: baggage light on dash, sensor was missing. Siliconed a used one in

Miscellaneous Labor \$0  
 Other \$0

\$0 \$1.16 \$0 \$0 \$0 \$1.16

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,010.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211330	05/08/2017	05/10/2017	Closed	0.00	

Description: Chip In Windsheild

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield Repair, Inv. # 2785770					\$40.00	\$40.00
75:Windows/windshields		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 11380 - 05/06/2017 - Chip in windshield left side

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$0.00  
 (0.00)

Labor Comments: put on board for mike the glass guy to look at

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$0 \$0 \$40.00 \$40.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,010.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211477	05/17/2017	05/23/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Rear outside dual tire looks a little low.		\$0	\$48.50		\$0.00	\$48.50

Maintenance Requested: 11412 - 05/17/2017 - Rear outside dual tire looks a little low.

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 9127 - JACOBS, ANDREW \$28.50  
 (0.57)

Labor Comments: found tire pressure low handed off to allen

9128 - DIAZ, ALLEN (0.40) \$20.00

Labor Comments: tightened up the valve stem

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$48.50 \$0 \$0 \$48.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 838,845.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211547	05/24/2017	05/26/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$64.00		\$0.00	\$64.00
Maintenance Requested: 11418 - 05/20/2017 - Driver States that there is an oil per DOT Inspec						
Requestor Notes: 1) Driver States that there is an oil per DOT Inspection						
2) Driver states that the brakes Squeel						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$64.00			
(1.28)						
Labor Comments: no oil leaks that are dripping. Multiple slow oil leaks like front and rear main seals, Cam Seal, Trans Bell housing seal. Steam cleaned the engine.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$64.00	\$0	\$0	<u>\$64.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 839,139.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211650	06/01/2017	06/02/2017	Closed	0.00	

Description: Window Latches, Buzzer

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
37:Warning, Strobe, 8-Ways		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11436 - 05/26/2017 - low air pressure warning buzzer inop						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: intermittent problem, will look into it						
Miscellaneous Labor			\$0			
Other					\$0	
75:Windows/windshields		\$0	\$17.50		\$0.00	\$17.50
Maintenance Requested: 11443 - 05/31/2017 - 5 windows will not lock						
Requestor Notes: 1st 3 on right/ 2nd 2 on drivers side						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$17.50			
(0.35)						
Labor Comments: They were not shut properly when opened by the DOT for its random inspection						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$17.50	\$0	\$0	<u>\$17.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 839,139.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211688	06/05/2017	06/06/2017	Closed	0.00	

Description: Tag Tire

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$353.68	\$83.50		\$0.00	\$437.18
Maintenance Requested: 11452 - 06/03/2017 - Right Rear Tag tire looks low check PSI						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Hub Cap, Stainless		\$10.08				
Steel: MW1273 (1.000)						
9705K LED Headlight (1.000)		\$84.42				
9706K LED Headlight (1.000)		\$84.42				
Pillsbury: Tire TB Recap Drive: 315/80R 22.5 TB Recap Drive (1.000)		\$174.76				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.67)			\$83.50			
Labor Comments: tag tire had a nail in it. replaced it						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$353.68	\$83.50	\$0	\$0	\$437.18

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 839,685.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211755	06/08/2017	06/14/2017	Closed	0.00	

Description: Air Filter, FF, A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$387.75	\$252.50		\$0.00	\$640.25
Pillsbury: Valve, Electric		\$111.13				
Unloader: 10610656 (1.000)						
Pillsbury: Coil Unloader, 24 volt: 16-02-1020 (1.000)		\$72.84				
03-29-1612 Cable Assy (1.000)		\$40.32				
Pillsbury: Spring-large baggage door: 03-29-1170 (1.000)		\$23.31				
Pillsbury: Plate Assembly, 05G Compressor: 16G-2-64 (1.000)		\$140.15				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (5.05)			\$252.50			
Labor Comments: While running the a/c, I could hear a leak a the compressor. Couldnt find it but could hear it, when I put my hand on the unloader. Shut off the kings valve sucked down the compressor and changed the unloader and solenoid Fill compressor back up and ran system. Still internal leaking. Shut of kings valves and sucked down the compressor, Pulled the head valve off, found parts bad. Replaced them ran system, no internal leaking.						
Miscellaneous Labor			\$0			
Other					\$0	
AF:Air Filter Replacement		\$42.21	\$41.00		\$0.00	\$83.21
Pillsbury: Filter Air: 6741 (1.000)		\$42.21				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.82)			\$41.00			
Labor Comments: replaced air filter						

replaced FF  
checked oils  
ran A/C

Miscellaneous Labor		\$0					
Other					\$0		
FF:Fuel Filter		\$8.53	\$0		\$0.00		\$8.53
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)		\$4.34					
Pillsbury: Filter Fuel: 3118 (1.000)		\$4.19					
Miscellaneous Parts		\$0					
7050 - STRAND, MATTHEW (0.00)			\$0.00				
Labor Comments: replaced FF							
Miscellaneous Labor							
Other					\$0		
		\$0	\$438.49	\$293.50	\$0	\$0	<u>\$731.99</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 840,513.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211878	06/20/2017	06/20/2017	Closed	0.00	

Description: Fast Idle, Latch

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$51.50		\$0.00	\$51.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.03)			\$51.50			

Labor Comments: Driver said everytime they put the bus in high idle it shut down. Pulled bus in and could not duplicate problem, Bus needed to go out.  
Found the front latch on the front bumper not holding, tired to readjust, needs new striker

Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$0	\$51.50	\$0	<u>\$51.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 840,513.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211888	06/20/2017	06/21/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
PM:Preventative Maintenance		\$0	\$50.00		\$0.00	\$50.00
Miscellaneous Parts		\$0				
9128 - DIAZ, ALLEN (1.00)			\$50.00			

Labor Comments: sewer pipe was leaking from clap

Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$0	\$50.00	\$0	<u>\$50.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 840,979.0

Location: PBG

Department: PBG5-Charter

<u>WO #</u>	<u>Open Date</u>	Recall:	<u>Close Date</u>	Campaign #	<u>Status</u>	<u>Downtime</u>	Date:	<u>Accident</u>
211934	06/24/2017		06/27/2017		Closed	0.00		

Description: check bus

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$16.50		\$0.00	\$16.50
Miscellaneous Parts		\$0				
9127 - JACOBS, ANDREW (0.33)			\$16.50			
Labor Comments: check engine oil level						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$16.50	\$0	\$0	<u>\$16.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 841,570.0

Location: PBG

Department: PBG5-Charter

<u>WO #</u>	<u>Open Date</u>	Recall:	<u>Close Date</u>	Campaign #	<u>Status</u>	<u>Downtime</u>	Date:	<u>Accident</u>
211992	06/29/2017		07/05/2017		Closed	0.00		

Description: LOF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$675.47	\$80.00		\$0.00	\$755.47
Pillsbury: Tensioner, Detroit: 23533015 (1.000)		\$200.47				
RO32715 ACC. Drive (1.000)		\$475.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.60)			\$80.00			
Labor Comments: Tensioner and Accesory Drive pulley were bad, Replaced both						
Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$10.67	\$37.50		\$0.00	\$48.17
Pillsbury: Stricker - Front		\$10.67				
Bumper: 03-21-1047 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.75)			\$37.50			
Labor Comments: Front bumper striker was shot, replaced it and adjusted it						
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$110.29	\$240.00		\$0.00	\$350.29
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)		\$15.56				
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)		\$10.00				
Pillsbury: Oil Bulk in Quarts: Oil 15W-40 Bulk (37.000)		\$84.73				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (4.80)			\$240.00			
Labor Comments: Serviced the Bus, Had a really hard time geting the bus to level out to lift, found leaking valve, tightened it Took on Road Test						
Miscellaneous Labor			\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			

Miscellaneous Labor	Labor Comments: Serviced the Bus	\$0					
Other						\$0	
		\$0	\$796.43	\$357.50	\$0	\$0	<u>\$1,153.93</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 841,806.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212069	07/08/2017	07/10/2017	Closed	0.00	

Description: dvd

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$19.00		\$0.00	\$19.00
Miscellaneous Parts		\$0				
9127 - JACOBS, ANDREW			\$19.00			
(0.38)						
Labor Comments: tape up right rear tv screen the clip is broken to hold it up right						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$19.00	\$0	\$0	<u>\$19.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 841,806.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212097	07/11/2017	07/19/2017	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
30:Electrical		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11568 - 07/11/2017 - turn signal indicator on the dash not working						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Labor Comments: worked just fine.						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$0	\$46.50		\$0.00	\$46.50
Maintenance Requested: 11569 - 07/11/2017 - Monitor in the back of the bus will not stay up						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Used Monitor (1.000)		\$0.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$46.50			
(0.93)						
Labor Comments: repalced the broken monitor						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 11560 - 07/07/2017 - rear tv screen door side hinges down						
Requestor Notes: passenger air temp can't be controlled - it's extremely cold or extremely cold not mater if temp is set at 60 or 80						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				



Work Order Detail

7050 - STRAND, MATTHEW	\$0.00					
(0.00)						
Miscellaneous Labor	\$0					
Other						\$0
	\$0	\$0	\$46.50	\$0	\$0	<u>\$46.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,262.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212235	07/20/2017	07/25/2017	Closed	0.00	

Description: DOT,sc,air leak

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$0	\$119.50		\$0.00	\$119.50
Work Comments: 13 -- Air leak at right front brake chamber line.						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (2.39)			\$119.50			
Labor Comments: 13 -- Air leak at right front brake chamber line. ---- Pull the end off. cut the line back and reinstalled the end.						
Miscellaneous Labor			\$0			
Other					\$0	
DO:DOT Inspection		\$0	\$160.00		\$0.00	\$160.00
Work Comments: DOT -- DOT Inspection..						
DOT Sticker @ \$2.00		\$0.00				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (3.20)			\$160.00			
Labor Comments: DOT -- DOT Inspection.. ---- Performed the Dot Inspection as per MN DOT Handbook.						
Miscellaneous Labor			\$0			
Other					\$0	
SC:Steam Clean		\$0	\$83.50		\$0.00	\$83.50
Work Comments: SC -- Steam clean ----						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.67)			\$83.50			
Labor Comments: SC -- Steam clean ---- Steam cleaned the bottom of the bus.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$363.00	\$0	\$0	<u>\$363.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,370.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212265	07/24/2017	07/25/2017	Closed	0.00	

Description: Air System

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$0	\$16.50		\$0.00	\$16.50
Maintenance Requested: 11604 - 07/22/2017 - air break leak. brakes squeak. chips in windshield						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$16.50			
(0.33)						
Labor Comments: When kneeling the bus the air hose would hit the dump valve and release air. Wrote up the windshield cracks for the windshield dude.						
Miscellaneous Labor			\$0			

Other \$0

\$0 \$0 \$16.50 \$0 \$0 \$16.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,786.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212309	07/26/2017	07/26/2017	Closed	0.00	

Description: Repair from 7-19-17 incident

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$294.00	\$451.75		\$0.00	\$745.75
replace three skirt panels (3.000)		\$294.00				
Miscellaneous Parts		\$0				
technician (6.95)			\$451.75			
Labor Comments: paint rub rails						
Miscellaneous Labor			\$0			
Other					\$0	
	\$451.75	\$294.00	\$451.75	\$0	\$0	\$745.75

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,971.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212324	07/27/2017	08/07/2017	Closed	0.00	

Description: A/C, Microphone, air leak, lights

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$26.00		\$0.00	\$26.00
Work Comments: 36 -- Right side front turn lamp out.						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.52)			\$26.00			
Labor Comments: 36 -- Right side front turn lamp out. ---- Removed and replaced the bulb ( 3157 bulb )						
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$198.22	\$938.50		\$0.00	\$1,136.72
Work Comments: 41 -- A/C not working						
16-04-1031 Coil (1.000)		\$93.32				
Pillsbury: Transducer		\$65.95				
Pressure MCI D4500:						
16-02-1012 (1.000)						
Pillsbury: Filter Dryer EL3:		\$38.95				
16-04-1004 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK			\$938.50			
Labor Comments: 41 -- A/C not working ---- Trouble shoot NO A/C issue. system keeps shutting down because of low pressure on the suction side of the system. Changed out the pressure transducer on the low side. Found that the liquid solenoid valve wasn't working. The coil was shorted out. Ordered and installed a new coil. topped off the						
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$133.50		\$0.00	\$133.50
Maintenance Requested: 11616 - 07/26/2017 - Bus leaking air when kneeling bus on or off						
Requestor Notes: Bus isn't signaling that air is low at 60psi						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				

Work Order Detail

0081 - WOLF, PATRICK (2.67)

\$133.50

Labor Comments: 49 -- Leaking air when kneeling thr bus. ---- The right front brake line is catching on the air tank bleeder. Turned the brake line so it wouldn't catch.

Miscellaneous Labor  
Other

\$0  
\$0

Radio/DVD/PA:Radio repair

\$0 \$0 \$0.00 \$0.00

Maintenance Requested: 11624 - 07/26/2017 - microphone not working. A/C not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
0081 - WOLF, PATRICK (0.00)

\$0  
\$0.00

Labor Comments: PA -- microphone notworking. ---- Works fine for me. Maybe someone should train the drivers.  
A/C not working is below in 41

Miscellaneous Labor  
Other

\$0  
\$0

\$0 \$198.22 \$1,098.00 \$0 \$0 \$1,296.22

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,971.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212509	08/07/2017	08/07/2017	Closed	0.00	

Description: Bathroom Lock

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$16.00		\$0.00	\$16.00

Maintenance Requested: 11705 - 08/05/2017 - bathroom door won't lock-no light inside

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
7050 - STRAND, MATTHEW  
(0.32)

\$0  
\$16.00

Labor Comments: fixed the bathroom lock door jam

Miscellaneous Labor  
Other

\$0  
\$0

\$0 \$0 \$16.00 \$0 \$0 \$16.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 843,971.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212515	08/07/2017	08/07/2017	Closed	0.00	

Description: Radio/PA

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$91.00		\$0.00	\$91.00

USED AMP For MCI (1.000)

\$0.00

Miscellaneous Parts  
7050 - STRAND, MATTHEW  
(1.82)

\$0  
\$91.00

Labor Comments: Found the Amp was not powering up. Replaced with a used one.

Miscellaneous Labor  
Other

\$0  
\$0

\$0 \$0 \$91.00 \$0 \$0 \$91.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 845,135.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212766	08/21/2017	09/05/2017	Closed	0.00	

Description: High beam indicator not working

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
33:Horn & Alarm		\$0	\$436.50		\$0.00	\$436.50

Work Comments: 33 -- Beepers keep going off, no Idiot lights light up.

Miscellaneous Parts  
0081 - WOLF, PATRICK (8.73)

\$0  
\$436.50

Labor Comments: 33 -- Beepers keep going off, no Idiot lights light up. ---- Worked with the tech. at 3-G trying to figure out what the problem is from . Switched out seven of the nine moduals in the bus. Still no diffarence. Had to leave the Piano modual that keeps the beepers on, so the high beam indicator light works. Sent the old piano modual in to 3-G for repairs. Waiting on new parts.

Miscellaneous Labor  
Other

\$0  
\$0

36:Lighting		\$0	\$166.00		\$0.00	\$166.00
-------------	--	-----	----------	--	--------	----------

Work Comments: 36 -- High beam indicator not working

Used piano modual from C&J  
(1.000)

\$0.00

Miscellaneous Parts  
0081 - WOLF, PATRICK (3.32)

\$0  
\$166.00

Labor Comments: 36 -- High beam indicator not working ---- Removed and replaced the piono modual .

Miscellaneous Labor  
Other

\$0  
\$0

CFR:Coolant Filter Replacement		\$5.64	\$18.50		\$0.00	\$24.14
--------------------------------	--	--------	---------	--	--------	---------

Work Comments: CFR -- Coolant filter replacement

Pillsbury: Filter Coolant  
Cummins ISM: 4071 (1.000)

\$5.64

Miscellaneous Parts  
0081 - WOLF, PATRICK (0.37)

\$0  
\$18.50

Labor Comments: CFR -- Coolant filter replacement ---- Removed and replaced the coolant filter.

Miscellaneous Labor  
Other

\$0  
\$0

Radio/DVD/PA:Radio repair		\$0	\$155.00		\$0.00	\$155.00
---------------------------	--	-----	----------	--	--------	----------

Maintenance Requested: 11733 - 08/08/2017 - Remote mic not working

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
0081 - WOLF, PATRICK (3.10)

\$0  
\$155.00

Labor Comments: Radio repair -- Remote mic not working ---- Charged up the mic. the mic. still will not turn. We need to send it in for repairs or buy a new one.

Miscellaneous Labor  
Other

\$0  
\$0

	\$0	\$5.64	\$776.00	\$0	\$0	\$781.64
--	-----	--------	----------	-----	-----	----------

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 845,327.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212921	08/30/2017	09/06/2017	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$122.58	\$90.00		\$0.00	\$212.58

Maintenance Requested: 11942 - 08/29/2017 - see comments  
 Requestor Notes: Outside white L & R turn lights not working  
 Coolant was low  
 window is loose at seat 31  
 Amber round light outside the door is out

Technician Response:

Maint Req Status: Completed

Pillsbury: Cornering Light, \$122.58  
 LED, MCI: 07-07-1476 (1.000)  
 Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$90.00  
 (1.80)

Labor Comments: replaced a bunch of lights and got some kneeling lights ordered

Miscellaneous Labor \$0  
 Other \$0  
 Radio/DVD/PA:Radio repair \$0 \$41.50 \$0.00 \$41.50  
 Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$41.50  
 (0.83)

Labor Comments: ordered parts to fix the wireless microphone.

Miscellaneous Labor \$0  
 Other \$0

\$0.00 \$122.58 \$131.50 \$0 \$0 \$254.08

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 845,327.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212997	09/05/2017	09/06/2017	Closed	0.00	

Description: Lav Handle, Engine Temp

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
35:Instrument & Gauges		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 11984 - 09/02/2017 - Engine temp gauge not working right.  
 Requestor Notes: Engine temp gauge not working right. Run in red. Water ok, belt ok, functioning ok-  
 shop on Sat said ok to run.

Nut for dump handle missing for restroom dump

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$0.00  
 (0.00)

Labor Comments: its not overheating, the gauge is 10-20 degrees over the actual engine temp.  
 Will see what Jacob wants to do.

Miscellaneous Labor \$0  
 Other \$0  
 79:Lavatory \$0 \$0 \$0.00 \$0.00

Maintenance Requested: 11982 - 09/02/2017 - red handle to dump valve is lose  
 Requestor Notes: red handle to dump valve is lose. Found laying in compartment when I dumped.  
 Needs tightening

Also needs water in toilet-no bucket, looked for bucket. Couldn't find. No one in  
 cleaning area to Fri at 3pm. Can't reach the water valve-someone please fill.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$0.00  
 (0.00)

Labor Comments: put the handle and new nut on

Miscellaneous Labor \$0

Other

\$0

\$0      \$0      \$0      \$0      \$0      \$0      \$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213225	09/18/2017	09/22/2017	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$850.00	\$85.00		\$0.00	\$935.00

Maintenance Requested: 60230 - 09/16/2017 - bus shut off while driving residential street and

Requestor Notes: 1) Tag driver side needs to be looked at. Inside tread is wearing and feels like blots are starting to come through

2) Side marker line passenger (this is hard to make out the handwriting, so I'm guessing here) in front lost-Mechanic changed out light and 1 side is loose....?

3) Bus turned itself of while carrying passengers down street.

4) Water temp gauge is running very high-might want to take a look

Technician Response:

Maint Req Status: Completed

07-08-119 engine cluster (1.000)		\$850.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.70)			\$85.00			

Labor Comments: Fixed the light I think they were talking about.

Checked the codes, one for low coolant and that would have shut the bus down.

Someone must have filled it back up.

Tag tires are perfect.

Replaced the Cluster, so the coolant read the right temp

Miscellaneous Labor			\$0			
Other					\$0	

\$0      \$850.00      \$85.00      \$0      \$0      \$935.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213302	09/21/2017	09/22/2017	Closed	0.00	

Description: Coolant Sensor, Engine Kill Switch

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
quit running while en route		\$109.47	\$157.50		\$0.00	\$266.97

Maintenance Requested: 60276 - 09/20/2017 - quit running while en route

Requestor Notes: bus engine quit running on 94 at 694. NOT FUN sat a minute and restarted.

\*\*This happened last weekend as well, when Tom Gillen drove it for a TCHT\*\*Rachel

Transmission clunks and jerks bus frequently when you take foot of gas pedal

Technician Response:

Maint Req Status: Completed

Pillsbury: Sensor Coolant		\$29.12				
Engine Shut-Down MCI D4500 w/ Detroit Series 60: 7L-8-1124 (1.000)						
Pillsbury: Sensor Coolant		\$61.04				
Surge Tank: 07-08-1119 (1.000)						

5/7/2019

Work Order Detail

Pillsbury: Fluid DELO \$16.00  
 Antifreeze ELC BULK: A/F  
 Chevron DELO 50/50 BULK (2.000)  
 Pillsbury: Connector, \$3.31  
 ThermoKing: 445835 (1.000)  
 Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$157.50  
 (3.15)

Labor Comments: Code for coolant level keeps popping up, changed the coolant sensors. Stripped out the one, so I had fun fixing that.

Engine kill switch in the battery box had loose connections. tightened them up

Miscellaneous Labor \$0  
 Other \$0

\$0 \$109.47 \$157.50 \$0 \$0 \$266.97

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213341	09/25/2017	09/25/2017	Closed	0.00	

Description: Already Fixed??

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 60303 - 09/23/2017 - bus shuts off when en route-multiple times

Requestor Notes: Bus STOPPED RUNNING TWICE on the road doing the city tour

Pipes leak toilet water (in the dump door)

Bus needs a new microphone0the mic doesn't always pick up the guides voice and also comes disconnected

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$0.00  
 (0.00)

Labor Comments: Old request already fixed.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$0 \$0 \$0 \$0.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,389.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213480	10/03/2017	10/04/2017	Closed	0.00	

Description: Engine Sensors, Wireless Microphone

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$25.00		\$0.00	\$25.00

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$25.00  
 (0.50)

Labor Comments: Bus would not start, Code for SRS and TRS Sensors, Got it started and into the garage.

Miscellaneous Labor \$0  
 Other \$0

40:Engine \$116.34 \$125.00 \$0.00 \$241.34  
 Pillsbury: Sensor Assy (trs): \$53.23

08929388 (1.000)							
Pillsbury: Sensor Assy (SRS):		\$63.11					
08929387 (1.000)							
Miscellaneous Parts		\$0					
7050 - STRAND, MATTHEW			\$125.00				
(2.50)							
Labor Comments: Replaced the TRS and SRS engine sensors.							
Miscellaneous Labor			\$0				
Other					\$0		
Radio/DVD/PA:Radio repair		\$0	\$21.50		\$0.00		\$21.50
Miscellaneous Parts		\$0					
7050 - STRAND, MATTHEW			\$21.50				
(0.43)							
Labor Comments: Got the wireless microphone back from REI, installed back into bus.							
Miscellaneous Labor			\$0				
Other					\$0		
		\$0.00	\$116.34	\$171.50	\$0	\$0	<u>\$287.84</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 978,762.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213664	10/12/2017	10/13/2017	Closed	0.00	

Description: PMI, Drag Link

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$94.65	\$56.00		\$0.00	\$150.65
Pillsbury: Draglink End RH		\$94.65				
EL3 MCI: 11-04-1005 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$56.00			
(1.12)						
Labor Comments: Replaced a bad drag link.						
Miscellaneous Labor			\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$183.34	\$226.00		\$0.00	\$409.34
Pillsbury: Filter Frame, Main		\$183.34				
Evap, EL3: 16-06-1093						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$226.00			
(4.52)						
Labor Comments: PMI						
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$277.99	\$282.00	\$0	<u>\$559.99</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 978,827.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213694	10/16/2017	10/16/2017	Closed	0.00	

Description: Mirror

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$0		\$0.00	\$0.00
Maintenance Requested: 60537 - 10/14/2017 - body work needed						
Requestor Notes: today the bus scraped garage door frame as putting coach away-approx 4' long above 1st and 2nd luggage doors.						
Technician Response:						



Miscellaneous Parts		Maint Req Status: Completed	\$0				
7050 - STRAND, MATTHEW				\$0.00			
(0.00)							
Labor Comments: will let body shop know							
Miscellaneous Labor				\$0			
Other					\$0		
77:Mirrors			\$0	\$0	\$0.00		\$0.00
Maintenance Requested: 60540 - 10/15/2017 - driver side mirror needs to be straightened							
Requestor Notes:							
Technician Response:							
Miscellaneous Parts		Maint Req Status: Completed	\$0				
7050 - STRAND, MATTHEW				\$0.00			
(0.00)							
Labor Comments: adjusted the mirror on Saturday							
Miscellaneous Labor				\$0			
Other					\$0		
			\$0	\$0	\$0	\$0	<u>\$0.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 978,827.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213707	10/16/2017	10/17/2017	Closed	0.00	

Description: Webasto Service

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$54.00		\$0.00	\$54.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$54.00			
(1.08)						
Labor Comments: Webasto Service						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$54.00	\$0	\$0	<u>\$54.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 978,827.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213764	10/19/2017	10/23/2017	Closed	0.00	

Description: repair scratches of passenger side and polish

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$1,790.50		\$0.00	\$1,790.50
Miscellaneous Parts		\$0				
9106 - MARIN RODRIGUEZ,			\$936.00			
CLAUDIO (18.72)						
9105 - PEREZ-LAZARO,			\$854.50			
ARMANDO (17.09)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$1,790.50	\$0	\$0	<u>\$1,790.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 979,146.0

Work Order Detail

Recall: Location: PBG Campaign # Department: PBG5-Charter Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213835	10/24/2017	10/24/2017	Closed	0.00	

Description: Lavatory

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$83.50		\$0.00	\$83.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.67)			\$83.50			
Labor Comments: Lavatory, When charging the bus with water, the gasket on the inside was leaking, causing water to drop in the engine compartment. Looking like a leak. Resealed it with RTV.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$83.50	\$0	\$0	<u>\$83.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 979,325.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213985	11/02/2017	11/02/2017	Closed	0.00	

Description: Mirror

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield Repair, Inv. # 2786162					\$40.00	\$40.00
267 - Superglass Windshield Repair, Inv. # 2786033, PO #					\$40.00	\$40.00
5527, Desc: Chip Repair						
77:Mirrors		\$0	\$3.50		\$0.00	\$3.50
Maintenance Requested: 60703 - 11/02/2017 - driver side mirror plastic frame broken						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.07)			\$3.50			
Labor Comments: not a safety concern						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$3.50	\$0	\$80.00	<u>\$83.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,044.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214216	11/20/2017	11/20/2017	Closed	0.00	

Description: Mirror

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$723.76	\$47.50		\$0.00	\$771.26
Maintenance Requested: 60854 - 11/18/2017 - Left mirror housing damaged, needs adjustment *com						
Requestor Notes: Service door is out of alignment at top. Closes hard						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Mirror Head:		\$723.76				
03-22-1053 (2.000)						
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW \$47.50  
(0.95)

Labor Comments: Mirror head damaged. Replaced it and adjusted it.

Miscellaneous Labor \$0  
Other \$0

\$0 \$723.76 \$47.50 \$0 \$0 \$771.26

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,260.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214406	12/04/2017	12/05/2017	Closed	0.00	

Description: Radio

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Radio/DVD/PA:Radio repair		\$0	\$21.50		\$0.00	\$21.50

Maintenance Requested: 60931 - 12/02/2017 - Radio-CD player-Mic Quick working completely halfw

Requestor Notes: Radio-CD player-Mic Quick working completely halfway though x-mas lights tour. If turned off the unit above the radio, the CD would play a few seconds then quit playing- cordless mic and regular mic also would not work

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
7050 - STRAND, MATTHEW \$21.50  
(0.43)

Labor Comments: Looked over the bus and found everything to be operational, left the radio on outside with the bus running for 3 hours and the mic and everything continued to work

Miscellaneous Labor \$0  
Other \$0

\$0 \$0 \$21.50 \$0 \$0 \$21.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,348.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214461	12/06/2017	12/08/2017	Closed	0.00	

Description: drive tire

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$1,500.00	\$235.00		\$0.00	\$1,735.00

Work Comments: 22 -- Drive tires need replacing.

Pillsbury: Tire, Steer,Toyo \$1,500.00

M144: 315/80R22.5 (4.000)

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (4.70) \$235.00

Labor Comments: 22 -- Drive tires need replacing. ----- Removed and replaced all four drive tires. Dimount and remount. Balanced, and torqued lug nuts to 450 LBS.

Miscellaneous Labor \$0  
Other \$0

\$0 \$1,500.00 \$235.00 \$0 \$0 \$1,735.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,348.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214570	12/12/2017	12/13/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$134.64	\$424.50		\$0.00	\$559.14
Work Comments: 21 -- Rubber bumpers for drive and tag axles are shot.						
Pillsbury: Stop-Bump, Drive Axle: 12-03-1025 (4.000)		\$134.64				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (8.49)			\$424.50			
Labor Comments: 21 -- Rubber bumpers for drive and tag axles are shot. ----- Removed and replaced all the bad rubber bumpers.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$134.64	\$424.50	\$0	\$0	<u>\$559.14</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,429.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214793	12/27/2017	12/27/2017	Closed	0.00	

Description: Air System, Air Drier

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$33.50		\$0.00	\$33.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.67)			\$33.50			
Labor Comments: Checked the rear torque arms. Bushings wearing but are still good.						
Miscellaneous Labor			\$0			
Other					\$0	
31:Charging		\$0	\$13.50		\$0.00	\$13.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.27)			\$13.50			
Labor Comments: Charging the bus. Dead in the washstall, had to jump start.						
Miscellaneous Labor			\$0			
Other					\$0	
49:Air System		\$0	\$46.50		\$0.00	\$46.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.93)			\$46.50			
Labor Comments: Drained air and filled with air condintiong alcohol.						
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$186.21	\$91.00		\$0.00	\$277.21
Pillsbury: AD-IP Air Dryer		\$57.25				
Desiccant Cartridge Bendix: 109493BXR (1.000)						
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$64.48				
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$64.48				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.82)			\$91.00			
Labor Comments: Air drier service. Helped driver with check engine lights on 2177 and 2178.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0.00	\$186.21	\$184.50	\$0	\$0	<u>\$370.71</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,697.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
214891	01/02/2018	01/04/2018	Closed	0.00	

Description: Radio, Door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$80.10	\$71.00		\$0.00	\$151.10
Pillsbury: Lock/Keys Kit EL3		\$80.10				
MCI: 3R-29-61 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.42)			\$71.00			
Labor Comments: Fuel door latch was not working properly, exchanged the tumblers out. Took for a drive. Door is noisy. Found spot the wind is entering, sealed it and added some weather stripping.						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair		\$394.00	\$26.50		\$0.00	\$420.50
Maintenance Requested: 61190 - 01/01/2018 - radio does not work-entry door does not seal						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Radio CD-2000,AM/ FM/CD,MOD ADV: 710338 (1.000)		\$394.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.53)			\$26.50			
Labor Comments: Swapped radios out to see if that is the ongoing problem.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$474.10	\$97.50	\$0	\$0	\$571.60

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 981,041.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215086	01/12/2018	01/15/2018	Closed	0.00	

Description: Door, Air system

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$141.91	\$186.50		\$0.00	\$328.41
Pillsbury: Drain Valve: 12100 (4.000)		\$31.96				
RO32934 Cut Off Air Valve (Reman) (1.000)		\$109.95				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.73)			\$186.50			
Labor Comments: Bus was leaning really bad in the barn. Sparyed down fittings found the left side air suspension valve was leaking at the casing. Ordered one from C&J. Waited for the part. Test drove a school bus.						
Miscellaneous Labor			\$0			
Other					\$0	
78:Doors Entrance / Exit		\$0	\$62.50		\$0.00	\$62.50
Maintenance Requested: 61283 - 01/11/2018 - poke with Jacob on trip. Top of door does not alwa						
Requestor Notes: spoke with Jacob on trip. Top of door does not always close properly. Leaves a gag for						

air 3/4 inch. Can be closed if door is pulled on while closing. Otherwise it latches on top inside plastic cover rather than inside steel catch.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$62.50  
 (1.25)

Labor Comments: Adjsuted the lock out a little, but its mainly due to the cold. Door works perfect in the barn or the shop.

Miscellaneous Labor \$0  
 Other \$0

\$0.00 \$141.91 \$249.00 \$0 \$0 \$390.91

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 980,921.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215106	01/15/2018	01/15/2018	Closed	0.00	

Description: Entrance Door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$11.50		\$0.00	\$11.50

Maintenance Requested: 61303 - 01/12/2018 - door does not close tightly

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$11.50  
 (0.23)

Labor Comments: Readjusted the door back.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$11.50 \$0 \$0 \$11.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 981,548.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215172	01/17/2018	01/25/2018	Closed	0.00	

Description: steering, suspension, entrance door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$174.00		\$0.00	\$174.00

Maintenance Requested: 61380 - 01/21/2018 - turning left steering sluggish/chatters

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 0081 - WOLF, PATRICK (3.48) \$174.00

Labor Comments: 20 -- Maint. req. -- turning left steering sluggish/chatters ----- Checked the seering linkage. both front and back. Didn't find anything wrong. Checked the res. topped it off. Road tested it. Did not feel any sluggish or here andy chattering.

Miscellaneous Labor \$0  
 Other \$0

21:Suspension		\$7.99	\$171.50		\$0.00	\$179.49
---------------	--	--------	----------	--	--------	----------

Work Comments: 21 -- Complaints about the bus tilting very bad in the front right.

Pillsbury: Drain Valve: 12100 \$7.99  
 (1.000)

Miscellaneous Parts \$0

Work Order Detail

0081 - WOLF, PATRICK (3.43)

\$171.50

Labor Comments: 21 -- Complaints about the bus tilting very bad in the front right. Got 6 lifts under the bus and raised it in the air. Checked all the air bags, hoses, tanks ect. Removed and replaced the right tag axle drain valve (leaking).

Miscellaneous Labor

\$0

Other

\$0

78:Doors Entrance / Exit

\$0 \$79.00

\$0.00

\$79.00

Work Comments: 78 -- Compants about the front door upper latch closing on the wrong side of the catch.

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (1.58)

\$79.00

Labor Comments: 78 -- Compants about the front door upper latch closing on the wrong side of the catch. ----- Adjusted the door closed sensor.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$7.99 \$424.50 \$0 \$0 \$432.49

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 982,835.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215693	02/21/2018	02/22/2018	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield Repair, Inv. # 2786337 40:Engine		\$0	\$0		\$0.00	\$40.00

Maintenance Requested: 61628 - 02/14/2018 - oil drip, front end shakes, chip in windshield-->

Requestor Notes: chip in windshield-driver's side-above the synovia tablet  
Front end shakes at freeway speed-steering wheel shakes  
Engine dripping oil

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
7050 - STRAND, MATTHEW  
(0.00)

\$0

\$0.00

Miscellaneous Labor  
Other

\$0

\$0

73:Seats

\$0 \$104.00

\$0.00

\$104.00

Maintenance Requested: 61669 - 02/18/2018 - seat 49 and 50 are loose-missing bolts

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts  
7050 - STRAND, MATTHEW  
(2.08)

\$0

\$104.00

Labor Comments: Refastened the seat.

Cleaned the oil off the engine, Looks like its leaking from the rocker extention.

Took for test drive, Front end seemed fine.

Wrote up the windshield for the glass guy.

Miscellaneous Labor  
Other

\$0

\$0

\$0 \$0 \$104.00 \$0 \$40.00 \$144.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 984,258.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
-------------	------------------	-------------------	---------------	-----------------	-----------------

216117                      03/19/2018                      03/20/2018                      Closed                      0.00

Description: Camera, Parking Brake Light

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
35:Instrument & Gauges		\$400.00	\$42.50		\$0.00	\$442.50
Maintenance Requested: 61810 - 03/07/2018 - see comments						
Requestor Notes: 1. on board camera in windshield fell down after hitting a pothole						
2. parking brake light doesn't light up						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Interlock Relay module: 07-18-1010 (1.000)		\$400.00				
Miscellaneous Parts 7050 - STRAND, MATTHEW (0.63)		\$0	\$31.50			
Labor Comments: Refastened the camera to the windshield.						
0081 - WOLF, PATRICK (0.22)			\$11.00			
Labor Comments: 2. Parking brake light doesn't light up ---- Checked the park brake switch. good.						
Tried a new Interlock module. Now they work fine.						
Miscellaneous Labor Other			\$0		\$0	
	\$0	\$400.00	\$42.50	\$0	\$0	\$442.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 984,436.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216266	03/28/2018	04/23/2018	Closed	0.00	

Description: LOF,PMI,Diff.,FF,HUB

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
DF:Differential Service		\$117.48	\$179.00		\$0.00	\$296.48
Work Comments: DF. -- Differential service.						
Pillsbury: Oil Gear Synthetic: Oil Gear 75W-90 BULK in quarts (20.000)		\$117.48				
Miscellaneous Parts 0081 - WOLF, PATRICK (3.58)		\$0	\$179.00			
Labor Comments: DF. -- Differential service. ----- Drained then refilled with new fluid.						
Miscellaneous Labor Other			\$0		\$0	
FF:Fuel Filter		\$8.53	\$0		\$0.00	\$8.53
Work Comments: FF -- Fuel Filters.						
Pillsbury: Filter Fuel: 3118 (1.000)		\$4.19				
Pillsbury: Filter, Fuel, MCI: 3120 (1.000)		\$4.34				
Miscellaneous Parts 0081 - WOLF, PATRICK (0.00)		\$0	\$0.00			
Labor Comments: FF -- Fuel Filters. ----- Removed and replaced both fuel filters.						
Miscellaneous Labor Other			\$0		\$0	
HUB:Hub Service		\$13.14	\$256.00		\$0.00	\$269.14
Work Comments: HUB -- Hub service						
Pillsbury: Oil Gear Synthetic: Oil Gear 75W-90 BULK in quarts (2.000)		\$13.14				
Miscellaneous Parts 0081 - WOLF, PATRICK (5.12)		\$0	\$256.00			
Labor Comments: HUB -- Hub service ----- Drained both steer and both tag axle, Hubs. Refilled with new gear lube.						
Miscellaneous Labor			\$0			



Other LOF:Lube, Oil, Filter	\$106.22	\$108.50	\$0	\$0.00	\$214.72
Work Comments: LOF -- Lube, Oil and Filter					
Pillsbury: Oil Bulk in Quarts:	\$76.59				
Oil 15W-40 Bulk (37.000)					
Pillsbury: Filter Media: 4WZ68 (7.000)	\$4.13				
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)	\$7.00				
Pillsbury: Fluid Windshield Washer Fluid BULK/Gal After Dilution: W/W Fluid BULK (2.000)	\$2.96				
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)	\$15.54				
Miscellaneous Parts 0081 - WOLF, PATRICK (2.17)	\$0	\$108.50			
Labor Comments: LOF -- Lube, Oil and Filter ---- Performed the service and safety check as per the attached sheet.					
Miscellaneous Labor		\$0			
Other			\$0		
PMI:Preventative Maintenance Inspection	\$100.00	\$0	\$0.00		\$100.00
Work Comments: PMI -- Preventative maintenance Inspection.					
03-22-1361 Mirror Bracket Arm, LH (1.000)	\$100.00				
Miscellaneous Parts 0081 - WOLF, PATRICK (0.00)	\$0	\$0.00			
Labor Comments: PMI -- Preventative maintenance Inspection. ----- Performed the preventative maintenance and Inspection as per the attached sheet.					
Miscellaneous Labor		\$0			
Other			\$0		
	\$0	\$345.37	\$543.50	\$0	\$0
					<u>\$888.87</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 984,611.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216595	04/18/2018	04/19/2018	Closed	0.00	

Description: 2-way install

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
51:Communications		\$619.00	\$196.00		\$0.00	\$815.00

Work Comments: 51 -- Install 2-way radio

2way install \$619.00 (1.000) \$619.00

Part Comments: Kit includes:

- \*HY-MD782U-1 UHF DMR Mobile Radio
- \*K-794 Line kit, very thick mount
- \*K332 Ground plane disc 6" dia, 3/8" mounting
- \*C-BNC58-CR connector, BNC-Male, R858, crimp
- \*B4502NS Antenna, UHF, no ground plane with spring
- \*HY-IGNITION SENSE accessory plug, ignition sense, hytera MD752/MD662 (professional wireless)

Miscellaneous Parts 0081 - WOLF, PATRICK (3.92)	\$0	\$196.00				
--	-----	----------	--	--	--	--

Labor Comments: 51 -- Install 2-way radio ---- Installed the 2-Way Radio.

Miscellaneous Labor		\$0				
Other				\$0		

	\$0	\$619.00	\$196.00	\$0	\$0	<u>\$815.00</u>
--	-----	----------	----------	-----	-----	-----------------

VIN: 1M8TRMPA6WP060245

License Plate:

5527: 1998 MCI EL3

Miles: 985,310.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216821	05/02/2018	05/08/2018	Closed	0.00	

Description: A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
20:Steering		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 62119 - 04/20/2018 - Steering-woobles Strays

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
20:Steering		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 62110 - 04/20/2018 - Brke squeaks bus shkes @ 60 steerg off

Requestor Notes: driver seat doesn't raise

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
37:Warning, Strobe, 8-Ways		\$17.83	\$0		\$0.00	\$17.83

Labor Comments: Took bus for a road test. Seemed to drive normal.  
Seat does go up and down.  
Brakes didnt seem to squeak to bad.

Maintenance Requested: 62138 - 04/23/2018 - no back up alarm horn

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Back Up Alarm: 56012 (1.000)		\$17.83				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.38)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
41:A/C & Heating		\$471.06	\$0		\$0.00	\$471.06

Labor Comments: Installed new backup alarm.

Pillsbury: Valve Assy, For 5527: 16-02-1034 (1.000)		\$380.33				
Pillsbury: oring: 16-02-1041pk (1.000)		\$5.18				
Pillsbury: Filter Dryer EL3: 16-04-1004 (1.000)		\$38.95				
Pillsbury: Freon R134A per Lb.: R134A (20.000)		\$46.60				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (5.28)			\$0.00			

Labor Comments: A/C leak out of the kingsvalve on the low side. Replaced the whole fitting. Changed out the filter drier. It held 150 pounds of nitrogen over night. Sucked the system down, held perfect vaccum for 30 mins Cleanded out the condensor and evapartor.. Added 20 pounds of freon to the system. Took for a road test.

Miscellaneous Labor			\$0			
Other					\$0	

Work Order Detail

\$0 \$488.89 \$0 \$0 \$0 \$488.89

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 985,666.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216952	05/10/2018	05/17/2018	Closed	0.00	

Description: mirrors

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
77:Mirrors		\$0	\$6.00		\$0.00	\$6.00

Maintenance Requested: 62251 - 05/09/2018 - Left Mirror arm is loose

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
9131 - CARNEY, JASON (0.12)	\$6.00

Labor Comments: tightened up mirror arm and double checked mirror angle for driver

Miscellaneous Labor	\$0
Other	\$0

\$0 \$0 \$6.00 \$0 \$0 \$6.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 986,402.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217187	05/23/2018	05/30/2018	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$859.50		\$0.00	\$859.50

Miscellaneous Parts	\$0
9106 - MARIN RODRIGUEZ, CLAUDIO (17.19)	\$859.50

Miscellaneous Labor	\$0
Other	\$0

\$0 \$0 \$859.50 \$0 \$0 \$859.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 986,632.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217346	06/05/2018	06/06/2018	Closed	0.00	

Description: Drivers Window

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$25.00		\$0.00	\$25.00

Maintenance Requested: 62246 - 05/08/2018 - driver's side window leaks when it rains

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW (0.50)	\$25.00

Labor Comments: Sealed up possible locations of water leaks on the drivers side window

Miscellaneous Labor	\$0
Other	\$0

\$0 \$0 \$25.00 \$0 \$0 \$25.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 987,796.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217473	06/15/2018	06/21/2018	Closed	0.00	

Description: radio and synovia base,P/S Flush,synovia base

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
39:Other Electrical		\$0	\$66.00		\$0.00	\$66.00

Maintenance Requested: 62475 - 06/14/2018 - Synovia unit is loose on dash

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0	\$66.00			
0081 - WOLF, PATRICK (1.32)			\$66.00			

Labor Comments: 39 -- Synovia unit is loose on dash ---- Screwed the base back into place.

Miscellaneous Labor			\$0			
Other					\$0	

40:Engine		\$0	\$32.50		\$0.00	\$32.50
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW (0.65)			\$32.50			
-------------------------------	--	--	---------	--	--	--

Labor Comments: Bus wouldnt start, Code for SRS. Checked the wiring. Bus fired up. Cleaned the connector and wiring. Bus started just fine after that.

Miscellaneous Labor			\$0			
Other					\$0	

49:Air System		\$0	\$36.00		\$0.00	\$36.00
Miscellaneous Parts		\$0				

7050 - STRAND, MATTHEW (0.72)			\$36.00			
-------------------------------	--	--	---------	--	--	--

Labor Comments: Checked for air leaks. Bus leans to the right. Did not find anything. Possibly small leaks in the air bags.

Miscellaneous Labor			\$0			
Other					\$0	

PS:Power Steering Flush		\$83.29	\$144.00		\$0.00	\$227.29
-------------------------	--	---------	----------	--	--------	----------

Work Comments: P/S -- Power steering flush

Pillsbury: Fluid ATF (Synthetic) Bulk Quart: ATF Synthetic Bulk (11.500)		\$72.91				
--	--	---------	--	--	--	--

Pillsbury: Element Power steering reservoir: 11-08-1074 (1.000)		\$10.38				
---	--	---------	--	--	--	--

Miscellaneous Parts		\$0	\$144.00			
0081 - WOLF, PATRICK (2.88)			\$144.00			

Labor Comments: P/S -- Power steering flush ---- Disconected the return line and ran fluid thru the p/s system till coming out clean.

Miscellaneous Labor			\$0			
Other					\$0	

Radio/DVD/PA:Radio repair		\$0	\$105.00		\$0.00	\$105.00
---------------------------	--	-----	----------	--	--------	----------

Maintenance Requested: 62456 - 06/11/2018 - radio and synovia base-see comments

Requestor Notes: radio doesn't work-top unit

Synovia unit is loose-missing a screw in base

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0	\$105.00			
0081 - WOLF, PATRICK (2.10)			\$105.00			

Labor Comments: RADIO/DVD/PA -- radio doesn't work-top unit ---- The radio works fine if you turn it on.

39 -- Synovia unit is loose-missing a screw in base ---- Screwed the base back into place.

Miscellaneous Labor			\$0			
Other					\$0	

\$0.00      \$83.29      \$383.50      \$0      \$0      \$466.79

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 989,411.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217770	07/10/2018	07/11/2018	Closed	0.00	

Description: polishing wheels

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$61.50		\$0.00	\$61.50
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS			\$61.50			
(1.23)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$61.50	\$0	\$0	<u>\$61.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 989,411.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217792	07/11/2018	07/25/2018	Closed	0.00	

Description: polishing wheels

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$255.00		\$0.00	\$255.00
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS			\$255.00			
(5.10)						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$255.00	\$0	\$0	<u>\$255.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 989,680.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217811	07/12/2018	07/25/2018	Closed	0.00	

Description: Engine

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$47.34	\$178.50		\$0.00	\$225.84

Maintenance Requested: 62594 - 07/06/2018 - see comments

Requestor Notes: microphone only works part of time

air conditioning stopped working, came back on after shutting bus down

Bus powered down at stop sign and had to be powered back on. Seemed OK after restarting

The red and amber engine lights came on briefly while idling but then went away

Technician Response:

Maint Req Status: Completed

Pillsbury: Sensor Coolant	\$31.82
Engine Shut-Down MCI	
D4500 w/ Detroit Series 60:	
7L-8-1124 (1.000)	
Pillsbury: Oil Bulk in Quarts:	\$15.52

Oil 15W-40 Bulk (7.500)  
 Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$178.50  
 (3.57)

Labor Comments: Engine code for low coolant level. Changed out the sensor. Checked the wiring, retied the wiring up. Found the bus was almost 2 gallons low on coolant. Filled to full mark. Microphone on order..

Replaced the pigtail for the TRS Sensor.

Greased the bus hoping to do a pmi. But charter needed the bus.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$47.34 \$178.50 \$0 \$0 \$225.84

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,275.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

WO #	Open Date	Close Date	Status	Downtime	Accident
218068	07/30/2018	08/27/2018	Closed	0.00	

Description: PMI,TF, DOT, Write-ups.

Detail	Discounts	Parts	Labor	Tires	Other	Total
12:Axles (rear)		\$722.87	\$1,914.50		\$0.00	\$2,637.37

Work Comments: 12 -- Drive axle sub-frame rotted out. Air bags shot.

Pillsbury: Shock Absorber, \$160.06  
 Drive, MCI: 12-05-1148 (2.000)  
 Pillsbury: Spring Air Bag, Drive \$503.62  
 Axle: 12-03-1041 (4.000)  
 0301742 Tree D 3/8x1/4 \$15.74  
 (1.000)  
 0301796 CYL N/F 1/2x1/4 \$26.69  
 (1.000)  
 0301682 Burr Oval DB 3/8x1/4 \$16.76  
 (1.000)  
 Miscellaneous Parts \$0  
 0081 - WOLF, PATRICK \$1,491.50

Labor Comments: 12 -- Drive axle sub-frame rotted out. Air bags shot. ----- Pulled 522 up to the shop. Removed the entire rear axle assembly. Blocked up the tag axle and pushed it back down to the body shop area. Removed the drive axle from both axle assemblies. Removed the subframe from 527. Mounted the subframe from 522 into 527. Mounted the drive axle from 527 back onto the subframe. Installed two new shocks. installed four new air springs. Had to remove a broken bolt from the frame of the rear boggy assembly. Hooked up all the air lines and ABS sensors. Remounted the leveling valves.

9127 - JACOBS, ANDREW \$210.50  
 (4.21)

Labor Comments: help pat pull axle out of burnt bus and put bus back at body shop

0146 - SHIPPY, CURTIS (4.25) \$212.50

Labor Comments: went out to pills and got a broken bolt out of the trailing arm bracket on a motor coach.

Miscellaneous Labor \$0  
 Other \$0

35:Instrument & Gauges \$0 \$459.00 \$0.00 \$459.00

Maintenance Requested: 62644 - 07/18/2018 - ISE fleet is not working.

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts \$0  
 9130 - PADEFORD, ERIC \$459.00  
 (9.18)

Labor Comments: tried a couple different spare screens had different issues with them put them on jacobs desk to get repaired

removed wire harness feeding synovia and cut out bad section reinstalled and test  
drove synovia worked as should  
wired in new keyed power

Miscellaneous Labor		\$0		
Other			\$0	
36:Lighting	\$0	\$38.50	\$0.00	\$38.50
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.77)		\$38.50		
Labor Comments: 36 -- Lighting ---- Replaced burnt out bulbs.				
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$0	\$374.00	\$0.00	\$374.00
Maintenance Requested: 62736 - 07/28/2018 - see comment				
Requestor Notes: A/C Stopped working at 1:00 PM with passengers. Rebooted a/c once. Did not start working Rear PSI dropped into red a couple of times. Less than 100 PSI Passenger door not working correctly as previously written up				
Technician Response: 41 -- A/C Stopped working at 1:00 PM with passengers.				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (7.48)		\$374.00		
Labor Comments: 41 -- A/C Stopped working at 1:00 PM with passengers. Rebooted a/c once. Did not start working see below Work code 41. 49 -- Rear PSI dropped into red a couple of times. Less than 100 PSI. This can happen easily in heavy traffic with the bus idling. 78 -- Passenger door not working correctly as previously written up ---- See work code 78 below.				
0146 - SHIPPY, CURTIS (0.00)		\$0.00		
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$68.68	\$87.50	\$0.00	\$156.18
Maintenance Requested: 62843 - 08/15/2018 - A/C stopped working. See Notes				
Requestor Notes: Driver restarted the bus and the A/C started working for an hour to hour and a half and then quit again.				
Technician Response:				
Maint Req Status: Completed				
Pillsbury: Coil 24 Volt A/C	\$68.68			
Comp. Unloader Valve MCI				
D4500: 16L-10-107 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$87.50		
(1.75)				
Labor Comments: Found a unloader not working. Replaced it and ran system. Freon level was good. Changed filters.				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$22.50	\$0.00	\$22.50
Maintenance Requested: 62653 - 07/18/2018 - overheard bin missing a screw see comments				
Requestor Notes: right side of coach, right side of bin Did not say passenger or driver side.....				
Technician Response: 72 -- Door hitting the front bumper.				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.45)		\$22.50		
Labor Comments: 72 -- right side of coach, right side of bin Did not say passenger or driver side..... ---- Replaced the missing screw. 72 -- Door hitting the front bumper. ---- Had to readjust the front bumper				
Miscellaneous Labor		\$0		
Other			\$0	
78:Doors Entrance / Exit	\$122.46	\$395.00	\$0.00	\$517.46
Maintenance Requested: 62730 - 07/27/2018 - see comments				
Requestor Notes: passenger door does not close and latch completely with door toggle switch. Buss stayed in low ride until door is pulled completely closed by hand and than latches closes.				

Work Order Detail

On pre trip one of the mechanics knew about the problem. He told me to pull door closed until fixed. NO problem doing so during run.

Technician Response: 78 -- passenger door does not close and latch completely with door toggle switch. Buss stayed in low ride until door is pu

Maint Req Status: Completed

Pillsbury: Bearing Mount hinge: 03-32-1008 (2.000)	\$122.46			
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW (0.18)		\$9.00		
Labor Comments: Pulled the bus in and checked the A/C. A/C was working as should				
0081 - WOLF, PATRICK (7.72)		\$386.00		
Labor Comments: 78 -- passenger door does not close and latch completely with door toggle switch. Buss stayed in low ride until door is pulled completely closed by hand and than latches closes.				
On pre trip one of the mechanics knew about the problem. He told me to pull door closed until fixed. NO problem doing so during run. ----- Pulled the front bumperet off. Removed the front door. Pulled the door frame out. Ground out the old bearings and replaced them. Put everything back together.				
Miscellaneous Labor		\$0		
Other			\$0	
DO:DOT Inspection	\$2.00	\$146.00	\$0.00	\$148.00
Work Comments: DO -- DOT Inspection				
DOT Sticker ( \$2.00 ) (1.000)	\$2.00			
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (2.92)		\$146.00		
Labor Comments: DO -- DOT Inspection ---- Performed the DOT inspection as per the attached sheet.				
Miscellaneous Labor		\$0		
Other			\$0	
MS:Misc	\$0	\$1.00	\$0.00	\$1.00
Maintenance Requested: 62808 - 08/10/2018 - see comments				
Requestor Notes: when filling toilet water sprays out of different areas of the engine-Pat said the hose inside must be leaking/loose				
Synovia not working				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
9130 - PADEFORD, ERIC (0.02)		\$1.00		
Labor Comments: clocked into on accident looking for synovia write up				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$0	\$135.00	\$0.00	\$135.00
Work Comments: PMI -- Preventative Maintenance Inspection				
Headlights: high/low beam:Pass		Horn:Pass		Leaks:Pass
Turn signals:Pass				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (2.70)		\$135.00		
Labor Comments: PMI -- Preventative Maintenance Inspection ---- Performed the PMI as per the attached sheet.				
Miscellaneous Labor		\$0		
Other			\$0	
TF:Transmission Flush	\$211.72	\$79.00	\$0.00	\$290.72
Work Comments: TF -- Transmission flush				
Pillsbury: Fluid ATF (Synthetic)	\$177.52			
Bulk Quart: ATF Synthetic Bulk (28.000)				
Pillsbury: Filter Kit	\$34.20			
Transmission Allison (Short Filter): 7741XE (1.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (1.58)		\$79.00		
Labor Comments: TF -- Transmission flush				
Miscellaneous Labor		\$0		
Other			\$0	



\$0.00 \$1,127.73 \$3,652.00 \$0 \$0 \$4,779.73

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,573.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218504	08/21/2018	08/22/2018	Closed	0.00	

Description: service call, Intake,

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
42:Air Intake		\$0	\$239.00		\$0.00	\$239.00

Work Comments: 42 -- Air Intake

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (4.78)

\$239.00

Labor Comments: 42 -- Air Intake ---- Looked over the turbo again. Pressure tested the CAC and all the boots.

Miscellaneous Labor

\$0

Other

\$0

95:Service Calls

\$0

\$132.50

\$0.00

\$132.50

Work Comments: 95 -- Service call

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (2.65)

\$132.50

Labor Comments: 95 -- Service call ---- Drove up to Hwy 5 And 34th. Looked over the bus. Turbo was ok. dint find anything wrong. Followed the driver back to the shop.

Miscellaneous Labor

\$0

Other

\$0

AF:Air Filter Replacement

\$42.00

\$22.50

\$0.00

\$64.50

Work Comments: AF -- Air Filter Replacement

Pillsbury: Filter Air: 6741

\$42.00

(1.000)

Miscellaneous Parts

\$0

0081 - WOLF, PATRICK (0.45)

\$22.50

Labor Comments: AF -- Air Filter Replacement ---- Removed and replaced the Air Filter.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$42.00 \$394.00 \$0 \$0 \$436.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,573.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218569	08/22/2018	08/28/2018	Closed	0.00	

Description: Turn Signal

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$10.50		\$0.00	\$10.50

Maintenance Requested: 62864 - 08/17/2018 - the right front turn signal and flasher bulb needs

Requestor Notes: to be replaced

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$10.50

(0.21)

Labor Comments: Changed right side front turn signal bulb.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$0 \$10.50 \$0 \$0 \$10.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,672.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218615	08/24/2018	08/28/2018	Closed	0.00	

Description: New Wiper Blades

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
58:Wiper/washers		\$73.56	\$0		\$0.00	\$73.56
Pillsbury: Wiper Blade MCI		\$73.56				
EL3: 03-34-1177 (2.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Labor Comments: Driver complaint. Replaced wiper blades						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$73.56	\$0	\$0	\$0	<u>\$73.56</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 991,919.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218678	08/28/2018	09/10/2018	Closed	0.00	

Description: CFR, Write-ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
48:Fuel System		\$0	\$263.50		\$0.00	\$263.50
Maintenance Requested: 62931 - 08/25/2018 - gassy or diesel smell in drivers area after drivin						
Requestor Notes: gassy or diesel smell in drivers area after drivin a while						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (5.27)			\$263.50			
Labor Comments: 48 -- gassy or diesel smell in drivers area after driving a while ---- Removed the panel over the fuel tank. Tightened several bolts into the fuel tank. Steam cleaned the fuel tank area. Put everything back together.						
Miscellaneous Labor			\$0			
Other					\$0	
CFR:Coolant Filter Replacement		\$5.69	\$6.50		\$0.00	\$12.19
Work Comments: CFR -- Coolant filter replacement						
Pillsbury: Filter Coolant		\$5.69				
Cummins ISM: 4071 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.13)			\$6.50			
Labor Comments: CFR -- Coolant filter replacement ---- Removed and replaced the coolant filter.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$5.69	\$270.00	\$0	\$0	<u>\$275.69</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 992,003.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218748	08/30/2018	09/14/2018	Closed	0.00	

Description: White Smoke

Work Order Detail

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$2,216.39	\$1,539.50		\$0.00	\$3,755.89
Pillsbury: Injector O-Ring 60: RTF26210 (2.000)		\$7.06				
Freight (1.000)		\$15.02				
R23538247 ARM/RLR ASM (1.000)		\$103.59				
R5236977 Injector (1.000)		\$284.19				
23539286 Tube (1.000)		\$30.13				
11506101 Nut (4.000)		\$1.80				
23507438 Stud, Exhaust (4.000)		\$17.44				
08929357 Bolt (9.000)		\$70.02				
23511667 Spacer (11.000)		\$70.73				
23511221 Manifold, Exhaust (1.000)		\$58.11				
23511222 Manifold, Exhaust (1.000)		\$58.90				
23519348 Manifold, Exhaust (1.000)		\$487.18				
23539193 Gasket, Manifold (3.000)		\$25.20				
23511667 Spacer (1.000)		\$6.43				
08929357 Bolt (3.000)		\$36.87				
SCH172743 Turbocharger, New (1.000)		\$750.00				
R23537686 Pump, Fuel (1.000)		\$193.72				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (30.79)			\$1,539.50			

Labor Comments: Bus is blowing out white smoke really bad. Had an exhaust manifold leak. Replaced the manifold and gaskets. During the inspection of the turbo, it showed signs of wear outside of normal patterns. Replaced the turbo and turbo gasket. Found that the fuel pump seemed weak, replaced the fuel pump and the gasket. Installed a clear line from the secondary fuel filter to the back of the head and watched the fuel being pumped into the head. It was not aerated at all. Next we manual cut out the injectors one at a time at the harness by putting a homeade breakout box. Every cylinder change except for cylinder 4. Replaced Injector number 4. During the inspection of the cam and rocker rollers. Cam has wear. The rocker rollers for the exhaust outside of operating specs, replaced them. Still smokes but everything Ive done helps. Took for 1 hour and 45 min test drive and everything drove great, one hiccup. But back into service and see what happens.

Miscellaneous Labor			\$0			
Other					\$0	
51:Communications		\$0	\$47.50		\$0.00	\$47.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.95)			\$47.50			

Labor Comments: Moved the 2-way microphone to the drivers preferred spot. Also moved 4 other buses

Miscellaneous Labor			\$0			
Other					\$0	

\$0      \$2,216.39      \$1,587.00      \$0      \$0      \$3,803.39

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 992,232.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219169	09/22/2018	09/25/2018	Closed	0.00	

Description: service call

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

Work Order Detail

40:Engine		\$0	\$0	\$0.00	\$0.00
	Maintenance Requested: 63052 - 09/14/2018 - see comments				
	Requestor Notes: charge filter light kept coming on when filling toilet with water, water comes pouring out all over different area of the engine and tube to dump when driving the bus would stop accelerating with foot on pedal and a big cloud of blue smoke came out of the exhaust. I did this a lot				
	Technician Response: Maint Req Status: Completed				
Miscellaneous Parts		\$0			
7050 - STRAND, MATTHEW (0.00)			\$0.00		
	Labor Comments: Took for test drive. Advised that the other 5 injectors should be replaced.				
Miscellaneous Labor			\$0		
Other				\$0	
95:Service Calls		\$0	\$16.50	\$0.00	\$16.50
	Work Comments: bus was stalling and smoking				
Miscellaneous Parts		\$0			
0142 - GALLINGER, CHAD (0.33)			\$16.50		
	Labor Comments: driver called bus was stalling and smoking got 530 ready to swap it out bus was swapped and 527 was parked in Mat's bay driver that swapped bus had no issues when driving from MOA to shop				
Miscellaneous Labor			\$0		
Other				\$0	
		\$0	\$0	\$16.50	\$0
				\$0	\$16.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 992,692.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219333	10/01/2018	10/17/2018	Closed	0.00	

Description: Engine, LOF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$1,883.68	\$1,848.50		\$0.00	\$3,732.18

Maintenance Requested: 63187 - 09/29/2018 - see comments

Requestor Notes: Bus has blue smoke coming out every time gas is pressed  
Bus hesitates when driving

Technician Response:

Maint Req Status: Completed

07-01-6001 relay (1.000)	\$51.80
05104701 seal, ring (6.000)	\$18.36
BOSRB5236977 injectors (5.000)	\$1,033.35
freight (1.000)	\$12.50
23511991 gasket (1.000)	\$27.93
23513556 harness injector (1.000)	\$263.11
23522323 harness (1.000)	\$354.51
Pillsbury: Sensor Assy (SRS): 08929387 (1.000)	\$68.89
Pillsbury: Sensor Assy (trs): 08929388 (1.000)	\$53.23
Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW (36.97)	\$1,848.50

Labor Comments: Engine was blowing white smoke really bad. Exhaust manifold leak, replaced manifold, found turbo bad, replaced turbo. Still smoked. Replaced the fuel pump due to shear age, installed a clear line from the secondary filter to the head to watch for air in the fuel. No air, took the CAC out of the equation. Still smokes. Installed a breakout box for the injectors found 4 to be missing. Replaced injector. Still smokes, decided to

Work Order Detail

do the rest. Reset the injector heights. Found the harness bad, swapped harness and ecms. Still smokes. Injector and Engine harness needed to be replaced. Decided to do both and replace both TRS and SRS sensors. No more smoke , took for really long test drive, sounds and runs better. Installed new harnesses before we pulled engine. Can't replicate the issue anymore. Changed oil and put back in service.

Miscellaneous Labor		\$0				
Other					\$0	
LOF:Lube, Oil, Filter	\$104.06	\$174.00	\$0.00			\$278.06
Pillsbury: Oil Analysis Kit: Sample Kit (1.000)	\$7.00					
Pillsbury: Filter Oil MCI D4500 w/Detroit Diesel 60 Series: 1971MP (2.000)	\$15.70					
Pillsbury: Oil Bulk in Quarts: Oil 15W-40 Bulk (36.000)	\$81.36					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (3.48)		\$174.00				
Labor Comments: LOF						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0.00	\$1,987.74	\$2,022.50	\$0	\$0	\$4,010.24

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219982	10/31/2018	11/01/2018	Closed	0.00	

Description: Webasto Tune Up, ETC...

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$22.14	\$11.50		\$0.00	\$33.64

Maintenance Requested: 63445 - 10/29/2018 - bulb issue and cable below dash, see comments

Requestor Notes: Flasher not working, left side, behind front wheel. Cable below dash, left of steering column needs to be secured out of the way.

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Non LED		\$22.14				
Amber Side Marker/Turn MCI EL3: 07-07-1003 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.23)			\$11.50			

Labor Comments: Replaced burnt out marker lamp

Miscellaneous Labor		\$0				
Other					\$0	
41:A/C & Heating	\$19.26	\$76.00	\$0.00			\$95.26

Pillsbury: Electrode Ignition dw-thermo wabasto: WE14846D (1.000)	\$13.01					
Pillsbury: Disk Photo no pre heat thermo: WE88440A (1.000)	\$6.25					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (1.52)		\$76.00				

Labor Comments: Webasto Tune Up

Miscellaneous Labor		\$0				
Other					\$0	
79:Lavatory	\$0	\$11.00	\$0.00			\$11.00

Maintenance Requested: 63420 - 10/25/2018 - see comments.

Requestor Notes: The toilet is leaking while being filled in three different spots.

Technician Response:  
 Maint Req Status: Completed

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$11.00  
 (0.22)

Labor Comments: Tightened up connections for lavatory.  
 Checked Fluids.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$41.40 \$98.50 \$0 \$0 \$139.90

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220311	11/15/2018	11/19/2018	Closed	0.00	

Description: 2-Way not working

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
51:Communications		\$0	\$13.50		\$0.00	\$13.50

Work Comments: 51 -- 2-Way not working

Miscellaneous Parts \$0  
 0081 - WOLF, PATRICK (0.27) \$13.50

Labor Comments: 51 -- 2-Way not working ----- 2-way not getting power. Traced the wires back to a fuse. Removed and replaced a blown fuse.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$13.50 \$0 \$0 \$13.50

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220604	11/29/2018	12/06/2018	Closed	0.00	

Description: Charging

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$0	\$105.00		\$0.00	\$105.00

Miscellaneous Parts \$0  
 7050 - STRAND, MATTHEW \$105.00  
 (2.10)

Labor Comments: Slow charging the batteries.  
 Checked Fluids.  
 Cleaned out the CAC and Radiator.

Miscellaneous Labor \$0  
 Other \$0

\$0 \$0 \$105.00 \$0 \$0 \$105.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,283.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220814	12/10/2018	12/21/2018	Closed	0.00	

Description: Air drier, Charging

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

Work Order Detail

31:Charging		\$0	\$106.00	\$0.00	\$106.00
	Work Comments: 31 -- Charging				
Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (2.12)			\$106.00		
	Labor Comments: 31 -- Charging ---- Load tested the batteries. Both are good. Was told to check for a battery draw. there is a small battery draw for the sonovia and camera systems. Charged the batteries up good.				
Miscellaneous Labor			\$0		
Other				\$0	
AD:Air Drier Service		\$131.56	\$123.50	\$0.00	\$255.06
	Work Comments: AD -- Air drier Service				
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$77.16			
Pillsbury: AD-IP Air Dryer		\$54.40			
Desiccant Cartridge Bendix: 109493BXR (1.000)					
Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (2.47)			\$123.50		
	Labor Comments: AD -- Air drier Service ---- Pulled the air drier off. Cleaned it all up. Installed a new purge valve and desc. filter. Mounted back on the bus. Checked for good power and ground at the heater wires.				
Miscellaneous Labor			\$0		
Other				\$0	
		\$0	\$131.56	\$229.50	\$0
				\$0	\$361.06

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 993,869.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221900	01/29/2019	02/01/2019	Closed	0.00	

Description: take off decal

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$220.00		\$0.00	\$220.00
Miscellaneous Parts		\$0				
1004 - PEREZ, YONI (4.40)			\$220.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$220.00	\$0	\$0	\$220.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 994,316.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222309	02/14/2019	03/01/2019	Closed	0.00	

Description: Write - ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$281.00		\$0.00	\$281.00

Maintenance Requested: 64478 - 02/16/2019 - Back end sits up too high - see comments

Requestor Notes: This driver had this bus on an earlier trip and Darlene Helman had it today. Ron thinks it sits up too high and wonders if the blocks that are put between the axle and the frame were accidentally left on the bus the last time it was serviced. He had trouble with it on his earlier trip. Picture from Ron forwarded to Jacob.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (5.62)			\$281.00		

Labor Comments: 21 -- This driver had this bus on an earlier trip and Darlene Helman had it today. Ron

Work Order Detail

thinks it sits up too high and wonders if the blocks that are put between the axle and the frame were accidentally left on the bus the last time it was serviced. He had trouble with it on his earlier trip. Picture from Ron forwarded to Jacob. ----  
Recalibrated the ride height.

Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$38.36	\$31.00	\$0.00	\$69.36

Maintenance Requested: 64473 - 02/16/2019 - Rear air pressure fluctuates. See notes.

Requestor Notes: Another driver on this trip, Ron Lischeid, thought that the back end of the bus was riding too high prior to the fluctuations starting.

Technician Response:

Maint Req Status: Completed

Pillsbury: Hose ASM, Front	\$38.36			
Brakes E-Coach: 04-20-1040				
(1.000)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.62)		\$31.00		

Labor Comments: 49 -- Another driver on this trip, Ron Lischeid, thought that the back end of the bus was riding too high prior to the fluctuations starting. ---- Checked into the rear air PSI. Found the Gauge reading 15 PSI lower than it really is. Trying to get a new dash. Found the right front brake hose broken. Removed and replaced the hose.

Miscellaneous Labor		\$0		
Other			\$0	
52:Electrical Accessories	\$0	\$44.00	\$0.00	\$44.00

Maintenance Requested: 64376 - 02/08/2019 - See comments

Requestor Notes: 1. Stone chip in windshield, right door side, just right of the video camera.  
2. Radio (music) won't turn on.  
3. Water rinse/refill on lavatory leaks behind the bullshead fitting (inside).

Technician Response: 75 -- . Stone chip in windshield, right door side, just right of the video camera.

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (0.88)		\$44.00		

Labor Comments: 75 -- . Stone chip in windshield, right door side, just right of the video camera. ---- Wrote up windshield repair on white board.  
52 -- . Radio (music) won't turn on. ---- Removed and replaced the radio with a good used one.  
79 -- . Water rinse/refill on lavatory leaks behind the bulkhead fitting (inside). ---- Removed the rear panel. found the leak cut the line back a little and refastened.

Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$159.00	\$0.00	\$159.00

Maintenance Requested: 64305 - 02/06/2019 - radio inop, overhead bin broken, see comments

Requestor Notes: radio not working-can't get lower cd player/radio to turn on  
overhead bin at 1 and 2 has a broken hinge

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (3.18)		\$159.00		

Labor Comments: 52 -- radio not working-can't get lower cd player/radio to turn on ---- Removed and replaced the radio with a good used one.  
72 -- overhead bin at 1 and 2 has a broken hinge ---- Screwed the hing back together.

Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$0	\$108.50	\$0.00	\$108.50

Maintenance Requested: 64481 - 02/16/2019 - See comments.

Requestor Notes: 1. Back of bus is raised too high. See previous maintenance request.  
2. First overhead on doorside has a screw missing on one hinge so it doesn't work very well.

Technician Response: 21 -- Back of bus is raised too high. See previous maintenance request. ---- Recalibrated the ride height

Maint Req Status: Completed

Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (2.17)		\$108.50		

Labor Comments: 21 -- Back of bus is raised too high. See previous maintenance request. ----



Work Order Detail

Recalibrated the ride height.  
 72 -- First overhead on doorside has a screw missing on one hinge so it doesn't  
 work very well. Reattached the screw.

Miscellaneous Labor							
Other						\$0	
75:Windows/windshields	\$0	\$0				\$0.00	\$0.00
Maintenance Requested: 64463 - 02/15/2019 - Washer fluid not coming out and reservoir is full.							
Requestor Notes:							
Technician Response:							
Maint Req Status: Completed							
Miscellaneous Parts							
0081 - WOLF, PATRICK (0.00)	\$0					\$0.00	
Labor Comments: 75 -- Washer fluid not coming out and reservoir is full. ---- Tied the windshield washers and they worked fine. something must have been frozen.							
Miscellaneous Labor							
Other						\$0	
	\$0	\$38.36	\$623.50	\$0	\$0		<u>\$661.86</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245 License Plate:

Miles: 994,807.0

Location: PBG Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222782	03/07/2019	03/08/2019	Closed	0.00	

Description: Write-ups

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$0	\$4.00		\$0.00	\$4.00

Maintenance Requested: 64726 - 03/06/2019 - See comments.

Requestor Notes: Entire bus leans badly to the right, all the time. Right turns are okay, but left turns are very uncomfortable.

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts						
0081 - WOLF, PATRICK (0.08)	\$0					\$4.00
Labor Comments: 21 -- Entire bus leans badly to the right, all the time. Right turns are okay, but left turns are very uncomfortable. ---- Calibrated all three ride heights.						
Miscellaneous Labor						
Other						\$0
78:Doors Entrance / Exit	\$0	\$292.50			\$0.00	\$292.50
Maintenance Requested: 64727 - 03/06/2019 - Right front cargo door latch broken.						
Requestor Notes:						
Technician Response: 78 -- Right front cargo door latch broken.						
Maint Req Status: Completed						
Miscellaneous Parts						
0081 - WOLF, PATRICK (5.85)	\$0					\$292.50
Labor Comments: 78 -- Right front cargo door latch broken. ---- Removed a good cargo door latch from 523 AND INSTALLED IT ON 527.						
Miscellaneous Labor						
Other						\$0
	\$0	\$0	\$296.50	\$0	\$0	<u>\$296.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245 License Plate:

Miles: 995,091.0

Location: PBG Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223139	03/19/2019	03/20/2019	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$20.00		\$0.00	\$20.00

5/7/2019

Work Order Detail

Miscellaneous Parts  
2138 - KREJCE, LUCAS

\$0 \$20.00

Labor Comments: Help pat with fixing and putting in of the window shade

Miscellaneous Labor  
Other

\$0 \$0

\$0 \$0 \$20.00 \$0 \$0 \$20.00

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 995,091.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223263	03/25/2019	03/27/2019	Closed	0.00	

Description: marker light has water in it

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$79.77	\$0		\$0.00	\$79.77
Pillsbury: Light MCI		\$79.00				
Conversion LED Amber: GG77090 (2.000)						
Pillsbury: Reflector Front Amber Gillig: 51-09325-001 (1.000)		\$0.77				
Miscellaneous Parts 0142 - GALLINGER, CHAD (0.00)		\$0	\$0.00			
Labor Comments: replaced front lower side reflectors and L/R marker light						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$79.77	\$0	\$0	\$0	<u>\$79.77</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 995,225.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223389	03/28/2019	04/01/2019	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CR:Creep		\$0	\$184.00		\$0.00	\$184.00
Miscellaneous Parts 2138 - KREJCE, LUCAS		\$0	\$184.00			
Labor Comments: Crept with Pat replaced license plate light, cleaned off four shocks, and replaced broken and rusted bolts in loose mud flap.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$184.00	\$0	\$0	<u>\$184.00</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 995,225.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223453	04/02/2019	04/22/2019	Closed	0.00	

Description: Radiator,belts,batteries

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$381.56	\$123.50		\$0.00	\$505.06
Work Comments: 31 -- Bus keeps needing jump start.						

Work Order Detail

Pillsbury: Battery 1400CCA Top Post Heavy Duty	\$381.56				
Workaholic: 8D-MHD(7271)					
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (2.47)		\$123.50			
Labor Comments: 31 -- Bus keeps needing jump start. ---- Removed and replaced both batteries.					
Miscellaneous Labor		\$0			
Other				\$0	
43:Cooling	\$33.10	\$841.00		\$0.00	\$874.10
Work Comments: 43 -- Radiator leaking.					
Pillsbury: Holder cup w/ mounting screws black: TH2BLK (2.000)	\$3.80				
Pillsbury: Fluid Coolant Bulk 50/50 After Dilution: A/F 50/50 Green BULK (5.000)	\$29.30				
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK		\$801.00			
Labor Comments: 43 -- Radiator leaking. ---- Pulled the radiator out of 5523 and installed it into 527. Ran the engine up to temp and topped off the coolant.					
2138 - KREJCE, LUCAS		\$40.00			
Labor Comments: Help Pat move radiators from one bus to 5527.					
Miscellaneous Labor		\$0			
Other				\$0	
Belt:Belt Replacement	\$94.06	\$119.00		\$0.00	\$213.06
Work Comments: Belt -- Belt replacement					
Pillsbury: Belt EL3: 08-27-1002 (1.000)	\$57.10				
Pillsbury: Belt, A/C, MCI, E- Coach: 08-27-1029 (1.000)	\$36.96				
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (2.38)		\$119.00			
Labor Comments: Belt -- Belt replacement ---- Removed and replaced the fan belt and the A/C belt.					
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$508.72	\$1,083.50	\$0	\$0
					\$1,592.22

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 996,016.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
224023	04/24/2019		Completed	0.00	

Description: list

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
38:Audio / Video Surveillance System		\$0	\$104.50		\$0.00	\$104.50

Maintenance Requested: 65190 - 04/19/2019 - See comments.

Requestor Notes: 1. PA/wireless microphone doesn't work along with radio//AUX sound don't work. FM radio has power. it's on/working but REI selector doesn't fully power up.  
2. Synovia/ISE system doesn't detect or record mileage (odometer or trip distance), nor engine hours/time. GPS does detect motion so ISE records drivers. Standby v. Off duty/break.

Technician Response:

Maint Req Status: Completed

15.4 inch monitor P/N T1588IR (1.000)	\$0.00				
Miscellaneous Parts	\$0				
0142 - GALLINGER, CHAD (2.09)		\$104.50			

Labor Comments: checked Synovia and video system every thing was working. checked P/A and radio they are working. Found 4 DVD screens not working replaced driver side center screen and ordered 3 more

Miscellaneous Labor	\$0				
---------------------	-----	--	--	--	--

Other			\$0	
40:Engine	\$0	\$126.00	\$0.00	\$126.00
	Maintenance Requested: 65142 - 04/16/2019 - No Power/smokes alot			
	Requestor Notes:			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts	\$0			
0142 - GALLINGER, CHAD		\$126.00		
(2.52)				
	Labor Comments: test drove ran fine			
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$0	\$0	\$0.00	\$0.00
	Maintenance Requested: 65080 - 04/09/2019 - no acceleration power. inop fuel gauge			
	Requestor Notes:			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts	\$0			
0142 - GALLINGER, CHAD		\$0.00		
(0.00)				
	Labor Comments: drove fine dash was replaced			
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$0	\$0	\$0.00	\$0.00
	Maintenance Requested: 64693 - 03/04/2019 - runs cold, heater, dvds-see comments			
	Requestor Notes: engine runs cold			
	heater will go off-then aux- the en			
	rear air gauge doesn't work			
	DVD players on bus:			
	Drivers side front and rear do work, the middle dvd has no picture			
	Pass side only the front works, middle screen won't come down			
	rear screen doesn't work			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts	\$0			
0142 - GALLINGER, CHAD		\$0.00		
(0.00)				
	Labor Comments: work done on different task			
Miscellaneous Labor		\$0		
Other			\$0	
41:A/C & Heating	\$0	\$0	\$0.00	\$0.00
	Maintenance Requested: 65128 - 04/15/2019 - Heat does not work			
	Requestor Notes: Heat does not work			
	smokes really bad			
	has a hard time going up hill			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts	\$0			
0142 - GALLINGER, CHAD		\$0.00		
(0.00)				
	Labor Comments: wrote up for no heat. Heat valves were closed for the summer			
Miscellaneous Labor		\$0		
Other			\$0	
49:Air System	\$0	\$316.00	\$0.00	\$316.00
	Maintenance Requested: 65204 - 04/20/2019 - Rear air tanks aren't building to 130			
	Requestor Notes:			
	Technician Response:			
	Maint Req Status: Completed			
Miscellaneous Parts	\$0			
0142 - GALLINGER, CHAD		\$316.00		
(6.32)				
	Labor Comments: checked air pressure at supply front and rear tanks all were same pressure checked sending units they were o/k installed used dash from parts room and adjusted air			

governor miles on removed dash 996,018 miles on installed dash 846,389

Miscellaneous Labor		\$0				
Other					\$0	
72:Body Misc	\$0	\$0		\$0.00		\$0.00
Maintenance Requested: 65186 - 04/18/2019 - See comments.						
Requestor Notes: 1. PA system doesn't power up. AM/FM radio turns on but cannot select any options, ie: "PA", "AUX", "CD", etc.						
2. Door side front luggage bay door won't open.						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
0142 - GALLINGER, CHAD (0.00)				\$0.00		
Labor Comments: checked baggage door it will open fine all other write ups all ready repaired						
Miscellaneous Labor				\$0		
Other					\$0	
	\$0	\$0	\$546.50	\$0	\$0	<u>\$546.50</u>

5527: 1998 MCI EL3

VIN: 1M8TRMPA6WP060245

License Plate:

Miles: 846,929.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
224162	04/30/2019	05/06/2019	Closed	0.00	

Description: Door switch broken

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$32.85	\$10.00		\$0.00	\$42.85
Work Comments: 78 -- Door switch broken						
Pillsbury: Switch Rocker Door EL3: 07-19-1016 (1.000)		\$32.85				
Miscellaneous Parts 0081 - WOLF, PATRICK (0.20)		\$0	\$10.00			
Labor Comments: 78 -- Door switch broken ---- Removed and replaced the inner door switch.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$32.85	\$10.00	\$0	\$0	<u>\$42.85</u>