

Work Order Detail

Labor Comments: 43 -- Steamed out the radiator and CAC. topped off the coolant.

Miscellaneous Labor						
Other						\$0
72:Body Misc	\$154.28	\$42.50		\$0.00		\$196.78

Work Comments: 72 -- Body misc. ---- Anti slip tape falling off the bottom step. Cleaned all the dirt and adhesive off the step and applied new tape.

Pillsbury: Headlight, LED, MCI: 9705K (1.000)	\$77.14					
Pillsbury: Headlight, LED, MCI: 9706K (1.000)	\$77.14					
Miscellaneous Parts 0081 - WOLF, PATRICK (0.85)	\$0			\$42.50		

Labor Comments: 72 -- Body misc. ---- Anti slip tape falling off the bottom step. Cleaned all the dirt and adhesive off the step and applied new tape.

Miscellaneous Labor						\$0
Other						\$0
A/C:Prep	\$422.54	\$196.50		\$0.00		\$619.04

Work Comments: A/C : Prepare for Summer.

Pillsbury: Water Valve repair kit, EL3: 16-06-1025 (2.000)	\$422.54					
Miscellaneous Parts 0081 - WOLF, PATRICK (3.93)	\$0			\$196.50		

Labor Comments: A/C : Prepare for Summer. ---- Removed all the panels. checked every brush on condenser and evap motors. All are at least 60 %. Rinsed out the condenser core, radiator and CAC. (very dirty) Removed and rebuilt a water valve.

Miscellaneous Labor						\$0
Other						\$0
	\$0	\$587.35	\$320.00	\$0	\$0	<u>\$907.35</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 804,764.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211276	05/04/2017	05/11/2017	Closed	0.00	

Description: Broken Headlamp

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$81.50		\$0.00	\$81.50
Miscellaneous Parts 7050 - STRAND, MATTHEW (1.63)		\$0	\$81.50			

Labor Comments: ran the a/c and cleaned out the condensor

Miscellaneous Labor						\$0
Other						\$0
72:Body Misc	\$95.00	\$133.50		\$0.00		\$228.50

Pillsbury: Holder cup w/ mounting screws black: TH2BLK (50.000)	\$95.00					
---	---------	--	--	--	--	--

Part Comments: installed by wash stall

Miscellaneous Parts 7050 - STRAND, MATTHEW (2.67)	\$0		\$133.50			
---	-----	--	----------	--	--	--

Labor Comments: took the headlamp that was smashed in out

Miscellaneous Labor						\$0
Other						\$0
	\$0	\$95.00	\$215.00	\$0	\$0	<u>\$310.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 804,764.0

Location: PBG

Department: PBG5-Charter

Work Order Detail

<u>WO #</u>	<u>Open Date</u>	Recall:	Campaign #	<u>Status</u>	<u>Downtime</u>	Date:	<u>Accident</u>
211291	05/04/2017			Closed	0.00		

Description: put a head light passenger side fix front bumper

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$668.50		\$0.00	\$668.50
Miscellaneous Parts		\$0				
9045 - BERMUDEZ, MARCOS (13.37)			\$668.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$668.50	\$0	\$0	<u>\$668.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 805,631.0

Location: PBG

Department: PBG5-Charter

<u>WO #</u>	<u>Open Date</u>	Recall:	Campaign #	<u>Status</u>	<u>Downtime</u>	Date:	<u>Accident</u>
211589	05/26/2017			Closed	0.00		

Description: DOT,door

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$0	\$213.50		\$0.00	\$213.50
Work Comments: 78 -- Entrance door switch not working.						
7L-8-553 outter door switch (from Eagan) (1.000)		\$0.00				
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (4.27)			\$213.50			
Labor Comments: 78 -- Entrance door switch not working. ---- Trouble shoot door problem. Found a blown fuse and a bad exterior door switch. Removed and replaced both.						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$0	\$177.50		\$0.00	\$177.50
Work Comments: CR -- Creep						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (3.55)			\$177.50			
Labor Comments: CR -- Creep ---- Creep bus and checked out everything to make sure it could pass a DOT.						
Miscellaneous Labor			\$0			
Other					\$0	
DO:DOT Inspection		\$2.00	\$50.00		\$0.00	\$52.00
DOT Sticker 2\$ (1.000)		\$2.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.00)			\$50.00			
Labor Comments: DOT						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$2.00	\$441.00	\$0	\$0	<u>\$443.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 803,989.0

Location: PBG

Department: PBG5-Charter

<u>WO #</u>	<u>Open Date</u>	Recall:	Campaign #	<u>Status</u>	<u>Downtime</u>	Date:	<u>Accident</u>
211735	06/07/2017			Closed	0.00		

Description: A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$78.93	\$205.00		\$0.00	\$283.93

Maintenance Requested: 11466 - 06/07/2017 - Air conditioning not cooling
 Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Freon R134A per \$27.96
 Lb.: R134A (12.000)
 Pillsbury: Viscosity 32 oz: PAG \$50.97
 Oil CQP100-32 (3.000)
 Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$205.00
 (4.10)

Labor Comments: low on freon, charged to operating range, maybe a little over
 checked for leaks on the a/c compressor
 steam cleaned the a/c compressor and engine compartment
 fixed the door lock
 fixed a really bad rattle

Miscellaneous Labor \$0
 Other \$0

\$0 \$78.93 \$205.00 \$0 \$0 \$283.93

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115 License Plate: PRZ9154

Miles: 807,825.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211919	06/22/2017	06/22/2017	Closed	0.00	

Description: Repair from 6-20-17 Incident

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$36.00	\$318.75		\$0.00	\$354.75
Miscellaneous Parts		\$36.00				
9024 - LEWISON, CHAD			\$318.75			

Labor Comments: sand and buff out doors
 Door will need to be fully painted in the future

Miscellaneous Labor \$0
 Other \$0

\$106.25 \$36.00 \$318.75 \$0 \$0 \$354.75

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115 License Plate:

Miles: 808,161.0

Location: PBG

Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
211972	06/27/2017	06/30/2017	Closed	0.00	

Description: PMI, FF, Coolant Filter

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$43.74	\$101.50		\$0.00	\$145.24
Pillsbury: Stop-Bump, Drive		\$33.66				
Axle: 12-03-1025 (1.000)						
Pillsbury: Hub Cap, Stainless		\$10.08				
Steel: MW1273 (1.000)						
Used Tire (1.000)		\$0.00				
Used Lug Nut Covers		\$0.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$101.50			
(2.03)						

Labor Comments: Right Tag tire was beat up really bad, missing all lug nut covers and hub cap. They
 must have hit something hard.
 Replaced the tire with a used one in the tire cage.
 Left tag bumper was falling apart, broke loose and replaced.

Work Order Detail

Miscellaneous Labor		\$0		
Other			\$0	
25:Transmission (Auto)	\$58.64	\$91.50	\$0.00	\$150.14
Pillsbury: Seal Rear	\$58.64			
Transmission Output Allison				
B500: 29552705 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$91.50		
(1.83)				
Labor Comments: Trans seal leaking, installed a used yoke. Old one has already went thru 2 speed sleeves. Replaced Seal				
Miscellaneous Labor		\$0		
Other			\$0	
40:Engine	\$200.47	\$24.00	\$0.00	\$224.47
Pillsbury: Tensioner, Detroit:	\$200.47			
23533015 (1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$24.00		
(0.48)				
Labor Comments: Serpentine belt was bouncing all over the place. Replaced the Tensioner.				
Miscellaneous Labor		\$0		
Other			\$0	
72:Body Misc	\$31.80	\$70.00	\$0.00	\$101.80
Pillsbury: Striker Assy-side	\$29.74			
sash: 03-27-1137 (2.000)				
Pillsbury: Light Bulb Pass.	\$2.06			
Sevice Module 28V 10W:				
03-08-1162 (2.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$70.00		
(1.40)				
Labor Comments: Replaced a set of window strikers and reading light bulbs				
Miscellaneous Labor		\$0		
Other			\$0	
CFR:Coolant Filter Replacement	\$63.39	\$0	\$0.00	\$63.39
Pillsbury: Filter Coolant w/Full	\$63.39			
Charge MCI D4500 w/ Detroit				
60 Series Engine: 4088				
(2.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$0.00		
(0.00)				
Labor Comments: repalced Coolant Filter				
Miscellaneous Labor		\$0		
Other			\$0	
FF:Fuel Filter	\$8.53	\$36.50	\$0.00	\$45.03
Pillsbury: Filter, Fuel, MCI:	\$4.34			
3120 (1.000)				
Pillsbury: Filter Fuel: 3118	\$4.19			
(1.000)				
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$36.50		
(0.73)				
Labor Comments: Replaced Fuel Filters and Coolant filter				
Miscellaneous Labor		\$0		
Other			\$0	
PMI:Preventative Maintenance Inspection	\$0	\$128.50	\$0.00	\$128.50
Miscellaneous Parts	\$0			
7050 - STRAND, MATTHEW		\$128.50		
(2.57)				
Labor Comments: PMI				
Miscellaneous Labor		\$0		
Other			\$0	

Work Order Detail

\$0.00 \$406.57 \$452.00 \$0 \$0 \$858.57

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 808,579.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212030	07/05/2017	07/07/2017	Closed	0.00	

Description: No A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$201.00		\$0.00	\$201.00

Maintenance Requested: 11546 - 07/03/2017 - No A/C

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (4.02)			\$201.00			

Labor Comments: 41 --- No A/C ---- Checked out the A/C It took the Inside temp down to 64 with no problem. The freon level is right in range also. Nothing found wrong with the A/C system.

Miscellaneous Labor			\$0			
Other					\$0	

\$0 \$0 \$201.00 \$0 \$0 \$201.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 808,579.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212046	07/06/2017	07/07/2017	Closed	0.00	

Description: Muffler

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
46:Exhaust System		\$754.93	\$136.50		\$0.00	\$891.43

Pillsbury: Exhaust Clamp 5"

\$5.36

Preformed Band Aluminized:

ABP N35-50PLA (1.000)

Pillsbury: Isolator Double U-

\$104.46

Shear: 08-20-1014 (3.000)

08-20-1024 muffler-

\$548.48

aluminized steel (1.000)

08-20-1025 pipe-tail exh strt

\$96.63

(1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$136.50

(2.73)

Labor Comments: Muffler had a hole in it. Replaced it and other hardware

Miscellaneous Labor			\$0			
---------------------	--	--	-----	--	--	--

Other					\$0	
-------	--	--	--	--	-----	--

\$0.00 \$754.93 \$136.50 \$0 \$0 \$891.43

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,055.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212381	07/31/2017	08/14/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$750.00	\$148.50		\$0.00	\$898.50

Work Comments: 41 -- #1 condensor fan on OverLoad

Rebuilt Condensor fan motor	\$0.00
(labeled DNI) (1.000)	
27 VDC GE Carrier Rebuild	\$750.00
Fan Motor (1.000)	
Miscellaneous Parts	\$0
0081 - WOLF, PATRICK (2.97)	\$148.50

Labor Comments: 41 -- #1 condensor fan on OverLoad ---- TRouble shoot condensor fan issue.
Removed and replaced the fan motor.

Miscellaneous Labor	\$0					
Other					\$0	
	\$0	\$750.00	\$148.50	\$0	\$0	<u>\$898.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,055.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212403	08/01/2017	08/01/2017	Closed	0.00	

Description: Toilet

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 11653 - 08/01/2017 - needs toilet treatments

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0
7050 - STRAND, MATTHEW	\$0.00
(0.00)	

Labor Comments: Dont know what this means, guessing its a Wash Stall responsibility

Miscellaneous Labor	\$0					
Other					\$0	
	\$0	\$0	\$0	\$0	\$0	<u>\$0.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,959.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212418	08/01/2017	08/01/2017	Closed	0.00	

Description: Solenoid

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$58.82	\$0		\$0.00	\$58.82
Pillsbury: Contactor 24VDC:		\$58.82				
16-04-1204 (1.000)						
Miscellaneous Parts		\$0				
Miscellaneous Labor			\$0			
Other					\$0	

	\$0	\$58.82	\$0	\$0	\$0	<u>\$58.82</u>
--	-----	---------	-----	-----	-----	----------------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 811,964.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
212877	08/28/2017	09/08/2017	Closed	0.00	

Description: Tag Tires/ Trans Flush

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
22:Tires		\$349.52	\$165.00		\$0.00	\$514.52
Maintenance Requested: 11931 - 08/28/2017 - bus vibration noticed by driver and passengers						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Tire TB Recap Tag: 315/80R 22.5 TB Recap Tag (2.000)		\$349.52				
Miscellaneous Parts 7050 - STRAND, MATTHEW (3.30)		\$0	\$165.00			
Labor Comments: Looked over the suspension. Found tag tire cupping and wearing on the inside. Repalced both tag tires with tag recaps and save the good tire on the right side. Took on test drive and did not feel much of a vibration.						
Miscellaneous Labor			\$0			
Other					\$0	
31:Charging		\$14.08	\$40.00		\$0.00	\$54.08
Pillsbury: Belt Serpentine (EL3): 25-060295 (1.000)		\$14.08				
Miscellaneous Parts 7050 - STRAND, MATTHEW (0.80)		\$0	\$40.00			
Labor Comments: Alternator belt ripping apart, repalced it						
Miscellaneous Labor			\$0			
Other					\$0	
48:Fuel System		\$7.97	\$128.50		\$0.00	\$136.47
Pillsbury: Drive Coupler: 23505249 (1.000)		\$6.70				
Pillsbury: Gasket Fuel Pump, Detroit Series 60: 23505248 (1.000)		\$1.27				
Miscellaneous Parts 7050 - STRAND, MATTHEW (2.57)		\$0	\$128.50			
Labor Comments: I got taken off this bus a couple times. Fuel pump leaking oil, replaced the gasket and coupler and sealed it with anerobic gasket maker.						
Miscellaneous Labor			\$0			
Other					\$0	
TF:Transmission Flush		\$204.84	\$105.50		\$0.00	\$310.34
Pillsbury: Filter Kit Transmission Allison (Short Filter): 7741XE (1.000)		\$33.20				
Pillsbury: Fluid ATF (Synthetic) Bulk Quart: ATF Synthetic Bulk (28.000)		\$171.64				
Miscellaneous Parts 7050 - STRAND, MATTHEW (2.11)		\$0	\$105.50			
Labor Comments: Trans flush and filter replacement.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$576.41	\$439.00	\$0	\$0	<u>\$1,015.41</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 812,021.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213102	09/11/2017	09/13/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$127.50		\$0.00	\$127.50
Miscellaneous Parts		\$0				
9127 - JACOBS, ANDREW (2.55)			\$127.50			
Labor Comments: recharge the a/c ssystem and steam off clutch						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$127.50	\$0	\$0	\$127.50

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,053.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213541	10/05/2017	10/06/2017	Closed	0.00	

Description: polish

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$315.00		\$0.00	\$315.00
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (6.30)			\$315.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$315.00	\$0	\$0	\$315.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,053.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213563	10/06/2017	10/09/2017	Closed	0.00	

Description: paint door will bring

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$306.00		\$0.00	\$306.00
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (6.12)			\$306.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$306.00	\$0	\$0	\$306.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,053.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213672	10/12/2017	10/13/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$12.75	\$72.50		\$0.00	\$85.25
Pillsbury: Electrode Ignition		\$12.75				
dw-thermo wabasto: WE14846D (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$72.50			

5/7/2019

Work Order Detail

Other						\$0	
PMI:Preventative Maintenance Inspection	\$0	\$0				\$0.00	\$0.00
Miscellaneous Parts	\$0						
7050 - STRAND, MATTHEW				\$0.00			
(0.00)							
Labor Comments: serviced the bus							
Miscellaneous Labor				\$0			
Other						\$0	
	\$0	\$109.54	\$427.50		\$0	\$0	<u>\$537.04</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,569.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213873	10/27/2017	10/30/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
75:Windows/windshields		\$0	\$26.50		\$0.00	\$26.50

Maintenance Requested: 60633 - 10/23/2017 - see comments

- Requestor Notes:
1. Power plug closest to the dash not working
 2. Driver's side last window is not closing tight
 3. Curbside, 4th window fogged up

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$26.50			
(0.53)						

Labor Comments: Shut the windows

Checked the outlet, there is power on both outlets.

Will see about changing the fogged up window.

Miscellaneous Labor			\$0			
Other					\$0	

	\$0	\$0	\$26.50	\$0	\$0	<u>\$26.50</u>
--	-----	-----	---------	-----	-----	----------------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,569.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
213929	10/31/2017	11/01/2017	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$40.00	\$40.00

Repair, Inv. # 2786162

22:Tires		\$1,500.00	\$149.00		\$0.00	\$1,649.00
----------	--	------------	----------	--	--------	------------

Pillsbury: Tire, Steer, Toyo

M144: 315/80R22.5 (4.000)

Miscellaneous Parts

7050 - STRAND, MATTHEW

(2.98)

Labor Comments: New Drive Tires

Miscellaneous Labor			\$0			
Other					\$0	

	\$0	\$1,500.00	\$149.00	\$0	\$40.00	<u>\$1,689.00</u>
--	-----	------------	----------	-----	---------	-------------------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Work Order Detail

<u>WO #</u>	<u>Open Date</u>	Recall:	Campaign #	<u>Status</u>	<u>Downtime</u>	Date:	<u>Accident</u>
214167	11/16/2017		11/17/2017	Closed	0.00		

Description: Charging, Lighting, Body Misc

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging		\$347.71	\$194.00		\$0.00	\$541.71
Pillsbury: Oil Bulk in Quarts:		\$6.87				
Oil 15W-40 Bulk (3.000)						
Pillsbury: Battery 1400CCA		\$340.84				
Top Post Heavy Duty						
Workaholic: 8D-MHD(7271)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$194.00			
(3.88)						

Labor Comments: batteries tested out to recharge them, charged each one for an hour. both tested out bad and replace. Replaced both baterries.

Miscellaneous Labor			\$0			
Other					\$0	
36:Lighting		\$78.02	\$49.00		\$0.00	\$127.02
Pillsbury: Ballast Interior Light		\$78.02				
EL3: 07-07-1040 (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$49.00			
(0.98)						

Labor Comments: Interior light was out, tried bulb first. Ballast was bad, replaced it.

Miscellaneous Labor			\$0			
Other					\$0	
72:Body Misc		\$0	\$76.00		\$0.00	\$76.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (1.52)			\$76.00			

Labor Comments: Fixed floor hatch trim.

Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$425.73	\$319.00	\$0	\$0
						<u>\$744.73</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

<u>WO #</u>	<u>Open Date</u>	Recall:	Campaign #	<u>Status</u>	<u>Downtime</u>	Date:	<u>Accident</u>
214362	11/29/2017		12/04/2017	Closed	0.00		

Description: air not building

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$12.99	\$306.00		\$0.00	\$318.99
Pillsbury: Governor, D2:		\$12.99				
H284358 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (6.12)			\$306.00			

Work Comments: 49 -- Air pressure woldn't build above 50 psi for the front and 90 for the rear.

Labor Comments: 49 -- Air pressure woldn't build above 50 psi for the front and 90 for the rear. ----

Removed and replaced the governor. Had to turn up the set point.

Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$12.99	\$306.00	\$0	\$0
						<u>\$318.99</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

5/7/2019

Work Order Detail

<u>WO #</u> 214569	<u>Open Date</u> 12/12/2017	<u>Close Date</u> 12/13/2017	<u>Status</u> Closed	<u>Downtime</u> 0.00	<u>Accident</u>
-----------------------	--------------------------------	---------------------------------	-------------------------	-------------------------	-----------------

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$160.50		\$0.00	\$160.50
Miscellaneous Parts		\$0				
9106 - MARIN RODRIGUEZ, CLAUDIO (3.21)			\$160.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$160.50	\$0	\$0	<u>\$160.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u> 214587	<u>Open Date</u> 12/13/2017	<u>Close Date</u> 12/14/2017	<u>Status</u> Closed	<u>Downtime</u> 0.00	<u>Accident</u>
-----------------------	--------------------------------	---------------------------------	-------------------------	-------------------------	-----------------

Description: rubber axle bumpers

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$33.66	\$116.00		\$0.00	\$149.66
Work Comments: 21 -- Rubber bumpers for drive and tag axles are shot.						
Pillsbury: Stop-Bump, Drive		\$33.66				
Axle: 12-03-1025 (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (2.32)			\$116.00			
Labor Comments: 21 -- Rubber bumpers for drive and tag axles are shot. ----- Removed and replaced all the bad rubber bumpers.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$33.66	\$116.00	\$0	\$0	<u>\$149.66</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u> 214837	<u>Open Date</u> 12/28/2017	<u>Close Date</u> 12/29/2017	<u>Status</u> Closed	<u>Downtime</u> 0.00	<u>Accident</u>
-----------------------	--------------------------------	---------------------------------	-------------------------	-------------------------	-----------------

Description: Air System

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
49:Air System		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.00)			\$0.00			
Labor Comments: Drained air from the system. Added alcohol to the system Creeped and checked fluids.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$0	\$0	\$0	<u>\$0.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u> 215060	<u>Open Date</u> 01/11/2018	<u>Close Date</u> 01/17/2018	<u>Status</u> Closed	<u>Downtime</u> 0.00	<u>Accident</u>
-----------------------	--------------------------------	---------------------------------	-------------------------	-------------------------	-----------------

Work Order Detail

<u>Detail</u>		Description: on Board charger not working.		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
31:Charging				\$0		\$311.00		\$0.00	\$311.00
Work Comments: 31 -- On board charger not working.									
<u>Miscellaneous Parts</u>				<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
0081 - WOLF, PATRICK (6.22)						\$311.00			
Labor Comments: 31 -- On board charger not working. ----- Removed and replaced the charger with a (Good Used) one we had out of 522.									
<u>Miscellaneous Labor</u>				<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Other						\$0		\$0	
				\$0	\$0	\$311.00	\$0	\$0	<u>\$311.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 813,712.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
215311	01/25/2018	01/30/2018	Closed	0.00	

<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
CR:Creep				\$149.00		\$0.00	\$149.00
<u>Miscellaneous Parts</u>				<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Total</u>
7050 - STRAND, MATTHEW (2.98)						\$149.00	
<u>Miscellaneous Labor</u>				<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Total</u>
Other						\$0	
				\$0	\$0	\$149.00	<u>\$149.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,270.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216196	03/23/2018	03/27/2018	Closed	0.00	

Description: Brake Lights

<u>Detail</u>		<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting			\$10.45	\$410.00		\$0.00	\$420.45

Maintenance Requested: 61945 - 03/22/2018 - Brake Lights are out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Pigtail, 3 Wire: 67090 (2.000)			\$3.12				
Pillsbury: Light Clearance Red: 1281369 (1.000)			\$7.33				
<u>Miscellaneous Parts</u>				<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Total</u>
7050 - STRAND, MATTHEW (8.20)						\$410.00	

Labor Comments: Both brake lights inop.

Tested brake switches, modules, swapped modules around. Narrowed it down to a short in the back of the harness. Cut the wire and got one brake light to work. So I knew it was from the left brake light to after the splice. Instead of cutting the harness apart I used a spare factory wire and wired the brake light in and they both work. Put everything back together.

Also dumped the wash stall water tanks on Saturday

<u>Miscellaneous Labor</u>				<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
Other						\$0		\$0	
				\$0	\$10.45	\$410.00	\$0	\$0	<u>\$420.45</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,365.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216459	04/10/2018	04/23/2018	Closed	0.00	

Description: A/C and Webasto, Radio Install

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$288.29	\$224.50		\$0.00	\$512.79
Pillsbury: Hub: 16J-2-12 (1.000)		\$116.21				
Pillsbury: Carrier Front Seal Kit O5G A/C Compressor MCID4500: 16L-2-112 (1.000)		\$95.33				
Pillsbury: Nozzle (0.65 GPH 80H)wabasto: WE470716 (3.000)		\$55.02				
Pillsbury: Electrode Ignition dw-thermo wabasto: WE14846D (1.000)		\$21.73				
Miscellaneous Parts 7050 - STRAND, MATTHEW (4.49)		\$0	\$224.50			
Labor Comments: New A/C front seal. Cleaned the webasto and replaced the nozzle and sparker.						
Miscellaneous Labor			\$0			
Other					\$0	
Radio/DVD/PA:Radio repair 619\$ radio install (1.000)		\$619.00	\$36.00		\$0.00	\$655.00
		\$619.00				
Part Comments: Kit includes: *HY-MD782U-1 UHF DMR Mobile Radio *K-794 Line kit, very thick mount *K332 Ground plane disc 6" dia, 3/8" mounting *C-BNC58-CR connector, BNC-Male, R858, crimp *B4502NS Antenna, UHF, no ground plane with spring *HY-IGNITION SENSE accessory plug, ignition sense, hytera MD752/MD662 (professional wireless)						
Miscellaneous Parts 9130 - PADELFFORD, ERIC (0.72)		\$0	\$36.00			
Labor Comments: Matt and i installed new two way radio						
7050 - STRAND, MATTHEW (2.18)			\$0.00			
Labor Comments: Radio Install.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$907.29	\$260.50	\$0	\$0	\$1,167.79

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,857.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216683	04/24/2018	05/02/2018	Closed	0.00	

Description: A/C Prep, Axle Gasket

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
12:Axles (rear)		\$9.17	\$0		\$0.00	\$9.17
Maintenance Requested: 62135 - 04/22/2018 - righth rear oil hub seal leaking						
Requestor Notes:						
Technician Response:						
Maint Req Status: Completed						
Pillsbury: Gasket Rear Axle		\$3.77				

Flange: GKT1008 (1.000)						
Pillsbury: Oil Gear Synthetic:		\$5.40				
Oil Gear 75W-90 BULK in quarts (1.000)						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(1.22)						
Labor Comments: Replaced the Right side drive axle gasket						
Miscellaneous Labor			\$0			
Other				\$0		
12:Axles (rear)		\$0	\$0	\$0.00		\$0.00
Maintenance Requested: 62130 - 04/22/2018 - see comments						
Requestor Notes: Oil leaking from drive axle and tag axle driver side						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(0.00)						
Miscellaneous Labor			\$0			
Other				\$0		
41:A/C & Heating		\$0	\$0	\$0.00		\$0.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(1.58)						
Labor Comments: Cleaned the condensor and evaporator and checked brushes						
Miscellaneous Labor			\$0			
Other				\$0		
		\$0	\$9.17	\$0	\$0	\$9.17

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 815,857.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216769	04/30/2018	05/08/2018	Closed	0.00	

Description: A/C

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$36.96	\$0		\$0.00	\$36.96
Pillsbury: Belt, A/C, MCI, E-Coach: 08-27-1029 (1.000)		\$36.96				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW			\$0.00			
(2.40)						
Labor Comments: belt was slipping and adjstued the air gap on the clutch and checked for leaks on the a/c compressor.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$36.96	\$0	\$0	\$0	\$36.96

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 816,262.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
216901	05/08/2018	05/11/2018	Closed	0.00	

Description: A/C not working

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
267 - Superglass Windshield					\$40.00	\$40.00
Repair, Inv. # 2786542						

41:A/C & Heating	\$136.89	\$364.00	\$0.00	\$500.89
Maintenance Requested: 62203 - 05/03/2018 - see comments				
Requestor Notes: A/C is not functioning back door (engine compartment) flies open				
Technician Response: Maint Req Status: Completed				
Pillsbury: Carrier Front Seal	\$95.33			
Kit O5G A/C Compressor				
MCID4500: 16L-2-112 (1.000)				
Pillsbury: Freon R134A per	\$41.56			
Lb.: R134A (17.835)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (7.28)		\$364.00		
Labor Comments: 41 -- A/C is not functioning ---- Closed off the A/C compressor. Reclaimed the freon. Removed the clutch assy. and the front seal. Cleaned up everything. Installed a new seal assy. Vacuummeddown the compressor. Opened the valves back up and filled the system back up with freon.				
72 -- back door (engine compartment) flies open ---- the release lever needs to be pulled back out in order to hold the door shut.				
Miscellaneous Labor		\$0		
Other			\$0	
HUB:Hub Service	\$0.57	\$141.50	\$0.00	\$142.07
Work Comments: HUB -- Hub Service				
Pillsbury: Oil Gear 80W-140	\$0.57			
Synthetic Mobil Delvac: Gear				
oil 80W-140 in pints (1.500)				
Miscellaneous Parts	\$0			
0081 - WOLF, PATRICK (2.83)		\$141.50		
Labor Comments: HUB -- Hub Service ---- Drained then refilled with new gear lube, the tag and steering hubs				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$137.46	\$505.50	\$0
			\$40.00	<u>\$682.96</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 816,416.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217391	06/07/2018	06/13/2018	Closed	0.00	

Description: DOT,Hub leak,tire,CFR,suspension

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
12:Axles (rear)		\$9.17	\$126.50		\$0.00	\$135.67
Work Comments: 12 -- Right drive axle leaking Gear oil						
Pillsbury: Gasket Rear Axle		\$3.77				
Flange: GKT1008 (1.000)						
Pillsbury: Oil Gear Synthetic:		\$5.40				
Oil Gear 75W-90 BULK in						
quarts (1.000)						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (2.53)			\$126.50			
Labor Comments: 12 -- Right drive axle leaking Gear oil ---- Pulled the axle out. Installed a new axle gasket and 2 new cones. Torqued to specs.						
9461 - BRIERCLIFFE,			\$0.00			
WILLIAM (0.00)						
Miscellaneous Labor			\$0			
Other					\$0	
21:Suspension		\$0	\$494.00		\$0.00	\$494.00
Work Comments: 21 -- Suspension = Drive axle v-Link shot						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (7.18)			\$359.00			
Labor Comments: 21 -- Suspension = Drive axle v-Link shot ---- Put up on lifts. and Jack stands.						

Work Order Detail

Pulled the old v-link out and installed a new one. Had to re tape one of the 3/4 " bolt holes.

9461 - BRIERCLIFFE, WILLIAM (2.70)		\$135.00			
Miscellaneous Labor		\$0			
Other				\$0	
22:Tires		\$0	\$137.00	\$0.00	\$137.00
	Work Comments: 22 -- Tire leaking at the valve stem.				
Miscellaneous Parts		\$0			
0081 - WOLF, PATRICK (1.39)		\$69.50			
	Labor Comments: 22 -- Tire leaking at the valve stem. ---- Pulled the tire off the us. Dismounted the tire and installed a new valve stem. Mounted back on the bus and torqued the lug nuts to 450 LBS.				
9461 - BRIERCLIFFE, WILLIAM (1.35)		\$67.50			
Miscellaneous Labor		\$0			
Other				\$0	
CFR:Coolant Filter Replacement	\$32.01	\$31.50		\$0.00	\$63.51
	Work Comments: CFR -- Coolant filter replacement.				
Pillsbury: Filter Coolant w/Full Charge MCI D4500 w/ Detroit 60 Series Engine: 4088 (1.000)	\$32.01				
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (0.63)		\$31.50			
	Labor Comments: CFR -- Coolant filter replacement. ---- Removed and replaced the coolant filter.				
Miscellaneous Labor		\$0			
Other				\$0	
DO:DOT Inspection	\$2.00	\$76.50		\$0.00	\$78.50
	Work Comments: DOT -- DOT Inspection				
DOT sticker \$2.00 (1.000)	\$2.00				
Miscellaneous Parts	\$0				
0081 - WOLF, PATRICK (1.53)		\$76.50			
	Labor Comments: DOT -- DOT Inspection ---- Performed the DOT inspection as per the attached sheet.				
9461 - BRIERCLIFFE, WILLIAM (20.47)		\$0.00			
Miscellaneous Labor		\$0			
Other				\$0	
	\$0	\$43.18	\$865.50	\$0	\$0
					<u>\$908.68</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 816,768.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO#</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217585	06/25/2018	06/26/2018	Closed	0.00	

Description: Maintenance Requests

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
11:Axles (front)		\$0	\$10.00		\$0.00	\$10.00

Maintenance Requested: 62508 - 06/20/2018 - Rt front hub oil leaking-drivers side moulding lse

Requestor Notes: passenger side front hub oil seal is leaking
moulding behind the front drivers side wheel at bottom of bus is barely hanging on

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts	\$0				
7050 - STRAND, MATTHEW (0.20)		\$10.00			

Labor Comments: Checked the front hubs, Both full of fluid. Cleaned them off.
Snapped back on the moulding the best I could, needs to go to the body shop.

Miscellaneous Labor		\$0			
Other				\$0	

\$0 \$0 \$10.00 \$0 \$0 \$10.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 817,804.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217847	07/16/2018	07/17/2018	Closed	0.00	

Description: Front Leveling Valve

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
21:Suspension		\$6.28	\$62.50		\$0.00	\$68.78

Maintenance Requested: 62628 - 07/14/2018 - the bus is stuck in kneel mode

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Valve ASM, Leveling,
RH: 12-06-1028 (1.000)

\$6.28

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(1.25)

\$62.50

Labor Comments: Front leveling valve rubber holder broke off. Put new one on.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$6.28 \$62.50 \$0 \$0 \$68.78

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 818,302.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
217996	07/25/2018	07/25/2018	Closed	0.00	

Description: Lighting

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
36:Lighting		\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 62698 - 07/24/2018 - lav light is out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(0.00)

\$0.00

Labor Comments: needs new microswitch, rigged it so it would work

Miscellaneous Labor

\$0

Other

\$0

36:Lighting \$42.56 \$267.50 \$0.00 \$310.06

Maintenance Requested: 62662 - 07/19/2018 - left side turn signal-mid out

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Non LED
Amber Side Marker/Turn MCI
EL3: 07-07-1003 (2.000)

\$42.56

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW
(5.35)

\$267.50

Labor Comments: replaced 2 side marker lamps

Miscellaneous Labor

\$0

Other

\$0

\$0 \$42.56 \$267.50 \$0 \$0 \$310.06

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 818,884.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218089	07/30/2018	08/01/2018	Closed	0.00	

Description: Leaking Hub, Air Filter

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
12:Axles (rear)		\$56.65	\$46.50		\$0.00	\$103.15

Maintenance Requested: 62724 - 07/27/2018 - leaking rear hub

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Oil Bulk in Quarts:

\$16.56

Oil 15W-40 Bulk (8.000)

Pillsbury: Oil Gear 80W-140

\$0.38

Synthetic Mobil Delvac: Gear

oil 80W-140 in pints (1.000)

Pillsbury: Hub Cap w/ Lube

\$39.71

Window Steer Axle MCI

D4500: 343-4176 (1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$46.50

(0.93)

Labor Comments: Replaced the hub cap that was leaking. Refilled with 80-140.

Checked engine oil found it 8 qts low.

Miscellaneous Labor

\$0

Other

\$0

79:Lavatory

\$0

\$0

\$0.00

\$0.00

Maintenance Requested: 62723 - 07/27/2018 - bathroom stinks

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: Next time let the Wash Stall know.

Miscellaneous Labor

\$0

Other

\$0

AF:Air Filter Replacement

\$33.98

\$0

\$0.00

\$33.98

Pillsbury: Filter Air EL3: 6774

\$33.98

(1.000)

Miscellaneous Parts

\$0

7050 - STRAND, MATTHEW

\$0.00

(0.00)

Labor Comments: Replaced air filter.

Miscellaneous Labor

\$0

Other

\$0

\$0 \$90.63 \$46.50 \$0 \$0 \$137.13

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 819,088.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218142	08/01/2018	08/03/2018	Closed	0.00	

Description: PMI

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

Technician Response:
 Maint Req Status: Completed

Pillsbury: Valve, Electric \$164.99
 Unloader: 10610656 (1.000)
 Pillsbury: Coil 24 Volt A/C \$55.75
 Comp. Unloader Valve MCI
 D4500: 16L-10-107 (1.000)
 Pillsbury: Freon R134A per
 Lb.: R134A (10.000) \$33.30
 Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$153.00
 (3.06)

Labor Comments: A/C not workng sufficently. Found leak at the one unloader base. Replaced the base and the electric unloader. Added 10 pounds of freon.

Miscellaneous Labor \$0
 Other \$0

\$0 \$254.04 \$222.00 \$0 \$0 \$476.04

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115 License Plate:

Miles: 819,925.0

Location: PBG Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218570	08/22/2018	08/28/2018	Closed	0.00	

Description: Body Misc

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$0	\$1.00		\$0.00	\$1.00

Maintenance Requested: 62876 - 08/20/2018 - See Notes

Requestor Notes: Driver Side 1st & Middle bay doors trim pieces are loose
 Doorside 1st seat floor side tile peeled off.

Technician Response:
 Maint Req Status: Completed

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$1.00
 (0.02)

Labor Comments: I glued the side piece inside up the other day. I let the body shop know about the baggage door trim pieces

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$1.00 \$0 \$0 \$1.00

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115 License Plate:

Miles: 820,284.0

Location: PBG Department: PBG5-Charter

Recall: Campaign # Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218626	08/24/2018	08/28/2018	Closed	0.00	

Description: FF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
01:Fluids		\$0	\$51.00		\$0.00	\$51.00

Miscellaneous Parts \$0
 7050 - STRAND, MATTHEW \$51.00
 (1.02)

Labor Comments: Checked fluids. took for test drive. Camshaft seal is leaking pretty bad.

Miscellaneous Labor \$0
 Other \$0

FF:Fuel Filter \$8.53 \$35.00 \$0.00 \$43.53
 Pillsbury: Filter Fuel: 3118 \$4.19
 (1.000)

Pillsbury: Filter, Fuel, MCI: 3120 (1.000)	\$4.34					
Miscellaneous Parts	\$0					
7050 - STRAND, MATTHEW (0.70)		\$35.00				
Labor Comments: FF						
Miscellaneous Labor		\$0				
Other					\$0	
	\$0	\$8.53	\$86.00	\$0	\$0	<u>\$94.53</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 820,462.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
218815	09/05/2018	09/10/2018	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$164.00		\$0.00	\$164.00
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (3.28)			\$164.00			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$164.00	\$0	\$0	<u>\$164.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 820,940.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219122	09/20/2018	09/25/2018	Closed	0.00	

Description: Bag Bay Handle

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
78:Doors Entrance / Exit		\$103.32	\$80.00		\$0.00	\$183.32
Maintenance Requested: 63085 - 09/19/2018 - see comment						
Requestor Notes: door side luggage door will not lock when driving down road it stays open						
Technician Response:						
Maint Req Status: Completed						
03-29-1232 bushing long (1.000)		\$10.54				
03-29-1168D handle (1.000)		\$92.78				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.60)			\$80.00			
Labor Comments: Bag bay handle was busted. Tried to use on from the junk bus. No go. Ordered one from C&J.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$103.32	\$80.00	\$0	\$0	<u>\$183.32</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 821,420.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219187	09/24/2018	09/24/2018	Closed	0.00	

Description: Heating, Air Drier

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$11.50		\$0.00	\$11.50
Maintenance Requested: 63121 - 09/22/2018 - see comments						
Requestor Notes: thermostat doesn't work properly in front. It keeps full heat on no matter the temp setting						
Technician Response:						
Maint Req Status: Completed						
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (0.23)			\$11.50			
Labor Comments: Heat valve for the driver was on. The control valve looks to have been rebuilt not to long ago.						
Miscellaneous Labor			\$0			
Other					\$0	
AD:Air Drier Service		\$165.48	\$123.50		\$0.00	\$288.98
Pillsbury: AD-IP Air Dryer Desiccant Cartridge Bendix: 109493BXR (1.000)		\$54.40				
Pillsbury: Purge Valve Repair Kit, AD-IP: K022105 (1.000)		\$77.16				
Pillsbury: Mounting Bracket Bendix AD-9 Air Dryer: 107695K (1.000)		\$33.92				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.47)			\$123.50			
Labor Comments: Rebuilt air drier. Went to take off the bracket the nut stripped on, ended up cutting bracket off and replacing it.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$165.48	\$135.00	\$0	\$0	<u>\$300.48</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 821,420.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219254	09/26/2018	09/28/2018	Closed	0.00	

Description: fix back dork damage

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$589.50		\$0.00	\$589.50
Miscellaneous Parts		\$0				
9105 - PEREZ-LAZARO, ARMANDO (11.79)			\$589.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$589.50	\$0	\$0	<u>\$589.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 825,400.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219870	10/25/2018	11/26/2018	Closed	0.00	

Description: service call,PMI, LOF

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
40:Engine		\$0	\$585.00		\$0.00	\$585.00

Maintenance Requested: 63408 - 10/24/2018 - bad engine oil leak
 Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0		
0081 - WOLF, PATRICK			\$585.00	
Labor Comments: 40 -- Bad engine oil leak ---- Steamed off the engine. ran the engine to find were the oil was coming from. Removed the air cleaner housing and all the intake pipes above the front of the engine. Opened the floor hatch. pulled both half's of the rocker off. cleaned up all around the seal area. Steamed off the rocker covers. Cleaned up the gaskets. Put new RTV in the corners. Torqued the cover bolts to specs. Put everything else back together.				
Miscellaneous Labor			\$0	
Other				\$0
40:Engine		\$0	\$29.00	\$0.00 \$29.00

Maintenance Requested: 63406 - 10/24/2018 - noticed an old & new puddle of oil once bus moved

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0		
0081 - WOLF, PATRICK (0.58)			\$29.00	
Labor Comments: 40 -- Noticed an old & a new puddle of oil once the bus was moved. ---- Most of the work done on detail 40 above.				
Miscellaneous Labor			\$0	
Other				\$0
43:Cooling		\$339.29	\$456.50	\$0.00 \$795.79

Work Comments: 43 -- Water pump leaking

R23539929 water pump \$339.29

(1.000)

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (9.13) \$456.50

Labor Comments: 43 -- Water pump leaking ---- Removed and replaced the water pump.

Miscellaneous Labor \$0

Other \$0

95:Service Calls \$0 \$50.00 \$0.00 \$50.00

Miscellaneous Parts \$0

9461 - BRIERCLIFFE, WILLIAM (1.00) \$50.00

Labor Comments: Driver had called saying the bus felt as though it was bucking, swapped it out with 5525, driving 526 back i noticed on decel that once it down shifted from 3rd to 2nd that the bus would buck forward and the driver also mentioned that the red trans light was on at one point.

Miscellaneous Labor \$0

Other \$0

LOF:Lube, Oil, Filter \$0 \$300.00 \$0.00 \$300.00

Work Comments: LOF -- Lube, Oil, Filter

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (6.00) \$300.00

Labor Comments: LOF -- Lube, Oil, Filter ---- Performed the lof as per the attached sheet.

Miscellaneous Labor \$0

Other \$0

PMI:Preventative Maintenance Inspection \$0 \$138.50 \$0.00 \$138.50

Work Comments: PMI -- Preventative Maintenance Inspection.

Headlights: high/low beam:Pass Horn:Pass Leaks:Pass

Turn signals:Pass

Miscellaneous Parts \$0

0081 - WOLF, PATRICK (2.77) \$138.50

Labor Comments: PMI -- Preventative Maintenance Inspection. ----- Performed the PMI as per the attached sheet.

Miscellaneous Labor \$0

Other \$0

PU:Pick-up & Delivery \$0 \$66.50 \$0.00 \$66.50

Miscellaneous Parts \$0

0150 - BERNARDY, ADAM \$66.50

(1.33)

Work Order Detail

Labor Comments: Drove 5522 up to air port and switched it out for this one. brought 5526 back to the shop do to check engine light and def light.

Miscellaneous Labor	\$0						
Other						\$0	
	\$0	\$339.29	\$1,625.50	\$0	\$0		<u>\$1,964.79</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 825,261.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
219999	11/01/2018	11/06/2018	Closed	0.00	

Description: Webasto Tune Up

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
41:A/C & Heating		\$0	\$135.50		\$0.00	\$135.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.71)			\$135.50			
Labor Comments: Webasto Tune Up						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$135.50	\$0	\$0	<u>\$135.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 825,400.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220034	11/05/2018	11/06/2018	Closed	0.00	

Description: Transmission

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$0	\$59.00		\$0.00	\$59.00
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.18)			\$59.00			
Labor Comments: Checked codes found codes for output sensor. Replaced the output sensor with used one from a previous tranny. Took for test drive, still shifted a little hard. Reset the Fast Adaptive and Unadaptive shifts. Started to shift better as I went thru the gears. Checked Transmission Fluid.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$59.00	\$0	\$0	<u>\$59.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 826,202.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220298	11/15/2018	11/19/2018	Closed	0.00	

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
79:Lavatory		\$0	\$21.00		\$0.00	\$21.00

Maintenance Requested: 63520 - 11/10/2018 - lever for holding tank was frozen-not dumped

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Work Order Detail

Miscellaneous Parts	\$0						
0081 - WOLF, PATRICK (0.42)		\$21.00					
Labor Comments: 79 -- lever for holding tank was frozen-not dumped ---- Dumped the toilet before I started to do the engine work.							
Miscellaneous Labor		\$0					
Other						\$0	
	\$0	\$0	\$21.00	\$0	\$0		<u>\$21.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 826,339.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
220943	12/13/2018	12/19/2018	Closed	0.00	

Description: repair and pait two doors back with molding winged

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
70:Body Sheet Metal		\$0	\$1,027.50		\$0.00	\$1,027.50
Miscellaneous Parts		\$0				
9106 - MARIN RODRIGUEZ, CLAUDIO (20.55)			\$1,027.50			
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$1,027.50	\$0	\$0	<u>\$1,027.50</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 826,339.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221037	12/18/2018	01/03/2019	Closed	0.00	

Description: Creep

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$80.26	\$106.00		\$0.00	\$186.26
04-02-1002 brake chamber (1.000)		\$80.26				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (2.12)			\$106.00			
Labor Comments: Replaced the left front chamber, it was rotting out.						
Miscellaneous Labor			\$0			
Other					\$0	
20:Steering		\$0	\$182.50		\$0.00	\$182.50
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (3.65)			\$182.50			
Labor Comments: Steer tires wearing on the inside edge. Found the toe was 1/4 inch out when it should be 1/16-1/8 in. Lubed and broke the tie rod tube loose. Adjusted to 1/16 inch in.						
Miscellaneous Labor			\$0			
Other					\$0	
CR:Creep		\$60.00	\$82.50		\$0.00	\$142.50
Pillsbury: Wiper Blade MCI EL3: 03-34-1177 (2.000)		\$60.00				
Miscellaneous Parts		\$0				
7050 - STRAND, MATTHEW (1.65)			\$82.50			
Labor Comments: Checked Fluids Changed wiper blades out Creeped bus and made list.						
Miscellaneous Labor			\$0			

Other \$0

\$0 \$140.26 \$371.00 \$0 \$0 \$511.26

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 827,588.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221638	01/17/2019	01/23/2019	Closed	0.00	

Description: hard shift

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$107.34	\$250.00		\$0.00	\$357.34
29544139 Sensor Assembly, Speed, Rear Output (1.000)		\$107.34				
Miscellaneous Parts		\$0				
0142 - GALLINGER, CHAD (5.00)			\$250.00			

Labor Comments: Had code 22-16 and 23-12 replaced out put speed sensor cleaned connections at shift selector , TCM and VIM road tested o/k

Miscellaneous Labor \$0
Other \$0

\$0.00 \$107.34 \$250.00 \$0 \$0 \$357.34

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 828,028.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
221977	02/01/2019	02/01/2019	Closed	0.00	

Description: Brake line broken

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
13:Brakes		\$38.75	\$111.50		\$0.00	\$150.25

Maintenance Requested: 64229 - 01/29/2019 - pass side front air line leaking

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Hose ASM, Front \$38.75
Brakes E-Coach: 04-20-1040 (1.000)

Part Comments: 13 --

Miscellaneous Parts \$0
0081 - WOLF, PATRICK (2.23) \$111.50

Labor Comments: 13 -- Right front brake hose broken ---- Removed and replaced the brake hose. tid all bake up again.

Miscellaneous Labor \$0
Other \$0

\$0 \$38.75 \$111.50 \$0 \$0 \$150.25

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 828,518.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222203	02/11/2019	02/15/2019	Closed	0.00	

Description: steering noise

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
---------------	------------------	--------------	--------------	--------------	--------------	--------------

Work Order Detail

20:Steering	\$0	\$69.00	\$0.00	\$69.00
Maintenance Requested: 64383 - 02/09/2019 - See comments.				
Requestor Notes: 1. Power steering makes a lot of grinding noises. 2. Driver-side window frosts over.				
Technician Response:				
Maint Req Status: Completed				
Miscellaneous Parts	\$0			
0142 - GALLINGER, CHAD (1.38)		\$69.00		
Labor Comments: checked steering topped off fluid test drove bus. no steering issues at this time adjusted fan to blow on window				
Miscellaneous Labor		\$0		
Other			\$0	
	\$0	\$0	\$69.00	\$0
			\$0	<u>\$69.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 830,803.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222619	02/27/2019	03/01/2019	Closed	0.00	

Description: Fuel door locked.

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
72:Body Misc		\$3.80	\$21.50		\$0.00	\$25.30
Maintenance Requested: 64476 - 02/16/2019 - Fuel door would not unlock - tried all 3 keys.						
Requestor Notes:						
Technician Response: 72 -- Fuel door would not unlock - tried all 3 keys.						
Maint Req Status: Completed						
Pillsbury: Holder cup w/ mounting screws black: TH2BLK (2.000)		\$3.80				
Miscellaneous Parts		\$0	\$21.50			
0081 - WOLF, PATRICK (0.43)						
Labor Comments: 72 -- Fuel door would not unlock - tried all 3 keys. ---- The fuel door unlock for me with the same key that opens the battery switch. Must have been frozen.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$3.80	\$21.50	\$0	\$0	<u>\$25.30</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 831,756.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
222722	03/05/2019	03/08/2019	Closed	0.00	

Description: service call

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
95:Service Calls		\$0	\$85.00		\$0.00	\$85.00
Miscellaneous Parts		\$0				
9461 - BRIERCLIFFE, WILLIAM (1.70)			\$85.00			
Labor Comments: called out for service call for the tranny being stuck in second gear, went out in service truck and cleared the codes and got it up and moving.						
Miscellaneous Labor			\$0			
Other					\$0	
	\$0	\$0	\$85.00	\$0	\$0	<u>\$85.00</u>

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 834,497.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223705	04/12/2019	04/22/2019	Closed	0.00	

Description: Interior lights, fog lights

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
25:Transmission (Auto)		\$0	\$10.00		\$0.00	\$10.00

Maintenance Requested: 64954 - 03/26/2019 - Transmission cut off twice

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Miscellaneous Parts		\$0	\$10.00			
2138 - KREJCE, LUCAS						

Labor Comments: Pat drove had no issues, checked fluid and it was good

Miscellaneous Labor			\$0			
Other					\$0	

36:Lighting		\$21.15	\$58.50		\$0.00	\$79.65
-------------	--	---------	---------	--	--------	---------

Maintenance Requested: 65082 - 04/09/2019 - see comments

Requestor Notes: bathroom light switch does not work
isle lights out (one on each side)
fog lights dont work

Technician Response:

Maint Req Status: Completed

Pillsbury: Light Bulb 12 Volt		\$21.15				
Mini Fog/Driving: BP1255/H3 (3.000)						

Miscellaneous Parts		\$0	\$58.50			
2138 - KREJCE, LUCAS						

Labor Comments: Added two new florescent bulbs inside for isle walkway. Put two new low beam fog lights in and one new bright fog light in.

Miscellaneous Labor			\$0			
Other					\$0	

40:Engine		\$11.30	\$12.50		\$0.00	\$23.80
-----------	--	---------	---------	--	--------	---------

Maintenance Requested: 65104 - 04/12/2019 - Needs oil badly!

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Pillsbury: Oil Bulk in Quarts:		\$11.30				
Oil 15W-40 Bulk (5.000)						

Miscellaneous Parts		\$0	\$12.50			
2138 - KREJCE, LUCAS						

Labor Comments: Added just under 5 quarts of oil to bus

Miscellaneous Labor			\$0			
Other					\$0	

	\$0	\$32.45	\$81.00	\$0	\$0	\$113.45
--	-----	---------	---------	-----	-----	----------

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 835,542.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223907	04/20/2019	04/22/2019	Closed	0.00	

Description: coolant low

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
43:Cooling		\$17.58	\$67.50		\$0.00	\$85.08

Maintenance Requested: 65203 - 04/20/2019 - Shut down a couple times; check anti-freeze?

Requestor Notes:

Technician Response:

Maint Req Status: Completed

Work Order Detail

Pillsbury: Fluid Coolant Bulk \$17.58
 50/50 After Dilution: A/F 50/50
 Green BULK (3.000)
 Miscellaneous Parts \$0
 (1.35) \$67.50

Labor Comments: bring bus over and check coolant level is not in sight glass fill and found was 3.5 low test cap and is fine look for leaks and found none trailer hook up

Miscellaneous Labor \$0
 Other \$0

\$0 \$17.58 \$67.50 \$0 \$0 \$85.08

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 835,968.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
223967	04/22/2019		Completed	0.00	

Description: no heat

<u>Detail</u>	<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
95:Service Calls		\$0	\$51.50		\$0.00	\$51.50
Miscellaneous Parts (1.03)		\$0				
			\$51.50			

Labor Comments:

Miscellaneous Labor \$0
 Other \$0

\$0 \$0 \$51.50 \$0 \$0 \$51.50

5526: 1998 MCI EL3

VIN: 1M8TRMPA4WP 060115

License Plate:

Miles: 836,653.0

Location: PBG

Department: PBG5-Charter

Recall:

Campaign #

Date:

<u>WO #</u>	<u>Open Date</u>	<u>Close Date</u>	<u>Status</u>	<u>Downtime</u>	<u>Accident</u>
224167	04/30/2019		In Progress	0.00	

<u>Discounts</u>	<u>Parts</u>	<u>Labor</u>	<u>Tires</u>	<u>Other</u>	<u>Total</u>
	\$0	\$0		\$0.00	\$0.00

Maintenance Requested: 65225 - 04/24/2019 - foot throttle sticks. holds at 1500 rpm sometimes

Requestor Notes:

Technician Response:

Maint Req Status: Requested

Miscellaneous Parts	\$0					
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
20:Steering		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
FF:Fuel Filter		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
LOF:Lube, Oil, Filter		\$0	\$57.50		\$0.00	\$57.50
Miscellaneous Parts		\$0				

5/7/2019

Work Order Detail

0081 - WOLF, PATRICK (1.15)			\$57.50			
Miscellaneous Labor			\$0			
Other					\$0	
PMI:Preventative Maintenance Inspection		\$0	\$0		\$0.00	\$0.00
Headlights: high/low beam:Pass	Horn:Pass			Leaks:Pass		
Turn signals:Pass						
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
PS:Power Steering Flush		\$0	\$0		\$0.00	\$0.00
Miscellaneous Parts		\$0				
0081 - WOLF, PATRICK (0.00)			\$0.00			
Miscellaneous Labor			\$0			
Other					\$0	
		\$0	\$0	\$57.50	\$0	\$0
						<u>\$57.50</u>