

**PREVOST****COACH FINAL RECORD**

1505

STE-CLAIRE, QUEBEC CANADA G0R 2V0		H345	Serial No.: 2PCH33498FC712844	Coach No. #
Date: 2014/10/21	Customer:			Rev.:

PARTS NAME	PART NUMBER	MAKE / MODEL	SERIAL
DEF Pump Module Cooling STARTER	21576178		36449
DEF Dosing Valve Cooling			044404308845510044
Particle filter	21990643		726014269
Module ACM Cooling	21870087	#PIECE DU FOURNISSEUR: 21870087	14380407
Transmission	572138	P572138	1S6610405686
Engine	MOTEUR VOLVO H345	13J435P	0131080871
NOx Sensor Inlet Cooling	21636091		1435716266644E07
SCR Assy Cooling	21437514	VOLVO #21488930	T12400003845607
NOx Sensor Outlet Cooling	22014032	25898 CONTINENTAL AUTOMOTIVE SYST.INC #22014032	1435516336643E08
Air Filter El.	530206	REV B: NELSON DIVISION #71828N-20	
Alt 1 Motor	564119	REV A: ROBERT BOSCH #0124655079	280514 1819
Alt 2 Motor	564119	REV A: ROBERT BOSCH #0124655079	280514 1820
Belt	5060110	DAYCO #21-2112	
Belt	5061285	DAYCO, MARK IV INDUSTRIES CANADA #21-2212	
Rear Bellow	630260	GOODYEAR TIRE & RUBBER CO. #IR11-243	
Aux. Axle Tag	621808	MOULES ET MODELES PCM INC. #621808	E931
NEW TAG DATE	621808	MOULES ET MODELES PCM INC. #621808	150714
Front Axle	612386		P14231004F
Differential	621909	ELEGANCE	SLRS00782190
Air Dryer	21440978	VOLVO #(21440978)	
Steering Box	661137	ZF #8098 955 817	
Compressor Big	950002	BITZER #4NFCY-012 (REV.5)	2586888437
Condenser Motor 1	565881	EBMPAST #W3G300-ER40-75	0600110041434004OSHW
Condenser Motor 2	565881	EBMPAST #W3G300-ER40-75	0600110041434004OSGW
Condenser Motor 3	565881	EBMPAST #W3G300-ER40-75	0600110041434004OSEW
Condenser Motor 4	565881	EBMPAST #W3G300-ER40-75	0600110041434004OSIW
Evaporator Motor	564216	AMETEK ROTRON #150215-00	27AUG14004320
Dryer	950332	ALCO CONTROL #064904	
Seat Driver	864372	REV A: ISRI #86728-01/00	N/A
Wheel Chair Lift	864809	RICON #F9TF-DE022	531218
Radiator CAC	21576796	REV A: TITANX #1040254-CR	S221030352-C02147
Radiator 1	21576796	REV A: TITANX #1040254-CR	S181040254-CR02367
Radiator 2	21576796	REV A: TITANX #1040254-CR	S021003673-C01974
Tires		MICHELIN	76184
		B6D735CX3514, B6D735CX3514, B6D735CX3714,	
		B6D735CX3714, B6D735CX3814, B6D735CX3714,	
		B6D735CX3714, B6D735CX3714, B6D735CX3714	
Rolling Resistance Tires			LRRA -TOUS PNEUS RES 7.
Wheel Size		ACCURIDE	29300PK-SLV21
		ALCOA	894641DB
			894642DB
			894643DB

**PAINT SECTION**

PAINT COLOR	MAKE	NUMBER
BLACK (STD)	BASISLACK (STANDOX)	MIX 571
WHITE	BASISLACK (STANDOX)	PREV 000
SILVER	BASISLACK (STANDOX)	PREV 013
WHITE (ROOF PANEL)	IMRON ELITE (DUPONT)	832133 EF
CLEAR COAT	IMRON ELITE (DUPONT)	8430S

**INTERIOR TRIM SECTION**

MATERIAL	COLOR	NUMBER
----------	-------	--------

# PREVOST

## COACH FINAL RECORD

STE-CLAIRE, QUEBEC CANADA G0R 2V0	H345	Serial No.: 2PCH33498FC712844	Coach No. #
Date: 2014/10/21	Customer:		Rev.:

FLOOR COVERING	GERFLOR SHIP	0764
STEP NOSING	CALEDONIA	6602
FABRIC	NAH 184	864276
	NAE 184	864279
CARPET	N/A	

### OPTIONAL EQUIPMENT SECTION

- EXTERIOR DOOR LOCKS: KEY CODE: NS8718
- KEYLESS IGNITION SWITCH
- RICON WCL REMOVABLE...WITH CASSETTE
- AUX. PREHEATING SYSTEM READY
- OVERHEAD A/C SYSTEM
- DIFFERENTIAL RATIO 3.58
- ENGINE BRAKE ON D13 ENGINE
- ROAD SPEED GOVERNOR 71 MPH
- IDLE SHUTDOWN: 15 MINUTES
- FUEL PRO 382
- ULTIMATE ENG. WARRANTY 5Y/500,000 MI., PARTS & LABOR (UE-5514)
- ALLISON AUT. TRANS. WARRANTY/5 YEARS (W/O RET.)
- DURABRIGHT WHEEL PROTECTORS
- CHROME NUTS & HUBS
- SPLASH GUARDS BETWEEN DIFF. AND TAG AXLES
- QUICK FRONT KNEELING SUSP. (LOW & HIGH BUOY)
- CREDIT: REMOVE...FIRE SUPPRESSION & TIRES MONITORING SYSTEMS
- CHROME RAMCO ELECTRIC HEATED EXT. MIRROR W/CONVEX ON TOP
- ISRI 6832 DRIVER SEAT 3PT. SEAT BELT AIR SUSP. W/ARMRESTS
- SIRIUS SATELITE RADIO (AM/FM/CD) DASH INST.
- TWO EXTRA SPEAKERS IN DRIVER AREA
- MICROPHONE OUTLET IN L.H. MODESTY PANEL
- MICROPHONE STUDIO TYPE (P/N 900745)
- VIDEO SYSTEM COMPONENTRY WITH DVD
- 15" WIDE SCREEN MONITORS UNDER PARCEL RACK (EA) QT. 4
- CENTRAL 15" FIXED MONITOR
- AV. PANEL WITH AUDIO JACK, VGA PORT, USB MODESTY PANEL LH
- BACK-UP CAMEA READY
- QR CODES (PASSENGER ROWS INCL. SAFETY VIDEO & CORPORATE DVD)
- SINGLE 1800 WAT INVERTOR
- 120V OUTLET IN #1 FRONT LEFT PARCEL RACK
- 120V OUTLET IN MODESTY PANELS
- TOILET PEPER ROLL DISPENSER (900656)
- SINK COVERED WITH STEEL PLATE PAINTED BEIGE
- AUXILIARY HOLDING TANK
- PASSENGER SIDE WINDOW BLINDS
- CLOSED-TYPE PARCEL RACKS
- AMAYA SEATS WITH SEAT BELTS, 56 PASS., A2TEN
- NO CARD TABLE
- SEAT LAYOUT #: D360829-1-19-1
- WIRING AND BRACKETS ONLY FOR FRONT AND SIDE DESTINATION SIGN TO BE INSTALLED



California Highway Patrol  
1551 Benicia Road  
Vallejo, CA 94591  
Phone: (707) 648-4180  
Internationally Accredited Agency CHP407F/343A

Report Number: CAA133443122  
Inspection Date: 02/19/2019  
Start: 12:30 PM PT End: 1:42 PM PT  
Inspection Level: V - Terminal  
HM Inspection Type: None

USDOT: 260010  
MC/MX#: 165764  
State#: 322487

Phone#: (707)585-9110  
Fax#: (707)584-4713

Driver:  
License#: State:  
Date of Birth:  
CoDriver:  
License#: State:  
Date of Birth:

Location: 520 EAST TODD RD, SANTA  
ROSA,  
Highway:  
County: SONOMA

Milepost: Shipper: N/A

Origin: N/A  
Destination: N/A

Bill of Lading: N/A  
Cargo: N/A

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	PVOS	2015	CA	CP97317	1505	2PCH33498FC712844	53000		26672442

**BRAKE ADJUSTMENTS**

Axle #	1	2	3
Right	N/A	N/A	N/A
Left	N/A	N/A	N/A
Chamber	DISC	DISC	DISC

**VIOLATIONS:** No violations were discovered

**HazMat:** No HM transported

**Placard:**

**Cargo Tank:**

**Special Checks:** No data for special checks

**State Information:**

Beat/Sub Area: 5407; Odometer: 289879; File Code Number: 219371; Regulated Vehicle: Y; Pre-Cleared Vehicle: N; Fuel Type: D; Passenger Capacity: 56; Veh #1 Type: 64; WC Passenger Capacity: 2; Bus Type: 1; SPAB Cert: 02/19/2019

Report Prepared By: Badge #:  
S. Watson A13344

Copy Received By:

X

X









California Highway Patrol  
1551 Benicia Road  
Vallejo, CA 94591  
Phone: (707) 648-4180  
Internationally Accredited Agency CHP407F/343A

Report Number: CAA161170755  
Inspection Date: 02/27/2018  
Start: 1:00 PM PD End: 2:23 PM PD  
Inspection Level: V - Terminal  
HM Inspection Type: None

USDOT: 260010 Phone#: (707)585-9110 Driver: License#: State:  
MC/MX#: 165764 Fax#: (707)584-4713 Date of Birth: CoDriver: State:  
State#: 322487 License#: State:  
Date of Birth:  
Location: SANTA ROSA AREA Milepost: Shipper: N/A  
Highway: Origin: N/A Bill of Lading: N/A  
County: SONOMA Destination: N/A Cargo: EMPTY

**VEHICLE IDENTIFICATION**

Unit	Type	Make	Year	State	Plate	Equipment ID	VIN	GVWR	CVSA Existing	CVSA #
1	BU	PVOS	2015	CA	CP97317	1505	2PCH33498FC712844	53000		25221154

**BRAKE ADJUSTMENTS**

Axle #	1	2	3
Right	N/A	N/A	N/A
Left	N/A	N/A	N/A
Chamber	DISC	DISC	DISC

**VIOLATIONS:** No violations were discovered**HazMat:** No HM transported**Placard:****Cargo Tank:****Special Checks:** No data for special checks**State Information:**

Beat/Sub Area: 5407; Odometer: 230528; File Code Number: 219371; Regulated Vehicle: Y; Pre-Cleared Vehicle: N;  
Fuel Type: D; Passenger Capacity: 56; Veh #1 Type: 64; WC Passenger Capacity: 2; Bus Type: 1; SPAB Cert:  
02/27/2018

**Report Prepared By:**

I. N. DUOA

**Badge #:**

A16117

**Copy Received By:**

X \_\_\_\_\_

X \_\_\_\_\_



# Vehicle Inspection Report

UNIT# 1505 DATE 10-2-19 MILEAGE 347,181

OK DEF

- ☐ 1. Entrance door, operation, markings, hand rails
- ☐ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☐ 3. Horns- air and electric
- ☐ 4. Drivers seat- mounting, adjustment, seat belt
- ☐ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☐ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☐ 7. Low air warning- audible and or visual 60 psi min
- ☐ 8. Air tanks- drain, test check valves, perform split system test
- ☐ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☐ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☐ 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☐ 13. Windows- cracks, mounting, leaks, labeling
- ☐ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☐ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☐ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☐ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☐ 18. Interior lighting and markings
- ☐ 19. Luggage bays- latches, handles, door operation, lighting
- ☐ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☐ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☐ 22. Engine accessories- mounting, cables, hoses, function
- ☐ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☐ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☐ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ 26. Cooling system- leaks radiator, hoses, miter box, fan clutch, coolant level
- ☐ 27. Air system overall- air dryer, valves, lines, hoses
- ☐ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☐ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☐ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☐ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☐ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☐ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☐ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☐ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☐ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☐ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☐ 38. Wheelchair lift- operation, safetys, markings, leaks, fluid level, cleanliness

REPLACE LH REAR REAR REFLECTOR

REPLACE BROKEN CHUMP

Notes:

Mechanic:

*[Signature]*

Signature:

*[Signature]*

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

# VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 10-4-19 MILEAGE: 347,181 MECHANIC: J. A. B. J.

## ITEMS REPAIRED OR REPLACED

### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACES LEAKING & BROKEN COOLANT CLAMP  
WITH NEW ONE

REPLACES LH REAR ~~LOW~~ LOWER RED REFLECTOR  
WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

*James A. B. J.*

# Vehicle Inspection Report

UNIT# 1505 DATE 9-23-19 MILEAGE 344020

OK DEF

- ☒ 1. Entrance door, operation, markings, hand rails
- ☒ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ 3. Horns- air and electric
- ☒ 4. Drivers seat- mounting, adjustment, seat belt
- ☒ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ 7. Low air warning- audible and or visual 60 psi min
- ☒ 8. Air tanks- drain, test check valves, perform split system test
- ☒ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ 12. Windshields, wipers, squirter, defrosters, sun shades, mirrors
- ☒ 13. Windows- cracks, mounting, leaks, labeling
- ☒ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ 16. HVAC- function, fans, motor brushes, filters leaks
- ☒ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ 18. Interior lighting and markings
- ☒ 19. Luggage bays- latches, handles, door operation, lighting
- ☒ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ 22. Engine accessories- mounting, cables, hoses, function
- ☒ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ 27. Air system overall- air dryer, valves, lines, hoses
- ☒ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheel chair lift- operation, safety, markings, leaks, fluid level, cleanliness

CLEANED HVAC UNIT &  
OIL FILTERS

Notes:

Mechanic:

Timmes

Signature:

James D. Belfrage

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 9.23.19 MILEAGE: 344,020 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

CLEANED ENTIRE HVAC UNIT DRIVERS SIDE  
CLEANED ALL A/C FILTERS

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

JAMES C. BRYAN

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 8-29-19 MILEAGE: 337,938 MECHANIC: JAMES / CREW

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED 3 COOLANT HOSE CLAMPS WITH NEW ONES

DRAINED COOLANT OLD MUSTY WATER ADDED NEW REPLACED DRAIN PLUG ON COOLANT REPLACED WITH NEW ONE

REPLACED WATER PUMP BELT WITH NEW ONE

REPLACED LH TAG TIRE WITH NEW ONE

Recharged A/C SYSTEM - (CREW)

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James O. Bryan

# Vehicle Inspection Report

UNIT# 1505 DATE 8-16-19 MILEAGE 336,084

OK DEF

- ☒ 1. Entrance door, operation, markings, hand rails
- ☒ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ 3. Horns- air and electric
- ☒ 4. Drivers seat- mounting, adjustment, seat belt
- ☒ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ 7. Low air warning- audible and or visual 60 psi min
- ☒ 8. Air tanks- drain, test check valves, perform split system test
- ☒ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ 12. Windshields, wipers, squirts, defrosters, sun shades, mirrors
- ☒ 13. Windows- cracks, mounting, leaks, labeling
- ☒ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ 16. HVAC- function, fans, motor brushes, filters leaks
- ☒ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ 18. Interior lighting and markings
- ☒ 19. Luggage bays- latches, handles, door operation, lighting
- ☒ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ 22. Engine accessories- mounting, cables, hoses, function
- ☒ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ 27. Air system overall- air dryer, valves, lines, hoses
- ☒ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

REPLACE HIGH BEAM  
DRIVER SIDE

FILL  
WINDSHIELD  
WATER  
FLUID  
RESERVOIR

OK OIL & FILTER  
CHANGE

Tube FRONT SUSPENSION

Notes:

Mechanic:

JAMES

Signature:

James C. Bringham

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 8-16-19 MILEAGE: 336,084 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

Lubed Front Suspensions  
Cleaned All A/C Filters  
Drained Oil Added New Replaced Oil Filters with  
New ones (2) #1791 (1) #1660  
Filled Windshield Washer Fluid Reservoir

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

*James A. Bryan*



# Vehicle Inspection Report

UNIT# 1505 DATE 7-31-19 MILEAGE 332,132

OK DEF

- ☐ 1. Entrance door, operation, markings, hand rails
- ☐ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☐ 3. Horns- air and electric
- ☐ 4. Drivers seat- mounting, adjustment, seat belt
- ☐ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☐ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☐ 7. Low air warning- audible and or visual 60 psi min
- ☐ 8. Air tanks- drain, test check valves, perform split system test
- ☐ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☐ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☐ 12. Windshields, wipers, squirts, defrosters, sun shades, mirrors
- ☐ 13. Windows- cracks, mounting, leaks, labeling
- ☐ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☐ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☐ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☐ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☐ 18. Interior lighting and markings
- ☐ 19. Luggage bays- latches, handles, door operation, lighting
- ☐ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☐ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☐ 22. Engine accessories- mounting, cables, hoses, function
- ☐ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☐ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☐ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☐ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☐ 27. Air system overall- air dryer, valves, lines, hoses
- ☐ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☐ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☐ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☐ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☐ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☐ 34. Transmission/differential function, leaks, fluid level, vents, mounting
- ☐ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☐ 36. Frame- cracks, dents, damage, rust, holes, cross members, mounting
- ☐ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☐ 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

REPLACE LH FRONT  
LOW BEAM  
HEAD LITE

Lube Front Suspension

Notes:

Mechanic:

JAMES

Signature:

James A. Bryson

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 345.05 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 7-31-19 MILEAGE 332,132 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

Lubed FRONT SUSPENSIONS  
REPLACES LH LOW BEAM HEAD LITE WITH NEW  
ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James O. Byrd

## VEHICLE REPAIR & SERVICE FORM

UNIT # 7505 DATE: 7-28-19 MILEAGE: 331,336 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☒ Right front ☒

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☒

#### TIRE PRESURES

Left front 120 Right front 120

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag 120

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED LH & RH TAG TIRES WITH RUN OUTS  
REPLACED LH & RH FRONT TIRES WITH NEW ONES

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James A. Brigham

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 7-17-19 MILEAGE: 326,787 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED CANNISTER FUEL FILTER WITH NEW  
ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

*James O'Brien*

# Vehicle Inspection Report

UNIT# 1505 DATE 7-15-19 MILEAGE 326,050

OK DEF

- ☐ 1. Entrance door, operation, markings, hand rails
- ☐ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☐ 3. Horns- air and electric
- ☐ 4. Drivers seat- mounting, adjustment, seat belt
- ☐ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☐ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☐ 7. Low air warning- audible and or visual 60 psi min
- ☐ 8. Air tanks- drain, test check valves, perform split system test
- ☐ 9. Fire extinguisher, triangle reflectors (first aid kit (optional)
- ☐ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☐ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☐ 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☐ 13. Windows- cracks, mounting, leaks, labeling
- ☐ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☐ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☐ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☐ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☐ 18. Interior lighting and markings
- ☐ 19. Luggage bays- latches, handles, door operation, lighting
- ☐ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☐ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☐ 22. Engine accessories- mounting, cables, hoses, function
- ☐ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☐ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☐ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ 26. Cooling system- leaks, radiator, hoses, water pump, fan clutch, coolant level
- ☐ 27. Air system overall- air dryer, valves, lines, hoses
- ☐ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☐ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels, tires cracks, lug nuts/studs, tread depth, separation, pressure
- ☐ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☐ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☐ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☐ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☐ 35. Drive shaft- U-joints, slip joint, dents, blocking, safety hoop, straps, bolts
- ☐ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☐ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

ADD COOLANT  
REPLACE 2 clamps

Notes:

Mechanic: JAMES

Signature: James J. Byrnes

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 7-15-19 MILEAGE: 326,050 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_

Wiper Blades \_\_\_\_\_

Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_

A/C: \_\_\_\_\_

Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED LH TAG TIRE WITH RUN OUT  
CLEANED ALL A/C FILTERS

REPLACED ② COOLANT HOSE CLAMPS WITH  
NEW ONES

ADDED 1 GALLON COOLANT

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James A. Bingham*

# Vehicle Inspection Report

UNIT# 1505 DATE 7-2-19 MILEAGE 321,381

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squinters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clacking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

REPAIRED GUINE PAD  
FOR BOAT SIDE WINDOW  
SHADE

REPAIRED FUEL  
DOOR LOCK

Notes:

Mechanic: ISAMS

Signature: James A. Bynum

This inspection is equal to: Annual 49CFR 396.17-23 Appendix B and V/C 34505 Title 13 CCR 1232(b)

# VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 7-2-19 MILEAGE: 321,381 MECHANIC: JAMES

## ITEMS REPAIRED OR REPLACED

### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

### LIST REPAIRS AND DISCRIPTION OF WORK

REPAIRED FUEL DOOR LOCK DRIVERS SIDE  
REPAIRED ~~RO~~ GUIDE ROD FOR WINDSHIELD SHADE  
DOOR SIDE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

*James A. Bingham*



# Vehicle Inspection Report

UNIT# 1505 DATE 6-10-19 MILEAGE 315,797

OK DEF

- ☒ 1. Entrance door, operation, markings, hand rails
- ☒ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ 3. Horns- air and electric
- ☒ 4. Drivers seat- mounting, adjustment, seat belt
- ☒ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ 7. Low air warning- audible and or visual 60 psi min
- ☒ 8. Air tanks- drain, test check valves, perform split system test
- ☒ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ 12. Windshields, wipers, squirter, defrosters, sun shades, mirrors - INSTALL CRTE HOOK - 1  
ASSIST HANDLE
- ☒ 13. Windows- cracks, mounting, leaks, labeling
- ☒ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ 18. Interior lighting and markings
- ☒ 19. Luggage bays- latches, handles, door operation, lighting
- ☒ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ 22. Engine accessories- mounting, cables, hoses, function
- ☒ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level - ADDED 1 GALLON COOLANT
- ☒ 27. Air system overall- air dryer, valves, lines, hoses
- ☒ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ 33. Steering- king pins, ball joints, linkage steering box, hoses, noise, function
- ☒ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

Notes:

Mechanic:

JAMES

Signature:

James A Bingham

This inspection is equal to: A manual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 6-10-19 MILEAGE: 315,797 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACE LH TAG TIRE WITH RUN ON  
FILL WINDSHIELD WASHER FLUID RESERVOIR

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James A. Benjamin*

# Vehicle Inspection Report

UNIT# 1505 DATE 5-15-19 MILEAGE 312,293

OK DEF

- ☐ 1. Entrance door, operation, markings, hand rails
- ☐ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☐ 3. Horns- air and electric
- ☐ 4. Drivers seat- mounting, adjustment, seat belt
- ☐ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☐ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☐ 7. Low air warning- audible and or visual 60 psi min
- ☐ 8. Air tanks- drain, test check valves, perform split system test
- ☐ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☐ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☐ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☐ 12. Windshields, wipers, squirts, defrosters, sun shades, mirrors
- ☐ 13. Windows- cracks, mounting, leaks, labeling
- ☐ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☐ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☐ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☐ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☐ 18. Interior lighting and markings
- ☐ 19. Luggage bays- latches, handles, door operation, lighting
- ☐ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☐ 22. Engine accessories- mounting, cables, hoses, function
- ☐ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☐ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☐ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☐ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☐ 27. Air system overall- air dryer, valves, lines, hoses
- ☐ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☐ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☐ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☐ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☐ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☐ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☐ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☐ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☐ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☐ 38. Wheelchair lift- operation, safetys, markings, leaks, fluid level, cleanliness

REPAIRED REAR  
BUMPER

Notes:

Mechanic:

James

Signature:

James A. Bryant

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 5-15-19 MILEAGE: 312,293 MECHANIC: James

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front [ ] Right front [ ]

Left O/drive [ ] Right O/drive [ ]

Left I/drive [ ] Right I/drive [ ]

Left tag [ ] Right tag [ ]

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front [ ] Right front [ ]

Left O/dr [ ] Right O/dr [ ]

Left I/dr [ ] Right I/dr [ ]

Left tag [ ] Right tag [ ]

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPAIRED REAR BUMPER STRAIGHTENED BRACKET  
AND PUSHED BUMPER BACK INTO BRACKET BOLTED  
ALL DOWN

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James C. Benjamin*

# Vehicle Inspection Report

UNIT# 1505 DATE 4-29-19 MILEAGE 309,067

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirter, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

REPLACE TIRE  
WITH NEW ONES

Notes:

Mechanic:

JAMES

Signature:

James A. Bryan

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1509 DATE: 4-20-19 MILEAGE: 309,067 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☒ Right O/drive ☒

Left I/drive ☒ Right I/drive ☒

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr 110 Right O/dr 110

Left I/dr 110 Right I/dr 110

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

TIRES REPLACED , 4 RH INVER & OUTER DRIVE

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James C. Blyden

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 4-16-19 MILEAGE: 304,448 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

FILLED WINDSHIELD WASHER RESEVOIR  
REPLACED LH HIGH BEAM WITH NEW BULB

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James A. Byston

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 4-10-19 MILEAGE: 302,219 MECHANIC: JAMES GREGG

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

(GREGG) - REPLACED SUPPORT PULLEY FOR WATER PUMP  
TENSIONER

FILLED WINDSHIELD WASHER FLUID RESERVOIR  
REPLACED 5 COOLANT HOSE CLAMPS REPLACED ONE  
EXHAUST HOSE CLAMP  
ADDED COOLANT

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE JAMES GREGG



# Vehicle Inspection Report

UNIT# 1505

DATE 4-8-19

MILEAGE 301,464

OK DEF

- ☐ 1. Entrance door, operation, markings, hand rails
- ☐ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☐ 3. Horns- air and electric
- ☐ 4. Drivers seat- mounting, adjustment, seat belt
- ☐ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☐ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☐ 7. Low air warning- audible and or visual 60 psi min
- ☐ 8. Air tanks- drain, test check valves, perform split system test
- ☐ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat, ventin tush, dump valves, holding tank(s)
- ☐ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☐ 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☐ 13. Windows- cracks, mounting, leaks, labeling
- ☐ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☐ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☐ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☐ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☐ 18. Interior lighting and markings
- ☐ 19. Luggage bays- latches, handles, door operation, lighting
- ☐ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☐ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☐ 22. Engine accessories- mounting, cables, hoses, function
- ☐ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☐ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☐ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☐ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☐ 27. Air system overall- air dryer, valves, lines, hoses
- ☐ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☐ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels, tires cracks, lug nuts/studs, tread depth, separation, pressure
- ☐ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☐ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☐ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☐ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☐ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☐ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☐ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☐ 38. Wheelchair lift- operation, safetys, markings, leaks, fluid level, cleanliness

REPLACE FAN  
MOTOR  
DUMP VALVE  
REFILLED TOILET TANK

USE RH TAGS

Notes:

Mechanic:

JAMES

Signature:

James J. Benjamin

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1605 DATE: 4-8-19 MILEAGE: 301,464 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☒

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag 120

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: \_\_\_\_\_ Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

CLEANED ALL A/C FILTERS  
REPLACED TAG TIRES WITH RUN OUTS LH & RH  
REPLACED BATHROOM FAN MOTOR WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James A. Byrnes

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 3-26-19 MILEAGE: 297,044 MECHANIC: JAMES / CREW

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACE LEFT HAND TIRE WITH RUN OUT  
INSTALLED wheel chair LIFT

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James A. B. Jr.*

# Vehicle Inspection Report

UNIT# 1505 DATE 3-6-19 MILEAGE 294,199

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirter, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hat 118, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

PATCHED ESCAPE HATCHES  
WITH FLEX SEAL TO  
STOP LEAKS

40K OIL & FILTER CHANGE

REPLACED CANISTER  
& SPIN ON FUEL  
FILTERS

Notes:

Mechanic:

JAMES

Signature:

James J. Bejman

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 3-6-19 MILEAGE: 294,199 MECHANIC: James

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

CLEANED ALL A/C FILTERS & BATHROOM VENT SCREEN

DRAINED OIL ADDED NEW REPLACED OIL FILTERS Q# 1660

Q# 1791 WITH NEW ONES

WATER & SPIN ON FUEL FILTERS

WITH NEW ONES

TIGHTENED LEAKING COOLANT HOSE CLAMPS APPROX 6

ADDED COOLANT

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

James C. Baffier

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE 2-18-19 MILEAGE: 289,879 MECHANIC: JAMES / CREW

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

Windshields

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

Wiper Blades

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Batteries

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED PASSENGER SIDE WINDSHIELD WITH  
NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

James V. Byham

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1565 DATE: 2-15-19 MILEAGE: 389,393 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED AIR FILTER WITH NEW ONE  
#6623

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

*James V. Byle*

# Vehicle Inspection Report

UNIT# 1505 DATE 1-28-19 MILEAGE 286,278

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels tires cracks, lug nuts/studs tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

VELCRO STRIPS

REPLACE HEATSHIELD CONNECTOR & LITE

SPARE TIRE

Notes:

Mechanic: James

Signature: James O. Bingham

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)



## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 1-28-19 MILEAGE: 286,278 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

SPARE - 120lbs

#### TIRE PRESURES

#### BRAKE PADS

Left front ☐ Right front ☐ Left front \_\_\_\_\_ Right front \_\_\_\_\_ Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐ Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_ Left O/dr ☐ Right O/dr ☐  
Left I/drive ☐ Right I/drive ☐ Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_ Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐ Left tag \_\_\_\_\_ Right tag \_\_\_\_\_ Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED HEAD LITE ~~HIGH BEAM~~ CONNECTOR WITH NEW  
ONE REPLACED HIGH BEAM HEAD LITE WITH NEW ONE  
CLEANED ALL A/C FILTERS & BATHROOM VENT SCREEN  
REPLACED SPARE TIRE WITH NEW ONE  
REPLACED VELCRO STRIPS BATHROOM DOOR

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James C. Bryan

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 1-19-19 MILEAGE 284,441 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☒ Right tag ☒

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED LH TAG TIRE WITH RUN OUT  
REPLACED LH & RH TAG AXLE BRAKE PADS  
WITH NEW ONES

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James A. Brighton*

# Vehicle Inspection Report

UNIT# 1505 DATE 1-7-19 MILEAGE 282,729

OK DEF

- ☐ 1. Entrance door, operation, markings, hand rails
- ☐ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☐ 3. Horns- air and electric
- ☐ 4. Drivers seat- mounting, adjustment, seat belt
- ☐ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☐ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☐ 7. Low air warning- audible and or visual 60 psi min
- ☐ 8. Air tanks- drain, test check valves, perform split system test
- ☐ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☐ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☐ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☐ 12. Windshields, wipers, squirts, defrosters, sun shades, mirrors
- ☐ 13. Windows- cracks, mounting, leaks, labeling
- ☐ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☐ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☐ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☐ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☐ 18. Interior lighting and markings
- ☐ 19. Luggage bays- latches, handles, door operation, lighting
- ☐ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☐ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☐ 22. Engine accessories- mounting, cables, hoses, function
- ☐ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☐ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☐ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☐ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☐ 27. Air system overall- air dryer, valves, lines, hoses
- ☐ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☐ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels tires- cracks, lug nuts/studs, tread depth, separation, pressure 5 new tires  
REPAIR
- ☐ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☐ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☐ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☐ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☐ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☐ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☐ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

N/A

Notes: \_\_\_\_\_

Mechanic: James

Signature: James V. Byham

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 1-7-19 MILEAGE: 282,129 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☒

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag 120

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED ALL TAG TIRE WITH RUN OUT  
REPIRED SNOW CHAINS

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James C. Byrd*

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 12-4-18 MILEAGE: 273,727 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED DRIVER SIDE LOW BEAM HEAD LITE

REPLACED VEHICLE STRIPS ON BATTERY SIDE WITH  
NEW

REPAIRED HEAD LITE BRACKET DRIVERS SIDE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James V. Bigham

# Vehicle Inspection Report

UNIT# 1505 DATE 11-30-18 MILEAGE 272,405

OK DEF

- ☒ 1. Entrance door, operation, markings, hand rails
- ☒ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ 3. Horns- air and electric
- ☒ 4. Drivers seat- mounting, adjustment, seat belt
- ☒ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ 7. Low air warning- audible and or visual 60 psi min
- ☒ 8. Air tanks- drain, test check valves, perform split system test
- ☒ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat venting, flush, dump valves, holding tank(s)
- ☒ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☒ 13. Windows- cracks, mounting, leaks, labeling
- ☒ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ 18. Interior lighting and markings
- ☒ 19. Luggage bays- latches, handles, door operation, lighting
- ☒ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ 22. Engine accessories- mounting, cables, hoses, function
- ☒ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ 27. Air system overall- air dryer, valves, lines, hoses
- ☒ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheelchair lift- operation, safetys, markings, leaks, fluid level, cleanliness

DOOR STRAPS

UPPER REAR RED CLEARANCE

REPLACE ENGINE DOOR STOPS

Notes:

Mechanic:

JAMES

Signature:

James A. Byrd

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 11-30-18 MILEAGE: JAMES ✓ MECHANIC: 272, 405

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front [ ] Right front [ ]

Left O/drive [ ] Right O/drive [ ]

Left I/drive [ ] Right I/drive [ ]

Left tag [ ] Right tag [ ]

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front [ ] Right front [ ]

Left O/dr [ ] Right O/dr [ ]

Left I/dr [ ] Right I/dr [ ]

Left tag [ ] Right tag [ ]

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

CLEANED ALL A/C FILTERS & BATHROOM VENT SCREEN  
REPLACED VELCRO STRIPPING BATHROOM DOOR  
REPLACED ENGINE DOOR STICKS WITH NEW ONES  
REPAIRED COVER TO ELECTRONICS DRIVER SIDE DOOR  
BELOW WINDOW  
REPLACED REAR UPPER ROP CLEARANCE 2ND FROM  
LEFT WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

*James A. Byham*

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 11-26-18 MILEAGE: 271,644 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☒  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front 120  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED RH FRONT TIRE WITH NEW ONE  
REPLACED LH LOW BEAM HEADLIGHT WITH  
NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James T. Byrd*



## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 11/15/16 MILEAGE: 270312 MECHANIC: Troy

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

Replaced Driver side Drive tire bearing's

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE \_\_\_\_\_

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 11/19/18 MILEAGE: 270312 MECHANIC: Troy

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

Changed oil in diff

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

Troy

# Vehicle Inspection Report

UNIT# 1505

DATE 10-23-18

MILEAGE 268,320

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clacking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safetys, markings, leaks, fluid level, cleanliness

Upper Door won't open  
Fully

Notes:

Mechanic: JAMES

Signature: James A. Burghen

This inspection is equal to: Annual 49CFR 396.17-23 Appendix B and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 10-23-18 MILEAGE: 268,320 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPAIR UPPER wheel chage Door wont open all the way

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James C. Bryson

# Vehicle Inspection Report

UNIT# 1505

DATE 10-9-18

MILEAGE 265,488

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators, mounting, cables ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safetys, markings, leaks, fluid level, cleanliness

Also inspect cable  
Replace ground cable & main power cable  
to alternators 1- alternator

Notes: \_\_\_\_\_

Mechanic: James

Signature: James D. Bingham

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 10-9-18 MILEAGE: 265,488 MECHANIC: James

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

Clean all A/C Filters & Bathroom VENT SCREEN

REPLACE POSITIVE MAIN CABLE TO ALTERNATORS WITH

NEW ONE ALSO REPLACED POSITIVE Jumper cable TO ALTERNATES  
WITH NEW ONE

REPLACED GROUND CABLE TO ALTERNATOR BOTTOM WITH NEW  
ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James C. Bryan

# Vehicle Inspection Report

UNIT# 1505 DATE 9-25-18 MILEAGE 265,021

OK DEF

- ☒ 1. Entrance door, operation, markings, hand rails
- ☒ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ 3. Horns- air and electric
- ☒ 4. Drivers seat- mounting, adjustment, seat belt
- ☒ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ 7. Low air warning- audible and or visual 60 psi min
- ☒ 8. Air tanks- drain, test check valves, perform split system test
- ☒ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ 12. Windshields, wipers, squirts, defrosters, sun shades, mirrors
- ☒ 13. Windows- cracks, mounting, leaks, labeling
- ☒ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ 18. Interior lighting and markings
- ☒ 19. Luggage bays- latches, handles, door operation, lighting
- ☒ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ 22. Engine accessories- mounting, cables, hoses, function
- ☒ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level - Clamps @ 3"
- ☒ 27. Air system overall- air dryer, valves, lines, hoses
- ☒ 28. Brakes lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

Notes:

Mechanic:

James

Signature:

James A. Bytner

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 9-25-18 MILEAGE: 245,021 MECHANIC: JAMES GLENN

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☒ Right I/dr ☒

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED RH DRIVE AXLE HUB SEAL WITH NEW ONE  
REPLACED LH & RH DRIVE AXLE BRAKE PADS WITH  
NEW ONES  
REPLACED #2 ATTENUATOR WITH ONE  
REPLACED 4 COOLANT CLAMPS/HOSE WITH NEW ONES  
INSIDE TAG AXLE RH FENDER WELL

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James A. Bryan*



# Vehicle Inspection Report

UNIT# 1505 DATE 8-29-18 MILEAGE 260,011

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

Notes:

Mechanic:

JAMES

Signature:

James A. Benfren

This inspection is equal to: Annual 49CFR 396.17-23 Appendix C and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 8-29-18 MILEAGE: 262011 MECHANIC: James

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

CLEANED ALL MC FILTERS & BATHROOM VENT SCREEN  
REPAIRED LH LOWER WHEEL CHAIR DOOR  
REPLACED RH MIDDLE BAY LOWER AMBER CLEARANCE  
LITE WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James A. Bynon

# Vehicle Inspection Report

UNIT# 1505 DATE 8-3-18 MILEAGE 256,230

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirts, defrosters, sun shades, mirrors FILL WASHER FLUID RESERVOIR
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks CLEAN COILS NEAR FACE
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

Notes: \_\_\_\_\_

Mechanic: James

Signature: James A. Byrnes

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 8-3-18 MILEAGE: 256,230 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

CLEANED ALL A/C FILTERS & BATHROOM VENT SCREEN

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James C. Byham

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505DATE: 7-25-18MILEAGE: 255,437MECHANIC: JAMES / GREGG

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐Left O/drive ☐ Right O/drive ☐Left I/drive ☐ Right I/drive ☐Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐Left O/dr ☐ Right O/dr ☐Left I/dr ☐ Right I/dr ☐Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_

Wiper Blades \_\_\_\_\_

Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_

A/C: (2)Alts. (1)(1) WATER PUMP

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED A/C COMPRESSOR WITH NEW ONEREPLACED A/C BELTS - WATER PUMP - & ALTERNATOR BELT  
WITH NEW ONESREPLACED A/C CLUTCH WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: James / Gregg

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 7-16-18 MILEAGE: 254,841 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front [ ] Right front [ ]  
Left O/drive [ ] Right O/drive [ ]  
Left I/drive [ ] Right I/drive [ ]  
Left tag [ ] Right tag [ ]

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front [ ] Right front [ ]  
Left O/dr [ ] Right O/dr [ ]  
Left I/dr [ ] Right I/dr [ ]  
Left tag [ ] Right tag [ ]

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED LOW BEAM HEAD LITE & PLUG IN  
WITH NEW ONES LH SIDE

REPLACED HI BEAM HEAD LITE WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

*James A. Bingham*

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 7-10-18 MILEAGE: 253,174 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPAIRED WINDSHIELD SHADES LH & RH TIGHTENED ALL  
MOUNTING SCREWS & ALL SCREWS LOOSE & BINDING SHADES  
UP & STARTED STEERING

READJUSTED FRONT LEVEL VALVE

ADDED 1 GALLON COOLANT

REPLACED RUBBER TIE DOWN FOR FIRST AID KIT

REPAIRED BRACKET TO HOLD DOWN FIRE EXTINGUISHER  
SEATS BEHIND DRIVER

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James T. Bigham

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 7-6-18 MILEAGE: 251,691 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☒ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag 120 Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED L&R 746 TIRE WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James C. [Signature]



# Vehicle Inspection Report

UNIT# 1505 DATE 7-3-18 MILEAGE 251,691

OK DEF

- ☐ 1. Entrance door, operation, markings, hand rails
- ☐ 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☐ 3. Horns- air and electric
- ☐ 4. Drivers seat- mounting, adjustment, seat belt
- ☐ 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☐ 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☐ 7. Low air warning- audible and or visual 60 psi min
- ☐ 8. Air tanks- drain, test check valves, perform split system test
- ☐ 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ 10. Restroom- lighting, seat venting, flush, dump valves, holding tank(s) NEVER STRIPS Bathroom
- ☒ 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights DRIVER'S SIDE
- ☒ 12. Windshields, wipers, squirters, defrosters, sun shades, MIRRORS REPAIR/REPLACE
- ☐ 13. Windows- cracks, mounting, leaks, labeling
- ☐ 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☐ 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ 16. HVAC- function, fans, motor brushes filters, leaks
- ☐ 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☐ 18. Interior lighting and markings
- ☐ 19. Luggage bays- latches, handles, door operation, lighting
- ☒ 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch 40% oil & Filter change
- ☒ 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☐ 22. Engine accessories- mounting, cables, hoses, function
- ☐ 23. Alternators- mounting, cables, ducting, pulleys, output
- ☐ 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☐ 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☐ 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☐ 27. Air system overall- air dryer, valves, lines, hoses
- ☐ 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☐ 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☐ 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☐ 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☐ 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☐ 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☐ 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☐ 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☐ 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☐ 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

Notes:

Mechanic: JAMES

Signature: James T. Brennan

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT # 1505 DATE: 7-3-18 MILEAGE: 251,691 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

DRAIN OIL ADDED NEW REMOVED OIL FILTERS REPLACED  
WITH NEW ONES (2) #1791 (1) #1660

CLEANED ALL A/C FILTERS & BATHROOM VENT SCREEN

REPLACED VELCRO STRIPS ON BATHROOM DOOR

REPLACED DRIVER SIDE REAR VIEW & CONCAVE MIRROR  
WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_ MECHANIC'S SIGNATURE: James A. Byrnes

# Vehicle Inspection Report

UNIT# 1505 DATE 6-15-18 MILEAGE 248,943

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirter, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

Notes: \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Mechanic: JAMES CREEG

Signature: James C. Byham

This inspection is equal to Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 5-25-18 MILEAGE: 244,768 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED BATHROOM FLUSH MOTOR WITH NEW  
ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James A. Bayliss

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 5-24-18 MILEAGE: 244,768 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

### LIST REPAIRS AND DISCRIPTION OF WORK

REPAIRED TOILET FLUSHING MOTOR

REPLACED ALTERNATOR TENSIONER PULLEY WITH  
NEW ONE

REPLACED BELTING ON IDLER PULLEY WITH NEW  
ONE FOR A/C BELTS

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James V. Bingham*

# Vehicle Inspection Report

UNIT# 1505 DATE 5-21-18 MILEAGE 244,038

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squinters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safetys, markings, leaks, fluid level, cleanliness

Notes:

Mechanic:

JAMES

Signature:

James J. Benjamin

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 5-21-18 MILEAGE: 244,038 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐  
Left O/drive ☐ Right O/drive ☐  
Left I/drive ☐ Right I/drive ☐  
Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_  
Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_  
Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_  
Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐  
Left O/dr ☐ Right O/dr ☐  
Left I/dr ☐ Right I/dr ☐  
Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: 1 A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

- 1: \_\_\_\_\_
- 2: \_\_\_\_\_
- 3: \_\_\_\_\_
- 4: \_\_\_\_\_
- 5: \_\_\_\_\_
- 6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED RADIATOR FAN BELT WITH NEW ONE

ADDED 1 GALLON OIL

ADDED 1 GALLON COOLANT

REPLACED VELCRO STRIPS BATHROOM DOOR

REPAIRED & REMOUNTED REAR LICENSE PLATE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James P. Burman*

# Vehicle Inspection Report

UNIT# 1505 DATE 4-18-18 MILEAGE 240,366

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

REPLACE BATHROOM FAN MOTOR

ADD WASHER FLUID

CLEANED EVAPORATOR RADIATOR

Notes:

Mechanic:

JAMES

Signature:

James T. Brinson

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)



## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 4-18-18 MILEAGE: 240,366 MECHANIC: JAMES

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

CLEANED ALL A/C FILTERS & BATHROOM VENT SCREEN  
CLEANED EVAPORATOR RADIATOR & VACUUMED

FILLED WINDSHIELD WASHER FLUID RESERVOIR

REPLACED BATHROOM FAN MOTOR WITH NEW ONE

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James Bigham*

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 4-5-18 MILEAGE: 290,102 MECHANIC: JAMES/GRELL

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_

Wiper Blades \_\_\_\_\_

Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_

A/C: \_\_\_\_\_

Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED PASSENGER SIDE WINDSHIELD WITH  
NEW ONE

PATCHED FRAME OF FRONT ROOF ESCAPE HATCH  
LEAKING THROUGH RIVETS & FRAMING

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

*James A. Brennan*

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 4-4-18 MILEAGE: 237,738 MECHANIC: JAMES GREGG

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields 1 Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

#### Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED DRIVER SIDE WINDSHIELD WITH NEW ONE  
REPAIRED SNOW CHAINS

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

James A. Bingham

## VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 4-3-18 MILEAGE: 237,738 MECHANIC: JAMES GREGG

### ITEMS REPAIRED OR REPLACED

#### TIRES

Left front ☐ Right front ☐

Left O/dr ☒ Right O/dr ☒

Left I/dr ☒ Right I/dr ☒

Left tag ☐ Right tag ☐

Windshields 1

#### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr 100 Right O/dr 100

Left I/dr 100 Right I/dr 100

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

Wiper Blades \_\_\_\_\_

#### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Batteries \_\_\_\_\_

Engine belts: \_\_\_\_\_ Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

#### LIST REPAIRS AND DISCRIPTION OF WORK

REPLACED LH & RH DRIVE TIRES WITH NEW ONES

REPLACED DRIVER SIDE WINDSHIELD WITH NEW ONE

REPAIRED DOOR SIDE REAR FENDER HOLD DOWN BRACKET

REPAIRED SNOW CHAINS

REPLACED AIR FILTER WITH NEW ONE #6623

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE: \_\_\_\_\_

James A. Bingham

# VEHICLE REPAIR & SERVICE FORM

UNIT #: 1505 DATE: 3-29-18 MILEAGE: 236,570 MECHANIC: JAMES

## ITEMS REPAIRED OR REPLACED

### TIRES

Left front ☐ Right front ☐

Left O/drive ☐ Right O/drive ☐

Left I/drive ☐ Right I/drive ☐

Left tag ☐ Right tag ☐

### TIRE PRESURES

Left front \_\_\_\_\_ Right front \_\_\_\_\_

Left O/dr \_\_\_\_\_ Right O/dr \_\_\_\_\_

Left I/dr \_\_\_\_\_ Right I/dr \_\_\_\_\_

Left tag \_\_\_\_\_ Right tag \_\_\_\_\_

### BRAKE PADS

Left front ☐ Right front ☐

Left O/dr ☐ Right O/dr ☐

Left I/dr ☐ Right I/dr ☐

Left tag ☐ Right tag ☐

Windshields \_\_\_\_\_ Wiper Blades \_\_\_\_\_ Batteries \_\_\_\_\_

Engine belts: Cooling fans: \_\_\_\_\_ A/C: \_\_\_\_\_ Alts.: \_\_\_\_\_

Warranty Part Numbers for replacement:

1: \_\_\_\_\_

2: \_\_\_\_\_

3: \_\_\_\_\_

4: \_\_\_\_\_

5: \_\_\_\_\_

6: \_\_\_\_\_

### LIST REPAIRS AND DISCRIPTION OF WORK

REPAIRED SNOW CHAINS

TOTAL WORK HOURS: \_\_\_\_\_

MECHANIC'S SIGNATURE

James A. Bunting

# Vehicle Inspection Report

UNIT# 1505

DATE 3-27-18

MILEAGE 235,888

OK DEF

- ☒ [ ] 1. Entrance door, operation, markings, hand rails
- ☒ [ ] 2. Instruments, dash lights, switches, knobs, levers, readouts, gauges
- ☒ [ ] 3. Horns- air and electric
- ☒ [ ] 4. Drivers seat- mounting, adjustment, seat belt
- ☒ [ ] 5. Air compressor/governor- cut in/cut out 85 min-130 max psi
- ☒ [ ] 6. Brake air leaks- 2 psi/minute (static), 3 psi/minute (applied)
- ☒ [ ] 7. Low air warning- audible and or visual 60 psi min
- ☒ [ ] 8. Air tanks- drain, test check valves, perform split system test
- ☒ [ ] 9. Fire extinguisher, triangle reflectors(3), first aid kit (optional)
- ☒ [ ] 10. Restroom- lighting, seat, venting, flush, dump valves, holding tank(s)
- ☒ [ ] 11. Exterior lights, turn signals, emergency flashers, back up alarm and lights
- ☒ [ ] 12. Windshields, wipers, squirters, defrosters, sun shades, mirrors
- ☒ [ ] 13. Windows- cracks, mounting, leaks, labeling
- ☒ [ ] 14. Emergency exits- roof hatches, side windows, labeling and operation
- ☒ [ ] 15. Multimedia system- PA, audio/video, CD/DVD, amp, speakers
- ☒ [ ] 16. HVAC- function, fans, motor brushes, filters, leaks
- ☒ [ ] 17. Passenger seats- mounting, seat belts, condition, sliding (if W/C equipped)
- ☒ [ ] 18. Interior lighting and markings
- ☒ [ ] 19. Luggage bays- latches, handles, door operation, lighting
- ☒ [ ] 20. Batteries- fluid, terminals, cables, corrosion, hold down, shut off switch
- ☒ [ ] 21. Engine bay- cleanliness, fluid leaks, fluid levels, belts, pulleys, mounts
- ☒ [ ] 22. Engine accessories- mounting, cables, hoses, function
- ☒ [ ] 23. Alternators- mounting, cables, ducting, pulleys, output
- ☒ [ ] 24. Exhaust- leaks, mounting, tail pipe, overall condition
- ☒ [ ] 25. Fuel system- leaks, hose routing, securement, tank mounting, filler necks/caps
- ☒ [ ] 26. Cooling system- leaks, radiator, hoses, miter box, fan clutch, coolant level
- ☒ [ ] 27. Air system overall- air dryer, valves, lines, hoses
- ☒ [ ] 28. Brakes- lining thickness, rotors, cracks, chambers, adjustment, operation
- ☒ [ ] 29. Parking brake- push/pull, release/apply, stays applied with complete loss of air
- ☒ [ ] 30. Wheels, tires- cracks, lug nuts/studs, tread depth, separation, pressure
- ☒ [ ] 31. Hubs- end play, leaks, ABS sensor, overall condition
- ☒ [ ] 32. Suspension- air bags, radius rods, bushings, shocks, mounting, leveling valves
- ☒ [ ] 33. Steering- king pins, ball joints, linkage, steering box, hoses, noise, function
- ☒ [ ] 34. Transmission/differential- function, leaks, fluid level, vents, mounting
- ☒ [ ] 35. Drive shaft- U-joints, slip joint, dents, clocking, safety hoop, straps, bolts
- ☒ [ ] 36. Frame- cracks, dents, damage, rust, holes, crossmembers, mounting
- ☒ [ ] 37. Chassis and undercarriage- overall condition, lubrication, dirt, grime build up
- ☒ [ ] 38. Wheelchair lift- operation, safety, markings, leaks, fluid level, cleanliness

N/A

Notes:

Mechanic: JAMES

Signature: James A. Brangan

This inspection is equal to: Annual 49CFR 396.17-23 Appendix G and V/C 34505 Title 13 CCR 1232(b)